

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

**SERVICE PRE-INVOICE**

Attn: Marcus (L.k.k.)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

5 days

Customer: WZM003 / MSIG INSURANCE
Chassis No: MRHGM26709P020344
License No: SJQ4934X
Mileage: 112824
Engine No: L15A71806685

Document No: SVO19033090
Printed By: CSLIM
Order Date: 27. May 2019
Order Time: 8:32:18 AM
Service Advisor: LIM CHOU SIONG

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 72765) OWNER: KASTURIBHAI D/O/ RAMIAH OWNER INSURER: NTUC INCOME INSURANCE ACC DATE: 10/05/2019 SURVEYED BY: LKK MARCUS DATE: 15/5/19 REF NO: TP INSURER: MSIG INSURANCE TP VEH: SLS5356Z						
71501-TM0-T00ZH	FACEREAR BUMPER	1	463.70	25	347.77	24.34	372.11
71598-TM0-T00	SPACER L RR BUMPER SIDE	1	14.80	25	11.10	0.78	11.88
91503-SZ3-003	CLIP, ABUMPER	2	3.90	25	5.85	0.41	6.26
75725-TM0-T00	EMBLEM RR I-VTEC	1	22.20	25	16.65	1.17	17.82
68500-TM0-T20ZZ	LID COMP TRUNK	1	420.90	25	315.67	22.10	337.77
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00		45.00	3.15	48.15
75701-TM0-000	EMBLEM H	1	17.80	25	13.35	0.93	14.28
	SUM PARTS:				755.39	52.88	808.27
BOSUN	0760	1	10.00		10.00	0.70	10.70
	SUNDRIES						
BA01R	1864	1	100.00		100.00	7.00	107.00
	REMOVE & RENEW REVERSE SENSORS-2 PCS (N)						
BMI03D	1864	1	180.00		180.00	12.60	192.60
	REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)						
BML02I	0760	1	100.00		100.00	7.00	107.00
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)						
BKRP02M	1864	1	1,120.00		1,120.00	78.40	1,198.40
	CUT OFF & RENEW RR PANEL. STRAIGHTEN ALIGN FLOOR PANEL INCLUDING FITTINGS ON ATTACHMENT ITEM						
BP05R	EXT-YBH	1	1,350.00		1,350.00	94.50	1,444.50
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(5P)						
	SUM LABOUR:				2,860.00	200.20	3,060.20
	TOTAL SGD				3,615.39	253.08	3,868.47
	Total Payable (SGD)						3,868.47

GST Amount is calculated from individual line(s)



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: MSIG INSURANCE (SINGAPORE) PTE LTD 16 RAFFLES QUAY HONG LEONG BUILDING SINGAPORE 048581	Document No.	: SQT19002572	Page	1
Registration No	: SJQ4934X	Date	: 11. Jun 2019	Customer No.	: WZM003
Chassis No	: MRHGM26709P020344	Svc Advisor	: LIM CHOU SIONG	Engine No	: L15A71806685
Model	: CITY 1.5 SV AUTO	Date Time	: 11. Jun 2019 6:16:11 PM	Surveyor Name	:
Owner's Name	: KASTURIBHAI D/O RAMIAH	Survey Date	:	Authorisation Date	:
Ins Policy No.	:				
Date of Accident	: 10/5/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 72765) OWNER: KASTURIBHAI D/O RAMIAH OWNER INSURER: NTUC INCOME INSURANCE ACC DATE: 10/05/2019 SURVEYED BY: LKK MARCUS DATE: 15/5/19 REF NO: TP INSURER: MSIG INSURANCE TP VEH: SLS5356Z SUPPLEMENTARY LABOUR & PARTS						
75701-TM0-000	EMBLEM H	1	17.80	25	13.35	0.93	14.28
				Sum Item	13.35	0.93	14.28

Survey By							
Date & Time				Total Amount	13.35	0.93	14.28
Excess				Total (Inclusive of GST)			14.28
Status							
Signature							

Printed on 11/6/2019 6:21:36 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.