

22/03/2014

ASS. REC. BY:

REF:

CS/INC19008514/Plg d307

Special Instruction:

Surveyor: Tauklich

ASSIGNMENT (Office)

From (Person): Annie Koh

of

INC

Date/Time: 14/5/19 @ 9:51am

Estimated Cost:

Bill to:

OD / FF / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLF 6832C

Insured:

SJF 1195P

at Workshop m/s

Esteem Performance

Tel:

87990066

of

385 Sin Ming Drive

Policy No:

Claim No:

MT/1043823-001

Sum Insured:

Excess:

Make of Veh:

D.O.A.

02/02/2019

(Client's Record)

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

Date/Time:

10:00am @ 14/5/19

Person Contacted:

Carmen

Vehicle

IN/OUT

Date/Time	Action/Instruction
	Estimate ✓
	SLF 6832C-X
	SJF 1195P-X
10/6/19 @	2:13pm confirmed with Jenny final fig. \$1300.00, 2 days.
	(led \$2683.77, 67%)


Surveyor

Taylor

REF: INC

ASSIGNMENT

From: _____ Date: **14/5/19**
 Estimated Cost: _____
 OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: **SLF 6832C**
 at Workshop m/s **Estium Performance**
 of **385 Sn Ming Drive**
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: **2** days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS **up**

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: **SLF 6832C** Yr Regn: **2461 Sep**
 Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **Toyota Prius Hybrid** C.C. **1798**
 Colour: **White** A/C: **Insured / Std / NI / NA**
 Sp. Reading: **242492** T/Radio: **Insured / Std / NI / NA**
 Eng/No: _____
 C/No: **JPKB3F4403531814**
 Gen. Cond: **Good** / Fair / Poor / Burnt
 Steering: **Inorder** / Jammed / Leaked / Burnt or
 Brake: **Inorder** / Jammed / Leaked / Burnt or
 Modi: **Nil** / ☒ S/Rim / STD A/Rim or
 Tyre Size: F: **195/65R15**
 R: **195/65R15**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.		D.O.I.	14/8/19 05/Sp

Survey held at **Estium Ref**

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 10 JUN 2019

Date/Time, File Pass to?

1) **14/6/19**

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I.: (\$ **1300.08**)

Days Of Repair: **2**

Resurvey No. of Trip: **1**

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Survey Fee:

Transportation:

☐ S + RS ☐ SI

☐ Photos

☐ Others

TOTAL

290

290

Nivitha (LKK Auto)

From: Cynthia Ang <Cynthia.Ang@income.com.sg>
Sent: Tuesday, 14 May 2019 11:16 AM
To: 'assignments@lkkauto.com'
Subject: RE: TP CASES FARMED OUT TO LKK ON 14/05/2019

Dear LKK,

Resend with the following details.

Thank you.

With Regards

Cynthia Ang
Admin Assistant
Motor Insurance
T +65 6430 7900
www.income.com.sg

income
made different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers

in with you

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

From: Annie Koh
Sent: Tuesday, 14 May 2019 9:51 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>; Cynthia Ang <Cynthia.Ang@income.com.sg>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Teng Ken Leong <kenleong.teng@income.com.sg>
Subject: RE: TP CASES FARMED OUT TO LKK ON 14/05/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	Helena Tan	MT/1044374-001	SGF9666E	EM-1 AUTO PTE. LTD.	BLK 8 #01-68 SIN MING INDUSTRIAL EST SECTOR C SINGAPORE 575643	KAREN / 9666+6556		YP4984D	11/05/2019	
2	Fiona Shen	MT/1043823-001	SLF6832C	ESTEEM PERFORMANCE PTE LTD	385 SIN MING DRIVE VICOM INSPECTION CENTRE SINGAPORE 575718	Carmen Lim/6484 1221 / 8799 0066	11:00-12:00	SJF1195P	02/02/2019	
3	Jeff Lin	MT/1044250-001	GBH2121E	FULCO AUTOCARE PTE LTD	176 SIN MING DRIVE #03-02 SIN MING AUTOCARE	Jenny / 96391626		YN6003H	09/05/2019	
4	David Phua	MT/1041919-002	GBB1695D	MEGA AUTO PTE LTD	160 SIN MING DRIVE #02-01 SIN MING AUTOCITY	MR MENG / 97582943		YP9237U	26/04/2019	
5	Azhari	MT/1043758-002	SBI2848G	SUPREME AUTO SERVICE PTE LTD	176 SIN MING DRIVE #02-01 SIN MING AUTOCARE SINGAPORE 575721	Admin / 64528211		GBJ1100L	09/05/2019	Call workshop b4 survey
6	Jared Liu	MT/1043407-002	SLG9127E	TEAMWORK GARAGE PTE LTD	53 UBI AVENUE 1 #01-24 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934	DARREN / 68442475		SMJ245D	06/05/2019	
7	Jared Liu	MT/1043815-002	SMA8238U	TEAMWORK GARAGE PTE LTD	53 UBI AVENUE 1 #01-24	SHU SHAN / 68442475		SJL1464G	09/05/2019	

8	Jared Liu	MT/1037847-002	SJW2484J	TEAMWORK GARAGE PTE LTD	PAYA UBI INDUSTRIAL PARK SINGAPORE 408934	53 UBI AVENUE 1 #01-24 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934	darren / 68442475	ER8010P	27/03/2019	
---	-----------	----------------	----------	-------------------------	---	--	-------------------	---------	------------	--

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Annie Koh
Senior Admin Assistant, Motor Insurance
T +65 6430 7899
www.income.com.sg



Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 10 June 2019 2:13 PM
To: jenny chong; Taufikh (LKKAUTO); SUR
Cc: carmen lim; serence ctc; coleen kwok
Subject: RE: FINALISED SLF6832C

Dear Jenny,

WITHOUT PREJUDICE

Confirm final fig \$1,300.08 and 2 repair days.

Kindly send the relevant documents to NTUC Insurance company.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: jenny chong <jenny@esteemperf.com.sg>
Sent: Saturday, 8 June 2019 11:58 PM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: carmen lim <carmen@esteemperf.com.sg>; serence ctc <serence@esteemperf.com.sg>; coleen kwok <coleen21@esteemperf.com.sg>
Subject: FINALISED SLF6832C

Dear Tau fi

Pls refer as attached.

Kindly confirm the finalised amount asap.

Thank you



Freundliche Grüße / Best Regards

Jenny Chong

Senior Operation Executive | Operation Division

Esteem Performance Pte Ltd

P: 6484 1221

F: 6484 7829

E: jenny@esteemperf.com.sg

5033 Ang Mo Kio Industrial Park 2 #01-259

(Head Office)

385 Sin Ming Drive Vicom Inspection Centre

(Showroom)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/02/2019 21:21
Date Of Accident	02/02/2019 17:10
Exact Location Of Accident	JUNCTION OF EUNOS LINK & KAKI BUKIT AVE 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLF6832C
Insured/Policyholder	
Name Of Registered Owner	GRAB RENTALS PTE LTD
Co Reg No	201617200G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66550005

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS HYBRID 1.8 CVT
Exact Purpose for which vehicle was being used at time of accident	HIRE & REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	A29069766MKF
Cover Note Number	

Driver

Name of Driver	LEE POH KAIT
NRIC No	S1816547C
Date Of Birth	18/07/1967
Occupation	OUTDOOR
Date Of Driving Pass	23/08/1988
Driving Experience	30 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93791811
Fax Number	
Contact Number	
EMail Address	SPENCER.LEE.LS98@GMAIL.COM

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : MR ANG GENDER: : MALE
Passenger 2	NAME: : P2 GENDER: : MALE
Passenger 3	NAME: : P3 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

My car SLF6832C was stationary at the traffic light junction of EUNOS LINK & KAKI BUKIT AVE 1, when suddenly a car SJF1195P hit onto rear of my SLF6832C. No injuries to all my passengers & me. That's all.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	RETRIEVING
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJF1195P
Vehicle Make/Model/Colour	TOYOTA/ESTIMA AERAS 2.4 A
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	NING TAU YEE

NRIC/Passport Number

S7116389Z

Contact Number

98509241

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN**IMPORTANT NOTICE**


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be completed by the **Policyholder** and/or the **Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

**VERIFIED BY AJAX MARS
REPORTING OFFICER
MOHD FADZLY BIN ISMAIL**

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel

Sketch Plan

ACCIDENT STATEMENT (2000 characters)

My car SLF6832C was stationary at the traffic light junction of EUNOS LINK & KAKI BUKIT AVE 1, when suddenly a car SJF1195P hit onto rear of my SLF6832C. No injuries to all my passengers & me. That's all.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MOHD FADZLY BIN ISMAIL

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

8 February 2019 at 3:55 PM

Date/Time:

8 February 2019 at 3:55 PM



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLF 6832 C

Parts	(a) Cost / List Price Items	\$	2,197.80
	Plus/Less 25%	\$	549.45
	Total of Cost / List	\$	1,648.35
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	245.00
Total Parts Cost		\$	1,893.35
Labour		\$	2,090.00
Total		\$	3,983.35

The above total will be subjected to 7% G.S.T.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a 'Without Prejudice' basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Name of Surveyor : Tan Jiah 97495749 / 67418434

Company : LKK

Survey conducted on : 14/5/19 at P 515pm

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 02 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$

(e) Signature of surveyor : Jupia

Date: 14/5/19



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SLF 6832 C**
Make & Model : **TOYOTA PRIUS**
Chassis No : **JTDKB3FU403531814**

Submit By : **Carmen Lim**
Year Manufacture : **2016**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear number plate	1	\$45.00	S.N	x nn
2	Reverse sensor	1	\$200.00	S.N	x nn
3	Rear bumper	1	\$497.50		de
4	Rear bumper clip	10	\$40.00		re
5	Rear bumper side retainer LH	1	\$112.70		x nn
6	Rear bumper side retainer RH	1	\$112.70		x nn
7	Rear bumper reinforcement	1	\$398.90		? x nn
8	Rear bumper lower garnish centre	1	\$582.60		cut
9	Rear bumper lower garnish LH	1	\$149.70		x
10	Rear bumper lower garnish RH	1	\$149.70		x
11	Rear bumper tow cover	1	\$31.70		x } pan
12	RH rear fender undershield	1	\$92.30		x
13	RH rear fender undershield clip	10	\$30.00		x
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SLF 6832 C** Submit By : **Carmen Lim**
Make & Model : **TOYOTA PRIUS** Year of Manufacture : **2016**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, END PANEL, SPARE TYRE COMPARTMENT)	\$800.00	200
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, END PANEL, SPARE TYRE COMPARTMENT)	\$800.00	200
3	TO Check wiring	\$50.00	30
4	To tuff coat.	\$50.00	X
5	To transfer boot mechanism to new boot	\$120.00	X
6	To conduct water leakage tests to ensure proper air and sealing	\$120.00	X
7	To remove & refit reverse sensor	\$150.00	30

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLF 6832 C

Finalised

Parts (a) Cost / List Price Items	\$ 1170.10	2,197.80
Plus/Less 25%	\$ 280.03	549.45
Total of Cost / List	\$ 840.07	1,648.35
(b) Nett Price Items		
Less		
Total of Nett Item		
(c) Special Nett Items	\$	245.00
Total Parts Cost	\$ 840.07	1,893.35
Labour	\$ 460.00	2,090.00
Total	\$ 1300.07	3,983.35

The above total will be subjected to 7% G.S.T.

Name of Surveyor	:	Tan Jiah	97495749 / 67418434
Company	:	LUK.	
Survey conducted on	:	14/5/19	at 9:51pm
<u>Remarks By Surveyor</u>			
(a) The repair of this vehicle is authorized / is not authorized until further notice.	sure (hkauto.com)		
(b) Recommended Days of Repair	:	02	day(s)
(c) Resurvey	:	Required / Not Required	Resurvey before paint.
(d) Excess	:	\$	part by part.
(e) Signature of surveyor	:	Jiah	Date: 14/5/19



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.

Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : SLF 6832 C
Make & Model : TOYOTA PRIUS
Chassis No : JTDKB3FU403531814

Submit By : Carmen Lim
Year Manufacture : 2016
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear number plate	1	\$45.00	S.N	X
2	Reverse sensor	1	\$200.00	S.N	X
3	Rear bumper	1	\$497.50		der
4	Rear bumper clip	10	\$40.00		re
5	Rear bumper side retainer LH	1	\$112.70		X
6	Rear bumper side retainer RH	1	\$112.70		X
7	Rear bumper reinforcement	1	\$398.90		?
8	Rear bumper lower garnish centre	1	\$582.60		cut
9	Rear bumper lower garnish LH	1	\$149.70		X
10	Rear bumper lower garnish RH	1	\$149.70		X
11	Rear bumper tow cover	1	\$31.70		X
12	RH rear fender undershield	1	\$92.30		X
13	RH rear fender undershield clip	10	\$30.00		X
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

31k 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829
Company Reg No. 200005485N / GST No. 20-0005485-N

1170.10



ESTEEM PERFORMANCE PTE LTD.

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SLF 6832 C** Submit By : **Carmen Lim**
Make & Model : **TOYOTA PRIUS** Year of Manufacture : **2016**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, END PANEL, SPARE TYRE COMPARTMENT)	\$800.00	200
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, END PANEL, SPARE TYRE COMPARTMENT)	\$800.00	200
3	TO Check wiring	\$50.00	30
4	To tuff coat.	\$50.00	X
5	To transfer boot mechanism to new boot	\$120.00	X
6	To conduct water leakage tests to ensure proper air and sealing	\$120.00	X
7	To remove & refit reverse sensor	\$150.00	30

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

Company Reg No. 200005485N / GST No. 20-0005485-N

460

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19008514/T1qd3e2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 11-06-2019



ATTN: FIONA SHEN

Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJF 1195P	Veh. Inspected	SLF 6832C
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1043823-001	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	14/05/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS HYBRID	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JTDKB3FU403531814	Colour	WHITE
Odometer	242492 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	YOKOHAMA	6 mm
L/H Front Tyre	195/65 R15	YOKOHAMA	6 mm
R/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm
L/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	02/02/2019	Inspect Date / Time	14/05/2019 (05:15 PM)
Survey held at	385 SIN MING DRIVE		
Repairer	ESTEEM PERFORMANCE PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 6832C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	497.50	497.50
10	REAR BUMPER CLIP	NECESSARY	40.00	40.00
1	REAR BUMPER SIDE RETAINER LH	NOT NECESSARY	112.70	-
1	REAR BUMPER SIDE RETAINER RH	NOT NECESSARY	112.70	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	398.90	-
1	REAR BUMPER LOWER GARNISH CENTRE	CUT	582.60	582.60
1	REAR BUMPER LOWER GARNISH LH	NOT NECESSARY	149.70	-
1	REAR BUMPER LOWER GARNISH RH	NOT NECESSARY	149.70	-
1	REAR BUMPER TOW COVER	NOT NECESSARY	31.70	-
1	RH REAR FENDER UNDERSHIELD	NOT NECESSARY	92.30	-
10	RH REAR FENDER UNDERSHIELD CLIP	NOT NECESSARY	30.00	-
	LESS 25% DISCOUNT		-549.45	-280.02
			1,648.35	840.08
<u>SPECIAL NETT ITEMS</u>				
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	45.00	-
1	REVERSE SENSOR (SN)	NOT NECESSARY	200.00	-
			245.00	-
<u>LABOUR</u>				
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, END PANEL, SPARE TYRE COMPARTMENT).		800.00	200.00
	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, END PANEL, SPARE TYRE COMPARTMENT).		800.00	200.00
	TO CHECK WIRING.		50.00	30.00
	TO TUFF COAT.	NOT NECESSARY	50.00	-
	TO TRANSFER BOOT MECHANISM TO NEW BOOT.	NOT NECESSARY	120.00	-
	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING.	NOT NECESSARY	120.00	-
	TO REMOVE & REFIT REVERSE SENSOR.		150.00	30.00
			2,090.00	460.00

Report Ref No. CS/INC19008514/T1qd3e2



GRAND TOTAL		3,983.35	1,300.08
RECOMMENDED COST OF REPAIRS (CONFIRMED)			1,300.08

Report Ref No. CS/INC19008514/T1qd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.