

ASS. REC. BY:

REF: CS/MSG19008531/Rlg d 3024

Special Instruction:

Surveyor: Rasul**ASSIGNMENT (Office)**From (Person): Vinimah D/o Raja Sengap

MS19

Date/Time: 14.5.19 15.54pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SJU 7506H

Insured:

at Workshop n/a SNG Ah Tee Motor & PanelTel: 62686183of Blk 3 Pioneer Road NorthPolicy No: A80457553mcxClaim No: 593267

Sum Insured:

Excess: \$3500.00

Make of Veh:

(Client's Record)

D.O.A

9.5.201915.5.2019CA **(REV)** / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 14.5.19 4.16pm

Person Contacted:

JoyceVehicle **(IN)** / OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SJU 7506H - X</u>
<u>16/5/19 @</u>	<u>5.10pm visit to Vinimah via Merimee. Pending Cof from respective</u>
<u>27/5/19</u>	<u>Submit Uneconomical Total Loss Report.</u>

Signature: *[Signature]*

REF: MS19

ASSIGNMENT

From:

Date:

15.5.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SJU 7506H

at Workshop m/s SNG AH Tee motor
of Bkt 3 Pioneer Road North

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

\$3500.00


(Client's Record)

Make of Veh:

Morning

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Est. or Market Value:

14K

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res:

Yes or No

Lum Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJU 7506H

Yr Regn:

2009 / 06C

Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

TOYOTA COROLLA ALTIS 1.6A c.c 1598

Colour:

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading:

133165

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MR053206 106162473

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ Order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ Order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modi: Nil / ☒ R/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

FALKEN

Front

Rear

R/Bal:

mm

R/Bal:

mm

L/Bal:

mm

L/Bal:

mm

D.O.A:

09/05/19

D.O.I:

15/05/19

Survey held at

SNG AH TEE

Des. of Damages:

Front

Rear

O/S

N/S

U/C

Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Surveyor to check on market value and rebate if the vehicle is economical to repair.
Manufacture year 2009. Please check on the tyres, brake and steering wheel
is in efficient condition prior to the accident.

Check on tyres in good condition, steering wheel checks in proper &
function well, brake test efficient.

RECEIVED 23 MAY 2019

Date/Time, File Pass to?

☐

: Preli. Report

11 23/5 2019

☐

: Final Report

Date/Time, File Return to?

29

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ + R/S \$

Photos

U/Bora

U/Bora

U/Bora

U/Bora

U/Bora

U/Bora

U/Bora

U/Bora

U/Bora

Report Format:

WER-00/14

Lump Sum / I.B.I: (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Weekend (\$

200

10

210

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 May 2019 Sendback Est	14 May 2019 11:52 S\$18,743.94	14 May 2019 15:54 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	BK SAN ENGINEERING PTE LTD , Co. Reg. No.: 200700618K, Tel: +6591009252								
Vehicle Reg. No.:	SJU7506H	Date of Loss:	09/05/2019 13:00 - :59 [112 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 593267	Policy/Cover Note No.:	A80457553MCX (Comprehensive) Coverage: 16/05/2018 - 15/05/2019						
		Excess:	S\$3,500.00						
Repairer:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18, 628457 Pioneer - Tel: 6268 6183								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Vimmala D/O Raja Singam - 65942471]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 15/05/2019]								
Driver/Custodian:	LAKSHMANAN PADIYAN (35 / Male) , NRIC: G6027454T, Tel: +6583338527 Email:								
Adj Asg. Remarks:	Please revert. Surveyor to check on market value and rebate if the vehicle is economical to repair. Manufacturing year:2009. Please check on the tyres,brake and steering wheel is in efficient condition prior to the accident.								
ASSOCIATED MAIL RECEIVED									
			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS									
		View All	Search Tasks	Create New Task	Complete				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Vimmla D/O Raja Singam

Date: 16 May 2019

Preliminary Advice

Vehicle No	: SJU7506H	Accident Date	: 09/05/2019
Make	: TOYOTA COROLLA ALTIS	Policy No.	: A80457553MCX
Assignment Date	: 14/05/2019	Excess	: S\$500.00
Date of Inspection	: 15/05/2019	Est. Duration of Repair	: 14.00
Inspection At	: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER) BLK 3 PIONEER ROAD NORTH, #01-18 SINGAPORE 628457		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front & n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,743.94
Revised Amount	:S\$	13,492.64
Check Items (Estimated)	:S\$	4,658.50
Total	:S\$	18,151.14

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	14,000.00
COE / PARF Rebate	:S\$	10,048.00
Salvage Value	:S\$	
Margin for Repair	:S\$	3,952.00

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis. PENDING REPAIR COST FROM REPAIRER.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0618K
Vehicle Details	
Vehicle No.:	SJU7506H
Vehicle to be Exported:	No
Intended Deregistration Date:	14 May 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	3ZZ4955502
Chassis No.:	MR053ZEE106162473
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$17,853.00
Original Registration Date:	28 Dec 2009
First Registration Date:	28 Dec 2009
Transfer Count:	1
Actual ARF Paid:	\$17,853.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Dec 2019
PARF Rebate Amount:	\$8,926.00
Intended COE Rebate Details	
COE Expiry Date:	27 Dec 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$18,150.00
COE Rebate Amount:	\$1,122.00
Total Rebate Amount:	\$10,048.00

The information contained herein is correct as at 10 May 2019

OK

14,000
10,048

3952

- Malaysian teen died after Instagram suicide post
- DIY punctured tyre
- 2016 Hyundai Elantra / Avante

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

BMW X1 SDrive 18i



Black On Black BMW X1 SUV in
Great Condition.
Direct Owner (Singapore)

Lake View Credit Pte Ltd

view our cars

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable

Browse by Category

« Back (1 2 3 4 5 6 7 8) Next »

Sort by Date Posted 20 results/page

149 vehicles

ALTIS 1.6

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	ALTIS 1.6		Any	Any	2009	Any	Any	Any	Available
	Toyota	Corolla Altis 1.6A (COE till 04/2024)	\$35,800	\$7,220 /yr	21-May-2009	1,598 cc	-	Sedan	Available
1 Owner Only! Well Maintained! Low Mileage Done! New Paintwork, \$4000 Worth Of Wear And Tear Parts Replacement Cost, Drive Off With No Worried, 100% In-house Loan And High Trade In Available, Doorstep... ASWIN (1994) Pte Ltd Posted: 10-May-2019 Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota									
	Toyota	Corolla Altis 1.6A (COE till 04/2024)	\$32,800	\$6,610 /yr	16-Jun-2009	1,598 cc	125,278 km	Sedan	Available
One Meticulous Owner. Under-Usage Low Mileage, Most Reliable Japanese Sedan Altis Ideally For Daily Drives. Cheapest In The Market, Don't Hesitate Anymore Grab The Lower April PQP, COE Prices Have Ris... Posted: 10-May-2019 Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota									
	Toyota	Corolla Altis 1.6A (COE till 04/2024)	\$32,800	\$6,630 /yr	27-Apr-2009	1,598 cc	-	Sedan	Available
Low Ownership Low Mileage! Well Groomed Inside Out. No Repairs Needed. Comes With 6 Months Warranty By Our In House Workshop. Free Island Wide Towing In Event Of Emergency. We Provide Loans, Trade In, ... Posted: 10-May-2019 Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota									
	Toyota	Corolla Altis 1.6A (COE till 04/2024)	\$32,800	\$6,620 /yr	28-Apr-2009	1,598 cc	129,000 km	Sedan	Available
Flexible In House Loans Are Available Monthly \$500-700, No Repaired Need, All Wear And Tear Replaced. New Paintwork. Low Fuel Consumption! Low Maintenance! Smooth And Reliable Engine. Hurry Call Now T... Tay Motor & Credit Pte Ltd Posted: 10-May-2019 Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota									
GET YOUR COE RENEWAL LOAN Is your COE expiring? Let us help you renew it! Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.									
	Toyota	Corolla Altis 1.6A (COE till 04/2029)	\$47,800	\$4,800 /yr	27-Apr-2009	1,598 cc	-	Sedan	Available
1 Owner, Excellent Condition For 5 Years COE, Well Maintained Interior Leather. Reliable Car And Hotly Sought After, Trade In Welcome, Car Available In Showroom For Viewing Now, Contact For More Infor... Posted: 09-May-2019 Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota									
	Toyota	Corolla Altis 1.6A (New 5-yr COE)	\$33,800	\$6,750 /yr	28-Jul-2009	1,598 cc	-	Sedan	Available
Well Maintained, Can Loan Up To 100% For Car Price, Low Monthly Installment, Bank Or In House Loan Available, Call Now! Motor Universe Credit Pte Ltd Posted: 09-May-2019 Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota									
Compare	Toyota	Corolla Altis 1.6A (New	\$36,800	\$7,350 /yr	22-May-2009	1,598 cc	-	Sedan	Available

**5-yr COE)**

Call Us Soon For An Appt And Dont Miss Out This Tip Top Condition Car. Buy With Your Heart At Ease Without Worries.

ABWIN (1994) Pte Ltd

Posted: 09-May-2019

Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota

**Toyota Corolla Altis 1.6A (New 10-yr COE)****\$44,800****\$4,480 /yr****19-Aug-2009****1,598 cc****-****Sedan****Available**

New Paintwork, Trade In Welcome, Bank And In House Loan All Available, Interested Please Call For Viewing, Viewing By Appointment Only.

Boeki Auto Pte Ltd

Posted: 09-May-2019

Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota

**Toyota Corolla Altis 1.6A (COE till 04/2024)****\$32,800****\$6,610 /yr****29-Jul-2009****1,598 cc****111,298 km****Sedan****Available**

One Meticulous Owner. Road Tax Till October 2019. Under-Usage Low Mileage. Most Reliable Japanese Sedan Altis Ideally For Daily Drives. Cheapest In The Market, Don't Hesitate Anymore Grab The Lower Ap...

Posted: 08-May-2019

Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota

**Toyota Corolla Altis 1.6A****\$17,800****N.A****18-Sep-2009****1,598 cc****-****Sedan****Available**

Trade In Welcome, Bank And In House Loan All Available, Interested Please Call For Viewing, Viewing By Appointment Only.

Boeki Auto Pte Ltd

Posted: 08-May-2019

Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota

**Sell your Car for \$3,000 More**

With over 15K cars sold via Auction and a 500+ Dealer Network, cars on sgCarMart Quotz typically receive up to \$3,000 above market value. Quotz Guarantees the Highest Selling Price in Singapore - if we fail, you get \$100 cash from us. Get your Car Listed Today.

Find out more!

**Toyota Corolla Altis 1.6A (New 5-yr COE)****\$30,888****\$6,170 /yr****25-Mar-2009****1,598 cc****113,000 km****Sedan****Available**

Free 1 Servicing Upon Purchase! 1 Year Warranty Engine And Gearbox! Engine Mounting Just Changed! 100% Loan Approval! Bank And In House Loan Available! No Gimmicks! Well Maintained, Super Low Genuine ...

Posted: 08-May-2019

Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota

**Toyota Corolla Altis 1.6A (COE till 04/2029)****\$46,777****\$4,710 /yr****20-Apr-2009****1,598 cc****1,010,123 km****Sedan****Available**

1 Owner Only, \$570 For Monthly Installment, New Paintwork, New 16" Rims, Low Mileage, Low Depreciation, Excellent Maintained Condition, No Repairs Needed And Comes With 6 Months Warranty.

Posted: 07-May-2019

Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota

**Toyota Corolla Altis 1.6A (COE till 04/2024)****\$32,800****\$6,670 /yr****14-Apr-2009****1,598 cc****88,000 km****Sedan****Available**

Well Maintained, Cheap And Well Conditioned! Groomed Inside Out. No Repairs Needed. Comes With 6 Months Warranty By Our In House Workshop. Free Island Wide Towing In Event Of Emergency. We Provide Loa...

Posted: 07-May-2019

Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota

**Toyota Corolla Altis 1.6A (New 10-yr COE)****\$47,800****\$4,780 /yr****23-Sep-2009****1,598 cc****108,000 km****Sedan****Available**

Loan Available. No Repair Needed, Just Change Full Set Original Mounting. Well Maintained And Service Regularly. Bank/In House Loan And Competitive Insurance Available. Viewing Also Available On Sunda...

Posted: 07-May-2019

Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota

**Toyota Corolla Altis 1.6A (New 5-yr COE)****\$30,800****\$6,150 /yr****29-Jul-2009****1,598 cc****127,000 km****Sedan****Available**

Genuine Selling Price. Well Maintain By Previous Owner. Just Spend \$1K On Wear And Tear. Call Now For More Enquirers. In House And Loan Available.

Posted: 07-May-2019

Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota

**Toyota Corolla Altis 1.6A (New 5-yr COE)****\$31,800****\$6,350 /yr****27-May-2009****1,598 cc****-****Sedan****Available**

Interest Rate From 3.25% Monthly Of \$488! 2 Owner Car, Price Include New Paint/New Leather Seats, Rims, Comes With 6 Months Engine And Gearbox Warranty, All Our Quality Pre-owned Car Are Selling At Low ...

Car World Automobile

Posted: 06-May-2019

Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota

**Toyota Corolla Altis 1.6A (COE till 04/2029)****\$46,300****\$4,650 /yr****13-May-2009****1,598 cc****145,000 km****Sedan****Available**

Compare



Cheapest In Town! New Paintwork Done At Showroom Condition. Original Low Mileage Done At 145000KM. Flexible Loan Packages With No Other Hidden Costs. Call Me Now For Viewing.

Ka-Hup Vehicles Trading

Posted: 06-May-2019

Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Altis 1.6A (COE till 02/2024)

\$31,777

\$6,740 /yr

02-Feb-2009

1,598 cc

112,506 km

Sedan

Available

1 Owner, \$560 For Monthly Installment, New Paintwork, New Rims, Low Mileage, Low Depreciation, Excellent Maintained Condition, No Repairs Needed And Comes With 6 Months Warranty.

Posted: 06-May-2019

Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Altis 1.6A (COE till 02/2029)

\$41,800

\$4,280 /yr

20-Feb-2009

1,598 cc

-

Sedan

Available

New 10 Year Coe, Depre 4.2k Only, All Wear N Tear Changed, New Tex, Beautiful Condition, Bank Loan Of In House Finance Available, Welcome Trade In, Call Now To View!

Posted: 05-May-2019

Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Altis 1.6A (COE till 04/2024)

\$32,800

\$6,610 /yr

15-May-2009

1,598 cc

160,000 km

Sedan

Available

High Loan Approval Rate! In House Financing Available, Low Mileage, New Paintwork, Excellent Exterior And Interior Conditions! Your Trustworthy And Reliable Japanese Sedan, Trade In Welcomed, View To ...

Posted: 04-May-2019

Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota

Save this search criteria, to get email alerts whenever a match is found.

Make: Model: Price: Depreciation: Reg Date: Eng Cap: Mileage: Veh Type: Status:

For old advertisements, view [Expired ads](#)

« Back (1 2 3 4 5 6 7 8) Next »

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & CPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used ALTIS 1.6, ALTIS 1.6 Singapore, used ALTIS 1.6 Singapore, used vehicles Singapore or even buy used ALTIS 1.6 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/05/2019 18:34
Date Of Accident	09/05/2019 13:00
Exact Location Of Accident	ALONG TUAS SOUTH BOULEVARD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJU7506H
Insured/Policyholder	
Name Of Registered Owner	BK SAN ENGINEERING PTE LTD
Co Reg No	200700618K
Email Address	BALAJI@BKSAN.COM
Mobile Phone No	
Alternative Phone No	OFFICE-67771719

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	80457553MCX
Cover Note Number	

Driver

Name of Driver	LAKSHMANAN PANDIYAN
Passport No/FIN	G6027454T
Date Of Birth	09/06/1983
Occupation	INDOOR
Date Of Driving Pass	06/05/2019
Driving Experience	0 YEAR AND 0 MONTH
Gender	MALE
Mobile Number	+65-83338527
Fax Number	
Contact Number	
EMail Address	BALAJI@BKSAN.COM

Address	BLK 966 JURONG WEST ST 93 #02-217
Postcode	640966
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT BY FALLEN TREE / OTHER OBJECTS
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT NO. T/20190509/2190

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	NA/UNKNOWN
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	HIT AGAINST TREE
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As per police report no: 7/20190509/2190

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

☒ Claim own policy
☐ Claim third party
☐ Claim OD / TP at other works fop _____
☐ For record purpose

Policy No. ADU4755340X
Insurer MCC Ver. No. ADU4755340X

Reporting Center Personnel's Signature
Name:
NRIC/FIN No:

Police Report



**SINGAPORE
POLICE FORCE**



T20190509/2190

1 of 3

Report No. T20190509/2190

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649616
Tel No. 1800-2550999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 09/05/2019 19:38	Video Report No.: J20190509/0075	Station Diary No.: 171
--	-------------------------------------	---------------------------

Informant's Particulars

Name of Informant: LAKSHMANAN PANDIYAN		Address: APT BLK 966 JURONG WEST STREET 93 #02-217 SINGAPORE 640966	
ID Type / ID No.: FIN NO / G6027454T		Contact No.: Home/Office:	Mobile: 83338527
Nationality: INDIAN		Email:	
Sex: Male	Age: 35	Date of Birth: 09/06/1983	Type of Informant: Driver
Race: Indian		Language: English	Institution / School Name:
Occupation: NETWORK ADMINISTRATOR		Driving Licence Information: Class: 2B.3 Date of Expiry:	

General Information of the Accident

Type of Accident: Non-Injury	Drink Drive: No	Date/Time of Accident: 09/05/2019 13:00	Type of Location: Straight Road
Location: Along Road 1 TUAS SOUTH BOULEVARD TUAS SOUTH BOULEVARD			
Weather: Clear	Road Surface: Dry	Road Speed Limit: 70 Km/h	
Traffic Flow: Two Way	Traffic Control: Traffic Light - Working	Traffic Volume: No Traffic	
Type of Collision: Moving Vehicle Against - Others			Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJU7506H	Car				Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Police Report



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999



T/20190509/2190

2 of 3

Report No. T/20190509/2190

CONTINUATION OF REPORT

Driver Name	LAKSHMANAN PANDIYAN	ID No.	G6027454T
Related Vehicle	SJU7506H (Car)	Contact No.	83338527
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the above said mentioned date, time and location, while I was driving my said company vehicle, the left side of the said vehicle had hit onto a tree and there is slightly damage on the vehicle. After the accident, the said tree had fall down onto the ground and the Police officers had came to attend to it. I was not injured during the accident and I had reported the said accident to my company. The Police Officers had advised me to lodge a police report at any nearest Police Centre.

Police Report



SINGAPORE
POLICE FORCE



T1221903032190

2 of 3

Police Station Of Origin:
Jurong West N.P.C.
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

Report No: T1221903032190

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /

Sr Staff Sgt ONG BOON TIONG

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
09/05/2019 19:38

Officer In Charge Of Case:

TP / GIA /

Staff Sgt WONG SIEU LUI

Contact No: 65476151

Classification Of Case:

Authentication Stamp

Signature:

Police Force

Sng Ah Tee Motor Pte Ltd
Blk 3 Pioneer Road North,
#01-18,
628457

Claim Reference:
Assessment number: SJU7506H-OD-AXA
Version: 1810
Date calculated: 14/05/2019 10:55 AM

Full Report
Registration: SJU7506H
Printed: 14/05/2019 10:55 AM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	MSIG Insurance (Singapore) Pte Ltd
Printed by:	DARREN SNG	Currency:	SGD
Claim Reference:		Date of Incident:	09/05/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	COROLLA E14
Sub Model:	ALTIS
Model Sheet Number:	70 CM 13
Registration:	SJU7506H
VIN number:	
Odometer:	

Model Specs

FROM 10/2009	AIR CONDITIONING	ELECT DOOR MIRRORS	FOG LAMPS
PAINTED DOOR HANDLES	1.6 LTR 82 KW	TWO COAT METALLIC	PREPARE OFF VEHICLE

Sng Ah Tee Motor Pte Ltd
Blk 3 Pioneer Road North,
#01-18,
628457

Claim Reference:
 Assessment number: SJU7506H-OD-AXA
 Version: 1810
 Date calculated: 14/05/2019 10:55 AM

Full Report
 Registration: SJU7506H
 Printed: 14/05/2019 10:55 AM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
 Date of Inspection:

Damage Areas

All ☐
 Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
NO NUMBER	ADJUST HEADLAMPS		3.0	15.00
043233	ALIGN VEHICLE CPL		12.0	60.00
B100	R + R LEFT WING		4.0	20.00
B100	R + R R/WING		4.0	20.00
B110)	RENEW L/F WING (REMOVED)		2.0	10.00
B110)	RENEW R/F WING (REMOVED)		2.0	10.00
NO NUMBER	R + R FRONT BUMPER REINFORCEMENT		2.0	10.00
B125	R + R FRONT LOCK CARRIER		3.0	15.00
B135	RENEW FR/LWR CROSSMEMBER		11.0	55.00
NO NUMBER	R + R L/F SILL MOULDING		2.0	10.00
B010	R + R FRONT BUMPER		5.0	25.00
B020)	RENEW FRONT BUMPER (REMOVED)		11.0	55.00
B040)	R + R LEFT HEADLAMP		1.0	5.00
B040)	R + R RIGHT HEADLAMP		1.0	5.00
B040)	RENEW HEADLAMP		1.0	5.00
NO NUMBER	RENEW FRONT NUMBER PLATE		2.0	10.00

Sng Ah Tee Motor Pte Ltd
Blk 3 Pioneer Road North,
#01-18,
628457

Claim Reference:

Assessment number: SJU7506H-OD-AXA

Version: 1810

Date calculated: 14/05/2019 10:55 AM

Full Report

Registration: SJU7506H

Printed: 14/05/2019 10:55 AM

Code	Description	WU	Price SGD
B060	R + R BONNET	3.0	15.00
B070)	RENEW BONNET (REMOVED)	1.0	5.00
B080	R + R BONNET HINGES	1.0	5.00
530111	R + R BONNET LOCK	5.0	25.00
B085	R + R FRONT SCREEN FRAME MOULDING	2.0	10.00
G010	R + R WINDSCREEN	31.0	155.00
B210	RENEW L/F DOOR	25.0	125.00
	INCLUDES: R + R DOOR, CONVERT ATTACHED PARTS		
NO NUMBER	R + R L/OUTER MIRROR HOUSING	1.0	5.00
670201)	R + R LEFT FRONT HINGE/S	11.0	55.00
671351A	R + R FRONT DOOR SEAL (ADD/WORK)	3.0	15.00
B210	RENEW L/R DOOR	24.0	120.00
	INCLUDES: R + R DOOR, CONVERT ATTACHED PARTS		
670211	R + R L/R DOOR HINGES	5.0	25.00
671361A	R + R REAR DOOR SEAL ADD/WORK	2.0	10.00
671061A)	R + R L/R AND R/R DOOR WINDOW GUIDE	1.0	5.00
B270	RENEW L/R SIDE PANEL	71.0	355.00
	INCLUDES: R + R TAILLAMP, BOOT CARPET AND ALL TRIMS IN THE REPAIR SECTION DOES NOT INCLUDE: R + R SEAT CUSHION, L/R SIDE WINDOW AND REAR BUMPER		
G020	R + R REAR PANEL WINDOW	28.0	140.00
B410	R + R REAR BUMPER	4.0	20.00
B420)	RENEW REAR BUMPER (REMOVED)	1.0	5.00
M260	R + R FUEL TANK	11.0	55.00
B260	RENEW ROOF SKIN	41.0	205.00
B430)	R + R HEADLINING	6.0	30.00
NO NUMBER	R + R UPPER INSTRUMENT PANEL	17.0	85.00
M010)	R + R AIR CONDITIONING CONDENSER	3.0	15.00
002889	DRAIN/REFILL AIR CONDITIONING	7.0	35.00
B440	R + R LEFT FRONT SEAT	2.0	10.00
B440	R + R RIGHT FRONT SEAT	2.0	10.00
B450)	R + R REAR SEAT CUSHION	1.0	5.00
B450)	R + R COMPLETE REAR SEAT CUSHION	1.0	5.00
B450)	R + R LEFT REAR SEAT BACK REST	1.0	5.00
B450)	R + R RIGHT REAR SEAT BACK REST	1.0	5.00
M020	R + R RADIATOR	6.0	30.00
	INCLUDES: BLEED COOLING SYSTEM		
M240	R + R EXHAUST SYSTEM CPL	5.0	25.00
420018)	R + R LEFT FRONT WHEEL	1.0	5.00

Sng Ah Tee Motor Pte Ltd
Blk 3 Pioneer Road North,
#01-18,
628457

Claim Reference:

Assessment number: SJU7506H-OD-AXA

Version: 1810

Date calculated: 14/05/2019 10:55 AM

Full Report

Registration: SJU7506H

Printed: 14/05/2019 10:55 AM

Code	Description	WU	Price SGD
420018)	R + R WHEEL/S (ADD/WORK)	1.0	5.00
420091A	R + R L/F WHEEL/TYRE	3.0	15.00
473101A)	DETACH + REFIT FRONT BRAKE CALIPER	3.0	15.00
431151)	DISS/ASS L/F UPPER SUSPENSION STRUT	1.0	5.00
431151A)	DETACH + REFIT L/F FRONT SUSPENSION STRUT	5.0	25.00
431151A)	DISS/ASS FRONT LOWER SUSPENSION STRUT	9.0	45.00
431151)	R + R LEFT FRONT SHOCK ABSORBER	4.0	20.00
431011)	R + R LEFT FRONT CONTROL ARM	2.0	10.00
	DOES NOT INCLUDE: VEHICLE ALIGNMENT		
431011A)	DETACH + REFIT UPPER AXLE RADIUS ARMS	8.0	40.00
434081A)	R + R FRONT STEERING KNUCKLE BEARING	5.0	25.00
434211)	R + R L/F STEERING KNUCKLE (WHEEL REM)	4.0	20.00
434211)	RENEW LEFT FRONT STEERING KNUCKLE	5.0	25.00
	DOES NOT INCLUDE: VEHICLE ALIGNMENT		
NO NUMBER	R + R REAR AXLE	22.0	110.00
	INCLUDES: R + R BOOT TRIMS AND WHEELS, BLEED BRAKE SYSTEM		
NO NUMBER	DIS + ASS REAR AXLE CARRIER (REMOVED) (SHOCK ABSORB, WHEEL HUB AND PROTECT PNL REMOVED)	6.0	30.00
	INCLUDES: AXLE ARM BRG REMOVE AND REFIT		
420091A	R + R LEFT REAR TYRE/WHEEL	3.0	15.00
473061A)	R + R REAR BRAKE DISC	2.0	10.00
NO NUMBER	R + R L/REAR BRAKE DISC SPLASH SHIELD	7.0	35.00
NO NUMBER	R + R R/REAR BRAKE DISC SPLASH SHIELD	7.0	35.00
421041A)	R + R REAR WHEEL HUB/S ADD/WORK	4.0	20.00
481251A)	R + R REAR SHOCK ABSORBER	5.0	25.00
481251)	R + R LEFT REAR SHOCK ABSORBER	3.0	15.00
481251)	R + R RIGHT REAR SHOCK ABSORBER	3.0	15.00
2143	L/INNER SILL REINF REPAIR	10.0*	50.00
2279	B-PILLAR L/SILL PNL REPAIR	15.0*	75.00
4105	L/R INNER WING REPAIR	15.0*	75.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		53.00	530.0
Alignment			
Measuring Work		1.20	12.0
Total of Labour			2,710.00

Sng Ah Tee Motor Pte Ltd
Blk 3 Pioneer Road North,
#01-18,
628457

Claim Reference:

Assessment number: SJU7506H-OD-AXA

Version: 1810

Date calculated: 14/05/2019 10:55 AM

Full Report

Registration: SJU7506H

Printed: 14/05/2019 10:55 AM

Paint

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	BONNET NEW PART PAINTING	21.0
	L/F WING NEW PART PAINTING	10.0
	FRT LWR CROSSMEMBER SURFACE PAINT	4.0
	LEFT FRONT DOOR NEW PART PAINTING	16.0
	L/R DOOR NEW PART PAINTING	14.0
	ROOF NEW PART PAINTING	54.0
	L/R SIDE PANEL NEW PART PAINTING	28.0
	L/F WHEEL NEW PART PAINTING	7.0
	L/R WHEEL NEW PART PAINTING	7.0
	FRONT BUMPER NEW PART PAINT K1R	13.0
	GRILLE NEW PART PAINT K1R	4.0
	L/F DOOR OUT HANDLE NEW PART PAINT K1R	3.0
	L/F LOCK CYL BRACKET NEW PART PAINT K1R	3.0
	L/DOOR FRT MOULDING NEW PART PAINT K1R	3.0
	L/R DOOR OUT HANDLE NEW PART PAINT K1R	3.0
	L/R LOCK CYL BRACKET NEW PART PAINT K1R	3.0
	L/DOOR REAR MOULDING NEW PART PAINT K1R	3.0
	L/SILL MOULDING NEW PART PAINT K1R	4.0
	REAR BUMPER NEW PART PAINT K1R	15.0
	LEFT A-PILLAR SURFACE PAINT	4.0
	RIGHT A-PILLAR SURFACE PAINT	4.0
	B-PILLAR L/SILL PNL SURFACE PAINT	6.0
	L/OUTER ROOF FRAME SURFACE PAINT	5.0
	R/OUTER ROOF FRAME SURFACE PAINT	5.0
	L/R INNER WING SURFACE PAINT	4.0

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	65.53
0741	L/F WING NEW PART PAINTING	21.16
1016	FRT LWR CROSSMEMBER SURFACE PAINT	4.23
1481	LEFT FRONT DOOR NEW PART PAINTING	44.38
1781	L/R DOOR NEW PART PAINTING	37.67
2351	ROOF NEW PART PAINTING	86.35
3481	L/R SIDE PANEL NEW PART PAINTING	38.50
7201	L/F WHEEL NEW PART PAINTING	5.16
9551	L/R WHEEL NEW PART PAINTING	5.16
0281	FRONT BUMPER NEW PART PAINT K1R	67.40

Sng Ah Tee Motor Pte Ltd
Blk 3 Pioneer Road North,
#01-18,
628457

Claim Reference:
 Assessment number: SJU7506H-OD-AXA
 Version: 1810
 Date calculated: 14/05/2019 10:55 AM

Full Report
 Registration: SJU7506H
 Printed: 14/05/2019 10:55 AM

Paint Material Per Part

Code	Description	Price SGD
0410	GRILLE NEW PART PAINT K1R	4.92
1567	L/F DOOR OUT HANDLE NEW PART PAINT K1R	0.98
1585	L/F LOCK CYL BRACKET NEW PART PAINT K1R	0.49
1685	L/DOOR FRT MOULDING NEW PART PAINT K1R	2.46
1867	L/R DOOR OUT HANDLE NEW PART PAINT K1R	0.98
1885	L/R LOCK CYL BRACKET NEW PART PAINT K1R	0.98
1985	L/DOOR REAR MOULDING NEW PART PAINT K1R	2.46
2207	L/SILL MOULDING NEW PART PAINT K1R	9.84
2581	REAR BUMPER NEW PART PAINT K1R	75.77
2227	LEFT A-PILLAR SURFACE PAINT	3.49
2228	RIGHT A-PILLAR SURFACE PAINT	3.49
2279	B-PILLAR L/SILL PNL SURFACE PAINT	14.19
2395	L/OUTER ROOF FRAME SURFACE PAINT	5.48
2396	R/OUTER ROOF FRAME SURFACE PAINT	5.48
4105	L/R INNER WING SURFACE PAINT	2.49

Labour Cost - Paint

Factor	50.00 SGD/h	Hrs	WU	Price SGD
Time Paint			243.0	
Preparation Main Work Metal		2.50	25.0	125.00
Preparation Comp. Work Plastic		0.50	5.0	25.00
Total	10 WU/h	27.30	273.0	1,365.00

Material Cost - Paint

	Price SGD
New Part Painting	303.91
New Part Painting - Plastic K1R	166.28
Surface-/Blend Paint	38.85
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
Total	546.64

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01/01	Price SGD
0251	LWR RADIATOR GRILLE	53112 02190	bis		40.00
0257	FRONT NUMBER PLATE	KNPL3	bt		0.00
0281	FRONT BUMPER	52119 02850	TBW		150.00
0317	L/F BUMPER BRACKET	52116 02140	NE		25.00

Sng Ah Tee Motor Pte Ltd
Blk 3 Pioneer Road North,
#01-18,
628457

Claim Reference:

Assessment number: SJU7506H-OD-AXA

Version: 1810

Date calculated: 14/05/2019 10:55 AM

Full Report

Registration: SJU7506H

Printed: 14/05/2019 10:55 AM

Code	Description	Part Number	Supplier	Price SGD
0318	R/F BUMPER BRACKET	52115 02140	nee /	25.00
0350	FRT BUMPER CLAMP KIT	USE SINGLE PARTS	lee /	10.00
0410	GRILLE	53100 02310	?	120.00
0431	GRILLE BADGE	75301 02050	?	25.00
0471	BONNET	53301 02230	bt /	230.00
0475	L/F HINGE	53420 02060	X	25.00
0476	R/F HINGE	53410 02060	X	25.00
0481	BONNET INSULATION	53341 02190	X	150.00
0493	BONNET LOCK	53510 02400	X	45.00
0527	RADIATOR GRILL SEAL	53395 02050	nee /	25.00
0530	FRONT BONNET SEAL	53381 02140	nee /	25.00
0571	L/HEADLAMP CPL	81150 02720	sea /	140.00
0572	R/HEADLAMP CPL	81110 02720	?	140.00
0741	L/F WING	53812 02250	bt /	130.00
0789	L/F WING CLAMP KIT	90119 06137	nee /	15.00
0811	BADGE "VVT-I" L	75351 02110	nee /	15.00
0841	L/WHEELHOUSE SHELL	53876 02270	cut /	60.00
1016	FRT LWR CROSSMEMBER	57104 02170	?	580.00
1391	L/COWL PANEL GRILLE	55709 02330	sea /	180.00
1392	R/COWL PANEL GRILLE	55708 02450	sea /	180.00
1401	WINDSCREEN	56101 02930	pho /	400.00
1410	LWR WINDSCREEN SEAL	56117 12300	nee /	0.00
1411	WINDSCREEN REP KIT	PZ491 00C1131	nee /	0.00
1423	UPP WINDSCREEN MLDG	75531 02190	nee /	45.00
1453	L/F WIPER ARM	85221 02280	sea /	70.00
1454	R/F WIPER ARM	85211 02270	sea /	70.00
1457	L/F WIPER BLADE	85222 12860	cut /	50.00
1458	R/F WIPER BLADE	85212 12480	cut /	50.00
1481	LEFT FRONT DOOR	67002 02340	nee /	400.00
1487	L/F UPPER DOOR HINGE	68720 12151	?	35.00
1495	L/F LOWER DOOR HINGE	68740 02100	?	35.00
1505	L/F DOOR CHECK	68610 02190	?	60.00
1509	L/F DOOR SEAL	67862 02230	nee /	75.00
1519	L/F DOOR WINDOW	68102 02291	sea /	180.00
1567	L/F DOOR OUT HANDLE	69211 AA020A0	cut /	45.00
1569	L/DOOR LOCK CYLINDER	69052 02170	sea /	150.00
1577	L/F DOOR LOCK	69040 0D270	?	180.00
1585	L/F LOCK CYL BRACKET	69217 12020	?	25.00
1619	L/INN WINDOW SEAL	68172 02180	nee /	70.00
1625	L/F OUT WINDOW SEAL	75720 02261	nee /	70.00
1685	L/DOOR FRT MOULDING	75732 02919	nee /	50.00
1697	L/F UPP DOOR STRIPE	75922 02150	nee /	70.00
1737	L/DOOR MIRROR	87940 02A70	pho /	270.00

Sng Ah Tee Motor Pte Ltd
Blk 3 Pioneer Road North,
#01-18,
628457

Claim Reference:

Assessment number: SJU7506H-OD-AXA

Version: 1810

Date calculated: 14/05/2019 10:55 AM

Full Report

Registration: SJU7506H

Printed: 14/05/2019 10:55 AM

Code	Description	Part Number	Supplier	Price SGD
1745	L/DOOR MIRROR HSG	87945 06903	MSB M13 ✓	0.00
1781	L/R DOOR	67004 02340	MSB ✓	400.00
1787	L/R UPPER DOOR HINGE	68760 0D030	?	35.00
1795	L/R LOWER DOOR HINGE	68780 0D030	?	35.00
1805	L/R DOOR CHECK	68630 02180	?	60.00
1809	L/R DOOR SEAL	67872 02190	MSB ✓	70.00
1835	L/R CORNER WDW SEAL	68189 02130	MSB ✓	70.00
1847	L/R WINDOW REGULATOR	69804 02210	?	250.00
1867	L/R DOOR OUT HANDLE	69211 AA020A0	MSB ✓	35.00
1877	L/R DOOR LOCK	69060 06060	?	180.00
1885	L/R LOCK CYL BRACKET	69227 06906	?	15.00
1897	L/R WINDOW CHANNEL	68152 02240	MSB ?	70.00
1919	L/R INN CHANNEL SEAL	68174 02140	?	70.00
1925	L/R OUT CHANNEL SEAL	75740 02240	?	70.00
1971	L/R UPP DOOR STRIPE	75924 02180	MSB ✓	70.00
1985	L/DOOR REAR MOULDING	75742 02917	MSB ✓	50.00
2207	L/SILL MOULDING	76912 02913	MSB ✓	280.00
2351	ROOF	63111 02330	MSB ✓	1,200.00
2581	REAR BUMPER	52159 02540	MSB ✓	180.00
2621	L/R BUMPER RR BRKT	52156 02110	MSB ✓	28.00
2622	R/F BUMPER RR BRKT	52155 02120	X	28.00
2623	L/W-HOUSE REAR SECT	52592 02180	MSB ✓	40.00
2650	RR BUMPER CLAMP KIT	USE SINGLE PARTS	MSB ✓	15.00
3160	REAR SCREEN BOND KIT	KNGKW12	MSB ✓	0.00
3163	REAR SCREEN FIX SET	USE SINGLE PARTS	MSB ✓	0.00
3164	SPACER	56115 30120	MSB ✓	0.00
3165	SPACER	56116 22050	MSB ✓	0.00
3169	LWR REAR WINDOW MLDG	64813 12180	X	0.00
3175	REAR WINDOW MOULDING	75571 02210	MSB ✓	70.00
3481	L/R SIDE PANEL	61602 02320	MSB ✓	380.00
4080	FUEL FILLER FLAP	77350 02080	Repair	45.00
4331	UPP INSTRUMENT PANEL	55302 02310B0	?	350.00
4957	HEADLINING	63310 02A40E0	MSB ✓	900.00
7053	L/F LWR AXLE ARM	48069 02210	?	70.00
7077	L/F STRUT	48520 09L60	?	150.00
7081	L/F STEERING KNUCKLE	43212 02270	?	150.00
7117	L/F WHEEL BEARING	90080 36137	?	45.00
7131	L/F WHEEL HUB	43502 02110	?	120.00

Sng Ah Tee Motor Pte Ltd
Blk 3 Pioneer Road North,
#01-18,
628457

Claim Reference:
 Assessment number: SJU7506H-OD-AXA
 Version: 1810
 Date calculated: 14/05/2019 10:55 AM

Full Report
 Registration: SJU7506H
 Printed: 14/05/2019 10:55 AM

Code	Description	Part Number	Supplier	Price SGD
7201	L/F WHEEL	42611 02B50	see /	0.00
7227	L/F TYRE	195/65 R 15 .. V	cut /	0.00
8780	LOWER ENGINE PROTECT	51451 02100	?	70.00
9081	REAR AXLE SUBFRAME	42110 02440	?	750.00
9181	L/R WHEEL HUB/BRG	42450 02210	?	320.00
9201	L/R SPRING LEG	48530 02670	?	75.00
9551	L/R WHEEL	42611 02B50	cut /	0.00
9565	L/R TYRE	195/65 R 15 .. V	cut /	0.00
1001	FRT BONNET INSULATOR	CLIP X10	see /	15.00
1004	SIDE SKIRT	CLIP X10	see /	30.00
1006	L/R INNER SHIELD	CLIP X8	DE /	12.00
1014	FRT PASSENGER	SUNVISOR	?	75.00
1015	FRT DRIVER	SUNVISOR	?	75.00
f: OEM Parts				0.00
n: Non-OEM Parts				11,713.00
u: Used parts				1,171.30
Savings				
Subtotal				11,713.00
Addition(+10.00%)				1,171.30
Total				12,884.30

Extras

Code	Description	Price SGD
1000	FRT NUMBER PLATE bf /	35.00*
1002	FRT WINDSCREEN SEALANT ne /	40.00*
1003	ERP BRACKET ne /	26.00*
1005	L/R QUARTER GLS SEALANT ne /	40.00*
1008	RR WINDSCREEN SEALANT ne /	40.00*
1009	L/R RIM 15" cut /	180.00*
1010	L/F TYRE 195/65R15 cut /	280.00*
1011	REAR RIM 15' cut /	180.00*
1012	REAR TYRE 195/65R15 cut /	280.00*
1013	ROOF LINING CLIP X16 ne /	27.00*
1016	CHECK WIRING ne /	30.00*
1017	WHEEL ALIGNMENT ne /	60
Total Extras		1,238.00

Sng Ah Tee Motor Pte Ltd
Blk 3 Pioneer Road North,
#01-18,
628457

Claim Reference:
 Assessment number: SJU7506H-OD-AXA
 Version: 1810
 Date calculated: 14/05/2019 10:55 AM

Full Report
 Registration: SJU7506H
 Printed: 14/05/2019 10:55 AM

Final Calculation

	SGD	SGD
Parts	11,713.00	
Addition(+10.00%)	1,171.30	
Total Parts		12,884.30
Labour Time Base 10 WU/h		
Total 530.0 WU X 50.00 SGD/h	2,650.00	
Alignment		
Measuring Work	60.00	
Total of Labour		2,710.00
Total Of Extras		1,238.00
Paint Work Time Base 10 WU/h		
Labour Cost 273.0 WU X 50.00 SGD/h	1,365.00	
Material Cost	546.64	
Total Paint Including Material		1,911.64
Repair Cost Excludes GST		18,743.94
GST (+7.0%)		1,312.08
Repair Cost Included GST		20,056.02

Comments

- * - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
-) - WU PARTIAL INCL IN OTHER POSITIONS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before and spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary part(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Passul
Hp 90010068
14 days
L/S
15/05/19 @ 1415
EXCESS: 3500
Revert
Revy after repair

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
 Assessment number: SJU7506H-OD-AXA
 Version: 1810
 Date calculated: 16/05/2019 12:04 PM

Full Report
 Registration: SJU7506H
 Printed: 16/05/2019 12:04 PM

Code	Description	Part Number	Supplier	Price SGD
9181	L/R WHEEL HUB/BRG	42450 02210		320.00
9201	L/R SPRING LEG	48530 02670		75.00
9551	L/R WHEEL	42611 02B50		0.00
9565	L/R TYRE	195/65 R 15 .. V		0.00
1001	FRT BONNET INSULATOR	CLIP X10		15.00
1004	SIDE SKIRT	CLIP X10		30.00
1006	L/R INNER SHIELD	CLIP X8		12.00
1014	FRT PASSENGER	SUNVISOR		75.00
1015	FRT DRIVER	SUNVISOR		75.00
				0.00
f: OEM Parts				Savings
n: Non-OEM Parts				Subtotal
u: Used parts				Addition(+10.00%)
				11,395.00
				1,139.50
Total				12,534.50

Extras

Code	Description	Price SGD
1000	FRT NUMBER PLATE	35.00*
1002	FRT WINDSCREEN SEALANT	40.00*
1003	ERP BRACKET	26.00*
1005	L/R QUARTER GLS SEALANT	40.00*
1008	RR WINDSCREEN SEALANT	40.00*
1009	L/R RIM 15"	180.00*
1010	L/F TYRE 195/65R15	196.00*
1011	REAR RIM 15'	180.00*
1012	REAR TYRE 195/65R15	196.00*
1013	ROOF LINING CLIP X16	27.00*
1016	CHECK WIRING	30.00*
1017	WHEEL ALIGNMENT	60.00*
Total Extras		1,050.00

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
 Assessment number: SJU7506H-OD-AXA
 Version: 1810
 Date calculated: 16/05/2019 12:04 PM

Full Report
 Registration: SJU7506H
 Printed: 16/05/2019 12:04 PM

Final Calculation

	SGD	SGD
Parts	11,395.00	
Addition(+10.00%)	1,139.50	
Total Parts		12,534.50
Labour Time Base 10 WU/h		
Total 519.0 WU X 50.00 SGD/h	2,595.00	
Alignment		
Measuring Work	60.00	
Total of Labour		2,655.00
Total Of Extras		1,050.00
Paint Work Time Base 10 WU/h		
Labour Cost 273.0 WU X 50.00 SGD/h	1,365.00	
Material Cost	546.64	
Total Paint Including Material		1,911.64
Repair Cost Excludes GST		18,151.14
GST (+7.0%)		1,270.58
Repair Cost Included GST		19,421.72

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
Assessment number: SJU7506H-OD-AXA
Version: 1810
Date calculated: 16/05/2019 12:04 PM

Full Report
Registration: SJU7506H
Printed: 16/05/2019 12:04 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	MSIG Insurance (Singapore) Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:		Date of Incident:	09/05/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	COROLLA E14
Sub Model:	ALTIS
Model Sheet Number:	70 CM 13
Registration:	SJU7506H
VIN number:	
Odometer:	

Model Specs

FROM 10/2009	AIR CONDITIONING	ELECT DOOR MIRRORS	FOG LAMPS
PAINTED DOOR HANDLES	1.6 LTR 82 KW	TWO COAT METALLIC	PREPARE OFF VEHICLE

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
 Assessment number: SJU7506H-OD-AXA
 Version: 1810
 Date calculated: 16/05/2019 12:04 PM

Full Report
 Registration: SJU7506H
 Printed: 16/05/2019 12:04 PM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
 Date of Inspection:

Damage Areas

All ☐
 Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
NO NUMBER	ADJUST HEADLAMPS		3.0	15.00
043233	ALIGN VEHICLE CPL		12.0	60.00
B100	R + R LEFT WING		4.0	20.00
B110)	RENEW L/F WING (REMOVED)		2.0	10.00
NO NUMBER	R + R FRONT BUMPER REINFORCEMENT		2.0	10.00
B125	R + R FRONT LOCK CARRIER		3.0	15.00
B135	RENEW FR/LWR CROSSMEMBER		11.0	55.00
NO NUMBER	R + R L/F SILL MOULDING		2.0	10.00
B010	R + R FRONT BUMPER		5.0	25.00
B020)	RENEW FRONT BUMPER (REMOVED)		11.0	55.00
NO NUMBER	R + R RIGHT FRONT OUTER BUMPER BRACKET		1.0	5.00
B040)	R + R LEFT HEADLAMP		1.0	5.00
B040)	R + R RIGHT HEADLAMP		1.0	5.00
B040)	RENEW HEADLAMP		1.0	5.00
NO NUMBER	RENEW FRONT NUMBER PLATE		2.0	10.00
B060	R + R BONNET		3.0	15.00

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:

Assessment number: SJU7506H-OD-AXA

Version: 1810

Date calculated: 16/05/2019 12:04 PM

Full Report

Registration: SJU7506H

Printed: 16/05/2019 12:04 PM

Code	Description	WU	Price SGD
B070)	RENEW BONNET (REMOVED)	1.0	5.00
B085	R + R FRONT SCREEN FRAME MOULDING	2.0	10.00
G010	R + R WINDSCREEN	31.0	155.00
B210	RENEW L/F DOOR	25.0	125.00
	INCLUDES: R + R DOOR, CONVERT ATTACHED PARTS		
NO NUMBER	R + R L/OUTER MIRROR HOUSING	1.0	5.00
670201)	R + R LEFT FRONT HINGE/S	11.0	55.00
671351A	R + R FRONT DOOR SEAL (ADD/WORK)	3.0	15.00
B210	RENEW L/R DOOR	24.0	120.00
	INCLUDES: R + R DOOR, CONVERT ATTACHED PARTS		
670211	R + R L/R DOOR HINGES	5.0	25.00
671361A	R + R REAR DOOR SEAL ADD/WORK	2.0	10.00
671061A)	R + R L/R AND R/R DOOR WINDOW GUIDE	1.0	5.00
B270	RENEW L/R SIDE PANEL	71.0	355.00
	INCLUDES: R + R TAILLAMP, BOOT CARPET AND ALL TRIMS IN THE REPAIR SECTION DOES NOT INCLUDE: R + R SEAT CUSHION, L/R SIDE WINDOW AND REAR BUMPER		
G020	R + R REAR PANEL WINDOW	28.0	140.00
B410	R + R REAR BUMPER	4.0	20.00
B420)	RENEW REAR BUMPER (REMOVED)	1.0	5.00
M260	R + R FUEL TANK	11.0	55.00
B260	RENEW ROOF SKIN	41.0	205.00
B430)	R + R HEADLINING	6.0	30.00
NO NUMBER	R + R UPPER INSTRUMENT PANEL	17.0	85.00
M010)	R + R AIR CONDITIONING CONDENSER	3.0	15.00
002889	DRAIN/REFILL AIR CONDITIONING	7.0	35.00
B440	R + R LEFT FRONT SEAT	2.0	10.00
B440	R + R RIGHT FRONT SEAT	2.0	10.00
B450)	R + R REAR SEAT CUSHION	1.0	5.00
B450)	R + R COMPLETE REAR SEAT CUSHION	1.0	5.00
B450)	R + R LEFT REAR SEAT BACK REST	1.0	5.00
B450)	R + R RIGHT REAR SEAT BACK REST	1.0	5.00
M020	R + R RADIATOR	6.0	30.00
	INCLUDES: BLEED COOLING SYSTEM		
M240	R + R EXHAUST SYSTEM CPL	5.0	25.00
420018)	R + R LEFT FRONT WHEEL	1.0	5.00
420018)	R + R WHEEL/S (ADD/WORK)	1.0	5.00
420091A	R + R L/F WHEEL/TYRE	3.0	15.00
473101A)	DETACH + REFIT FRONT BRAKE CALIPER	3.0	15.00

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
 Assessment number: SJU7506H-OD-AXA
 Version: 1810
 Date calculated: 16/05/2019 12:04 PM

Full Report
 Registration: SJU7506H
 Printed: 16/05/2019 12:04 PM

Code	Description	WU	Price SGD
431151)	DISS/ASS L/F UPPER SUSPENSION STRUT	1.0	5.00
431151A)	DETACH + REFIT L/F FRONT SUSPENSION STRUT	5.0	25.00
431151A)	DISS/ASS FRONT LOWER SUSPENSION STRUT	9.0	45.00
431151)	R + R LEFT FRONT SHOCK ABSORBER	4.0	20.00
431011)	R + R LEFT FRONT CONTROL ARM	2.0	10.00
	DOES NOT INCLUDE: VEHICLE ALIGNMENT		
431011A)	DETACH + REFIT UPPER AXLE RADIUS ARMS	8.0	40.00
434081A)	R + R FRONT STEERING KNUCKLE BEARING	5.0	25.00
434211)	R + R L/F STEERING KNUCKLE (WHEEL REM)	4.0	20.00
434211)	RENEW LEFT FRONT STEERING KNUCKLE	5.0	25.00
	DOES NOT INCLUDE: VEHICLE ALIGNMENT		
NO NUMBER	R + R REAR AXLE	22.0	110.00
	INCLUDES: R + R BOOT TRIMS AND WHEELS, BLEED BRAKE SYSTEM		
NO NUMBER	DIS + ASS REAR AXLE CARRIER (REMOVED) (SHOCK ABSORB, WHEEL HUB AND PROTECT PNL REMOVED)	6.0	30.00
	INCLUDES: AXLE ARM BRG REMOVE AND REFIT		
420091A	R + R LEFT REAR TYRE/WHEEL	3.0	15.00
473061A)	R + R REAR BRAKE DISC	2.0	10.00
NO NUMBER	R + R L/REAR BRAKE DISC SPLASH SHIELD	7.0	35.00
NO NUMBER	R + R R/REAR BRAKE DISC SPLASH SHIELD	7.0	35.00
421041A)	R + R REAR WHEEL HUB/S ADD/WORK	4.0	20.00
481251A)	R + R REAR SHOCK ABSORBER	5.0	25.00
481251)	R + R LEFT REAR SHOCK ABSORBER	3.0	15.00
481251)	R + R RIGHT REAR SHOCK ABSORBER	3.0	15.00
2143	L/INNER SILL REINF REPAIR	10.0*	50.00
2279	B-PILLAR L/SILL PNL REPAIR	15.0*	75.00
4080	FUEL FILLER FLAP REPAIR		
4105	L/R INNER WING REPAIR	15.0*	75.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		51.90	519.0
Alignment			
Measuring Work		1.20	12.0
Total of Labour			2,655.00

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
 Assessment number: SJU7506H-OD-AXA
 Version: 1810
 Date calculated: 16/05/2019 12:04 PM

Full Report
 Registration: SJU7506H
 Printed: 16/05/2019 12:04 PM

Paint

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	BONNET NEW PART PAINTING	21.0
	L/F WING NEW PART PAINTING	10.0
	FRT LWR CROSSMEMBER SURFACE PAINT	4.0
	LEFT FRONT DOOR NEW PART PAINTING	16.0
	L/R DOOR NEW PART PAINTING	14.0
	ROOF NEW PART PAINTING	54.0
	L/R SIDE PANEL NEW PART PAINTING	28.0
	L/F WHEEL NEW PART PAINTING	7.0
	L/R WHEEL NEW PART PAINTING	7.0
	FRONT BUMPER NEW PART PAINT K1R	13.0
	GRILLE NEW PART PAINT K1R	4.0
	L/F DOOR OUT HANDLE NEW PART PAINT K1R	3.0
	L/F LOCK CYL BRACKET NEW PART PAINT K1R	3.0
	L/DOOR FRT MOULDING NEW PART PAINT K1R	3.0
	L/R DOOR OUT HANDLE NEW PART PAINT K1R	3.0
	L/R LOCK CYL BRACKET NEW PART PAINT K1R	3.0
	L/DOOR REAR MOULDING NEW PART PAINT K1R	3.0
	L/SILL MOULDING NEW PART PAINT K1R	4.0
	REAR BUMPER NEW PART PAINT K1R	15.0
	LEFT A-PILLAR SURFACE PAINT	4.0
	RIGHT A-PILLAR SURFACE PAINT	4.0
	B-PILLAR L/SILL PNL SURFACE PAINT	6.0
	L/OUTER ROOF FRAME SURFACE PAINT	5.0
	R/OUTER ROOF FRAME SURFACE PAINT	5.0
	L/R INNER WING SURFACE PAINT	4.0

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	65.53
0741	L/F WING NEW PART PAINTING	21.16
1016	FRT LWR CROSSMEMBER SURFACE PAINT	4.23
1481	LEFT FRONT DOOR NEW PART PAINTING	44.38
1781	L/R DOOR NEW PART PAINTING	37.67
2351	ROOF NEW PART PAINTING	86.35
3481	L/R SIDE PANEL NEW PART PAINTING	38.50
7201	L/F WHEEL NEW PART PAINTING	5.16
9551	L/R WHEEL NEW PART PAINTING	5.16
0281	FRONT BUMPER NEW PART PAINT K1R	67.40

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
 Assessment number: SJU7506H-OD-AXA
 Version: 1810
 Date calculated: 16/05/2019 12:04 PM

Full Report
 Registration: SJU7506H
 Printed: 16/05/2019 12:04 PM

Paint Material Per Part

Code	Description	Price SGD
0410	GRILLE NEW PART PAINT K1R	4.92
1567	L/F DOOR OUT HANDLE NEW PART PAINT K1R	0.98
1585	L/F LOCK CYL BRACKET NEW PART PAINT K1R	0.49
1685	L/DOOR FRT MOULDING NEW PART PAINT K1R	2.46
1867	L/R DOOR OUT HANDLE NEW PART PAINT K1R	0.98
1885	L/R LOCK CYL BRACKET NEW PART PAINT K1R	0.98
1985	L/DOOR REAR MOULDING NEW PART PAINT K1R	2.46
2207	L/SILL MOULDING NEW PART PAINT K1R	9.84
2581	REAR BUMPER NEW PART PAINT K1R	75.77
2227	LEFT A-PILLAR SURFACE PAINT	3.49
2228	RIGHT A-PILLAR SURFACE PAINT	3.49
2279	B-PILLAR L/SILL PNL SURFACE PAINT	14.19
2395	L/OUTER ROOF FRAME SURFACE PAINT	5.48
2396	R/OUTER ROOF FRAME SURFACE PAINT	5.48
4105	L/R INNER WING SURFACE PAINT	2.49

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor	50.00 SGD/h		
Time Paint		243.0	
Preparation Main Work Metal	2.50	25.0	125.00
Preparation Comp. Work Plastic	0.50	5.0	25.00
Total	10 WU/h	27.30	273.0

Material Cost - Paint

	Price SGD
New Part Painting	303.91
New Part Painting - Plastic K1R	166.28
Surface-/Blend Paint	38.85
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
Total	546.64

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01/01	Price SGD
0251	LWR RADIATOR GRILLE	53112 02190			40.00
0257	FRONT NUMBER PLATE	KNPL3			0.00
0281	FRONT BUMPER	52119 02850			150.00
0317	L/F BUMPER BRACKET	52116 02140			25.00

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
 Assessment number: SJU7506H-OD-AXA
 Version: 1810
 Date calculated: 16/05/2019 12:04 PM

Full Report
 Registration: SJU7506H
 Printed: 16/05/2019 12:04 PM

Code	Description	Part Number	Supplier	Price SGD
0318	R/F BUMPER BRACKET	52115 02140		25.00
0350	FRT BUMPER CLAMP KIT	USE SINGLE PARTS		10.00
0410	GRILLE	53100 02310		120.00
0431	GRILLE BADGE	75301 02050		25.00
0471	BONNET	53301 02230		230.00
0527	RADIATOR GRILL SEAL	53395 02050		25.00
0530	FRONT BONNET SEAL	53381 02140		25.00
0571	L/HEADLAMP CPL	81150 02720		140.00
0572	R/HEADLAMP CPL	81110 02720		140.00
0741	L/F WING	53812 02250		130.00
0789	L/F WING CLAMP KIT	90119 06137		15.00
0811	BADGE "VVT-I" L	75351 02110		15.00
0841	L/WHEELHOUSE SHELL	53876 02270		60.00
1016	FRT LWR CROSSMEMBER	57104 02170		580.00
1391	L/COWL PANEL GRILLE	55709 02330		180.00
1392	R/COWL PANEL GRILLE	55708 02450		180.00
1401	WINDSCREEN	56101 02930		400.00
1410	LWR WINDSCREEN SEAL	56117 12300		0.00
1411	WINDSCREEN REP KIT	PZ49I 00C1131		0.00
1423	UPP WINDSCREEN MLDG	75531 02190		45.00
1453	L/F WIPER ARM	85221 02280		70.00
1454	R/F WIPER ARM	85211 02270		70.00
1457	L/F WIPER BLADE	85222 12860		50.00
1458	R/F WIPER BLADE	85212 12480		50.00
1481	LEFT FRONT DOOR	67002 02340		400.00
1487	L/F UPPER DOOR HINGE	68720 12151		35.00
1495	L/F LOWER DOOR HINGE	68740 02100		35.00
1505	L/F DOOR CHECK	68610 02190		60.00
1509	L/F DOOR SEAL	67862 02230		75.00
1519	L/F DOOR WINDOW	68102 02291		180.00
1567	L/F DOOR OUT HANDLE	69211 AA020A0		45.00
1569	L/DOOR LOCK CYLINDER	69052 02170		150.00
1577	L/F DOOR LOCK	69040 0D270		180.00
1585	L/F LOCK CYL BRACKET	69217 12020		25.00
1619	L/INN WINDOW SEAL	68172 02180		70.00
1625	L/F OUT WINDOW SEAL	75720 02261		70.00
1685	L/DOOR FRT MOULDING	75732 02919		50.00
1697	L/F UPP DOOR STRIPE	75922 02150		70.00
1737	L/DOOR MIRROR	87940 02A70		270.00
1745	L/DOOR MIRROR HSG	87945 06903		0.00
1781	L/R DOOR	67004 02340		400.00
1787	L/R UPPER DOOR HINGE	68760 0D030		35.00

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:

Assessment number: SJU7506H-OD-AXA

Version: 1810

Date calculated: 16/05/2019 12:04 PM

Full Report

Registration: SJU7506H

Printed: 16/05/2019 12:04 PM

Code	Description	Part Number	Supplier	Price SGD
1795	L/R LOWER DOOR HINGE	68780 0D030		35.00
1805	L/R DOOR CHECK	68630 02180		60.00
1809	L/R DOOR SEAL	67872 02190		70.00
1835	L/R CORNER WDW SEAL	68189 02130		70.00
1847	L/R WINDOW REGULATOR	69804 02210		250.00
1867	L/R DOOR OUT HANDLE	69211 AA020A0		35.00
1877	L/R DOOR LOCK	69060 06060		180.00
1885	L/R LOCK CYL BRACKET	69227 06906		15.00
1897	L/R WINDOW CHANNEL	68152 02240		70.00
1919	L/R INN CHANNEL SEAL	68174 02140		70.00
1925	L/R OUT CHANNEL SEAL	75740 02240		70.00
1971	L/R UPP DOOR STRIPE	75924 02180		70.00
1985	L/DOOR REAR MOULDING	75742 02917		50.00
2207	L/SILL MOULDING	76912 02913		280.00
2351	ROOF	63111 02330		1,200.00
2581	REAR BUMPER	52159 02540		180.00
2621	L/R BUMPER RR BRKT	52156 02110		28.00
2623	L/W-HOUSE REAR SECT	52592 02180		40.00
2650	RR BUMPER CLAMP KIT	USE SINGLE PARTS		15.00
3160	REAR SCREEN BOND KIT	KNGKWI2		0.00
3163	REAR SCREEN FIX SET	USE SINGLE PARTS		
3164	SPACER	56115 30120		0.00
3165	SPACER	56116 22050		0.00
3169	LWR REAR WINDOW MLDG	64813 12180		0.00
3175	REAR WINDOW MOULDING	75571 02210		70.00
3481	L/R SIDE PANEL	61602 02320		380.00
4331	UPP INSTRUMENT PANEL	55302 02310B0		350.00
4957	HEADLINING	63310 02A40E0		900.00
7053	L/F LWR AXLE ARM	48069 02210		70.00
7077	L/F STRUT	48520 09L60		150.00
7081	L/F STEERING KNUCKLE	43212 02270		150.00
7117	L/F WHEEL BEARING	90080 36137		45.00
7131	L/F WHEEL HUB	43502 02110		120.00
7201	L/F WHEEL	42611 02B50		0.00
7227	L/F TYRE	195/65 R 15 .. V		0.00
8780	LOWER ENGINE PROTECT	51451 02100		70.00
9081	REAR AXLE SUBFRAME	42110 02440		750.00

...CLAIM SUBFOLDER...(Pending for Survey Report)

Total Loss

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Status
Main	14 May 2019	14 May 2019 11:52 S\$18,743.94	14 May 2019 15:54 Edit Adj Rpt	S\$13,492.64 Edit Estimates	S\$13,492.64 View Rpt	Pending for Survey Report

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	BK SAN ENGINEERING PTE LTD, Co. Reg. No.: 200700618K, Tel: +6591009252								
Vehicle Reg. No.:	SJU7506H	Date of Loss:	09/05/2019 13:00 - :59 [112 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 593267	Policy/Cover Note No.:	A80457553MCX (Comprehensive) Coverage: 16/05/2018 - 15/05/2019						
		Excess:	S\$500.00						
Repairer:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18, 628457 Pioneer - Tel: 6268 6183								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Vimmaia D/O Raja Singam - 65942471]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 13/06/2019]								
Driver/Custodian:	LAKSHMANAN PADIYAN (35 / Male), NRIC: G6027454T, Tel: +6583338527 Email:								
Adj Asg. Remarks:	Please revert. Surveyor to check on market value and rebate if the vehicle is economical to repair. Manufacturing year:2009. Please check on the tyres,brake and steering wheel is in efficient condition prior to the accident.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
MSIG_SG (22/05/2019): Alert - Adj Mandate Revoked - SJU7506H - Claim Handler: Vimmaia D/O Raja Singam									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SJU7506H (593267)
OD
May 9 2019 1:00PM
[BK SAN ENGINEERING PTE LTD]
Sng Ah Tee Motor & Panel Service Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	14/05/19 11:52	Repairer Estimates	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/05/19 17:10	Adjuster Immediate Advice	Load HTM	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/05/19 14:04	General View	Load JPG	☒
2	16/05/19 14:04	General View	Load JPG	☒
3	16/05/19 14:04	General View	Load JPG	☒
4	16/05/19 14:04	General View	Load JPG	☒
5	16/05/19 14:04	General View	Load JPG	☒
6	16/05/19 14:04	General View	Load JPG	☒
7	16/05/19 14:04	General View	Load JPG	☒
8	16/05/19 14:04	General View	Load JPG	☒
9	16/05/19 14:04	General View	Load JPG	☒
10	16/05/19 14:04	General View	Load JPG	☒
11	16/05/19 14:04	General View	Load JPG	☒
12	16/05/19 14:04	General View	Load JPG	☒
13	16/05/19 14:04	General View	Load JPG	☒
14	16/05/19 14:04	General View	Load JPG	☒
15	16/05/19 14:04	General View	Load JPG	☒
16	16/05/19 14:04	General View	Load JPG	☒
17	16/05/19 14:04	General View	Load JPG	☒
18	16/05/19 14:04	General View	Load JPG	☒
19	16/05/19 14:04	General View	Load JPG	☒
20	16/05/19 14:04	General View	Load JPG	☒
21	16/05/19 14:04	General View	Load JPG	☒
22	16/05/19 14:04	General View	Load JPG	☒
23	16/05/19 14:04	General View	Load JPG	☒
24	16/05/19 14:04	General View	Load JPG	☒
25	16/05/19 14:04	General View	Load JPG	☒
26	16/05/19 14:04	General View	Load JPG	☒
27	16/05/19 14:04	General View	Load JPG	☒
28	16/05/19 14:04	General View	Load JPG	☒
29	16/05/19 14:04	General View	Load JPG	☒
30	16/05/19 14:04	General View	Load JPG	☒
31	16/05/19 14:04	General View	Load JPG	☒
32	16/05/19 14:04	General View	Load JPG	☒
33	16/05/19 14:05	General View	Load JPG	☒
34	16/05/19 14:05	General View	Load JPG	

Assessment Reports			1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
				☒
35	16/05/19 14:05	General View	 Load JPG	☒
36	16/05/19 14:05	General View	 Load JPG	☒
37	16/05/19 14:05	General View	 Load JPG	☒
38	16/05/19 14:05	General View	 Load JPG	☒
39	16/05/19 14:05	General View	 Load JPG	☒
40	16/05/19 14:05	General View	 Load JPG	☒
41	16/05/19 14:05	General View	 Load JPG	☒
42	16/05/19 14:05	General View	 Load JPG	☒
43	16/05/19 14:05	General View	 Load JPG	☒
44	16/05/19 14:05	General View	 Load JPG	☒
45	16/05/19 14:05	General View	 Load JPG	☒
46	16/05/19 14:05	General View	 Load JPG	☒
47	16/05/19 14:05	General View	 Load JPG	☒
48	16/05/19 14:05	General View	 Load JPG	☒
49	16/05/19 14:05	General View	 Load JPG	☒
50	16/05/19 14:05	General View	 Load JPG	☒
51	16/05/19 14:05	General View	 Load JPG	☒
52	16/05/19 14:05	General View	 Load JPG	☒
53	16/05/19 14:05	General View	 Load JPG	☒
54	16/05/19 14:05	General View	 Load JPG	☒
55	16/05/19 14:05	General View	 Load JPG	☒
56	16/05/19 14:05	General View	 Load JPG	☒
57	16/05/19 14:05	General View	 Load JPG	☒
58	16/05/19 14:05	General View	 Load JPG	☒
59	16/05/19 14:05	Chassis Number	 Load JPG	☒
60	16/05/19 14:05	General View	 Load JPG	☒
61	16/05/19 14:05	General View	 Load JPG	☒
62	16/05/19 14:05	General View	 Load JPG	☒
63	16/05/19 14:05	General View	 Load JPG	☒
64	16/05/19 14:05	General View	 Load JPG	☒
65	16/05/19 14:05	General View	 Load JPG	☒
66	16/05/19 14:05	General View	 Load JPG	☒
67	16/05/19 14:05	General View	 Load JPG	☒
68	16/05/19 14:05	General View	 Load JPG	☒
69	16/05/19 14:05	General View	 Load JPG	☒
70	16/05/19 14:05	General View	 Load JPG	☒
71	16/05/19 14:05	General View	 Load JPG	☒
72	16/05/19 14:05	General View	 Load JPG	☒
73	16/05/19 14:05	General View	 Load JPG	☒
74	16/05/19 14:05	General View	 Load JPG	☒
75	16/05/19 14:05	General View	 Load JPG	☒
76	16/05/19 14:05	General View	 Load JPG	☒
77	16/05/19 14:05	General View	 Load JPG	☒
78	16/05/19 14:05	General View	 Load JPG	☒
79	16/05/19 14:05	General View	 Load JPG	☒
80	16/05/19 14:05	General View	 Load JPG	☒
81	16/05/19 14:05	General View	 Load JPG	☒
82	16/05/19 14:05	General View	 Load JPG	☒
83	16/05/19 14:05	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
84	16/05/19 14:05	General View	 Load JPG	☒
85	16/05/19 14:05	General View	 Load JPG	☒
86	16/05/19 14:05	General View	 Load JPG	☒
87	16/05/19 14:05	General View	 Load JPG	☒
88	16/05/19 14:05	General View	 Load JPG	☒
89	16/05/19 14:05	General View	 Load JPG	☒
90	16/05/19 14:05	General View	 Load JPG	☒
91	16/05/19 14:05	General View	 Load JPG	☒
92	16/05/19 14:05	General View	 Load JPG	☒
93	16/05/19 14:05	General View	 Load JPG	☒
94	16/05/19 14:05	General View	 Load JPG	☒
95	16/05/19 14:05	General View	 Load JPG	☒
96	16/05/19 14:05	General View	 Load JPG	☒
97	16/05/19 14:05	General View	 Load JPG	☒
98	16/05/19 14:05	General View	 Load JPG	☒
99	16/05/19 14:05	General View	 Load JPG	☒
100	16/05/19 14:05	General View	 Load JPG	☒
101	16/05/19 14:05	General View	 Load JPG	☒
102	16/05/19 14:05	General View	 Load JPG	☒
103	16/05/19 14:05	General View	 Load JPG	☒
104	16/05/19 14:05	General View	 Load JPG	☒
105	16/05/19 14:05	General View	 Load JPG	☒
106	16/05/19 14:05	General View	 Load JPG	☒
107	16/05/19 14:05	General View	 Load JPG	☒
108	16/05/19 14:05	Odometer Reading	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	14/05/19 11:52	E-filed GIA report	 Load PDF	
2	14/05/19 11:52	CI,IC,DL	 Load TIF	
3	14/05/19 11:52	Repair Estimates	 Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	14/05/19 14:27	Driving licence validity status	 Load PDF	
2	15/05/19 08:42	Driver's NRIC - Passing date is 02/05/2009	 Load PDF	
3	27/05/19 09:38	Discharge Form	 Load DOCX	
4	27/05/19 09:51	Email to OI on the discharge form/CTL offer	 Load PDF	
5	27/05/19 11:57	Signed DV	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG19008531/R1QD3E2

Date: 28/05/2019

REFERENCE

Insured/Claimant: BK SAN ENGINEERING PTE LTD

Policy No: A80457553MCX

Date of Loss: 09/05/2019

Nature of Claim: OD

Claim No: 593267

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJU7506H

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A)

Engine No: 3ZZ4955502

Reg. Date: 28/12/2009 (Man. Year: 2009)

Chassis No: MR053ZEE106162473

Colour: Grey

Odometer: 133165 km

Engine Capacity: 1598 cc

Market Value/New Car Price: S\$14,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Falken 6 mm

Rear Left Side: Falken 6 mm

Front Right Side: Falken 6 mm

Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth.

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,884.30	7,876.00	5,008.30	38.87
Miscellaneous Items	1,238.00	1,050.00	188.00	15.19
Paintwork Materials	546.64	546.64	0.00	0.00
Labour	2,710.00	2,655.00	55.00	2.03
Paintwork Labour	1,365.00	1,365.00	0.00	0.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,743.94	13,492.64	5,251.30	28.02
- Excess (S\$)	0.00	3,500.00	-3,500.00	
(S\$)	18,743.94	9,992.64	8,751.30	46.69
+ GST 7.00/7.00% (S\$)	1,312.08	699.48	612.60	46.69
Nett Amount (S\$)	20,056.02	10,692.12	9,363.90	46.69

INSPECTION

Date of Assignment: 14/05/2019 Present Location:

Sng Ah Tee Motor & Panel Service Pte Ltd
(Pioneer)

Date Inspected: 15/05/2019 Inspected At:

Sng Ah Tee Motor & Panel Service Pte Ltd
(Pioneer)
Blk 3 Pioneer Road North, #01-18
Singapore 628457

Estimated Period of Repair: 0.0 days

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(EXCLUDE CHECK ITEMS S\$4,658.50 NETT)

TOTAL LOSS ASPECT

Market Value : \$14,000.00
OMV : \$17,853.00
PARF Rebate (1) : \$ 8,926.00
Quota Premium Paid : \$18,150.00
COE Rebate (2) : \$ 1,122.00
Total Rebate (1) + (2) = : \$10,048.00

The total amount incurred will be Market Value \$14,000.00 minus Total Rebate \$10,048.00 = \$3,952.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 May 2019)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJU7506H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SPARE PARTS (WCP)		12,884.30 F	*7,160.00 F
Sub Total (S\$)					12,884.30	7,160.00
+ Margin on L,N Items 0.00/10.00% (S\$)					0.00	716.00
Total Parts (S\$)					12,884.30	7,876.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Materials</u>				
1	1	TOTAL PAINT / MATERIAL	546.64	546.64
<u>Miscellaneous Items</u>				
2	1	SPARE PART SPECIAL NETT	1,238.00	1,050.00
Sub Total (S\$)			1,784.64	1,596.64

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	TOTAL PAINTWORK	New	1,365.00	1,365.00
<u>Labour Items</u>				
2	TOTAL PANEL / MECHANICAL	New	2,710.00	2,655.00
Gross Labour Cost (S\$)			4,075.00	4,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >