



CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk A #01-11 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R

GST Reg No.: 201718369R

REMESH KUMAR PILLAI

21/05/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP 11516

Shirley

WBAWL72020J297985

Accident date: 10/05/2019

Estimated repair cost for vehicle no: SLZ6885U BMW 335i 3.0 A '09

CHASSIS: WBAWL72020J297985

S/n	Qty	Items	U/price	Amount
1	1	Front Bonnet <i>Repair</i>		\$1,869.00 *
2	1	Front Bonnet Emblem Logo <i>NEW</i>		\$96.00 ✓
3	2	Front Head Lamp <i>contd NEW</i>	\$2,013.80	\$4,027.60 ✓
4	2	Front Head Lamp Lower Bracket <i>contd NEW</i>	\$112.90	\$225.80 112.90
5	1	Front Bumper <i>delid</i>		\$2,800 1600/30
6	10	Front Bumper Clip <i>NEW</i>	\$6.50	\$65.00 30
7	2	Front Bumper Side Retainer <i>NEW</i>	\$28.00	\$56.00 +
8	1	Front Bumper Number Plate <i>delid</i>		\$50.00 -
9	1	Front Bumper Towing Cover <i>NEW</i>		\$32.00 +
10	2	Front Bumper Wiper Nozzle Cover <i>NEW</i>	\$38.00	\$76.00 +
11	1	Front Bumper Centre Lower Garnish <i>NEW</i>		\$189.00 +
12	1	Front Bumper Reinforcement <i>NEW</i>		\$650.30 +
13	2	Front Bumper Fog Lamp <i>NEW</i>	\$343.60	\$687.20 +
14	2	Front Bumper Fog Lamp Cover <i>NEW</i>	\$80.90	\$161.80 +
15	2	Front Grille <i>NEW</i>	\$221.80	\$443.60 +
16	1	Front Grille Inner Cover <i>NEW</i>		\$239.30 +
17	1	Front Support Panel <i>NEW</i>		\$573.50 +

Subtotal :- \$10,874.80

Number Plate : 50.

Bumper 1600 (SN)

Clips 30.

Logo 96.

list: 176

less 10%: 158.4.

S.N. / 600.

4316.50

4100.67 S.N. / 600

9442.1

Labour charges

To reset computer		\$380.00	*
To check wiring		\$150.00	30
Tuff kote	830	\$150.00	*
Panel beating		\$1,400.00	300
Spray painting		\$1,600.00	500

Subtotal :- \$3,680.00

Total:- \$14,554.80

15922.10

total: 653067

c/s 5.2K.

04 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3 (04 Days)

total: 258840.

u/s : 2K.