| Survajor : _ '            | anger                               | ASS               | IGNMENT        | (Office)    |                |                 |          |
|---------------------------|-------------------------------------|-------------------|----------------|-------------|----------------|-----------------|----------|
| From (Person):            | Irana Tan Gek Ing                   | of                | MSIG           |             | Date/          | Time: 14-5.19   | 15:56 p. |
| Estimated Cost            |                                     |                   | Bi             | ll to:      |                |                 |          |
| OD (TP) WS To Inspect Veh | TP RES / OD RES / EVicle No: SLZ 68 |                   | /MV/CS         |             | Insured:       | SM ( 5402       | ×        |
| at Workshop m             | us chew motor                       |                   |                |             | Tel: 4         | 479241          |          |
| of NO 1 \$91              | a Buril Ave 6 )                     | # 61-             | -11/41         |             |                |                 |          |
| Policy No: 20             | 1088176                             |                   |                | Claim No: _ | 593241         |                 |          |
| Sum Insured:_             |                                     |                   |                | Excess: _   |                |                 |          |
| Make of Veh:              |                                     |                   |                |             | D.O.A          | 10.05.20        | 019      |
|                           | REP. / REV 24 HRS                   | " (wp") Person Co |                | surri       | н.о<br>Vehicle | D. Endorsement: |          |
| Date/Time                 | Action/Instruction (                | /) (              | Stimate.       |             |                |                 |          |
|                           | QZ 6885 V -                         | X                 |                |             |                |                 |          |
|                           | SM(5402 x -                         | ×                 |                |             | 1.             |                 |          |
| 16/03/15                  | @ 09:23.                            | am.               | revet          | pedage      | eatines        | from -          | anger -  |
|                           | reposer to                          | Iren              | e tan          | v; 4        | Me'mus         |                 |          |
| 16/03/15                  | apor to                             | In<br>In          | revet<br>e tan | via.        | merimus        | tom -           | 7/-      |

(costing)

# ...CLAIM SUBFOLDER...(New Assignment)

| Case      | Notified           | Est Submitted     | Adj Assigned                         | Adj Rpt        | Adj Submitted            | Ins Auth'ed  | Status  |               |
|-----------|--------------------|-------------------|--------------------------------------|----------------|--------------------------|--|---|---------------|
| Main      | 14 May 2019        |                   | 14 May 2019<br>15:56<br>Assign       |                |                          |  | New Assig<br>Cancel Ca                          | 280,000 (270) |
|           | Main               | Ref               | erence                               | Clair          | n Details                | Docume   | ents  | Show All      |
| LAIM S    | UBFOLDER DET       | TAILS             |                                      |                | THE THE STREET SHOWS AND | [Cre   | ated by insu                                    | rer]          |
| nsured:   |                    | DARRE             | LL LOO KAH MUI                       | N, ID: S9121   | 177Z, Tel: +6598         | 3231806  |   | (M. (4)       |
| ain Clair | mant:              | KUMAR             | PILLAI REMESH                        | I, ID: S1507   | 5243                     |  |   |               |
| ehicle Re | eg. No.:           | SLZ68             | 885U                                 | Dat            | e of Loss:               | [116   | 5/2019 10:00<br>6 Months and 2<br>Reg Date (Man | 6 Days From   |
| laim Typ  | e:»                | <b>TP</b> / 5     | 93241                                | Poli           | cy/Cover Note No.:       | Cove   | 88176 (Compre<br>grage: 07/07/20<br>7/2019      |               |
| ehicle Re | eg. No. (Insured): | SMC54             | 02X                                  | Poli           | cy No. (Claimant):       |  |   |               |
|           | 16 M2              |                   |                                      | Exc            | ess:                     |  |   |               |
| epairer:  |                    |                   | 4otor Pte Ltd (H<br>179241 / 6509554 |                | ukit Ave 6, #01-11       | /41, Autobay@Kak   | Bukit, 417883                                   | Kaki Bukit -  |
| landling  | Insurer:           | MSIG I<br>6594 25 | nsurance (Singa<br>541]              | pore) Pte. Ltd | I. (HQ) - Tel: +65       | 6827 7888 [Hai   | ndled by Irene                                  | Tan Gek Ing   |
| djuster:  |                    | LKK Au            | to Consultants P                     | te Ltd (HQ) -  | Tel: 6256-3561           | [Imm.Advice  | due 15/05/2                                     | 019]          |
|           | stodian (Insured)  | DARREL            | L LOO KAH MUN (                      | ) , NRIC: S9   | 121377Z, Tel: +6         | 5598231806 Email:  |   |               |
| d) Asg. F | Remarks:           | SURVEY            | AGREE ON SJE -F                      | REQ TO ASSIGN  | LKK. LIABILITY:1         | 00% CONTACT: SU  | IKYI CHONG 67                                   | 47 9241       |
| SSOCI     | ATED MAIL REC      | EIVED             |                                      |                |                          | View All   | Compos  | se Case Mail  |
| here are  | no mail for this c | ase.              |                                      |                |                          | and the last state of the last |   |               |
| 8         |                    |                   |                                      |                |                          |  |   | 2 10 10 10 10 |
| ALL ASS   | OCIATED TASK       | S                 |                                      |                | View All Sear            | ch Tasks Cre   | ate New Task                                    | Complete      |
| Due Da    |                    | Type Task G       | roup Subject                         | Handler        | Assigned By              | Completed On   | Created   | On Done       |

#### **View Sent Message**

This mail is associated with:

\*SLZ6885U (593241) [SMC5402X]

TP

KUMAR PILLAI REMESH May 10 2019 10:00AM [DARRELL LOO KAH MUN] Chew Motor Pte Ltd

Resend

View Recipients

Print Message | Delete Message | Forward

From

LKK Auto Consultants Pte Ltd (LKK\_HQ), sent on 16/05/2019 09:23 AM.

To

irene\_tan@sg.msig-asia.com

CC

sur@lkkauto.com

Subject

SLZ6885U (593241) [SMC5402X] TP

Dear Irene,

Please be informed that we have inspected the vehicle SLZ 6885U on 15/05/2019.

We are pending estimate from repairer.

Thank you.

Best Regards, Shirley Hiew | Case Handler LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

#### **DOCUMENTS SUMMARY**

There are no documents.

**New Cars** 

**Used Cars** 

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

Available


Luxury

- Is it alright to pay more for the Toyota brand?
- Lazada good deals lobang!
- Inconsistent RPM









Owner, Trade-Ins, Insurance And Loans Available. Please Co...

BMW 3 Series 335i

POSTHE: 11 Play-2019 Tage: 2009 RMW 3251, 2009 bnns 335, RMW 3251, brow 1351, RMW, 3351, Used BMW

\$43,888

N.A

Look Here If You Are Looking For A Super Fast, Flashy A Nd Affordable BMW Family Car. New Paint Works, New Interior Leather, Roof Lining, New 3-way Adjustable Collover, New PS4S Tyres, All Wear And Te...

29-Jul-2009

2,979 cc

170,000 km





BMW 3 Series 335i Convertible \$51,000 \$24,200 /yr 17-Dec-2009 2,979 cc 82,000 km

Beautifully And Extensively Maintained, LTA Inspection Just Done, Regularly Serviced And Maintained, Wear And Tear Parts Upgraded, Truly A Worthwhile Unit Not To Be Missed, Please Call For An Appointm...

7. Posted: 03-May-2019. Tass: 2009 BMW 335i, 3009 bmw 335i, BMW 335i, bmw 335i, BMW, 335i, Used BMW.

Save this search criteria, to get email alerts whenever a match is found.

▼ 🚊 Price ▼ 😩 Depreciation ▼ 😩 Reg Date ▼ 💲 Eng Cap ▼ 😩 Mileage ▼ 🥞 ▼ Model Veh Type ▼

For old advertisements, view Expired ads

20 ▼ results/page

Sports

Available

**BEAUTIFUL** 

Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

spCarMart is the number one can classified for pureflet import cars, Toyota, Flooda, Wassin, Missiphahi & BMW. There are plenty of cars for sale, from varie, brucks, sedim cars, houry cars, sports arm or stationwagons, StV, MIV. Nistrabuck, to CDE cars & OPC cars. You can also buy fraction, wirk up car laters, financial services, low milesage cars, car branch, carpark rates & car insurance. Find buy used 135, 375 Singapore, used 335 Singapore, used 335, used vehicles Singapore or even buy used 335 Singapore. We have new car dealers comprising partitlet importers, authorised on dealers, and used car dealers on our site, find new car procedure, and new car promotoris. Visit our partner sites for job openings for Singapore jobs, real estat properties for said, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COT results.

All prices and other information displayed on sgCarMart.com are guiltiered from sources and based on algorithms that are believed by sgCarMart.com to be rotable, but no assurance can be given that this information is accounte, complete or current, sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accountry of this information.

Follow sgCarMart.com











About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement ©2004-2019 sgCarMart, All rights reserved.



#### > Back to OneMotoring

# Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

7624J

Vehicle Details

Vehicle No.:

SLZ6885U

Vehicle to be Exported:

No

Intended Deregistration Date:

10 May 2019

Vehicle Make:

B.M.W.

Vehicle Model:

335I 3.0L SMT ABS D/AB HID

TURBO 2WD 2DR

Primary Colour:

Grey

Manufacturing Year:

2008

Engine No.:

06576959N54B30A WBAWL72020JZ97985

Chassis No.: Maximum Power Output:

225.0 kW (301 bhp)

Open Market Value:

\$73,719.00

Original Registration Date:

14 Aug 2009

First Registration Date:

14 Aug 2009

Transfer Count:

7

Actual ARF Paid:

\$73,719.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

13 Aug 2019

PARF Rebate Amount:

\$36,859.00

Intended COE Rebate Details

COE Expiry Date:

13 Aug 2019

COE Category:

B - Car (1601cc & above)

COE Period(Years):

10

QP Paid:

\$18,890.00

COE Rebate Amount:

\$487.00

Total Rebate Amount:

\$37,346.00

The information contained herein is correct as at 10 May 2019

OK

MSI/E19060949 / SME Motor Pte Ltd - Kaiz Sulut ENTRY DATE 8 TIME 10/05/2019 16/29 SUBMITTED 8Y: Chia Per Ying

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wiful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available.

|                            | ACCIDENT STATEMENT                  |  |
|----------------------------|-------------------------------------|--|
| Date Of Report             | 10/05/2019 16:29                    |  |
| Date Of Accident           | 10/05/2019 10:30                    |  |
| Exact Location Of Accident | CARPARK OF MOUNT ELIZABETH HOSPITAL |  |
| Country/State of Loss      | SINGAPORE                           |  |

| Country/State of Loss       | SINGAPORE              |  |
|-----------------------------|------------------------|--|
|                             | DETAILS OF OWN VEHICLE |  |
| Vehicle Registration Number | SLZ6885U               |  |
| Insured/Policyholder        |                        |  |
| Name Of Registered Owner    | KUMAR PILLAI REMESH    |  |
| NRIC No                     | S1507624J              |  |
| Email Address               | NOEMAIL                |  |
| Mobile Phone No             | (LOCAL) +65-98502052   |  |
| Alternative Phone No        | OFFICE-98502052        |  |
| Vehicle Particulars         |                        |  |
|                             | DAMA/                  |  |

| Manufacturer | BMW  |
|--------------|------|
| Model        | 3351 |

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?

THIRD PARTY If No, Please state action to be taken PRIVATE CAR Vehicle Category

Insurance Company

AXA INSURANCE PTE LTD Name of Insurance Company

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number GA437337

Cover Note Number

Driver

KARTIKEYEN PILLAI S/O REMESH KUMAR PILLAI Name of Driver

S9220595I NRIC No Date Of Birth 10/06/1992 Occupation INDOOR 01/11/2010 Date Of Driving Pass

8 YEARS AND 6 MONTHS Driving Experience

MALE Gender

(LOCAL) +65-98502052 Mobile Number

Fax Number Contact Number

EMail Address NOEMAIL Address

50 CHOA CHU KANG NORTH 7 #08-16

Postcode

Vehicle

689527

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

CHILDREN

Vehicle Registration Number of Driver's Own

-

Insurance Company of Driver's Own Vehicle

-

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

2

involved in the accident

NO

Was any body injured in the Accident?

Was any injured conveyed to hospital by

ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

YES

soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

2

Passenger 1

NAME:

: FELICIA

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

NO.

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

#### Circumstances of Accident

I WAS TRAVELLING IN THE CARPARK OF MOUNT ELIZABETH HOSPITAL. SUDDENLY, VEHICLE B REVERSED WITHOUT CHECKING. I FOLLOWED SUIT TO REVERSE. HOWEVER, I HAD TO STOP AS THERE WAS ANOTHER VEHICLE BEHIND OF ME. THEN, I FELT AN IMPACT. VEHICLE B DID NOT STOP AND HIT ONTO THE FRONT PORTION OF MY VEHICLE. AS A RESULT, MY FRONT NUMBER PLATE WAS DAMAGED AND ALSO MY BUMPER.

#### Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

#### **DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number Vehicle Make/Model/Colour SMC5402X

Details Of Properties

VEHICLE B

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage No. Of Passenger (Including Driver)

#### Sketch Plan #2 Pg. 1

A. SIZBERGY

B. SI

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

| then, I fet an impact tenico is an not exp<br>and but outo the front portion of my renico.  The a result, my front number that was domaged | venicle behind of me.  Then, I felt an impact tenicle is all not supported by outsite from partial of my renicle.  The a result, my from number that was damaged |        | reverse.            | Without checking. 1- | followed |
|--|--|--------|---------------------|----------------------|----------|
| and but outo the front portion of my renicle.  As a result, my front number that was domaged   | and but outo the front portion of my renicle.  As a result, my front number that was domaged   |        |                     | as there was a       | nather   |
| As a regult, my foot number Plate was damaged  | As a reliation my food number Plate was damaged and also my lamper.  |        |                     |                      |          |
| a at the text of the section   |  | As a l | erutt, my travil ne | imber Plate was do   | waged    |
|  |  |        |                     |                      |          |

DECLARATION

I/We declare the foregoing particulars are true in every respect.

- AW

Policyholder's Signature Date & Time: Oriver's Signature (If driver is not the policyholder) Date & Time:

Reporting Centre Dessonnel's Signature Name: NRIC/FIN No.



REMESH KUMAR PILLAI Blk 1 Kaki Bukit Ave 6 # 01-43 Singapore 417883

# CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk A #01-11 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R GST Reg No.: 201718369R

21/05/2019

36idey. WBAGG 72020J2575 85

Accident date: 10/05/2019

Estimated repair cost for vehicle no: SLZ6885U BMW 335i 3.0 A '09

CHASSIS: WBAWL72020JZ97985

| S/n | Qty | Items                                | U/price    | Amount     |
|-----|-----|--------------------------------------|------------|------------|
| 1   | 1   | Front Bonnet Peir                    |            | \$1,869.00 |
| 2   | 1   | Front Bonnet Emblem Logo Alex        |            | \$96.00    |
| 3   | 2   | Front Head Lamp                      | \$2,013.80 | \$4,027.60 |
| 4   | 2   | Front Head Lamp Lower Bracket 2H and | \$112.90   | \$225.80   |
| 5   | 1   | Front Bumper Dela                    |            | \$ 2800    |
| 6   | 10  | Front Bumper Clip Kun                | \$6.50     | \$65.00    |
| 7   | 2   | Front Bumper Side Retainer           | \$28.00    | \$56.00    |
| 8   | 1   | Front Bumper Number Plate            |            | \$50.00    |
| 9   | 1   | Front Bumper Towing Cover            |            | \$32.00    |
| 10  | 2   | Front Bumper Wiper Nozzle Cover      | \$38.00    | \$76.00    |
| 11  | 1   | Front Bumper Centre Lower Garnish    |            | \$189.00   |
| 12  | 1   | Front Bumper Reinforcement Au        |            | \$650.30   |
| 13  | 2   | Front Bumper Fog Lamp AH W           | \$343.60   | \$687.20   |
| 14  | 2   | Front Bumper Fog Lamp Cover          | \$80.90    | \$161.80   |
| 15  | 2   | Front Grille                         | \$221.80   | \$443.60   |
| 16  | 1   | Front Grille Inner Cover Me ~        |            | \$239.30   |
| 17  | 1   | Front Support Panel XLL ~            |            | \$573.50   |

Subtotal :-\$10,874.80

4316:50 4100 67 8-N-1600

9442.1

## Labour charges

To reset computer

\$380.00

To check wiring

\$150.00 30

Tuff kote

830

\$150.00

Panel beating

\$1,400.00 300

Spray painting

\$1,600.00 500

Subtotal :-

\$3,680.00

Total:-

\$14,554.80

15922-10

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before latter spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- . No itlegal modification(s) is allowed
- . Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/MSG19008535/AGSD3N2

Date:

12/09/2019

REFERENCE

Handling Insurer:

MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

29088176

SMC5402X

Claimant Vehicle No:

Date of Loss:

SLZ6885U 10/05/2019 Insured Vehicle No:

Nature of Claim:

TP

Claim No: 593241

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No:

SLZ6885U

Make & Model:

BMW 335I, 3.0 (A)

Engine No: Chassis No:

Odometer:

06576959N54B30A WBAWL72020JZ97985

181756 km

Reg. Date: Colour:

14/08/2009 (Man. Year: 2008) Grey

2979 cc

**Engine Capacity:** Market Value/New Car

N/A

Price:

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

**General Condition:** 

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable):

**CONDITION OF TYRES** 

Front Tyre Size:

235/35R19

Rear Tyre Size:

235/35R19

Front Left Side:

Rear Left Side:

Front Right Side:

Achilles 6 mm Achilles 6 mm

Rear Right Side:

Achilles 6 mm Achilles 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                    | Repairer's | Adjuster's | Difference | Diff % |
|-----------------------------------|------------|------------|------------|--------|
| Parts                             | 12,242.10  | 5,700.67   | 6,541.43   | 53.43  |
| Miscellaneous Items               | 0.00       | 0.00       | 0.00       |        |
| Labour                            | 3,680.00   | 830.00     | 2,850.00   | 77.45  |
| Paintwork Labour                  | 0.00       | 0.00       | 0.00       |        |
| Towing                            | 0.00       | 0.00       | 0.00       |        |
| Calculated Gross Total (S\$)      | 15,922.10  | 6,530.67   | 9,391.43   | 58.98  |
| Approved Total (Overridden) (S\$) |            | 5,200.00   |            |        |
| (S\$)                             | 15,922.10  | 5,200.00   | 10,722.10  | 67.34  |
| + GST 7.00/7.00% (S\$)            | 1,114.55   | 364.00     | 750.55     | 67.34  |
| Nett Amount (S\$)                 | 17,036.65  | 5,564.00   | 11,472.65  | 67.34  |

INSPECTION

Date of Assignment:

14/05/2019

Date Inspected:

15/05/2019 Inspected At:

Chew Motor Pte Ltd (HQ)

No 1 Kaki Bukit Ave 6, #01-11/41,

Autobay@Kaki Bukit Singapore 417883

Estimated Period of Repair:

4.0 days

Manager: Hiew May Fung Adjuster: XING GUO QIANG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 12 Sep 2019)

Parts: N/A BMW 335I 3.0 (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLZ6885U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

| No. |             | nended Parts<br>Part No. Particulars | Condition         | Repairer's  | Amount       |
|-----|-------------|--------------------------------------|-------------------|-------------|--------------|
| 1   | 1           | *FRONT BONNET                        | Repair            | 1,869.00 F  | *-FL         |
| 2   | 1           | *FRONT BONNET EMBLEM LOGO            | Necessary         | 96.00 F     | *96.00 FL    |
| 3   | 2           | *FRONT HEAD LAMP                     | Cracked           | 4,027.60 F  | *4,027.60 FL |
| 4   | 1           | *FRONT HEAD LAMP LOWER BRACKET       | O/s Cracked       | 225.80 F    | *112.90 FL   |
| 5   | 10          | *FRONT BUMPER CLIP                   | Necessary         | 65.00 F     | *30.00 FL    |
| 6   | 2           | *FRONT BUMPER SIDE RETAINER          | Not Necessary     | 56.00 F     | *-FL         |
| 7   | 1           | *FRONT BUMPER NUMBER PLATE           | Deformed          | 50.00 F     | *50.00 FL    |
| 0.5 | 1           | *FRONT BUMPER TOWING COVER           | Not Necessary     | 32.00 F     | *-FL         |
| 9   | 2           | *FRONT BUMPER WIPER NOZZLE COVER     | Not Necessary     | 76.00 F     | *-FL         |
| 10  | 1           | *FRONT BUMPER CENTRE LOWER GARNISH   | Not Necessary     | 189.00 F    | *-FL         |
| 11  | 1           | *FRONT BUMPER REINFORCEMENT          | Not Necessary     | 650.30 F    | *-FL         |
| 12  | 2           | *FRONT BUMPER FOG LAMP               | Not Necessary     | 687.20 F    | *-FL         |
| 13  | 2           | *FRONT BUMPER FOG LAMP COVER         | Not Necessary     | 161.80 F    | *-FL         |
| 14  | 2           | *FRONT GRILLE                        | Not Necessary     | 443.60 F    | *-FL         |
| 15  | 1           | *FRONT GRILLE INNER COVER            | Not Necessary     | 239.30 F    | *-FL         |
| 16  | 1           | *FRONT SUPPORT PANEL                 | Not Necessary     | 573.50 F    | *- FL        |
| 17  | 1           | *FRONT BUMPER                        | Deformed          | 2,800.00 FS | *1,600.00 FS |
|     | anchise par | rt. S=SpcNett. L=ListItemDisc.       |                   |             | 70.00        |
|     |             |                                      | Sub Total (S\$)   | 12,242.10   | 5,916.50     |
|     |             | - List Item Discount on L Item       |                   | 0.00        | 215.83       |
|     |             |                                      | Total Parts (S\$) | 12,242.10   | 5,700.67     |

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

| No   | Particulars       | Lab.Type                                   | Repairer's | Amount |
|------|-------------------|--|------------|--------|
| Labo | our Items         |  |            |        |
| 1    | TO RESET COMPUTER | New  | 380.00     | 0.00   |
| 2    | TO CHECK WIRING   | New  | 150.00     | 30.00  |
| 3    | TUFF KOTE         | New  | 150.00     | 0.00   |
| 4    | PANEL BEATING     | New  | 1,400.00   | 300.00 |
| 5    | SPRAY PAINTING    | New  | 1,600.00   | 500.00 |
|      |                   | Gross Labour Cost (S\$)                    | 3,680.00   | 830.00 |
|      | Ren               | ort was unsubmitted during this print-out. |            |        |

< END OF ESTIMATES >