

ASS. REC. BY:

REF:

C8/FCI/9008542/GVD3

Special Instruction:

Carrier:

GA

ASSIGNMENT (Office)

From (Person):

Karen Tan

of

FCI

Date/Time:

2:24 pm @ 14/5/19

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SPW 2818C

Insured:

SHA 72264

at Workshop m/s

Insurance's Auto

Tel:

9008 9959

of

Blk 134 Pasir Ris St. 11 #04-253

Policy No:

Claim No:

D19003158 MFST

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 12/05/2019

CA / REV / REP. / REV 24 HRS 'DS'

14/5/2019

H.O.D. Endorsement:

Date/Time:

3:01 pm @ 14/5/19

Person Contacted:

Dick

Vehicle IN/OUT

Date/Time

Action/Instruction

Estimate (✓)

Insp: Blk 503 B, Amk Ind. Prk A #01-405

SPW 2818C-X

SHA 72264-X

16/5/19

Email preli revised to FCI

62

REF: FCI

0811F

ASSIGNMENT

From: Date: 15/5/2019

Estimated Cost:

OD / ☒ WS / TP RES / QD RES / EVA / INV / MVTo inspect Vehicle No: SFW 2818C
at Workshop n/s Insurance's Auto
of 5038, AMIC Ind. Prk 2 # 01-405

Insured:

Policy No.:

Claims No.:

Sum Insured: Excess:

(Client's Record)

Make of Veh: Pls call before going
Dick @ 900899159

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: ~~\$50K~~ \$54K.

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Secn: Consistent? : Yes or No

Est. Repairs: 11 days Res.: Yes or No

Lump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 'Ds'

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SFW 2818C Yr Regn: 29 Apr 2011

Type: ☒ M. Car / ☐ M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 523i 2.5 CC 2497

Colour: white A/C: Insured / Std / Nil / NA

Sp. Reading: 168432 T/Radio: Insured / Std / Nil / NA

Eng/No:

C/No: WBAFP 320 90c 865954

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/40ZR19

R: 215/35ZR19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. D.O.L. 15-05-19

Survey held at w/s 12pm

Des. of Damages: Frt / Rear / ☒ O/S / N/S / U/C / Rooftop orThe ☒ U/C / Chassis frame / Body Structure affected due to collision.
N/S Frt, ~~BS~~

Date / Time Action / Instruction

repair limit \$16K.

21/6/19 paid \$14,900 with Dick (Red 22, 15.38, 60%)

RECEIVED 21 JUN 2019

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 21/6 - typist

Report Format: CWS

Lump Sum / I.B.I.: (\$ 14,900/2)

Days Of Repair: 11

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

3 + 02: \$1

Photo: 586

Others: 659

21/6/19

27x15=405

1701 405

90

50150

122

847

MOTOR SURVEY ASSIGNMENT

Date	13-05-2019	Our Ref No. D19003158MFSH
Accident Date	12-05-2019	Claim Type. Third Party
Insured Vehicle	SHA7226U	Third Party Vehicle. SFW2818C
Survey Location	BLK 134 PASIR RIS ST 11 #04-253	
Contact Person.	DICK	
Contact No.	90089959/ 0	Fax No. 64455393
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	INSURANCE'S AUTO	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 16 May 2019 2:41 PM
To: 'CWS Motor Claims'
Cc: 'Karen Tan'; SUR
Subject: RE: SURVEY ASSESSMENT - D19003158MFSH/1, SFW 2818C
Attachments: SFW 2818C PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SFW 2818C
Date of survey: 15/5/2019
Number of days : 10 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 14 May 2019 3:02 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19003158MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that repairer arrange survey on 15/05/2019.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Tuesday, 14 May 2019 2:24 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19003158MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19003158MFSH

Our ref: CS/FCI19008542/Gvd3

Date: 16/5/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LIMITED

WITHOUT PREJUDICE

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SFW 2818C


We thank you for your instruction on 14/5/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 15/5/2019 at the premises of M/s INSURANCE'S AUTO and have the following to report:-

Workshop Estimate Amount	:S\$36,509.40
Revised Estimate Amount	:S\$15,383.45
"Check" Items Amount	:S\$12,955.41
Market Value	:S\$
LTA Reimbursement Value	:S\$
Nett Value	:S\$

Description of Damage:

The vehicle sustained damages at the n/s front and o/s portion. The undercarriage affected due to collision



Comments/Present Status:

Damages Consistent

Yours faithfully,

XING GUO QIANG (HP 8288 0282)

M.MATAI, AMSAE-A

Automotive Assessor

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	0811F
Vehicle No.:	SFW2818C
Vehicle to be Exported:	No
Intended Deregistration Date:	15 May 2019
Vehicle Make:	B.M.W.
Vehicle Model:	523I 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV
Primary Colour:	White
Manufacturing Year:	2011
Engine No.:	03107732N52B25AF
Chassis No.:	WBAFP32090C865954
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$48,220.00
Original Registration Date:	29 Apr 2011
First Registration Date:	29 Apr 2011
Transfer Count:	2
Actual ARF Paid:	\$48,220.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Apr 2021
PARF Rebate Amount:	\$26,521.00
COE Expiry Date:	28 Apr 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$56,801.00
COE Rebate Amount:	\$11,091.00
Total Rebate Amount:	\$37,612.00

The information contained herein is correct as at 15 May 2019

OK

BMW 5 Series 523i **\$55,588** \$15,990 /yr 15-Jun-2011 2,497 cc 72,000 km **Available**

No Repairs Needed. New Aircon Compressor Replaced Last Week. Selling Due To Upgrading. Number Plate Will Be Retained. No Dealers/Consignment. Please Only Sms Or Whatsapp To Arrange Viewing. Price Nego...

Office No. - -

Erik - 88338666

BMW 5 Series 523i Highline **\$55,800** \$14,660 /yr 28-Jun-2011 2,497 cc 76,750 km Fave Auto International Pte Ltd **Available**

Very Low Mileage Done At 76,750 Km Only! 2 Owners. Original Beautiful Grey Paintwork With No Touch Up Required. Very Clean And Neat Dakota Grey Leather Interior With No Sticky Handles Or Defaced Butto...

Office No. - 69090152

Ken Tung - 81133145

BMW 5 Series 523i **\$50,800** \$13,450 /yr 29-Jun-2011 2,497 cc 145,000 km Seng Hup Auto Pte Ltd **Available**

Cheapest In Town! Loan Available, PML Unit, Very Good For Short Term Usage, Well Maintained, No Repairs Needed, Good Condition, Price Still Negotiable, Call To View It Now.

Office No. - 67771983

Vincent Tan - 96710179 | Ryan Ong - 94745721

BMW 5 Series 523i Sunroof **\$54,800** \$14,190 /yr 20-Jul-2011 2,497 cc 130,000 km 88 Motor Trading **Available**

S Pass, EP Or LTV Pass Welcome To Loan! In House Loan Or Bank Loan Available! Balloon Scheme Available! Easy And Flexible Loan Approval! We Are sgCarMart Premium Dealer! Viewing And Test Drive Availab...

Office No. - 62911187

Mr Ho - 96811390 | Jeremy - 97625070 | Ben - 90913551 | Nicholas - 81001945

BMW 5 Series 523i **\$52,800** \$14,160 /yr 22-Jul-2011 2,497 cc 89,000 km Auto Zoom Enterprise Pte Ltd **Available**

Low Mileage Of 89000Km Only! Neat/Clean/Stock Condition, Engine And Gearbox In Tip Top Condition, Perfect Undercarriage With No Unnecessary Sound, View And Test Drive To Believe!

Office No. - 63421000

Jeffrey - 90041167 | Stanley Chua - 96813489 | Robin - 97603335

BMW 5 Series 523i Sunroof **\$55,800** \$15,550 /yr 25-Jul-2011 2,497 cc - Prime Car Traders Pte Ltd **Available**

One Owner Only. Well Maintained. Good Condition. Low Down Payment, Low Interest Rate. Balloon Scheme Available. Call/SMS For More Details.

Office No. - 63166000

Jason - 93881975

BMW 5 Series 523i **\$52,800** \$13,760 /yr 29-Aug-2011 2,497 cc 91,000 km First CarMart Motor **Available**

Well Maintained Agent Unit With Low Mileage! Owner Upgraded To Porsche! Come With SDD Carplate! Please Call For Appointment To View!

Office No. - 67420070

Leslie Chong - 97431381 | Koh Peng - 97693336 | Sebastian Yeo - 97477566

BMW 5 Series 523i **\$55,000** \$14,480 /yr 31-Aug-2011 2,497 cc 111,500 km **Available**

Full PML And External Workshop Servicing Records. In Tip Top Condition.

Office No. - -

Rui - 96935349

BMW 5 Series 523i **\$54,000** \$14,600 /yr 02-Sep-2011 2,497 cc 115,000 km Monster Motors Pte Ltd **Available**

Full M5 Body Kit, Original Breyton Rims 20" With Warranty Card, Full PZero Tyres, Eisenman Exhaust, Front Brakes 6 Pot, 4 Aprakovic Exhaust Tips, Blistein Shock Absorbers, New Paint Metallic Grey High...

Office No. - -

Lincoln - 93673686 | Alex Lim - 92207602

BMW 5 Series 523i **\$54,800** \$14,110 /yr 30-Sep-2011 2,497 cc 110,000 km **Available**

Executive Popular Luxury Sedan That Blends Perfectly For Business And Leisure. Immaculate Condition.

Office No. - -

Thomas - 96337757

BMW 5 Series 523i Highline **\$61,800** \$15,260 /yr 21-Oct-2011 2,497 cc - MS Carz **Available**

► bmw 523i Used Vehicle List (20 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availability
BMW 5 Series 523i	\$45,800	\$14,040 /yr	07-Jan-2011	2,996 cc	-	Highline Automotive	Available

Selling Close To Export Price, Rare 3.0 Unit I. Enjoy The Sheer Pleasure Of Driving An Inline 6 With Good Space And Comfort. Bank/In-House Loan And Competitive Insurance Available. Speak To Our Sales ...

Office No. - 67778887

Kelvin Lim - 96651675 | Henry Ong - 98516566

BMW 5 Series 523i	\$45,888	\$14,180 /yr	21-Jan-2011	2,497 cc	122,000 km	Mandai Motor Trading	Available
--------------------------	-----------------	--------------	-------------	----------	------------	----------------------	------------------

Good Condition. Well Maintained. Flexible & Fast Arrangement For Loan & Insurance. Trade In Are Welcomed! Hurry Call Our Friendly Sales For More Info Or Visit Us At Our Showroom For Test Drive!

Office No. - 67775585

Heng Heng - 90058812 | Ms Li Jin - 97548093 | Mr Ee - 96275585

BMW 5 Series 523i	\$46,800	\$14,700 /yr	24-Feb-2011	2,497 cc	-	ST Carz Pte Ltd	Available
--------------------------	-----------------	--------------	-------------	----------	---	-----------------	------------------

Well Maintained F10 For Sale! Original Paintwork, Warranty Provided! Luxury, Spacious And Comfortable, Bank/ High Loan Available, High Trade In Welcome. Call Us For Viewing Now!

Office No. - 64654747

Daven - 88225151 | Ryan - 90778009 | Chris - 83565566

BMW 5 Series 523i	\$45,000	\$13,670 /yr	24-Feb-2011	2,497 cc	140,000 km	AMS Motors Pte Ltd	Available
--------------------------	-----------------	--------------	-------------	----------	------------	--------------------	------------------

Full PML Maintained, Good Condition, Original 18 Inch Rims, No Modifications, Black Leather Interior, Road Tax Till August 2019, Call For Viewing Now.

Office No. - 66944888

Alan Ng - 92233333

BMW 5 Series 523i	\$47,800	\$13,400 /yr	15-Mar-2011	2,497 cc	-	SG Car Consign Pte Ltd	Available
--------------------------	-----------------	--------------	-------------	----------	---	------------------------	------------------

Very Well Maintained, Service Regularly And Well Taken Care Of By A Careful Lady Look No Further! Best Value For Your Money. Direct Owner's Beautiful Champagne Brown With Elegant Biege Leather Upholster...

Office No. - 61000200

Danny Loh - 97622873 | Andy Tay - 94891030 | Joey Kwan - 87158050

BMW 5 Series 523i	\$48,800	\$15,060 /yr	31-Mar-2011	2,497 cc	-	Asia Carz Auto	Available
--------------------------	-----------------	--------------	-------------	----------	---	----------------	------------------

Office No. - -

Jack - 85712226

BMW 5 Series 523i Highline	\$51,800	\$14,450 /yr	27-Apr-2011	2,497 cc	90,000 km	Midas Cars Pte Ltd	Available
-----------------------------------	-----------------	--------------	-------------	----------	-----------	--------------------	------------------

Highline PML Model With Low Mileage Yet Lowest Depreciation, Beautiful White With Gray Interior! High Spec With GPS, Auto Tailgate And Parking Assist. Excellent Condition. Well Maintained. Great Condi...

Office No. - -

Roger - 81812192 | Kenny - 88288898

BMW 5 Series 523i	\$50,000	\$14,290 /yr	29-Apr-2011	2,497 cc	125,000 km	Monster Motors Pte Ltd	Available
--------------------------	-----------------	--------------	-------------	----------	------------	------------------------	------------------

Gearbox Overhaul, New Road Tax Till Oct. Comes With Engine And Gearbox Warranty. Loan And Trade In Available. Viewings Strictly By Appointment Only.

Office No. - -

Edwin - 94999696 | Calvin - 90673002

BMW 5 Series 523i Sunroof	\$53,800	\$14,400 /yr	03-Jun-2011	2,497 cc	-	Happy Motoring Pte Ltd	Available
----------------------------------	-----------------	--------------	-------------	----------	---	------------------------	------------------

Latest Addition~ Sporty White BMW 523i Guarantee Condition! No Repairs Required, Expensive BBS Rims New Tyres, Quiet Engine, I-Drive, Bluetooth Connectivity, Paddle Shifter, Park Assist, Trade In Welc...

Office No. - 68442228

Sham - 84228768 | Khoo - 96803004

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/05/2019 16:36
Date Of Accident	12/05/2019 17:45
Exact Location Of Accident	SIMS AVE TOWARDS CHANGI
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFW2818C
Insured/Policyholder	
Name Of Registered Owner	TAN HOCK TIONG
NRIC No	S7530811F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-85112818
Alternative Phone No	OFFICE-85112818

Vehicle Particulars

Manufacturer	BMW
Model	523i
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA464442/1
Cover Note Number	

Driver

Name of Driver	TAN HOCK TIONG
NRIC No	S7530811F
Date Of Birth	15/10/1975
Occupation	INDOOR
Date Of Driving Pass	08/08/1995
Driving Experience	23 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-85112818
Fax Number	
Contact Number	OFFICE-85112818
EMail Address	NOEMAIL

Address APT BLK 476B UPPER SERANGOON VIEW #16-528
Postcode 532476
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident CHAIN COLLISION
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 3
Was any body injured in the Accident? YES
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 2
Passenger 1 NAME: : MARIA TERESA MAHALAYNE
GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
Police Station Name 10 UBI AVENUE 3
Police Station Address ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact TEL NO: - FAX NO:
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHA7226U
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category TAXI
Name of Driver ZAKARIAH BIN YAHYA
NRIC/Passport Number S1498144F
Contact Number 90250961
Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SKA6606C
Vehicle Make/Model/Colour KIA SORENTO
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver CUPIDO CAESAR GIACOMO
NRIC/Passport Number S2772091I
Contact Number 96384717
Address
Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)


DETAILS OF INJURED PERSON 1

Name TAN HOCK TIONG
Approximate Age
Injuries Sustain
Injured person in which vehicle? SFW2818C
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address APT BLK 476B UPPER SERANGOON VIEW
#16-528
Postcode 532476

DETAILS OF INJURED PERSON 2

Name MARIA TERESA MAHALAYNE
Approximate Age
Injuries Sustain
Injured person in which vehicle? SFW2818C
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along Sim Ave towards Changi junction of Paya Lebar Road (Slip Road) a taxi SHA 7226U came out without stop and collided against my vehicle and the impact push my vehicle move to the right and hit onto a vehicle SKA 6606C after the accident I felt my neck strain and went to EGH and was given 3 days medical leave. I also want to state that time of accident I had a passenger on the front seat (Maria Teresa Mahalingam.)

DECLARATION

(We declare the foregoing particulars are true in every respect.)

Policyholder's Signature
 Date & Time

Driver's Signature
 (if driver is not the policyholder)
 Date & Time

Reporting Constable's Signature
 Name
 CRIC No.



24 HOURS TOWING SERVICES

KAOLIN MOTOR TRADING CO

Thomson Road Post Office, P.O. Box 95, Singapore 915704

Tel: 6452 0716, 6458 4013

Registration No. 21645200K

**CASH SALE
JOB ORDER**No. **7012195**

Messrs

Cash

Date

*12/05/2019*Vehicle No. *SLW 2818 C*Model *BMW 523*Destination *Sims Ave / Pungit Lchar Rd to workshop*

Time In

Time Out

Remarks

Amount \$ *1200*

- ☐ Change Spare Tyre / Jumpstart
☐ Basement / Multi Carpark
☒ Accident
☒ Using King Dolly (Extra Trailer)
☐ Lowered Bodykit / Suspension

- ☐ Loaded With Goods
☐ Dismantle Shaft / Brake / Equipment
☐ Open Door
☐ Crane up / Winch out

Driver

Received By

bizSAFE

Insurance's Auto

Blk 5038 Ang Mo Kio Ind. Park 2 #01-405

Singapore 569541.

Fax: 64455393. Email: insurancesauto@hotmail.com

Tel: 90089959.

Tan Hock Tiong

Blk 476 B Upper Serangoon View #16-528

Singapore 532476.

Vehicle No : SFW 2818 C
Chassis No : WBAFP32090C865954
Make : BMW 523i
Year : 2001

QTY	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1	Front Bumper / <i>TN</i>		\$1,435.40 /
1	Front Side Retainer LH / <i>re</i>		\$25.00 /
1	Front Bumper Washer Cover x <i>NN</i>		\$57.00 x
1	Front Bumper Loer Garnish LH x <i>NN</i>		\$82.00 x
1 set	Front Bumper Clips / <i>MC</i>		\$80.00 30
1	Front Bumper Emblem 'Logo' / <i>MC</i>		\$80.00 /
1	Bonnet x <i>Repair</i>		\$1,890.30 x
1	Bonnet Catch LH x <i>MC</i>		\$58.00 /
1	Front Fender LH / <i>buc</i>	780	\$984.90 /
1	Bonnet Lock LH x <i>NN</i>		\$160.00 x
1	Front Grill LH x <i>NN</i>		\$280.00 x
1	Front Fender Inner Shield LH / <i>re</i>	220	\$327.80 /
1	Front Fender Inner Shield Clips / <i>MC</i>	30	\$60.00 /
1	Front Fender Signal Lamp LH x <i>NN</i>		\$105.10 x
1	Front Head Lamp Assy LH / <i>CHA</i>	2650	\$2,960.30 /
1	Front Head Lamp Bracket LH / <i>wt</i>	155	\$185.30 /
1	Front Fog Lamp Assy LH x <i>BR</i>	311.2	\$376.00 /
1	Front Fog Lamp Garnish LH x <i>re</i>	125	\$155.00 /
1	Front Lower Arm LH x <i>BT</i>	280	\$626.25 /
1	Front Upper Arm LH x <i>BT</i>	308	\$525.30 /
1	Front Knuckle Arm LH x <i>MC</i>		\$679.50 /
1	Front Knuckle Bearing LH x <i>MC</i>		\$185.00 /
1	Front Wheel Hup LH x <i>BT</i>		\$513.20 /
1	Front Shock Absorber LH x <i>BT</i>	522.3	\$635.85 /

1	Front Anti Low Bar LH	X	BT	233.6	\$481.50	/
1	Front Steering Rack LH	X	NN	X	\$1,381.00	/
1	Rear Bumper	X	NN	X	\$1,563.25	/
1 set	Rear Bumper Clips	X		X	\$80.00	/
1	Rear Door Assy RH	/	buc	1688.9	\$1,884.50	/
1	Rear Door Weatherstrip RH	/	BT	168.85	\$285.00	/
1	Rear Door Lock RH	X	DM		\$271.00	/
2	Rear Door Upper/Lower Hinges RH	X	NN	X	\$110.00	/
1	Rear Door Checker RH	X		X	\$58.00	/
1	Rear Door Inner Trimboard RH	X		X	\$1,720.00	/
1	Rear Door Outer Handle RH	X	NN	X	\$394.00	/
1	Rear Door Glass Motor RH	X	BT		\$359.85	/
1	Rear Door Glass Chancellor	X	NN	X	\$168.55	/
1	Rear Fender RH	/	buc	1339	\$1,969.10	/
1	Rear Fender Inner Shield RH	/	TN	139	\$170.20	/
1	Rear Rockel Panel RH	X	repair	X	\$503.05	/
1	Rear Shock Absorber RH	X		X	\$521.00	/
1	Rear Bearing RH	X	NN	X	\$194.65	/
1	Rear Wheel Hup	X		X	\$184.15	/
					\$24,766.00	
					Less 10%	\$2,476.60
						\$22,289.40

12587.8
10% = 11329.02

Special Nett Item

1 set Giovanna Sport Rim 19"	2 pcs. 1 set	@ 800	1600	\$4,800.00	/
2 units Tyre 275/35ZR19	1 pc. 1 Dis.	@ 400	(60%) 240	\$1,600.00	/
1 pc Front Bumper Sensor	/	DM	200	\$400.00	/
2pcs Sideskirt LH/RH @\$1300.00	/	at. @ 800	1600	\$2,600.00	/
2pcs decorative stickers (side skirt) LH/RH @\$60.00	/		100	\$120.00	/
1pc decortive sticker (Headlamp Assy) LH	/		20	\$25.00	/
			3760		

Labour Charges

To remove and replaced damaged parts including straightening repositioning replacement parts.

1200 (1000) \$1,500.00

Supply Paint Material and necessary items. To respray replaced and other affected panels

1400 \$1,800.00

Towing with KING DOLLY

/ \$120.00

Reconnect wiring at the damage section and check for proper functions.

30 \$75.00

To remove/refit fuel tank to facilitate repair.

70 60 \$300.00

To remove/ replace front(LH) and rear (RH) undercarriage.

200 \$400.00

To perform 4 wheel alignment

60 \$200.00

To carry out anti rust treatment on affected panels.

✓ \$80.00

To check and reset fault reading setting with the aid or dignostic kit.

150 \$200.00

3/00

Grand Total :

\$36,509.40

37,015.38

11 10 Days.

[Signature]
16/5/19

lump sum repair.

After repair photos.

Guo Qiang - 82880282.

15/5/19.

Guo Qiang @ lkk auto. com.

18657.22

20%: 14900

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
Acknowledged by Repairer
Signature:
Date:

Insurance's Auto

Blk 5038 Ang Mo Kio Ind. Park 2 #01-405
Singapore 569541.

Fax: 64455393. Email: insurancesauto@hotmail.com
Tel: 90089959.

Tan Hock Tiong

Blk 476 B Upper Serangoon View #16-528
Singapore 532476.

Vehicle No : SFW 2818 C
Chassis No : WBAFP32090C865954
Make : BMW 523i
Year : 2001

QTY	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair - SUPPLEMENTARY

1	Front Caster Arm LH	1 BT	298	\$562.20
				\$562.20
			Less 10%	\$56.22
				\$505.98

268.2

Grand Total : \$505.98




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19008542/Gvd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 27-06-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 7226U	Veh. Inspected	SFW 2818C	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19003158MFSH	Excess (\$)	0.00	
Assign From	KAREN TAN	Assign Date	14/05/2019	
2. Vehicle Particulars & Condition				
Make & Model	BMW 523i 2.5	c.c	2497	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	WBAFP32090C865954	Colour	WHITE	
Odometer	168432	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/40Z R19	YOKOHAMA	5 mm	
L/H Front Tyre	245/40Z R19	YOKOHAMA	5 mm	
R/H Rear Tyre	275/35Z R19	YOKOHAMA	5 mm	
L/H Rear Tyre	275/35Z R19	YOKOHAMA	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/05/2019	Inspection Date	15/05/2019	
Survey held at	INSURANCE'S AUTO BLK 5038 ANG MO KIO INDUSTRIAL PARK 2 #01-405 SINGAPORE 569541			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		11 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFW 2818C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	TORN	1,435.40	1,435.40
1	FRONT SIDE RETAINER LH	DEFORMED	25.00	25.00
1	FRONT BUMPER WASHER COVER	NOT NECESSARY	57.00	-
1	FRONT BUMPER LOER GARNISH LH	NOT NECESSARY	82.00	-
1	SET FRONT BUMPER CLIPS	NECESSARY	80.00	30.00
1	FRONT BUMPER EMBLEM 'LOGO'	NECESSARY	80.00	80.00
1	BONNET	TO REPAIR SEE LABOUR	1,890.30	-
1	BONNET CATCH LH	DAMAGED	58.00	58.00
1	FRONT FENDER LH	BUCKLED	984.90	780.00
1	BONNET LOCK LH	NOT NECESSARY	160.00	-
1	FRONT GRILL LH	NOT NECESSARY	280.00	-
1	FRONT FENDER INNER SHIELD LH	DEFORMED	327.80	220.00
1	FRONT FENDER INNER SHIELD CLIPS	NECESSARY	60.00	30.00
1	FRONT FENDER SIGNAL LAMP LH	NOT NECESSARY	105.10	-
1	FRONT HEAD LAMP ASSY LH	CRACKED	2,960.30	2,650.00
1	FRONT HEAD LAMP BRACKET LH	CUT	185.30	155.00
1	FRONT FOG LAMP ASSY LH	BROKEN	376.00	311.20
1	FRONT FOG LAMP GARNISH LH	DEFORMED	155.00	125.00
1	FRONT LOWER ARM LH	BENT	626.25	280.00
1	FRONT UPPER ARM LH	BENT	525.30	308.00
1	FRONT KNUCKLE ARM LH	BENT	679.50	679.50
1	FRONT KNUCKLE BEARING LH	NECESSARY	185.00	185.00
1	FRONT WHEEL HUP LH	BENT	513.20	513.20
1	FRONT SHOCK ABSORBER LH	BENT	635.85	522.30
1	FRONT ANTI LOW BAR LH	BENT	481.50	233.60
1	FRONT STEERLING RACK LH	NOT NECESSARY	1,381.00	-
1	REAR BUMPER	NOT NECESSARY	1,563.25	-
1	SET REAR BUMPER CLIPS	NOT NECESSARY	80.00	-
1	REAR DOOR ASSY RH	BUCKLED	1,884.50	1,688.90
1	REAR DOOR WEATHERSTRIP RH	NECESSARY	285.00	168.85

Report Ref No. CS/FCI19008542/Gvd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR DOOR LOCK RH	DAMAGED	271.00	271.00
2	REAR DOOR UPPER/LOWER HINGES RH @\$55.00	NOT NECESSARY	110.00	-
1	REAR DOOR CHECKER RH	NOT NECESSARY	58.00	-
1	REAR DOOR INNER TRIMBOARD RH	NOT NECESSARY	1,720.00	-
1	REAR DOOR OUTER HANDLE RH	NOT NECESSARY	394.00	-
1	REAR DOOR GLASS MOTOR RH	BENT	359.85	359.85
1	REAR DOOR GLASS CHANCELLOR RH	NOT NECESSARY	168.55	-
1	REAR FENDER RH	BUCKLED	1,969.10	1,339.00
1	REAR FENDER INNER SHIELD RH	TORN	170.20	139.00
1	REAR ROCKER PANEL RH	TO REPAIR SEE LABOUR	503.05	-
1	REAR SHOCK ABSORBER RH	NOT NECESSARY	521.00	-
1	REAR BEARING RH	NOT NECESSARY	194.65	-
1	REAR WHEEL HUP	NOT NECESSARY	184.15	-
1	FRONT CASTER ARM LH (ADDITIONAL)	BENT	562.20	298.00
	LESS 10% DISCOUNT		-2,532.82	-1,288.58
			22,795.38	11,597.22
	<u>SPECIAL NETT ITEMS</u>			
1	SET GIOVANNA SPORT RIM 19"(SN)	CUT	4,800.00	1,600.00
2	UNITS TYRE 245/40 ZR19 (\$400.00) (60%)(SN)	DISTORTED-1PC ONLY	1,600.00	240.00
1	FRONT BUMPER SENSOR (SN)	DAMAGED	400.00	200.00
2	SIDESKIRT LH/RH @\$1300.00 (SN)	CUT	2,600.00	1,600.00
2	DECORATIVE STICKERS (SIDE SKIRT) LH/RH @\$60.00 (SN)	NECESSARY	120.00	100.00
1	DECORATIVE STICKER (HEADLAMP ASSY) LH (SN)	NECESSARY	25.00	20.00
			9,545.00	3,760.00
	<u>LABOUR</u>			
	TO REMOVE AND REPLACED DAMAGED PARTS INCLUDING STRAIGHTENING REPOSITIONING REPLACEMENT PARTS. INCLUSIVE OF THE REPAIR OF BONNET AND REAR ROCKER PANEL RH.		1,500.00	1,200.00
	SUPPLY PAINT MATERIAL AND NECESSARY ITEMS. TO RESPRAY REPLACED AND OTHER AFFECTED PANELS.		1,800.00	1,400.00
	TOWING WITH KING DOLLY.		120.00	120.00

Report Ref No. CS/FCI19008542/Gvd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	RECONNECT WIRING AT THE DAMAGE SECTION AND CHECK FOR PROPER FUNCTIONS.		75.00	30.00
	TO REMOVE / REFIT FUEL TANK TO FACILITATE.		300.00	60.00
	TO REMOVE / REPLACE FRONT (LH) AND REAR (RH) UNDERCARRIAGE.		400.00	200.00
	TO PERFORM 4 WHEEL ALIGNMENT.		200.00	60.00
	TO CARRY OUT ANTI RUST TREATMENT ON AFFECTED PANELS.		80.00	80.00
	TO CHECK AND RESET FAULT READING SETTING WITH THE AID OR DIAGNOSTIC KIT.		200.00	150.00
			4,675.00	3,300.00
GRAND TOTAL			37,015.38	18,657.22
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				14,900.00

Report Ref No. CS/FCI19008542/Gvd3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.