

Insurance's Auto

Blk 5038 Ang Mo Kio Ind. Park 2 #01-405

Singapore 569541.

Fax: 64455393. Email: insurancesauto@hotmail.com

Tel: 90089959.

Tan Hock Tiong

Blk 476 B Upper Serangoon View #16-528

Singapore 532476.

Vehicle No : SFW 2818 C
Chassis No : WBAFP32090C865954
Make : BMW 523i
Year : 2001

QTY	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair - SUPPLEMENTARY

1	Front Caster Arm LH	1 BT	298	\$562.20
				\$562.20
			Less 10%	\$56.22
				\$505.98

268.2

Grand Total : \$505.98