



CARZ AUTO SERVICES PTE LTD

UEN/ GST 201409457D

61 WOODLANDS IND PARK E9 (E9 PREMIUM) #04-04 Singapore 757047

Email: alex@carzauto.com.sg

Tel: 65 6493 1924

Fax: 65 6493 1928

Insurance Company:	AIG Asia Pacific Insurance Pte Ltd		
Address:	78 Shenton Way #07-16, Singapore 079120		
Telephone:	6419 3000	Fax:	6835 7416
Email:			
Make/ Model :	HONDA CITY	Date:	10/6/2019
Chassis No :	MRHGM26509P020483	Vehicle No:	SKA 8096 K
Date/Time of Accident :	11/5/2019 8:00		

Materials Cost/ Spare Parts Cost

TO BE COMPLETED BY SERVICE ADVISOR

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$	PARTS DISCOUNT	FINAL PRICE \$
1	BOOTLID <i>BUC /</i>	1	\$ 450.80	20%	\$ 360.64
2	BOOTLID TOP LOCK <i>Jam /</i>	1	\$ 58.80	20%	\$ 47.04
3	BOOTLID LOGO <i>nec /</i>	1	\$ 28.30	20%	\$ 22.64
4	BOOTLID EMBLEM CITY <i>nec /</i>	1	\$ 25.20	20%	\$ 20.16
5	BOOTLID STOPPER <i>nec /</i>	2	\$ 21.00	20%	\$ 16.80
6	BOOTLID EMBLEM IVTEC <i>nec /</i>	1	\$ 35.20	20%	\$ 28.16
7	BOOTLID OUTER MOULDING <i>nn X</i>	1	\$ 155.70	20%	\$ 124.56
8	BOOTLID WEATHERSTRIP <i>DEF /</i>	1	\$ 102.10	20%	\$ 81.68
9	REAR BUMPER <i>DEF /</i>	1	\$ 483.70	20%	\$ 386.96
10	REAR BUMPER SIDE RETAINER <i>nec /</i>	2	\$ 59.60	20%	\$ 47.68
11	REAR BUMPER BRACKET <i>nec /</i>	2	\$ 44.20	20%	\$ 35.36
12	REAR TAIL LAMP <i>CRA-LH /</i>	1 2	\$ 411.40	20%	\$ 329.12 165
13	REAR TAIL LAMP PANEL LH <i>Repair x</i>	1	\$ 120.60	20%	\$ 96.48
14	REAR END PANEL <i>BUC /</i>	1	\$ 383.60	20%	\$ 306.88
15	REAR END PANEL TOP GARNISH <i>CRA /</i>	1	\$ 98.60	20%	\$ 78.88
16	REAR FLOOR PANEL TOP BOARD <i>CRA /</i>	1	\$ 151.60	20%	\$ 121.28

SPECIAL ITEMS	PARTS DESCRIPTION	QTY	PRICE \$	FINAL PRICE \$
1	REAR BUMPER CLIP <i>nec /</i>	8	\$ 32.00	\$ 256.00 30
2	REAR TAIL LAMP CLIP <i>nec /</i>	4	\$ 16.00	\$ 64.00 10
3	REAR END PANEL TOP GARNISH CLIP <i>nec /</i>	3	\$ 12.00	\$ 36.00 10
4	REAR REVERSE SENSOR <i>Shorted /</i>	1	\$ 280.00	\$ 280.00 200
Total Cost				\$ 2,444.32

Labour Works/ Panel Beating Related Works	
Job Scope	Quotation
TO RENEW DAMAGED PARTS, REPLACED AND REALIGNED HYDRAULIC, ALIGNED ALL PARTS	\$ 900 1,000.00
Spray Painting	
Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 800 1,000.00
Others Cost (Accident Repair Related Expenses)	
Job Scope	Quotation
TO TUFFCOAT AFFECTED AREA	\$ 50 250.00
TO REMOVE/ REFIX INTERIOR UPHOLSTERY	\$ 40 80.00
TO REMOVE/ REFIX WIRING CHECKS	\$ 30 60.00
TO REMOVE/ REPLACE REVERSE SENSORS	\$ 30 100.00
TO SENT FOR LTA INSPECTION CENTER AND REMOVE AND REFIX SEAL REAR NUMBER PLATE	\$ 100 150.00
	\$ 640.00
Total Others Cost	
GRAND TOTAL	\$ 5,084.32

CARZ AUTO SERVICES PTE LTD

Person Incharge: Ms Jeslyn Chua
 Job Title: Account Assistant
 Mobile: 65 8322 7418
 Email: jeslyn@carzauto.com.sg

LKK Auto Consult will hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Here Ie-LKK
 10/6/19

L/S 6 days.

