



TeamWork Garage Pte Ltd
 53 Ubi Avenue 1 #01-23/24 Spore 408934
 Paya Ubi Industrial Park
 Tel : 6844 2475
 E-mail : claims@teamworkgarage.com
 Register number : 201015366H

REPAIR PERFORMA INVOICE

First Capital Insurance Ltd
 6 Raffled Quay
 Singapore 048580

Vehicle number	SMJ6584K
Make / Model	TOYOTA/VELLFIRE
Chassis number	JTNGF3DH408020778
Accident date	02 April 2019
Reference	1904-14

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	REAR LH SLIDING DOOR	2875.00
1	REAR LH LOCK	621.00
1	REAR LH FENDER	1725.00
1	REAR BUMPER	730.25
2	REAR BUMPER RETIANER	310.50
1	REAR AXLE BEAM	3199.30
1	REAR WHEEL HUB AND BEARING LH	968.30
1	REAR SHOCK ABSORBER LH	143.75
1	REAR LH SILL GARNISH	879.75
		11452.85
	Less 25%	2863.21
	Subtotal	8589.64
	Balance C/F	
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
	Balance B/F	8589.64
1 SET	REAR BUMPER CLIP	30.00
1 BOT	BRAKE FULD	50.00
1	RIM	600.00
	Subtotal	680.00
	Balance C/F	9269.64
S/No	<u>LABOUR AND MISCELLANEOUS CHARGES</u>	
	Balance B/F	9269.64
1	CHECK REAR WIRING AND LIGHTNING SYSTEM	60.00
2	REMOVE AND REFIT REAR REVERSE SENSOR	150.00
3	TRANSFER PARTS ATTACHMENT FROM REAR SLIDING DOOR TO NEW	200.00
4	CHECK REAR WHEEL ALIGNMENT	150.00
5	REMOVE AND REPLACE REAR UNDERCARRIAGE PARTS	200.00
6	PANEL BEATING ON AFFECTED AREAS	1200.00
7	SPRAY PAINTING ON AFFECTED AREAS	1000.00
8	APPLY ANTI RUST ON AFFECTED AREAS	150.00
	Subtotal	3110.00
	Grand total	12379.64