

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933
Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376
Reg. No: 201427944N

TO	: FWD	DATE	: 13-May-19
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SJG2611T	Ashes	
MODEL	: TOYOTA COROLLA ALTIS 1.6		
CHASSIS NO		M205BREH104541680	
<u>ACCIDENT DETAILS</u>		DATE	: 11-May-19
		TIME	: 14:50HRS
THIRD PARTY REQUESTOR / CONTACT		:	JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOTLID <i>Bucleled</i>	1	\$ 830.00	\$ 830.00
2	BOOTLID LOGO <i>Ne</i>	1	\$ 68.60	\$ 68.60
3	BOOTLID LOCK <i>Ne</i>	1	\$ 320.00	\$ 320.00
4	BOOTLID LAMP LH <i>Ne</i>	2	\$ 345.00	\$ 690.00
5	BOOTLID WEATHERSTRIP <i>Ne</i>	1	\$ 175.10	\$ 175.10
6	REAR BUMPER <i>Deled</i>	1	\$ 580.00	\$ 580.00
7	REAR BUMPER SIDE RETAINER <i>Ne</i>	2	\$ 101.00	\$ 202.00
8	REAR BUMPER REFLECTOR LH <i>Ne</i>	1	\$ 88.00	\$ 88.00
9	REAR BUMPER REINFORCEMENT <i>Best</i>	1	\$ 460.00	\$ 460.00
10	REAR AIRVENT LH <i>Deled</i>	1	\$ 98.20	\$ 98.20
11	TAILLAMP LH <i>Ne</i>	1	\$ 480.00	\$ 480.00
12	TAILLAMP PANEL LH <i>Repr</i>	1	\$ 388.20	\$ 388.20
13	TAILLAMP LOWER BRACKET LH <i>Ne</i>	1	\$ 58.00	\$ 58.00
14	REAR END PANEL <i>Repr</i>	1	\$ 820.00	\$ 820.00
15	REAR END PANEL TOP GARNISH <i>Ne</i>	1	\$ 350.00	\$ 350.00

TOTAL PRICE \$ 5,608.10
LESS 25% \$ 1,402.03

2766.8
2075.10

SUB TOTAL PRICE \$ 4,206.08

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>HE M</i>	1	\$ 50.00	\$ 50.00 <i>x</i>
2	REAR BUMPER CLIPS(SET) <i>HE M</i>	1	\$ 20.00	\$ 20.00 <i>-</i>
3	REAR BUMPER LOWER LID <i>Cracked</i>	1	\$ 1,200.00	\$ 1,200.00 <i>700</i>
4	REAR TAILLAMP CLIPS(SET) <i>HE M</i>	1	\$ 20.00	\$ 20.00 <i>-</i>
5	REAR END PANEL SEALANT <i>HE M</i>	1	\$ 80.00	\$ 80.00 <i>x</i>
6	REAR END PANEL TOP GARNISH CLIPS(SET) <i>HE M</i>	1	\$ 20.00	\$ 20.00 <i>x</i>
7	REVERSE SENSOR <i>HE M</i>	1	\$ 220.00	\$ 220.00 <i>x</i>

TOTAL \$ 1,610.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING. INCLUSIVE OF THE REPAIR OF TAILLAMP PANEL AND SPARE TYRE PANEL	\$ 1,200.00	<i>800-</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	<i>900</i>	
3	WIRING	\$ 50.00	<i>30</i>	
4	TUFF COAT	\$ 180.00	<i>x</i>	
5	TO CONDUCT WATER LEAKAGE TEST	\$ 250.00	<i>x</i>	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 120.00	<i>50</i>	
TOTAL		\$3,000.00		

ESTIMATE REPORT

TOTAL PARTS COST : \$ 5,816.08
TOTAL LABOUR COST : \$ 3,000.00
TOTAL REPAIR COST : \$ 8,816.08

APPROVED DETAILS
SURVEYOR :

CONTACT NO

PART BY PART / LUMP SUM
NO OF DAYS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

FAX :

Adrian Ling.
4/s 15/05/19.
05 Days.

total: 4395.10
2/s: 3.5k.

740

1580