



Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

SEAH KIAN SOON
BLK 9 BEDOK SOUTH AVE 2 #12-534
SINGAPORE 460009

Attention : THE OWNER
Contact : 97883317

Estimate : ES006673

Date : 13/05/2019
Vehicle Num. : SFQ2929Y
Make/Model : HONDA CRV 2.0L AT-2008
Chassis/Eng# : JHLRE28308C202324/R20A12702201
Accident Date : 13/05/2019
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	TAIL GATE	bt 1,284.60	
2.	1	CRV EMBLEM	rec 85.00	
3.	2	REAR W/SCREEN MOULDING SIDE	96.00 ule 192.00	
4.	1	REAR W/SCREEN MOULDING LOWER	ne 110.00	
5.	1	TAIL GATE OUTER LOWER GARNISH	my 480.60	
6.	10	TAIL GATE OUTER GARNISH CLIP	11.00 ne 110.00	
7.	1	TAIL GATE OUTER HANDLE	212.00	
8.	1	BOOT WEATHERSTRIP	twi 182.00	
9.	1	REAR END PANEL	7 689.00	
10.	1	REAR END PANEL TOP GARNISH	7 183.40	
11.	1	REAR BUMPER	de 964.00	
12.	1	REAR BUMPER REINFORCEMENT	7 452.00	
13.	6	REAR BUMPER CLIP	8.00 ne 48.00	
14.	1	REAR BUMPER SIDE PAD R/H	LH-RY, RH-de 315.00	
15.	1	REAR BUMPER REFLECTOR R/H	int 50.40	
16.	1	TAIL LAMP R/H	7 462.60	
17.	1	SPARE TIRE PANEL	RY 1,105.40	
18.	1	SPARE TIRE PANEL TOP GARNISH	x 484.00	
19.	1	TAIL GATE INNER LOCK	bt 235.00	
List TotalS\$:				7,645.00
20.00% Discount S\$:			Rear exhaust ? photo	1,529.00
				6,116.00
SPECIAL NETT ITEMS :				
1.	1	REAR W/SCREEN SEALANT	ne 65.00	
2.	1	REVERSE SENSING UNIT (SET OF 4 SENSORS)	200 ne 380.00	
Special Nett Total S\$:				445.00

CONTINUE / ...

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged:

Signature:

Date:



Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

SEAH KIAN SOON
BLK 9 BEDOK SOUTH AVE 2 #12-534
SINGAPORE 460009

Attention : THE OWNER
Contact : 97883317

Estimate : ES006673

Date : 13/05/2019
Vehicle Num. : SFQ2929Y
Make/Model : HONDA CRV 2.0L AT-2008
Chassis/Eng# : JHLRE28308C202324/R20A12702201
Accident Date : 13/05/2019
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR :				
REMOVE & REINSTALL REAR W/SCREEN GLASS	120		180.00	
TRANSFER TAILGATE COMPONENT TO NEW GATE	60		150.00	
CHANGE TAIL LAMP AND CHECK LIGHTING	30		45.00	
RUST PROOFING TREATMENT	40		150.00	
SPRAY PAINT DAMAGED AREA AFFECTED	700		980.00	
TO CUT OFF REAR END PANEL, SPARE TIRE PANEL, KNOCK AND STRAIGHTEN REAR CHASSIS FRAME AND CHANGE ALL NECESSARY PARTS	800		1,100.00	
Labour Total S\$:				2,605.00

Taufik 97495749 /
- WP' 67418434
Lumpsum
Resumy after repair
6 days
taufik@lkhands.com
14/5/19 230pm

SingDollars : Nine Thousand One Hundred Sixty-Six Only

COMPLETEVMS PTE LTD

Total S\$: 9,166.00
=====

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun