

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5525J**AAD1905-078***Not Authorized*
L/Sing &

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration:

SHC 5525J
 VF1ABL15AUC278866
 RENAULT
 LATITUDE
 9.5.19
III
 15/8/2014

	PART	LIST
1	1 BUMPER COVER REAR	\$ <i>R</i> 1,108.46 <i>X</i>
2	1 BUMPER LOWER REAR	\$ <i>Rd/Lwr</i> 768.84 ✓
3	1 BUMPER BRACKET CTR REAR	\$ <i>Sm</i> 113.47
4	1 BUMPER BRACKET SIDE RH REAR	\$ <i>Sm</i> 135.97
5	1 BUMPER RETAINER RH REAR	\$ <i>Sm</i> 44.99
6	1 BUMPER REFLECTOR RH	\$ <i>Sm</i> 43.61
7	1 BUMPER BRACKET SIDE LH REAR	\$ <i>Sm</i> 135.97
8	1 BUMPER RETAINER LH REAR	\$ <i>Sm</i> 44.99
9	1 BUMPER REFLECTOR LH	\$ <i>Sm</i> 43.61
10	1 BUMPER BEAM REAR	\$ <i>R</i> 777.52
11	1 BUMPER BEAM BRACKET LH REAR	\$ <i>R</i> 225.95
12	1 BUMPER BEAM BRACKET RH REAR	\$ <i>R</i> 225.95
13	1 OUTER PANEL REAR (End Panel)	\$ <i>R</i> 1,471.77
14	1 OUTER PANEL REAR (End Panel)TRIM	\$ <i>Sm</i> 404.56
15	1 TAILLAMP RH	\$ <i>Sm</i> 552.55
16	1 TAILLAMP PANEL RH	\$ <i>R</i> 986.70
17	1 TAILLAMP LH	\$ <i>Sm</i> 552.55
18	1 TAILLAMP PANEL LH	\$ <i>R</i> 986.70
19	1 BOOT REAR	\$ <i>R</i> 2,872.68
20	1 BOOT FINISHER	\$ <i>Sm</i> 470.06
21	1 BOOT WHEATERSTRIP	\$ <i>Sm</i> 323.05
22	1 BOOT REFLECTOR LAMP LH	\$ <i>Sm</i> 493.35
23	1 BOOT REFLECTOR LAMP RH	\$ <i>Sm</i> 493.35
24	1 BOOT BADGE 'RENAULT'	\$ <i>vn</i> 225.36
25	1 BOOT BADGE	\$ <i>vn</i> 225.36
26	1 BOOT STRUT LH	\$ <i>Sm</i> 276.08
27	1 BOOT STRUT RH	\$ <i>Sm</i> 276.08
28	1 BOOT HINGE LH	\$ <i>R</i> 367.84
29	1 BOOT HINGE RH	\$ <i>R</i> 367.84

Trans-cab Auto Services Pte Ltd

AAD1905-078

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5525J

30	1	BOOT INNER TRIM	\$	Sh	586.45	X
31	1	BOOT SWITCH	\$	Sh	168.13	X
32	1	BOOT LOCK	\$	R	202.67	X
33	1	BOOT LOCK CATCH	\$	R	74.40	X
TOTAL			\$		16,046.87	
10%			\$		1,604.69	
			\$		14,442.19	

Special Nett

1	1SET	PARKING AID	\$	Sh	700.00	}
2	1SET	REAR BUMPER CLIP	\$	nn	66.00	
3	1SET	BUMPER BRACKET CTR CLIP	\$	nn	33.00	
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	nn	10.00	
5	1SET	BUMPER RETAINER RH CLIP RR	\$	nn	20.00	
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	nn	10.00	
7	1SET	BUMPER RETAINER CLIP LH RR	\$	nn	20.00	
8	1SET	BUMPER LOWER REAR RIVET	\$	nn	22.00	
9	1SET	BUMPER LOWER REAR CLIP	\$	nn	66.00	}
10	1	BOOT STICKER "Trans-cab"	\$	nn	30.00	
11	1	BOOT STICKER "6555-3333"	\$	nn	30.00	
12	1	EXHAUST MOUNTING REAR	\$	nn	17.82	
13	2	REAR WINDSCREEN SEALANT	\$	nn	80.00	
14	1	WINDSCREEN MOULDING	\$	nn	100.00	
15	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	
16	1	BOOT INNER TRIM CLIP	\$	nn	45.00	
17	1SET	BOOT FINISHER CLIP	\$	nn	24.20	
18	1	TAILLAMP CLIP LH	\$	nn	5.00	
19	1	TAILLAMP CLIP RH	\$	nn	5.00	
TOTAL			\$		1,384.02	

TOTAL PARTS \$ 15,826.21**LABOUR**

To Check Electrical Lighting Concerned.	\$	nn	170.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn	170.00	X
To Rust-Proofing Of The Affected Areas.	\$	nn	170.00	X

Trans-cab Auto Services Pte Ltd

AAD1905-078

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5525J

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	<i>2201</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>na</i> 380.00	<i>X</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>na</i> 170.00	<i>X</i>
To reinstall rear bumper parking sensor.	\$	<i>na</i> 170.00	<i>X</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	<i>* 601</i>
To repair and realign rear exhaust pipe.	\$	<i>na</i> 170.00	<i>X</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>na</i> 170.00	<i>X</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>na</i> 170.00	<i>X</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>na</i> 170.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>na</i> 220.00	<i>X</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00	<i>X</i>
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00	<i>X</i>

TOTAL \$ 8,890.00

Over All Total \$ 24,716.21

LUMP SUM (REPAIR DAY) 10-DAYS
1 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed.
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: