

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Eng Huey Ni

Date: 17 May 2019

Preliminary Advice

Insured Vehicle No	:	SLT2645D		
TP Vehicle No	:	SHB4573G	Accident Date	: 10/05/2019
Make	:	HYUNDAI I40	Assignment Date	: 14/05/2019
Date of Inspection	:	14/05/2019	Est. Duration of Repair	: 2 days
Inspection At	:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:	S\$ 1,320.00
Revised Amount	:	S\$ 940.00
Check Items (Estimated)	:	S\$ 0.00
Total	:	S\$ 940.00
Lump Sum Repair	:	S\$ 750.00

Total Loss Consideration

New for Old Value	:	S\$
Pre-Accident Value	:	S\$
COE / PARF Rebate	:	S\$
Salvage Value	:	S\$
Margin for Repair	:	S\$

Remarks

- () The vehicle is economical/not economical for repair.
(X) The above survey was conducted on a 'without prejudice' basis.