

T K MOTOR WORKSHOP

1 KAKI BUKIT AVE 6 #02-56
SINGAPORE 417883
TEL: 96273323 FAX: 68442641
CO. REG NO :53049097L

Third Party AXA
Lump Sum 8 day.

TK MOTOR WORKSHOP
BLK 510B YISHUN ST 51 #12-599
SINGAPORE 762510

TPAXA
Xiao Tony

DATE: 20/05/2019

By Hand: 31/7/19.

DEAR SIR

JmYSRCS3A

ACCIDENT DATE:10/05/2019

ESTIMATE COST OF REPAIRS BILL TO MITSUBISHI LANCER CAR NO:SMD6770X

1	PC REAR BOOTLID RUBBER	at	\$S	121.00	121.00	NETT ✓
1	PC REAR BOOTLID KEY LOCK	then		198.00	198.00	NETT ✓
1	PC REAR BOOTLID	Dented		525.00	525.00	NETT ✓
2	PC REAR BOOTLID HINGE	then		184.00	184.00	NETT ✓
1	PC REAR BOOTLID LOCK	Damaged		78.00	78.00	NETT ✓
4	PC REAR BOOTLID EMBLEM	then		192.00	192.00	NETT ✓
2	PC REAR TAILLAMP	at		848.00	848.00	NETT 644
2	PC REAR TAILLAMP INNER PANEL	Regis		156.00	156.00	NETT ✓
4	PC REAR TAILLAMP CLIP	then		24.00	24.00	NETT ✓
1	PC REAR FENDER INNER TRIMBOARD R/H	Not Me		212.00	212.00	NETT ✓
1	PC REAR END PANEL	Dented		368.00	368.00	NETT ✓
1	PC REAR END PANEL GARNISH	Deformed		121.00	121.00	NETT ✓
1	PC REAR SPARE WHEEL GARNISH	then		151.00	151.00	NETT ✓
1	PC REAR BUMPER	Deformed		696.00	696.00	NETT ✓
8	PC REAR BUMPER CLIP	then		28.00	28.00	NETT ✓
1	PC REAR BUMPER REINFORCEMENT	But		181.00	181.00	NETT ✓
2	PC REAR BUMPER SIDE RETAINER	then	4583	96.00	96.00	NETT ✓
2	PC REAR BUMPER REVERSE SENSOR	Damaged		200.00	200.00	S/NETT ✓
2	PC REAR BUMPER BRACKET	then	4124.70	72.00	72.00	NETT ✓
1	PC REAR NO. PLATE GARNISH	cracked		298.00	298.00	S/NETT ✓
2	PC NO.PLATE LAMP	then	SN:200.	96.00	96.00	NETT ✓
4	PC REAR BOOTLID SPOILER CLIP	then		20.00	20.00	NETT ✓
1	PC REAR BOOTLID SPOILER	cracked		698.00	698.00	NETT ✓
1	PC REAR BOOTLID SPOILER THIRD BRAKE LIGHT ASSY	cracked		312.00	312.00	NETT ✓
1	PC REAR BUMPER LOWER SPOILER	Regis		698.00	698.00	NETT ✓
6	PC REAR BUMPER LOWER SPOILER CLIP	then		30.00	30.00	NETT ✓

TO CHECK WRING.	50.00	50.00	30
TO SPRAY PAINTING.	1,200.00	1,200.00	100
TO TOP-UP AIR-CON GAS.	100.00	100.00	X
TO REMOVE & REFIX REAR INTERIOR UPHOLSTERY & CUSHION.	80.00	80.00	60
TO LABOUR CHARGE FOR PANEL BEATING, WELDING, REMOVING ALL DAMAGED PARTS & REPLACING OF THE NEW PARTS ETC.	900.00	900.00	800
TO APPLY UNDERCOATING ON THE REPAIRED & REPLACED PANEL FOR RUST PROTECTION.	80.00	80.00	60
TO MEASURE, DRILL THE REPLACED BUMPER, POSITION & REINSTALL REAR BUMPER, CONTROL UNIT, CHECK & TEST FOR FUNCTIONING.	80.00	80.00	50 200

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TOTAL \$S

9,093.00

Total: 6324.70

h/c SK

07 Days