

**Indeco**

No. 39 DEFU LANE 12, SINGAPORE 539139

VEHICLES &amp; EQUIPMENT DIVISION

Tel: (65) 382 2736 FAX: (65) 6382 2817

**ACCIDENT REPAIR ESTIMATES**

Our Ref:

Type of Claim : TPVehicle No. : SME926ZMake & Model : BLUE SGYear of Manufacture : 2018Chassis No. : VL4BCEB4RJT003309Engine No. : 922403A18W062345179Policy No. : B 29112616 MCYTime of Accident : 07:30Ins Company : AXA Insurance Pte LtdExcess : Date of Accident : 27/2/2019Suggested Days of Repair : **Repair Estimates**Parts (a) Cost / List Price Items \$ 1,158.00Plus/Less 15% \$ 173.70Total of Cost / List \$ 1,331.70(b) Nett Price Items \$ -Less \$ -Total of Nett Item \$ -(c) Special Nett Items \$ 45.00Total Parts Cost (Appendix A) \$ 1,376.70Labour (Appendix B) \$ 1,450.00Total Repair Cost \$ 2,826.70

The above total will be subjected to 7% G.S.T.

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Name of Surveyor : Guo Qiang. - 8288 0282Company : LKK.Survey conducted on : 14/5/19. at **Remarks By Surveyor**

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 2 day(s)(c) Resurvey : Required / Not Required(d) Excess : \$ (e) Signature of surveyor :  Date: *part by rot.  
before paint photo.*



VEHICLES & EQUIPMENT DIVISION

No . 39 DEFU LANE 12, SINGAPORE 539139

Tel: (65) 382 2736 FAX: (65) 6382 2817

### ESTIMATED REPAIR COST DETAILS

Vehicle No : SME926Z Case Owner : 0

Make & Model : BLUE SG Year Manufacture : \_\_\_\_\_

Chassis No : VL4BCEB4RHT002923 Engine No : 922403A18W062345179

Date & Time : \_\_\_\_\_ Supplier : \_\_\_\_\_

Order By : \_\_\_\_\_ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N
1	REAR BUMPER ASSY / CAA	1	\$ 850.00	\$ 850.00		
2	REAR BUMPER REFLECTOR WITH LAMP LH / CAA	1	\$ 50.00	\$ 50.00		
3	REAR BUMPER REINFORCEMENT ?	1	\$ 85.00	\$ 85.00		
4	REAR BUMPER REINFORCEMENT BRACKET LH ?	1	\$ 20.00	\$ 20.00		
5	REAR BUMPER SPONGE ?	1	\$ 75.00	\$ 75.00		
6	REAR NUMBER PLATE W CASING / CAA	1				\$ 45.00
7	NUMBER PLATE LAMP LH X / NN	1	\$ 58.00	\$ 58.00		
8	REAR BUMPER SCREW / M.C.	10	\$ 2.00	\$ 20.00		
9						
11						
12						
13						
14						
15						
16						
17						
18						
19						
20						
21						
22						
23						
24						
25						
26						
27						
28						
29						
30						

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

**TOTAL** \$ 1,140.00 \$ 1,158.00 \$ - \$ 45.00



Tel: (65) 382 2736 FAX: (65) 6382 2817

Vehicle No. :	<u>SME926Z</u>
Make & Model :	BLUE SG

Case Owner	:	<u>0</u>
Year of Manufacture	:	<b>2018</b>

[illegible]

*Note: The above estimate of repair is based on visual assessment of the external affected areas. Any*