



Tel: (65) 382 2736 FAX: (65) 6382 2817

Our Ref:

Vehicle No. : **SME926Z**

Make & Model : BLUE SG

Year of Manufacture : 2018

Chassis No. VL4BCEB4RJT003309

Engine No. : 922403A18W062345179

Policy No. : B 29112616 MCY

Time of Accident : 07:30

Ins Company : AXA Insurance Pte Ltd

Excess :

Date of Accident : 27/2/2019

Suggested Days of Repair :

Parts	(a) Cost / List Price Items	\$	1,158.00
	Plus/Less 15%	\$	173.70
	Total of Cost / List	\$	1,331.70
	(b) Nett Price Items	\$	-
	Less	\$	-
	Total of Nett Item	\$	-
	(c) Special Nett Items	\$	45.00
Total Parts Cost (Appendix A)		\$	1,376.70
Labour (Appendix B)		\$	1,450.00
Total Repair Cost		\$	2,826.70

The above total will be subjected to 7% G.S.T.

Name of Surveyor :

Company :

Survey conducted on _____ : _____ at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : day(s)

(c) Resurvey : Required / Not Required

(d) Excess :\$_____

(e) Signature of surveyor : Date:



VEHICLES & EQUIPMENT DIVISION

No . 39 DEFU LANE 12, SINGAPORE 539139

Tel: (65) 382 2736 FAX: (65) 6382 2817

ESTIMATED REPAIR COST DETAILS

Vehicle No : SME926Z Case Owner : 0

Make & Model : BLUE SG Year Manufacture : _____

Chassis No : VL4BCEB4RHT002923 Engine No : 922403A18W062345179

Date & Time : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N
1	REAR BUMPER ASSY	1	\$ 850.00	\$ 850.00		
2	REAR BUMPER REFLECTOR WITH LAMP LH	1	\$ 50.00	\$ 50.00		
3	REAR BUMPER REINFORCEMENT	1	\$ 85.00	\$ 85.00		
4	REAR BUMPER REINFORCEMENT BRACKET LH	1	\$ 20.00	\$ 20.00		
5	REAR BUMPER SPONGE	1	\$ 75.00	\$ 75.00		
6	REAR NUMBER PLATE W CASING	1				\$ 45.00
7	NUMBER PLATE LAMP LH	1	\$ 58.00	\$ 58.00		
8	REAR BUMPER SCREW	10	\$ 2.00	\$ 20.00		
9						
11						
12						
13						
14						
15						
16						
17						
18						
19						
20						
21						
22						
23						
24						
25						
26						
27						
28						
29						
30						

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

TOTAL

\$ 1,140.00 \$ 1,158.00 \$ - \$ 45.00



Tel: (65) 382 2736 FAX: (65) 6382 2817

Vehicle No. : SME926Z
Make & Model : BLUE SG

Case Owner	:	<u>0</u>
Year of Manufacture	:	2018

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any