

chirler

Survey

Jiale

23.05@2pm

www Dealer

Performance Motors Limited

Sole Dealer for Singapore
Co Reg No: 197401155W GST Reg No M2-0020081-X
Toll-Free Number (1800-2200269)

111, Alexandra Road
Singapore 119944
Fax 64767772

280, Tampong Arany Road
East Coast Centre
Singapore 438101
Fax 63445772

111, Alexandra Road
Singapore 119944
Fax 64766621 (ASTAR/Sales)
64766624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

13 MAY 2019

ESTIMATE

Estimate No. : b1 51175	Page No. : 1 of 4
Date Estimated : 13/05/2019	
Prepared By : Inthiran A/L Thurasamy	

- ESTIMATE REPAIR FOR - Leong Toh Leng David 61 Grange Rd #22-01 Singapore 249570	- ACCOUNT - 121 AIG Asia Pacific Insurance Pte. Ltd. 78 Shenton Way #08-16 Chartis Building Singapore 079120
--	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJA88Z	JY31727	11/12/2002	325CiA-C	0

DESCRIPTION	VALUE
To replace front left fender and repair left door.	1275 1700 2550.00
Painting front left fender and left door.	1593 1770.00
To check electrical wiring systems for proper function.	150 177.00
To carry out body cavity preservation. (Per panel).	100 118.00
Sundries.	? 80.00
Total Labour 1:	4,695.00

DESCRIPTION	QTY	PRIC	VALUE
FRT LH FENDER b1/	1	629.60	629.60
Total Parts :			629.60

LKK Auto Corp. Ltd. hereby notify the Repairer of the following: • To rectify defects after spray painting. • To display damaged vehicle during survey. • Parts prices are subject to confirmation.	Claims OD / ☒ / Uninsured losses / Direct Settlement	
	Regn No: 23/05/19 @ 1430 Date/Time Surveyor's Name: <i>P. Rave</i> Signature: <i>[Signature]</i>	Claim No.: Excess \$: Sign: Approved: <i>[Signature]</i>
• This part is not to be replaced if repaired. • No defect will be allowed. • Sign immediately if not in agreement and is subject to hold in view from Insurance Company.	Labour 1: 4,695.00 Parts: 629.60 Labour 2: 0.00 Excess: 0.00 Total: 5,324.60	
	Grand Total: 5,697.32	

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 167421559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 51175
Date Estimated : 13/05/2019
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Leong Toh Leng David
61 Grange Rd
#22-01

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 249570

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJA88Z	JY31727	11/12/2002	325CiA-C	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace front LH fender and attachments include making good the front LH door and knocking out dents caused by the accident	1275.00		1,275.00 ✓
To spray paint front LH fender and front LH door	1593.00		1,593.00 ✓
To check electrical wiring systems and lightings at the LH section for proper function	150.00		150.00 ✓
To carry out body cavity preservation (Per panel)	100.00		100.00 ✓
Sundries	80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
FRT LH FENDER	632.40	1.00		632.40 ✓
# RIVET	0.45	3.00		1.35 ✓

SUPPLEMENTARY ITEMS

Total Labour :	3,198.00
Total Parts :	633.75
Total Labour & Parts :	3,831.75
Deduction for Excess :	0.00
Total Repair Costs less Excess:	3,831.75
GST @7%:	268.22
Grand Total :	4,099.97

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 181421559W, GST Reg. No. M2-0020281-X



SUPPLEMENTARY

Estimate No. : b1 51175
Date Estimated : 13/05/2019
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Leong Toh Leng David
61 Grange Rd
#22-01

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 249570

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJA88Z	JY31727	11/12/2002	325CiA-C	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

# RIVET	0.45	3.00		1.35 <i>see</i>
---------	------	------	--	-----------------

Total Labour :	0.00
Total Parts :	1.35
Total Labour & Parts :	1.35