

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKD 9262 A - FRONT

S/N	Nature of Jobs	Estimated Charges
11	To remove and transfer both front door's multi-lock system and power window devices. Inspect for damages.	s/n \$ 560.00 280.
12	To dismantle and renew front bumper, bonnet, both front fenders, both headlights and both front doors. Cut out and renew lhs fender support and closing element. To repair lhs upper A-pillar. Align both front chassis frames to specification of origin. Renew front lock carrier and align to position. Re-organise front crash management components. Reinstall all parts removed.	\$ 12,250.00 5000.
13	To respray front bumper, both front fenders, bonnet, both A-pillar, engine compartment, hinges, lhs front fender top support and front doors. To carry out joint sealant work and stone chip treatment.	\$ 8,700.00 4150. 7 x 550 = 3850 Hinge x 2 = 150 x 2 = 300
14	To renew lhs front rim, rhs front rim and rhs rear rim. To carry out wheel alignment.	s/n \$ 360.00 ✓
TOTAL FRONT LABOUR CHARGES		: \$ <u>36,890.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKD 9262 A - REAR

S/N	Nature of Jobs	Estimated Charges	
1	To remove and reinstall rear parking aid. Check function.	s/n \$	280.00 ✓
2	To renew rear windscreen and rhs 1/4 glass to facillitate fender renewal.	s/n \$	600.00 ✓
3	To remove and transfer rhs rear door's multi-lock system and power window devices. Inspect for damages.	s/n \$	280.00 ✓
4	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	s/n \$	1,400.00 ✓
TOTAL LABOUR CHARGES		:	\$ 2,560.00 ✓

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKD 9262 A - REAR

S/N	Nature of Jobs	Estimated Charges
5	To remove and reinstall rear seat, back rest and hat tray.	s/n \$ 780.00 ✓
6	To dismantle rear bumper, rear lid and rhs rear door. Cut out and weld rhs rear fender. To renew rear bumper and rhs rear door. Re-organise rear crash management components. Reinstall all parts removed.	\$ 6,300.00 3520.
7	To respray rear bumper, rhs rear fender, rhs rear door, rhs sill panel, door entrances, roof channel, drain panel and end panelling. To carry out stone chip treatment and joint sealer works.	\$ 5,700.00 2750 5x550 = 2750
8	To carry out diagnostic check.	s/n \$ 384.00 ✓
REAR - TOTAL LABOUR CHARGES		: <u>\$ 15,724.00</u> ✓

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKD 9262 A - FRONT

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted</i>	\$ 1,830.00	✓
2	FRONT BUMPER FIXING PARTS <i>Distorted</i>	\$ 170.00	✓
3	FRONT BUMPER GUIDE SECTION - LH / RH <i>LH 2nd</i>	\$ 70.00	35
4	FRONT BUMPER GRILLE - CENTER <i>Distorted</i>	\$ 146.00	✓
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>Distorted</i>	\$ 488.00	✓
6	FRONT BUMPER CLOSING ELEMENT - LH / RH	\$ 540.00	✓
7	FRONT BUMPER COVER TRIM - LH / RH <i>Distorted</i>	\$ 296.00	✓
8	FRONT BUMPER ADAPTER - LH / RH <i>Distorted</i>	\$ 68.00	✓
9	RADIATOR GRILLE <i>smashed</i>	\$ 1,301.00	✓
10	RADIATOR GRILLE CLOSING ELEMENT <i>smashed</i>	\$ 174.00	✓
11	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>distorted</i>	\$ 342.00	171
12	FRONT BUMPER REINFORCEMENT <i>Best</i>	\$ 660.00	✓
13	FOAM FILLER PIECE <i>smashed</i>	\$ 172.00	✓
14	FRONT BUMPER REINFORCEMENT COVER <i>Distorted</i>	\$ 111.00	✓
15	A/C STICKER <i>Green</i>	\$ 7.00	✓
16	CAUTION STICKER	\$ 13.00	✓
17	HORN - HIGH TONE ?	\$ 182.00	?
18	FRONT FENDER- LH / RH <i>Distorted</i>	\$ 1,556.00	✓
19	FRONT FENDER RIVER <i>on</i>	\$ 30.00	✓
20	FRONT FENDER ATTACHMENT PARTS ?	2 \$ 130.00	?
SUB FRONT TOTAL SPARE PARTS		\$ 8,286.00	✓

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKD 9262 A - FRONT

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	FRONT FENDER REAR BRACKET- LH / RH ?	\$ 50.00	✓
22	FRONT FENDER CENTER BRACKET - LH / RH <i>Best</i>	\$ 70.00	✓
23	FRONT FENDER BRACE- LH / RH <i>Distorted</i>	\$ 176.00	✓
24	FRONT FENDER CLOSING ELEMENT - LH <i>used</i>	\$ 30.00	✓
25	FRONT FENDER INSULATION - LH ?	\$ 38.00	?
26	FRONT WHEEL HOUSING LINER SEAL - LH ?	\$ 31.00	?
27	FRONT WHEEL HOUSING LINER- LH / RH <i>LH 2nd</i>	\$ 316.00 158	
28	FRONT WHEEL HOUSING LINER ATTACHMENT ? 2	\$ 161.00	?
29	BONNET <i>Distorted</i>	\$ 2,898.00	✓
30	BONNET ATTACHMENT PARTS <i>new</i>	\$ 149.00	✓
31	BONNET HINGE- LH / RH <i>Best</i>	\$ 112.00	✓
32	BONNET GAS FILLED STRUT ?	\$ 109.00	?
33	BONNET CATCH - TOP <i>Dist</i>	\$ 81.00	✓
34	BONNET STRIKER - LH / RH	\$ 200.00	✓
35	BONNET EDGE PROTECTION <i>Distorted</i>	\$ 25.00	✓
36	FRONT FENDER REAR TOP COVER - LH / RH <i>new</i>	\$ 74.00	✓
37	BONNET CATCH - BOTTOM <i>Set</i>	\$ 58.00	✓
38	PLENUM CHAMBER RUBBER <i>Not new</i>	\$ 53.00	✗
39	BONNET LOCK WITH SWITCH <i>Dist</i> 2	\$ 367.00	✓
40	BONNET LOCK WITH SWITCH COVER <i>Distorted</i> 2	\$ 7.00	✓
SUB FRONT TOTAL SPARE PARTS		\$ 5,005.00	✓

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKD 9262 A - FRONT

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
41	BONNET BOWDEN CABLE - CENTER ?	\$ 53.00	?
42	BONNET LOCK CABLE ?	\$ 67.00	?
43	BONNET LOCK CABLE COVER ?	\$ 9.00	?
44	BONNET HANDLE PULL BRACKET ?	\$ 35.00	✓
45	BONNET ACTUATING LEVER ?	\$ 45.00	✓
46	PLENUM CHAMBER ADAPTER - LH <i>del</i>	\$ 12.00	✓
47	BONNET SOUND ABSORBER <i>crushed</i>	\$ 201.00	✓
48	PLENUM CHAMBER <i>del</i>	\$ 164.00	✓
49	PLENUM CHAMBER COVER <i>new</i>	\$ 15.00	✓
50	FRONT FENDER SIDE MEMBER - LH UPPER <i>crushed</i>	\$ 384.00	✓
51	FRONT FENDER BRACKET - LH <i>del</i>	\$ 59.00	✓
52	HEADLIGHT - LH / RH <i>LH smashed</i>	\$ 10,058.00	5029
53	HEADLIGHT HEAT SINK - LH ?	\$ 666.00	?
54	HEADLIGHT POWER MODULE <i>del</i>	\$ 693.00	?
55	HEADLIGHT CONTROL UNIT ?	\$ 508.00	?
56	HEADLIGHT VENTILATION HOSE ?	\$ 36.00	?
57	HEADLIGHT LIFT CYLINDER - LH / RH <i>LH smashed</i>	\$ 256.00	128
58	HEADLIGHT LIFT CYLINDER HOSE ?	\$ 61.00	?
59	HEADLIGHT LIFT CYLLINDER HOSE JOINT ?	2 \$ 7.00	?
60	WATER RESERVIOR PUMP <i>del</i>	2 \$ 265.00	✓
SUB FRONT TOTAL SPARE PARTS		\$ 13,594.00	✓

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKD 9262 A - FRONT

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
61	WATER RESERVOIR <i>cracked</i>	\$ 186.00	✓
62	WATER RESERVOIR STRAINER ?	\$ 19.00	?
63	WATER RESERVOIR TANK CAP ?	\$ 19.00	?
64	WATER RESERVIOR CORRUGATED PIPE ?	\$ 75.00	?
65	LOCK CARRIER <i>Distorted</i>	\$ 663.00	✓
66	A/C CONDENSER <i>Distorted</i>	\$ 503.00	✓
67	A/C REFRIGERANT LINE ?	2 \$ 1,062.00	?
68	RADIATOR ?	\$ 878.00	?
69	ADDITIONAL RADIATOR ?	\$ 837.00	?
70	COOLANT <i>re</i>	\$ 84.00	✓
71	RADIATOR FAN ?	\$ 1,483.00	?
72	LOCK CARRIER AIR GUIDE - LH / RH <i>LH Distorted</i>	\$ 44.00	22
73	LOCK CARRIER SEAL <i>re</i>	\$ 8.00	✓
74	LOCK CARRIER AIR GUIDE - UPPER CENTRE <i>Distorted</i>	\$ 11.00	✓
75	CHARCOAL CANISTER ?	\$ 294.00	?
76	FRONT AIR DUCT - CENTER <i>Distorted</i>	\$ 53.00	✓
77	FRONT AIR DUCT WATER DRAIN HOSE ?	\$ 31.00	?
78	FRONT AIR DUCT AIR HOSE ?	\$ 62.00	?
79	INTERCOOLER SEAL ?	\$ 13.00	?
80	TURBO AIR SUCTION PIPE ?	\$ 129.00	?
SUB FRONT TOTAL SPARE PARTS		\$ 6,454.00	✓

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKD 9262 A - FRONT

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
81	AIR FILTER <i>could</i>	\$ 252.00	✓
82	INTKE MANIFOLD INTERCOOLER ?	\$ 692.00	?
83	INTKE MANIFOLD INTERCOOLER SEAL ?	\$ 26.00	?
84	THROTTLE VALVE CONTROL ELEMENT ?	\$ 973.00	?
85	THROTTLE VALVE CONTROL ELEMENT SEAL ?	\$ 16.00	?
86	INTKE MANIFOLD ?	\$ 588.00	?
87	INTKE MANIFOLD SEAL ?	\$ 13.00	?
88	INTKE MANIFOLD HOSE ?	\$ 129.00	?
89	FUSE BOX HOUSING COVER <i>corrected ?</i>	\$ 45.00	?
90	FUSE BOX TOP COVER <i>could</i>	\$ 78.00	✓
91	FUSE CLOSING ELEMENT ?	\$ 22.00	?
92	FUSE HOLDER ?	\$ 21.00	?
93	FUSE BOX RELAY PLATE ?	\$ 13.00	?
94	MULTI - FUSE ?	\$ 41.00	?
95	UNDER COVER NOISE INSULATION ?	\$ 239.00	?
96	FRONT WINDSCREEN <i>could</i>	\$ 988.00	✓
97	FRONT WINDSCREEN FOIL <i>in</i>	\$ 128.00	✓
98	FRONT WINDSCREEN MIRROR SPRING CLIP <i>see</i>	\$ 20.00	✓
99	FRONT WINDSCREEN DEFLECTOR - LH / RH <i>see</i>	\$ 170.00	✓
100	FRONT DOOR - LH <i>Dented.</i>	\$ 2,279.00	✓
SUB FRONT TOTAL SPARE PARTS		\$ 6,733.00	✓

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKD 9262 A - FRONT

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
101	FRONT DOOR SEAL - LH <i>hu</i>	\$ 146.00	✓
102	BONDING AGENT ?	\$ 90.00	?
103	CLEANING SOLUTION ?	\$ 130.00	?
104	APPLICATOR ?	\$ 14.00	?
105	FRONT DOOR - RH <i>Payis</i>	\$ 2,279.00	+
106	FRONT DOOR SEAL - RH <i>hu</i>	\$ 146.00	+
107	FRONT DOOR ATTACHMENT PARTS <i>hu</i>	\$ 218.00	+
108	FRONT DOOR CATCH - LH <i>hu</i>	2 \$ 191.00	+
109	FRONT DOOR CORNER TRIM - LH / RH <i>hu</i>	\$ 82.00	+
110	FRONT DOOR WINDOW TRIM STRIP- LH / RH <i>hu</i>	\$ 470.00	+
111	FRONT DOOR WINDOW SLOT SEAL CHROME- LH / RH <i>hu</i>	\$ 564.00	282
112	DATA PLATE FOR TYRE PRESSURE <i>hu</i>	\$ 26.00	+
113	GEARBOX MECHATRONIC ?	\$ 3,690.00	?
114	HYDRAULIC OIL <i>hu</i> ?	\$ 49.00	+
115	FRONT NO. PLATE <i>hu</i>	S/N \$ 60.00	✓
SUB FRONT TOTAL SPARE PARTS		\$ 48,227.00	✓
TOTAL FRONT LABOUR CHARGES		\$ 36,890.00	✓
GRAND TOTAL (FRONT)		\$ 85,117.00	✓

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKD 9262 A - REAR

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>replaced</i>	\$ 1,793.00	✓
2	REAR BUMPER STICKY PAD	\$ 21.00	✓
3	REAR BUMPER FIXING PARTS <i>3 new</i>	\$ 175.00	✓
4	REAR BUMPER ADAPTER	\$ 34.00	✓
5	REAR BUMPER TOP GUIDE SECTION - LH / RH <i>new</i>	\$ 30.00	✓
6	REAR BUMPER TOP GUIDE SECTION PIN <i>new</i>	2 \$ 53.00	✓
7	REAR BUMPER SPOILER <i>new</i>	\$ 216.00	✓
8	REAR BUMPER REFLECTOR - RH <i>new</i>	\$ 38.00	✓
9	REAR TAIL LIGHT OUTER - RH <i>cracked</i>	\$ 800.00	✓
10	REAR TAIL LIGHT OUTER TRIM- RH <i>new</i>	\$ 27.00	✓
11	GROMMET <i>new</i>	\$ 3.00	✓
12	REAR BUMPER GUIDE SECTION - RH <i>new</i>	\$ 60.00	✓
13	REAR FENDER - RH <i>Distorted</i>	\$ 2,110.00	✓
14	REAR WINDSCREEN <i>new</i>	\$ 742.00	✓
15	PRIMER <i>new</i>	2 \$ 49.00	✓
16	REAR 1/4 GLASS - RH <i>new</i>	\$ 520.00	✓
17	REAR DOOR - RH <i>Dented</i>	\$ 2,279.00	✓
18	REAR DOOR SEAL - RH <i>new</i>	\$ 146.00	✓
19	BONDING AGENT <i>?</i>	\$ 45.00	?
20	CLEANING SOLUTION <i>?</i>	\$ 65.00	?
SUB REAR TOTAL SPARE PARTS		\$ 9,206.00	✓

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKD 9262 A - REAR

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	APPLICATOR ?	\$ 7.00	?
22	REAR DOOR CATCH - RH <i>new</i>	\$ 85.00	+
23	REAR DOOR ATTACHMENT PARTS - RH <i>new</i>	\$ 117.00	+
24	REAR WHEEL HOUSING LINER <i>new</i>	\$ 223.00	+
25	REAR WHEEL HOUSING ATTACHMENT PARTS <i>new</i>	\$ 81.00	+
26	REAR SUB FRAME	\$ 940.00	+
27	REAR SUB FRAME BOLTS	\$ 93.00	+
28	REAR SUB FRAME RUBBER BUSHES	\$ 91.00	+
29	REAR TRACK CONTROL ARM - LH	\$ 336.00	+
30	REAR STABILIZER	\$ 372.00	+
31	REAR WHEEL BEARING HOUSING - LH	\$ 532.00	+
32	REAR WHEEL BEARING HOUSING BOLTS	\$ 61.00	+
33	REAR WHEEL BEARING - LH	\$ 442.00	+
34	REAR GUIDE JOINT - LH	\$ 117.00	+
35	REAR COUPLING ROD	\$ 88.00	+
36	REAR ABSORBER - LH	\$ 251.00	+
37	REAR ABSORBER MOUNT - LH	\$ 114.00	+
38	REAR ABSORBER MOUNT BEARING - LH	\$ 50.00	+
39	REAR ABSORBER BOLTS - LH	\$ 43.00	+
40	REAR DRIVE SHAFT - LH	\$ 2,208.00	+
SUB REAR TOTAL SPARE PARTS		\$ 6,251.00	✓

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKD 9262 A - REAR

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
41	REAR DRIVE SHAFT BOLTS	\$ 31.00	X
42	REAR TIE ROD END - LH	\$ 118.00	X
43	STEERING WHEEL AIR BAG	\$ 3,141.00	✓
44	PASSENGER AIR BAG UNIT	\$ 4,238.00	✓
45	HEAD AIR BAG UNIT - LH	\$ 1,708.00	✓
46	HEAD AIR BAG UNIT - RH	\$ 1,708.00	✓
47	KNEE AIR BAG UNIT	\$ 1,708.00	✓
48	AIR BAG CONTROL UNIT	\$ 1,606.00	✓
49	AIR BAG CRASH SENSOR	\$ 1,146.00	✓
50	FRONT SEAT BELT - LH/RH	2 \$ 2,010.00	✓
51	SEAT BELT ADJUSTER	2 \$ 361.00	?
52	MULTIFUNCTION STEERING WHEEL	\$ 2,169.00	?
53	DASHBOARD	\$ 3,887.00	✓
54	DASHBOARD AIR VENT TRIM	\$ 138.00	?
55	DASHBOARD LOUDSPEAKER TRIM	\$ 86.00	?
56	TRAY FOR DRIVER SIDE	\$ 413.00	?
57	HEAD LINER	\$ 1,613.00	✓
58	FRONT GRAB HANDLE - LH/RH	2 \$ 258.00	?
59	REAR GRAB HANDLE - LH/RH	2 \$ 258.00	?
60	A-PILLAR TRIM - LH/RH	2 \$ 294.00	?
SUB REAR TOTAL SPARE PARTS		\$ 26,891.00	✓

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKD 9262 A - REAR

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
61	INTERIOR LIGHT - FRONT ?	\$ 659.00	?
62	MICROPHONE WITH WIRING - FRONT ?	\$ 213.00	?
63	FRONT WINDSCREEN SEALANT	S/N \$ 200.00	✓
64	REAR WINDSCREEN SEALANT	S/N \$ 200.00	✓
65	REAR 1/4 GLASS SEALANT	S/N \$ 100.00	✓
66	ACRYLIC SEALANT	S/N \$ 360.00	✓
67	CRAVITY WAX	S/N \$ 280.00	✓
68	STONE CHIP TREATMENT	S/N \$ 360.00	✓
69	METAL FILLER POWDER	S/N \$ 280.00	✓
70	TYRE RIM - FRONT LH / RH / REAR RH <i>Front cut</i>	PRICE TBC	7.2
71	SUNDRIES ?	\$ 1,500.00	?
TOTAL SPARE PARTS - REAR		\$ 46,500.00	✓
TOTAL LABOUR CHARGES - REAR		\$ 15,724.00	
GRAND TOTAL - REAR		\$ 62,224.00	✓
GRAND TOTAL (FRONT+ REAR)		\$ 147,341.00	✓

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Part prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date

Name

: Adrian Lim

Surveyed Date

: 14/05/19.

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

: Not Authorised , 42 Days .

According to police report,
accident caused by sizeure, & 4 (driver).
Covered under insurance ???

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo

Body Repair Manager

Allan Wu

Claims Consultant

...CLAIM SUBFOLDER...(Pending for Survey Report)

Total Loss

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 May 2019 Edit Reg		14 May 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	GWEE SIONG MENG, ID: S7342062H, Tel: +6597351563		
Vehicle Reg. No.:	SKD9262A	Date of Loss:	15/04/2019 18:00 - :59 [2 Months and 20 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 2693871107SG	Policy/Cover Note No.:	1900009429 (Comprehensive)
		Excess:	
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Sim, Priscilla-LK - 6419 1755] Priscilla-lk.sim@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 27/05/2019]		
Driver/Custodian:	GWEE SIONG MENG (45), NRIC: S7342062H, Tel: +6597351563 Email:		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKD9262A (2693871107SG)**
OD
Apr 15 2019 6:00PM
[GWEE SIONG MENG]
Premium Automobiles Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/05/19 17:05	Adjuster Immediate Advice	Load HTM	☐
2	22/05/19 16:55	Adjuster Immediate Advice	Load HTM	☐
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/05/19 11:20	General View	Load JPG	☒
2	15/05/19 11:20	General View	Load JPG	☒
3	15/05/19 11:20	Chassis Number	Load JPG	☒
4	15/05/19 11:20	General View	Load JPG	☒
5	15/05/19 11:20	General View	Load JPG	☒
6	15/05/19 11:20	General View	Load JPG	☒
7	15/05/19 11:20	General View	Load JPG	☒
8	15/05/19 11:20	General View	Load JPG	☒
9	15/05/19 11:20	General View	Load JPG	☒
10	15/05/19 11:20	General View	Load JPG	☒
11	15/05/19 11:20	General View	Load JPG	☒
12	15/05/19 11:20	General View	Load JPG	☒
13	15/05/19 11:20	General View	Load JPG	☒
14	15/05/19 11:20	General View	Load JPG	☒
15	15/05/19 11:20	General View	Load JPG	☒
16	15/05/19 11:20	General View	Load JPG	☒
17	15/05/19 11:20	General View	Load JPG	☒
18	15/05/19 11:20	General View	Load JPG	☒
19	15/05/19 11:20	General View	Load JPG	☒
20	15/05/19 11:20	General View	Load JPG	☒
21	15/05/19 11:20	General View	Load JPG	☒
22	15/05/19 11:20	General View	Load JPG	☒
23	15/05/19 11:20	General View	Load JPG	☒
24	15/05/19 11:20	General View	Load JPG	☒
25	15/05/19 11:20	General View	Load JPG	☒
26	15/05/19 11:20	General View	Load JPG	☒
27	15/05/19 11:20	General View	Load JPG	☒
28	15/05/19 11:20	General View	Load JPG	☒
29	15/05/19 11:20	General View	Load JPG	☒
30	15/05/19 11:20	General View	Load JPG	☒
31	15/05/19 11:20	General View	Load JPG	☒
32	15/05/19 11:20	General View	Load JPG	☒

Assessment Reports			1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
33	15/05/19 11:20	General View	 Load JPG	☒
34	15/05/19 11:20	General View	 Load JPG	☒
35	15/05/19 11:20	General View	 Load JPG	☒
36	15/05/19 11:20	General View	 Load JPG	☒
37	15/05/19 11:20	General View	 Load JPG	☒
38	15/05/19 11:20	General View	 Load JPG	☒
39	15/05/19 11:20	General View	 Load JPG	☒
40	15/05/19 11:20	General View	 Load JPG	☒
41	15/05/19 11:20	General View	 Load JPG	☒
42	15/05/19 11:20	General View	 Load JPG	☒
43	15/05/19 11:20	General View	 Load JPG	☒
44	15/05/19 11:20	General View	 Load JPG	☒
45	15/05/19 11:20	General View	 Load JPG	☒
46	15/05/19 11:20	General View	 Load JPG	☒
47	15/05/19 11:20	General View	 Load JPG	☒
48	15/05/19 11:20	General View	 Load JPG	☒
49	15/05/19 11:20	General View	 Load JPG	☒
50	15/05/19 11:20	General View	 Load JPG	☒
51	15/05/19 11:20	General View	 Load JPG	☒
52	15/05/19 11:20	General View	 Load JPG	☒
53	15/05/19 11:20	General View	 Load JPG	☒
54	15/05/19 11:20	General View	 Load JPG	☒
55	15/05/19 11:20	General View	 Load JPG	☒
56	15/05/19 11:20	General View	 Load JPG	☒
57	15/05/19 11:20	General View	 Load JPG	☒
58	15/05/19 11:20	General View	 Load JPG	☒
59	15/05/19 11:20	General View	 Load JPG	☒
60	15/05/19 11:20	General View	 Load JPG	☒
61	15/05/19 11:20	General View	 Load JPG	☒
62	15/05/19 11:20	General View	 Load JPG	☒
63	15/05/19 11:20	General View	 Load JPG	☒
64	15/05/19 11:20	General View	 Load JPG	☒
65	15/05/19 11:20	General View	 Load JPG	☒
66	15/05/19 11:20	General View	 Load JPG	☒
67	15/05/19 11:20	General View	 Load JPG	☒
68	15/05/19 11:20	General View	 Load JPG	☒
69	15/05/19 11:20	General View	 Load JPG	☒
70	15/05/19 11:20	General View	 Load JPG	☒
71	15/05/19 11:20	General View	 Load JPG	☒
72	15/05/19 11:20	General View	 Load JPG	☒
73	15/05/19 11:20	General View	 Load JPG	☒
74	15/05/19 11:20	General View	 Load JPG	☒
75	15/05/19 11:20	General View	 Load JPG	☒
76	15/05/19 11:20	General View	 Load JPG	☒
77	15/05/19 11:20	General View	 Load JPG	☒
78	15/05/19 11:20	General View	 Load JPG	☒
79	15/05/19 11:20	General View	 Load JPG	☒
80	15/05/19 11:20	General View	Load JPG	☒

Assessment Reports			1 per page ▼	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
81	15/05/19 11:20	General View	 Load JPG	✓
82	15/05/19 11:20	General View	 Load JPG	✓
83	15/05/19 11:20	General View	 Load JPG	✓
84	15/05/19 11:20	General View	 Load JPG	✓
85	15/05/19 11:20	General View	 Load JPG	✓
86	15/05/19 11:20	General View	 Load JPG	✓
87	15/05/19 11:20	General View	 Load JPG	✓
88	15/05/19 11:20	General View	 Load JPG	✓
89	15/05/19 11:20	General View	 Load JPG	✓
90	15/05/19 11:20	General View	 Load JPG	✓
91	15/05/19 11:20	General View	 Load JPG	✓
92	15/05/19 11:20	General View	 Load JPG	✓
93	15/05/19 11:20	General View	 Load JPG	✓
94	15/05/19 11:20	General View	 Load JPG	✓
95	15/05/19 11:20	General View	 Load JPG	✓
96	15/05/19 11:20	General View	 Load JPG	✓
97	15/05/19 11:20	General View	 Load JPG	✓
98	15/05/19 11:20	General View	 Load JPG	✓
99	15/05/19 11:20	General View	 Load JPG	✓
100	15/05/19 11:20	General View	 Load JPG	✓
101	15/05/19 11:20	General View	 Load JPG	✓
102	15/05/19 11:20	General View	 Load JPG	✓
103	15/05/19 11:20	General View	 Load JPG	✓
104	15/05/19 11:20	General View	 Load JPG	✓
105	15/05/19 11:20	General View	 Load JPG	✓
106	15/05/19 11:20	General View	 Load JPG	✓
107	15/05/19 11:20	General View	 Load JPG	✓
108	15/05/19 11:20	General View	 Load JPG	✓
109	15/05/19 11:20	General View	 Load JPG	✓
110	15/05/19 11:20	General View	 Load JPG	✓
111	15/05/19 11:20	General View	 Load JPG	✓
112	15/05/19 11:20	General View	 Load JPG	✓
113	15/05/19 11:20	General View	 Load JPG	✓
114	15/05/19 11:20	General View	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/05/19 11:19	Singapore Accident Statement	 Load PDF	
2	15/05/19 11:19	Police Report	 Load PDF	
3	15/05/19 11:19	Certificate of Insurance	 Load PDF	
4	15/05/19 11:19	Driver's Driving License	 Load PDF	
5	15/05/19 11:19	NEW CAR ADVERTISEMENT	 Load PDF	
6	15/05/19 17:05	Log card (if available)	 Load PDF	
7	21/05/19 09:20	MEDICAL PROOF	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	17/05/19 15:21	Police Report	 Load JPG	✓
2	17/05/19 15:22	Police Report	 Load JPG	✓
3	17/05/19 15:22	Police Report	 Load JPG	✓

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG19008577/AQD3S2

Date: 29/05/2019

REFERENCE

Insured/Claimant: GWEE SIONG MENG Policy No: 1900009429
Date of Loss: 15/04/2019 Nature of Claim: OD Claim No: 2693871107SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKD9262A**
Make & Model: AUDI A3, 999cc SEDAN TFSI (A) Engine No: CHZC26217
Reg. Date: 26/01/2019 (Man. Year: 2018) Chassis No: WAUZZZ8VXK1013950
Colour: Grey Odometer: 0 km
Engine Capacity: 999 cc
Market Value/New Car Price: S\$120,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/50 R17 Rear Tyre Size: 205/50 R17
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 14/05/2019
Date Inspected: 14/05/2019 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 0.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

New Car Value :	\$136,460.00
Market Value :	\$120,000.00
OMV :	\$ 22,100.00
PARF Rebate (1) :	\$ 17,205.00
Quota Premium Paid :	\$ 26,170.00
COE Rebate (2) :	\$ 20,936.00
Total Rebate (1) + (2) = :	\$ 38,141.00

The total amount incurred will be Market Value \$120,000.00 minus Total Rebate \$38,141.00 = \$81,859.00 before excess.

The total amount incurred will be New Car Value \$136,460 minus Total Rebate \$38,141.00 = \$98,319.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >