

Trans-cab Auto Services Pte Ltd

AAD1905-108

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9859P*4/5 \$9650 / 5/1/14*

Vehicle No.:

SHD 9859P

Chassis No.:

VF1ABL15AUC277374

Vehicle Make:

RENAULT

Vehicle Model:

LATITUDE

Date of Accident :

11.5.19

Third Party Insurer :

TOKIO MARINE

Date Of Registration:

9/5/2014

		PART		LIST
1	1	BUMPER COVER REAR	- <i>Renault</i>	\$ 1,108.46
2	1	BUMPER LOWER REAR	- <i>on</i>	\$ 768.84
3	1	BUMPER BRACKET CTR REAR	- <i>on</i>	\$ 113.47
4	1	BUMPER BRACKET SIDE RH REAR	X <i>on</i>	\$ 135.97
5	1	BUMPER RETAINER RH REAR	X <i>on</i>	\$ 44.99
6	1	BUMPER REFLECTOR RH	X <i>on</i>	\$ 43.61
7	1	BUMPER BRACKET SIDE LH REAR	- <i>on</i>	\$ 135.97
8	1	BUMPER RETAINER LH REAR	- <i>on</i>	\$ 44.99
9	1	BUMPER REFLECTOR LH	- <i>on</i>	\$ 43.61
10	1	BUMPER BEAM REAR	- <i>But</i>	\$ 777.52
11	1	BUMPER BEAM BRACKET LH REAR	- <i>But</i>	\$ 225.95
12	1	BUMPER BEAM BRACKET RH REAR	- <i>But</i>	\$ 225.95
13	1	BOOT REAR	- <i>Renault</i>	\$ 2,872.68
14	1	BOOT FINISHER	X <i>on</i>	\$ 470.06
15	1	BOOT WHEATERSTRIP	X <i>on</i>	\$ 323.05
16	1	BOOT REFLECTOR LAMP LH	X <i>on</i>	\$ 493.35
17	1	BOOT REFLECTOR LAMP RH	X <i>on</i>	\$ 493.35
18	1	BOOT BADGE 'RENAULT'	- <i>on</i>	\$ 225.36
19	1	BOOT BADGE	- <i>on</i>	\$ 225.36
20	1	BOOT STRUT LH	X <i>on</i>	\$ 276.08
21	1	BOOT STRUT RH	X <i>on</i>	\$ 276.08
22	1	BOOT HINGE LH	X <i>on</i>	\$ 367.84
23	1	BOOT HINGE RH	X <i>on</i>	\$ 367.84
24	1	BOOT INNER TRIM	X <i>on</i>	\$ 586.45
25	1	BOOT SWITCH	X <i>on</i>	\$ 168.13
26	1	BOOT LOCK	X <i>But</i>	\$ 202.67
27	1	BOOT LOCK CATCH	X <i>on</i>	\$ 74.40
28	2	LICENCE PLATE LAMP	X <i>on</i>	\$ 50.52
29	2	BOOT RUBBER PLUG	X <i>on</i>	\$ 221.81
30	1	FENDER PANEL INNER TRIM REAR RH	X <i>on</i>	\$ 671.45

Trans-cab Auto Services Pte Ltd

AAD1905-108

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9859P

31	1	FENDER PANEL REAR RH	X	see	\$	3,299.13
32	1	WHEELARCH REAR RH	X	see	\$	543.47
33	1	FENDER PANEL REAR LH	X	see	\$	3,299.13
34	1	FENDER PANEL INNER TRIM REAR LH	X	see	\$	671.45
35	1	WHEELARCH REAR LH	X	see	\$	543.47
36	1	TAILLAMP RH	X	see	\$	552.55
37	1	TAILLAMP PANEL RH	X	see	\$	986.70
38	1	TAILLAMP LH	—	see	\$	552.55
39	1	TAILLAMP PANEL LH	—	see	\$	986.70
40	1	OUTER PANEL REAR (End Panel)	—	see	\$	1,471.77
41	1	OUTER PANEL REAR (End Panel)TRIM	—	see	\$	404.56
42	1	SPARE WHEEL PANEL (Luggage Floor Panel)	X	see	\$	2,189.88
43	1	SPARE WHEEL PANEL TRIM	X	see	\$	612.21
44	1	EXHAUST REAR	←	see	\$	7,489.05
45	1	EXHAUST CAP REAR	X	see	\$	230.49
46	1	FUEL FLAP	X	see	\$	343.57
TOTAL						\$ 36,212.51
10%						\$ 3,621.25
						\$ 32,591.26

Special Nett

1	1SET	PARKING AID	—	see	\$	700.00 600
2	1SET	REAR BUMPER CLIP	—	see	\$	66.00
3	1SET	BUMPER BRACKET CTR CLIP	—	see	\$	33.00
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	X	see	\$	10.00
5	1SET	BUMPER RETAINER RH CLIP RR	X	see	\$	20.00
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	—	see	\$	10.00
7	1SET	BUMPER RETAINER CLIP LH RR	—	see	\$	20.00
8	1SET	BUMPER LOWER REAR RIVET	—	see	\$	22.00
9	1SET	BUMPER LOWER REAR CLIP	—	see	\$	66.00
10	1	EXHAUST MOUNTING REAR	X	see	\$	17.82
11	1SET	BOOT FINISHER CLIP	X	see	\$	24.20
12	1	BOOT STICKER "Trans-cab"	—	see	\$	30.00
13	1	BOOT STICKER "6555-3333"	—	see	\$	30.00
14	1	BOOT INNER TRIM CLIP	X	see	\$	45.00
15	1SET	FENDER WHEELARCH REAR RH CLIP	X	see	\$	35.00
16	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	X	see	\$	385.00
17	1	SPARE TYRE	X	see	\$	330.00

Trans-cab Auto Services Pte Ltd

AAD1905-108

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9859P

18	1	FENDER INNER TRIM CLIP RH	X	22	\$	28.00
19	1	TAILLAMP CLIP RH	X	22	\$	5.00
20	2	REAR WINDSCREEN SEALANT	X	22	\$	80.00
21	1	WINDSCREEN MOULDING	X	22	\$	100.00
22	1	REAR WINDSCREEN INNER SPONGE SEAL	X	22	\$	100.00
23	1	TAILLAMP CLIP LH	-	22	\$	5.00
24	1	FENDER INNER TRIM CLIP LH	X	22	\$	28.00
25	1SET	FENDER WHEELARCH REAR LH CLIP	X	22	\$	35.00
26	1	Rear left tyre	X	500	\$	330.00
27	1	Rear left tyre rim	X	500	\$	380.00
28	1	Rear right tyre	X	500	\$	330.00
29	1	Rear right tyre rim	X	500	\$	380.00
					TOTAL	\$ 3,645.02

TOTAL PARTS \$ 36,236.28

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00 800
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00 800
To reinstall rear bumper parking sensor.	\$	170.00 40
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 50
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00 X 22
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00 50
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00 X 22

Trans-cab Auto Services Pte Ltd

AAD1905-108

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9859P

To check steering geometry and computer wheel alignment	\$	220.00 X 1/2
To Rust-Proofing Of The Affected Areas.	\$	170.00 50
To repair and realign rear exhaust pipe.	\$	170.00 X 1/2
To transfer of tire, rim and on wheel balancing.	\$	170.00 X 1/2
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00 X 1/2
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00 X 1/2
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00 X 1/2
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	380.00 X 1/2
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00 50
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00 X 1/2
To apply paint protection system (PPS) maintain and enhancement	\$	380.00 X 1/2
To Check Electrical Lighting Concerned.	\$	170.00 30
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	380.00 X 1/2

TOTAL \$ 16,580.00

Over All Total \$ 52,816.28

(LUMP SUM) Repair Days 20 DAYS

Kahin 10000
11/14/5/19 1600 hrs
5 Days
L/S
After Repair photo

96719399