

Sumera Khatun

REF: CC3/TMI 19008578/ Klvd 3n2

Estimated Cost: _____
 To Inspected Vehicle No: _____
 at Workshop mile: _____
 Insured: _____
 Policy No: MK000193
 Claims No: M1903397
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sure: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

SHD 9859P 9 May 2019
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Renault Latitude cc 1995
 Colour: M-Red/White A/C: Ins φ / Std / NI / NA
 Sp. Reading: 438276 T/Radio: Ins φ / Std / NI / NA
 Eng/No: _____
 C/No: V FIA B L 15 A Y C 277374
 Gen. Cond: Good / φ / Poor / Burnt
 Steering: In φ / Jammed / Leaked / Burnt or
 Brake: In φ / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD φ / Rim or
 Tyre Size: F: 215 / 60R16
 R: _____
 BS / DUN / EXMOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or harti
 Front: _____ Rear: _____
 R/Bal: 7 mm R/Bal: 7 mm
 L/Bal: 7 mm L/Bal: 2 mm
 D.O.A: 11/5/19 D.O.L: 14/5/19
 Survey held at Transcal
 Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or
Rear a/s.
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SHD 9859P - X
	SEL 312 X - X
29/5/19	Chd 415 \$ 9650 / 50% (Reel 43, 166.28, 82%)
RECEIVED 7 MAY 2019	

Date Time, File Pass to? : Prell. Report
 : Final Report
 Date Time, File Return to?
 29/5- typist
 TP
 US \$ 9650/-

Days Of Repair: 5
 Resurvey No. of Trip: 1
 Add Fee: : Site Insp. (\$)
 : Interview (\$)
 : Test (\$)

Survey Fee:	
Transportation:	250
S + RS:	10
Phone:	
Copy:	
	260

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 May 2019		15 May 2019 13:48 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS				[Created by insurer]					
Insured:	LCRF PTE LTD , Co. Reg. No.: 201624597K								
Main Claimant:	TRANS-CAB SERVICES PTE LTD , Co. Reg. No.: 200303878K								
Vehicle Reg. No.:	SHD9859P	Date of Loss:	11/05/2019 22:00 - :59						
Claim Type:	TP / M1903397	Policy/Cover Note No.:	MK000193 (Third Party Only) Coverage: 25/02/2019 - 24/02/2020						
Vehicle Reg. No. (Insured):	SLL372X	Policy No. (Claimant):							
		Excess:	S\$1,600.00						
Repairer:	Trans-Cab Services Pte Ltd (HQ) 2 Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666								
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Telma Gomez - 65926402]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 27/05/2019]								
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 15 May 2019 11:16 AM
To: motorclaims@tokiomarine.com.sg
Cc: SUR
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - TRANS-CAB AUTO SERVICES PTE LTD, DOA: 11/05/2019 , SHD 9859P (TP Vehicle), SLL 372X (OI Vehicle)
Attachments: TP GIA REPORT.pdf, POLICE REPORT.pdf, ESTIMATE.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHD 9859P at M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63 SINGAPORE 569111 on 14/05/2019

Enclosed herewith a copy of TP's GIA report, Police Report and estimated cost of repair .

Meanwhile, kindly create claim in merimen for our necessary action.

Thank you.

Best Regards,

Shirley Hiew | Case Handler (On Behalf Veron)

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Kalvin Ang (LKKAuto)

From: weichunkong <weichunkong@transcab.com.sg>
Sent: Wednesday, 29 May 2019 8:51 AM
To: 'Candy Kong'
Cc: Calvin Ang (LKKAuto)
Subject: RE: SHD 9859P

Hi all,

SHD9859P Net book value is \$ 45,089.06

Thanks
Best regards

CK



TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Candy Kong [<mailto:candy.kong@transcab.com.sg>]
Sent: Tuesday, 28 May, 2019 9:14 AM
To: 'weichunkong' <weichunkong@transcab.com.sg>
Cc: kalvinang@lkkauto.com
Subject: SHD 9859P

Hi CK

Kindly provide me the Book value of SHD 9859P (Tokio).
DOA : 11/5/2019 10:30 PM

Thks & Rqqs
Candy Kong
Claims Service Assistant



TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line : (65) 6287 6666 Fax Line: (65) 6257 1330
Websife: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Calvin Ang (LKKAuto) [<mailto:kalvinang@lkkauto.com>]
Sent: Tuesday, 28 May, 2019 9:11 AM
To: Candy Kong <candy.kong@transcab.com.sg> (candy.kong@transcab.com.sg) <candy.kong@transcab.com.sg>
Subject: SHD 9859P

Morning Candy,

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHD9859P
Vehicle to be Exported:	Yes
Intended Deregistration Date:	13 May 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	M9R8839C001184
Chassis No.:	VF1ABL15AUC277374
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	09 May 2014
First Registration Date:	09 May 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 May 2022
PARF Rebate Amount:	\$8,748.00

Intended COE Rebate Details

COE Expiry Date:	08 May 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$60,414.00
COE Rebate Amount:	\$22,544.00
Total Rebate Amount:	\$31,292.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 13 May 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/05/2019 13:17
Date Of Accident	11/05/2019 22:30
Exact Location Of Accident	PIE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD9859P
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666

Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

Driver

Name of Driver	PETER TAY SOON CHUAN
NRIC No	S0197912D
Date Of Birth	23/07/1952
Occupation	OUTDOOR
Date Of Driving Pass	12/01/1978
Driving Experience	41 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97615260
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	NO. 21 CARISBROOKE GROVE
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: : GERALDINE LOW - 87002061 GENDER: : FEMALE
Passenger 2	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 3	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 4	NAME: : UNKNOWN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BISHAN NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 20 BISHAN STREET 23 , POSTCODE: 579757 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-5529999 - FAX NO: 65561905
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Please see the attach Police Report T/20190513/2028.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLL372X
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver SIM TOCK LAM
NRIC/Passport Number S2609856D
Contact Number 87175311
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name PETER TAY SOON CHUAN
Approximate Age
Injuries Sustain
Injured person in which vehicle? SHD9859P
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please see the attached police report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Amanda
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Police Report Pg. 1



**SINGAPORE
POLICE FORCE**



T/20190513/2028

1 of 4

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

Report No. T/20190513/2028

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 13/05/2019 11:05	Video Report No.:	Station Diary No.: 31
--	-------------------	--------------------------

Informant's Particulars

Name of Informant: PETER TAY SOON CHUAN		Address: 21 CARISBROOKE GROVE SINGAPORE 558797	
ID Type / ID No.: NRIC NO / S0197912D		Contact No.: Home/Office: Mobile: 97615260	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 66	Date of Birth: 23/07/1952	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: Taxi driver		Driving Licence Information: Class: 3 Date of Expiry:	

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 11/05/2019 22:30	Type of Location: Straight Road
Location: Along Road 1 PAN ISLAND EXPRESSWAY Along Pan Island Expressway towards Jurong before BKE Exit. Lamp Post Number: 1104				
Weather: Cloudy		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control:	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No	Type	Make	Model	Color	Condition	No. of Passengers
SHD9859P	Car	RENAULT	LATITUDE 2.0L DCI AUTO D/AB 4DR	Red	Slightly Damaged	4
SLL372X	Car	HONDA	VEZEL HYBRID 1.5X AUTO	Black	Slightly Damaged	3



**SINGAPORE
POLICE FORCE**



T/20190513/2028

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

2 of 4
Report No. T/20190513/2028

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Passenger			
Name	GERALDINE LOW	ID No.	NIL
Related Vehicle	SHD9859P (Car)	Contact No.	67002061
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	PETER TAY SOON CHUAN	ID No.	S0197912D
Related Vehicle	SHD9859P (Car)	Contact No.	97615260
Hospital/Clinic	HORIZON MEDICAL CENTRE	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	13/05/2019	Date Discharge	NIL
No. of Days granted Medical Leave	04	Degree of Injury	Slight
Driver			
Name	SIM TOCK LAM	ID No.	S2609856D
Related Vehicle	SLL372X (Car)	Contact No.	87175311
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the abovementioned, date, time, and location, I was driving my taxi (SHD9859P) along Lane 4 when the vehicle in front of me jam braked. I managed to brake and stop on time. However, the car behind me (SLL372X) did not manage to stop on time and its front bumper had collided onto the rear bumper of my taxi. None of my passengers were hurt at that point of time. I got out and exchanged particulars with the driver of SLL372X. My taxi suffered slight damages to the rear bumper.

At that the time of the accident, I did not feel any pain. However on 12/05/2019 I felt pain on my neck, upper and lower back, and my knee and went to consult a doctor on the 13/05/2019 and I was given 4



**SINGAPORE
POLICE FORCE**



T/20190513/2028

3 of 4

Report No. T/20190513/2028

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

CONTINUATION OF REPORT

days of MC.

My passenger



**SINGAPORE
POLICE FORCE**



T/20190513/2028

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

4 of 4

Report No. T/20190513/2028

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: E / M MUHAMMAD MUHSIN 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 13/05/2019 11:05
Officer In Charge Of Case: TP / AEIT / Sgt 2 SHARIFAH NOR FARIZAN BINTE SYED MOHD SAID Contact No.: 65-72000000	Classification Of Case:
Authentication Stamp NP156  SINGAPORE POLICE FORCE  SIGNATURE	

Trans-cab Auto Services Pte Ltd

AAD1905-108

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9859P

l/s \$9650 / 50%

Vehicle No.:	SHD 9859P
Chassis No.:	VF1ABL15AUC277374
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	11.5.19
Third Party Insurer :	TOKIO MARINE
Date Of Registration:	9/5/2014

		PART		LIST
1	1	BUMPER COVER REAR <i>- Rebuilt</i>	\$	1,108.46
2	1	BUMPER LOWER REAR <i>- on</i>	\$	768.84
3	1	BUMPER BRACKET CTR REAR <i>- on</i>	\$	113.47
4	1	BUMPER BRACKET SIDE RH REAR <i>X on</i>	\$	135.97
5	1	BUMPER RETAINER RH REAR <i>X on</i>	\$	44.99
6	1	BUMPER REFLECTOR RH <i>X on</i>	\$	43.61
7	1	BUMPER BRACKET SIDE LH REAR <i>- on</i>	\$	135.97
8	1	BUMPER RETAINER LH REAR <i>- on</i>	\$	44.99
9	1	BUMPER REFLECTOR LH <i>- on</i>	\$	43.61
10	1	BUMPER BEAM REAR <i>- Rebuilt</i>	\$	777.52
11	1	BUMPER BEAM BRACKET LH REAR <i>- Rebuilt</i>	\$	225.95
12	1	BUMPER BEAM BRACKET RH REAR <i>- Rebuilt</i>	\$	225.95
13	1	BOOT REAR <i>- Rebuilt</i>	\$	2,872.68
14	1	BOOT FINISHER <i>X on</i>	\$	470.06
15	1	BOOT WHEATERSTRIP <i>X on</i>	\$	323.05
16	1	BOOT REFLECTOR LAMP LH <i>X on</i>	\$	493.35
17	1	BOOT REFLECTOR LAMP RH <i>X on</i>	\$	493.35
18	1	BOOT BADGE 'RENAULT' <i>- on</i>	\$	225.36
19	1	BOOT BADGE <i>- on</i>	\$	225.36
20	1	BOOT STRUT LH <i>X on</i>	\$	276.08
21	1	BOOT STRUT RH <i>X on</i>	\$	276.08
22	1	BOOT HINGE LH <i>X on</i>	\$	367.84
23	1	BOOT HINGE RH <i>X on</i>	\$	367.84
24	1	BOOT INNER TRIM <i>X on</i>	\$	586.45
25	1	BOOT SWITCH <i>X on</i>	\$	168.13
26	1	BOOT LOCK <i>X on</i>	\$	202.67
27	1	BOOT LOCK CATCH <i>X on</i>	\$	74.40
28	2	LICENCE PLATE LAMP <i>X on</i>	\$	50.52
29	2	BOOT RUBBER PLUG <i>X on</i>	\$	221.81
30	1	FENDER PANEL INNER TRIM REAR RH <i>X on</i>	\$	671.45

Trans-cab Auto Services Pte Ltd

AAD1905-108

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9859P

31	1	FENDER PANEL REAR RH	X <i>see</i>	\$	3,299.13
32	1	WHEELARCH REAR RH	X <i>see</i>	\$	543.47
33	1	FENDER PANEL REAR LH	X <i>see</i>	\$	3,299.13
34	1	FENDER PANEL INNER TRIM REAR LH	X <i>see</i>	\$	671.45
35	1	WHEELARCH REAR LH	X <i>see</i>	\$	543.47
36	1	TAILLAMP RH	X <i>see</i>	\$	552.55
37	1	TAILLAMP PANEL RH	X <i>see</i>	\$	986.70
38	1	TAILLAMP LH	— <i>see</i>	\$	552.55
39	1	TAILLAMP PANEL LH	— <i>see</i>	\$	986.70
40	1	OUTER PANEL REAR (End Panel)	— <i>see</i>	\$	1,471.77
41	1	OUTER PANEL REAR (End Panel)TRIM	— <i>see</i>	\$	404.56
42	1	SPARE WHEEL PANEL (Luggage Floor Panel)	X <i>see</i>	\$	2,189.88
43	1	SPARE WHEEL PANEL TRIM	X <i>see</i>	\$	612.21
44	1	EXHAUST REAR	— <i>see</i>	\$	7,489.05
45	1	EXHAUST CAP REAR	X <i>see</i>	\$	230.49
46	1	FUEL FLAP	X <i>see</i>	\$	343.57
				TOTAL	\$ 36,212.51
				10%	\$ 3,621.25
					\$ 32,591.26

Special Nett

1	1SET	PARKING AID	— <i>see</i>	\$	700.00 <i>600</i>
2	1SET	REAR BUMPER CLIP	— <i>see</i>	\$	66.00
3	1SET	BUMPER BRACKET CTR CLIP	— <i>see</i>	\$	33.00
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	X <i>see</i>	\$	10.00
5	1SET	BUMPER RETAINER RH CLIP RR	X <i>see</i>	\$	20.00
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	— <i>see</i>	\$	10.00
7	1SET	BUMPER RETAINER CLIP LH RR	— <i>see</i>	\$	20.00
8	1SET	BUMPER LOWER REAR RIVET	— <i>see</i>	\$	22.00
9	1SET	BUMPER LOWER REAR CLIP	— <i>see</i>	\$	66.00
10	1	EXHAUST MOUNTING REAR	X <i>see</i>	\$	17.82
11	1SET	BOOT FINISHER CLIP	X <i>see</i>	\$	24.20
12	1	BOOT STICKER "Trans-cab"	— <i>see</i>	\$	30.00
13	1	BOOT STICKER "6555-3333"	— <i>see</i>	\$	30.00
14	1	BOOT INNER TRIM CLIP	X <i>see</i>	\$	45.00
15	1SET	FENDER WHEELARCH REAR RH CLIP	X <i>see</i>	\$	35.00
16	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	X <i>see</i>	\$	385.00
17	1	SPARE TYRE	X <i>see</i>	\$	330.00

Trans-cab Auto Services Pte Ltd

AAD1905-108

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9859P

18	1	FENDER INNER TRIM CLIP RH	X	21	\$	28.00
19	1	TAILLAMP CLIP RH	X	22	\$	5.00
20	2	REAR WINDSCREEN SEALANT	X	23	\$	80.00
21	1	WINDSCREEN MOULDING	X	24	\$	100.00
22	1	REAR WINDSCREEN INNER SPONGE SEAL	X	25	\$	100.00
23	1	TAILLAMP CLIP LH	X	26	\$	5.00
24	1	FENDER INNER TRIM CLIP LH	X	27	\$	28.00
25	1SET	FENDER WHEELARCH REAR LH CLIP	X	28	\$	35.00
26	1	Rear left tyre	X	29	\$	330.00
27	1	Rear left tyre rim	X		\$	380.00
28	1	Rear right tyre	X		\$	330.00
29	1	Rear right tyre rim	X		\$	380.00

TOTAL	\$	3,645.02
--------------	-----------	-----------------

TOTAL PARTS	\$	36,236.28
--------------------	-----------	------------------

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00 ⁸⁰⁰
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00 ⁸⁰⁰
To reinstall rear bumper parking sensor.	\$	170.00 40
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 50
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00 X 21
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00 50
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00 X 21

Trans-cab Auto Services Pte Ltd

AAD1905-108

No. 2 Ang Mo Kio Street 63 Singapore 569111


Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9859P

To check steering geometry and computer wheel alignment	\$	220.00 X 1/2
To Rust-Proofing Of The Affected Areas.	\$	170.00 50
To repair and realign rear exhaust pipe.	\$	170.00 X 1/2
To transfer of tire, rim and on wheel balancing.	\$	170.00 X 1/2
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00 X 1/2
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00 X 1/2
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00 X 1/2
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	380.00 X 1/2
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00 50
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00 X 1/2
To apply paint protection system (PPS) maintain and enhancement	\$	380.00 X 1/2
To Check Electrical Lighting Concerned.	\$	170.00 50
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	380.00 X 1/2

Kahin 1000s
11/14/5/19 1600 hrs
5 Days
L/S
After Repair photo



TOTAL \$ 16,580.00

Over All Total \$ 52,816.28

(LUMP SUM) Repair Days 20 DAYS

96719399

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI19008578/K1VD3N2

Date: 03/06/2019

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MK000193
Claimant Vehicle No :	SHD9859P	Insured Vehicle No :	SLL372X
Date of Loss:	11/05/2019	Nature of Claim:	TP
		Claim No:	M1903397

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD9859P	Engine No:	M9R8839C001184
Make & Model:	RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR (A)	Chassis No:	VF1ABL15AUC277374
Reg. Date:	09/05/2014 (Man. Year: 2013)	Odometer:	438276 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Giti 7 mm	Rear Left Side:	Giti 7 mm
Front Right Side:	Giti 7 mm	Rear Right Side:	Giti 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	36,236.26	10,229.77	26,006.49	71.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	16,580.00	1,870.00	14,710.00	88.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	52,816.26	12,099.77	40,716.49	77.09
Approved Total (Overridden) (S\$)		9,650.00		
	(S\$) 52,816.26	9,650.00	43,166.26	81.73
+ GST 7.00/7.00% (S\$)	3,697.14	675.50	3,021.64	81.73
Nett Amount (S\$)	56,513.40	10,325.50	46,187.90	81.73

INSPECTION

Date of Assignment:	15/05/2019		
Date Inspected:	14/05/2019	Inspected At:	Trans-Cab Services Pte Ltd (HQ) 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	5.0 days		

Adjuster: KALVIN ANG WEI KUN

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 03 Jun 2019)
Parts: 143	RENAULT LATITUDE 2.0 L DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD9859P)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BUMPER COVER REAR	Deformed	1,108.46 FL	*1,108.46 FL
2	1	*BUMPER LOWER REAR	Cracked	768.84 FL	*768.84 FL
3	1	*BUMPER BRACKET CTR REAR	Cracked	113.47 FL	*113.47 FL
4	1	*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*- FL
5	1	*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*- FL
6	1	*BUMPER REFLECTOR RH	Serviceable	43.61 FL	*- FL
7	1	*BUMPER BRACKET SIDE LH REAR	Cracked	135.97 FL	*135.97 FL
8	1	*BUMPER RETAINER LH REAR	Cracked	44.99 FL	*44.99 FL
9	1	*BUMPER REFLECTOR LH	Cracked	43.61 FL	*43.61 FL
10	1	*BUMPER BEAM REAR	Bent	777.52 FL	*777.52 FL
11	1	*BUMPER BEAM BRACKET LH REAR	Bent	225.95 FL	*225.95 FL
12	1	*BUMPER BEAM BRACKET RH REAR	Bent	225.95 FL	*225.95 FL
13	1	*BOOT REAR	Buckled	2,872.68 FL	*2,872.68 FL
14	1	*BOOT FINISHER	Serviceable	470.06 FL	*- FL
15	1	*BOOT WEATHERSTRIP	Serviceable	323.05 FL	*- FL
16	1	*BOOT REFLECTOR LAMP LH	Serviceable	493.35 FL	*- FL
17	1	*BOOT REFLECTOR LAMP RH	Serviceable	493.35 FL	*- FL
18	1	*BOOT BADGE RENAULT	Necessary	225.36 FL	*225.36 FL
19	1	*BOOT BADGE	Necessary	225.36 FL	*225.36 FL
20	1	*BOOT STRUT LH	Serviceable	276.08 FL	*- FL
21	1	*BOOT STRUT RH	Serviceable	276.08 FL	*- FL
22	1	*BOOT HINGE LH	Serviceable	367.84 FL	*- FL
23	1	*BOOT HINGE RH	Serviceable	367.84 FL	*- FL
24	1	*BOOT INNER TRIM	Serviceable	586.45 FL	*- FL
25	1	*BOOT SWITCH	Serviceable	168.13 FL	*- FL
26	1	*BOOT LOCK	Jammed	202.67 FL	*202.67 FL
27	1	*BOOT LOCK CATCH	Serviceable	74.40 FL	*- FL
28	2	*LICENCE PLATE LAMP	Serviceable	50.52 FL	*- FL
29	2	*BOOT RUBBER PLUG	Serviceable	221.81 FL	*- FL
30	1	*FENDER PANEL INNER TRIM REAR RH	Serviceable	671.45 FL	*- FL
31	1	*FENDER PANEL REAR RH	Serviceable	3,299.13 FL	*- FL
32	1	*WHEELARCH REAR RH	Serviceable	543.47 FL	*- FL
33	1	*FENDER PANEL REAR LH	Repair	3,299.13 FL	*- FL
34	1	*FENDER PANEL INNER TRIM REAR LH	Serviceable	671.45 FL	*- FL
35	1	*WHEELARCH REAR LH	Serviceable	543.47 FL	*- FL
36	1	*TAILLAMP RH	Serviceable	552.55 FL	*- FL
37	1	*TAILLAMP PANEL RH	Serviceable	986.70 FL	*- FL
38	1	*TAILLAMP LH	Cracked	552.55 FL	*552.55 FL
39	1	*TAILLAMP PANEL LH	Buckled	986.70 FL	*986.70 FL
40	1	*OUTER PANEL REAR (END PANEL)	Buckled	1,471.77 FL	*1,471.77 FL
41	1	*OUTER PANEL REAR (END PANEL) TRIM	Cracked	404.56 FL	*404.56 FL
42	1	*SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	Repair	2,189.88 FL	*- FL
43	1	*SPARE WHEEL PANEL TRIM	Serviceable	612.21 FL	*- FL
44	1	*EXHAUST REAR	Serviceable	7,489.05 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
45	1	*EXHAUST CAP REAR	Serviceable	230.49 FL	*- FL
46	1	*FUEL FLAP	Serviceable	343.57 FL	*- FL
47	1	*SET PARKING AID	Shorted	700.00 FS	*600.00 FS
48	1	*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
49	1	*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
50	1	*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
51	1	*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
52	1	*SET BUMPER BRACKET SIDE CLIP LH RR	Necessary	10.00 FS	*10.00 FS
53	1	*SET BUMPER RETAINER CLIP LH RR	Necessary	20.00 FS	*20.00 FS
54	1	*SET BUMPER LOWER REAR RIVET	Necessary	22.00 FS	*22.00 FS
55	1	*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
56	1	*EXHAUST MOUNTING REAR	Serviceable	17.82 FS	*- FS
57	1	*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*- FS
58	1	*BOOT STICKER TRANS-CAB	Necessary	30.00 FS	*30.00 FS
59	1	*BOOT STICKER 6555-3333	Necessary	30.00 FS	*30.00 FS
60	1	*BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	*- FS
61	1	*SET FENDER WHEELARCH REAR RH CLIP	Not Necessary	35.00 FS	*- FS
62	1	*SPARE TYRE RIM (ROUE 7J 16H 2547)	Serviceable	385.00 FS	*- FS
63	1	*SPARE TYRE	Serviceable	330.00 FS	*- FS
64	1	*FENDER INNER TRIM CLIP RH	Not Necessary	28.00 FS	*- FS
65	1	*TAILLAMP CLIP RH	Not Necessary	5.00 FS	*- FS
66	2	*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
67	1	*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
68	1	*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
69	1	*TAILLAMP CLIP LH	Necessary	5.00 FS	*5.00 FS
70	1	*FENDER INNER TRIM CLIP LH	Not Necessary	28.00 FS	*- FS
71	1	*SET FENDER WHEELARCH REAR LH CLIP	Not Necessary	35.00 FS	*- FS
72	1	*REAR LEFT TYRE	Serviceable	330.00 FS	*- FS
73	1	*REAR LEFT TYRE RIM	Serviceable	380.00 FS	*- FS
74	1	*REAR RIGHT TYRE	Serviceable	330.00 FS	*- FS
75	1	*REAR RIGHT TYRE RIM	Serviceable	380.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

	Sub Total (\$\$)	39,857.51	11,268.41
- List Item Discount on L Items 10.00/10.00% (\$\$)		3,621.25	1,038.64
	Total Parts (\$\$)	36,236.26	10,229.77

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	800.00
2	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	6,000.00	800.00
3	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	40.00
4	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	50.00
5	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
6	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	50.00
7	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
8	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
9	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	50.00
10	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
11	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	0.00
12	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING	New	380.00	0.00
13	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
14	TO TRANSFER OF REAR WINDSCREEN FITTINGS AD CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
15	TO TRANSFER OF REAR BUMPER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
16	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	50.00
17	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR	New	380.00	0.00
18	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT	New	380.00	0.00
19	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	30.00
20	TO DROP DIESEL TANK,PIPES,HOSES TO FACILITATE BODYWORK REPAIR,FINAL CHECKING AND TESTING	New	380.00	0.00
Gross Labour Cost (S\$)			16,580.00	1,870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >