

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jocelyn Ng Shin Bun

Date: 15 May 2019

Preliminary Advice

Vehicle No	: SKF8438G	Accident Date	: 10/05/2019
Make	: HYUNDAI ELANTRA	Policy No.	: 80458949
Assignment Date	: 15/05/2019	Excess	: S\$500.00
Date of Inspection	: 15/05/2019	Est. Duration of Repair	: 4 days
Inspection At	: NPH Auto Service (HQ) Blk 9005 Tampines Steet 93, #01-246/254 Singapore 528839		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,344.11
Revised Amount	:S\$	1,728.61
Check Items (Estimated)	:S\$	467.50
Total	:S\$	2,196.11

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	34,000.00
COE / PARF Rebate	:S\$	28,075.00
Salvage Value	:S\$	
Margin for Repair	:S\$	5,925.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.