

ASS. REC. BY:

REF: CS/MSG19008527/ U vcl302

Special Instructions:

Survivor: marraASSIGNMENT (Office)From (Person): Jocelyn Ng Sun Bun of MSGDate/Time: 15.5.2019 10:55AM

Estimated Cost: _____

Bill to: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CSTo Inspect Vehicle No: SKF 8438G

Insured: _____

at Workshop m/s NPH Auto ServiceTel: 67840663of Bik 9005 Tampineq Street 93

Policy No: _____

Claim No: 593120

Sum Insured: _____

Excess: \$500.00

Make of Veh: _____

D.O.A. 10.05.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 15.5.19 10:55AMPerson Contacted: marraVehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SKF 8438G - NA/INC19008463/24</u> <u>D.O.A. 10/05/2019</u>
<u>15/05/19</u>	<u>@ 17:34 pm revised IA to Jocelyn via merimen</u>
<u>15/05/19</u>	<u>@ 17:36 pm mandate request and authome report to</u> <u>Jocelyn via merimen</u>
<u>16/5/19</u>	<u>Recd approved \$1728.61 from Jocelyn by merimen</u>
<u>16/5/19</u>	<u>Informed Peggy c/a ex \$500 by email</u>

CS/MSG19008587/0003

008/11/2019 wel

REF:

MS167

ASS. REC. BY: Marcus

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKT-84386

at Workshop m/s NPH

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: 500

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$ 34k.

IDAC Accident Rpt: ☒ Consistent? : Yes or NoGIA / PR Seen: ☒ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 131 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTA 28075

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKF 84386

Yr Regn: 7/12

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: Hyundai

Elantra c.c 1591

Colour: Silver

A/C: Insured / Std / NI / NA

Sp. Reading: 111971

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHDH41CMCU572LS8

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55 ZR16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front: 6

Rear: 6

R/Bal: 6 mm

R/Bal: 6 mm

L/Bal: 6 mm

L/Bal: 6 mm

D.O.A: 10/5/19

D.O.I: 15/5/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

R/L

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction 345 2nd Rep

net 5928

29/5/19 Final fig \$1733.61 confirmed by email (Ref 706.70, 29/5)

RECEIVED 30 MAY 2019

29/5/2019

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 30/5- typist

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

) \$ + RS \$

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

Report Format: merimen

Lump. Sum / I.B.I: (\$ 1733.61)

TOTAL

160

190
10
160

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 May 2019 11:03 Sendback Est	14 May 2019 11:20 S\$2,344.11	15 May 2019 10:55 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

Insured:	LOW CHEE KEAN, ID: S69097661, Tel: +6581869228, Email: NOEMAIL		
Vehicle Reg. No.:	SKFB438G	Date of Loss:	10/05/2019 11:00 - :59 [82 Months From LTA Reg Date (Man Yr)]
Claim Type:	OD / 593120	Policy/Cover Note No.:	80458949 (Comprehensive) Coverage: 10/07/2018 - 09/07/2019
		Excess:	S\$500.00
Repairer:	NPH Auto Service (HQ) Blk 9005 Tampines Steet 93, #01-246/254, 528839 Tampines - Tel: 6784 0663		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jocelyn Ng Shin Bun]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 16/05/2019]		
Driver/Custodian:	LOW CHEE KEAN (50 / Male), NRIC: S69097661, Tel: +6581869228 Email: NOEMAIL		
Adj Asg. Remarks:	Please revert.		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Received Message

This mail is associated with :

SKF8438G (593120)

OD

May 10 2019 11:00AM

[LOW CHEE KEAN]

NPH Auto Service

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 29/05/2019 17:33 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$1733.61) - SKF8438G - Claim Handler: Jocelyn Ng Shin Bun

Approved:1733.61:a if c

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jocelyn Ng Shin Bun

Date: 29 May 2019

Preliminary Advice

Vehicle No	: SKF8438G	Accident Date	: 10/05/2019
Make	: HYUNDAI ELANTRA	Policy No.	: 80458949
Assignment Date	: 15/05/2019	Excess	: S\$500.00
Date of Inspection	: 15/5/2019	Est. Duration of Repair	: 4
Inspection At	: NPH AUTO SERVICE		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,440.31 (incl.supplementary \$96.20)
Revised Amount	:S\$	1,733.61 (incl.supplementary \$96.20)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,733.61

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	34,000.00
COE / PARF Rebate	:S\$	28,075.00
Salvage Value	:S\$	
Margin for Repair	:S\$	5,925.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 16 May 2019 10:06 AM
To: nphauto@pacific.net.sg; SUR; peggy@nphauto.com
Subject: SKF 8438G-DOA: 10/5/2019 (MSIG OD)

Dear Peggy,

As instructed by our client , please proceed to repair the **insured vehicle SKF 8438G (Excess S\$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

SKF8438G (593120)

OD

May 10 2019 11:00AM

[LOW CHEE KEAN]

NPH Auto Service

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 16/05/2019 09:19 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$1728,61) - SKF8438G - Claim Handler: Jocelyn Ng Shin Bun

Approved:1728,61:a if c

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jocelyn Ng Shin Bun

Date: 15 May 2019

Preliminary Advice

Vehicle No	: SKF8438G	Accident Date	: 10/05/2019
Make	: HYUNDAI ELANTRA	Policy No.	: 80458949
Assignment Date	: 15/05/2019	Excess	: S\$500.00
Date of Inspection	: 15/05/2019	Est. Duration of Repair	: 4 days
Inspection At	: NPH Auto Service (HQ) Blk 9005 Tampines Steet 93, #01-246/254 Singapore 528839		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,344.11
Revised Amount	:S\$	1,728.61
Check Items (Estimated)	:S\$	467.50
Total	:S\$	2,196.11

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	34,000.00
COE / PARF Rebate	:S\$	28,075.00
Salvage Value	:S\$	
Margin for Repair	:S\$	5,925.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9766I
Vehicle Details	
Vehicle No.:	SKF8438G
Vehicle to be Exported:	No
Intended Deregistration Date:	15 May 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	ELANTRA 1.6 AT ABS D/AB 2WD 4DR
Primary Colour:	Silver
Manufacturing Year:	2012
Engine No.:	G4FGCU580127
Chassis No.:	KMHDH41CMCU572158
Maximum Power Output:	95.6 kW (128 bhp)
Open Market Value:	\$14,405.00
Original Registration Date:	10 Jul 2012
First Registration Date:	10 Jul 2012
Transfer Count:	0
Actual ARF Paid:	\$14,405.00 722
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Jul 2022
PARF Rebate Amount:	\$9,363.00
Intended COE Rebate Details	
COE Expiry Date:	09 Jul 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$59,421.00
COE Rebate Amount:	\$18,712.00
Total Rebate Amount:	\$28,075.00

The information contained herein is correct as at 15 May 2019

OK

SGCARMART.COM

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

Login

Sign up

Invest with Fast Direct Execution

Multi-awarded, multi-regulated broker

USAN BOLT

OFFICIAL SPONSOR

XM

WWW.XM.COM

Our services involve a significant risk and can result in the loss of your invested capital. T&Cs Apply

Open an Account

Post an Advertisement

Sell it yourself! Advertise it at just \$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Coe Renewal Toyota Vios 1.5A

2.98% p.p.A \$0 Admin Fees@Gv
Finance 2 Years Warranty \$1500
Down Monthly From \$448
GV Credit Pte Ltd - StarAd

Free VICOM evaluation

Free grooming and 6 months maintenance

In-house workshop ensures quality service

Member of SYTA and hire purchase association

100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

www.ympt.com

Browse by Category

Sort by Date Posted

20 results/page

7 vehicles

Hyundai Elantra

Advanced Search

Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Hyundai Elantra		Any	Any	2012	Any	Any	Any	Available
	Hyundai Elantra	1.6A	\$32,800	\$9,330 /yr	14-Feb-2012	1,591 cc	95,000 km	Sedan	Available
6 Months Warranty. Brand New Engine Mounting. Valve Cover Gasket Replaced, New Stabilizer Brush, ABS Sensor, Excellent Condition, Accident Free, Trade In Welcome.									
Posted: 14-May-2019 Tags: 2012 Hyundai Elantra, 2012 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai									
	Hyundai Elantra	1.6A	\$34,555	\$10,190 /yr	14-Mar-2012	1,591 cc	98,000 km	Sedan	Available
Don't Miss It! No Wasted Trip. Hurry Before COE Up Again! Free 6 Month Road Tax Till SEP 2019! Enjoy 2.28% Loan Interest! 100% Loan Available! Original Paint Works! Well Maintained, Free Car SPA Polis...									
Cars Inn Credit Pte Ltd									
Posted: 13-May-2019 Tags: 2012 Hyundai Elantra, 2012 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai									
	Hyundai Elantra	1.6A Elite	\$37,800	\$10,700 /yr	28-Mar-2012	1,591 cc	-	Sedan	Available
New Arrival, Only 1 Owners, Very Well Maintained, New Paintwork, Very Clean Interiors, Elegant Grey With Black Leather Seats. We Have A Few Units To Choose From. High Loan Available. Trade In Are Welc...									
Posted: 10-May-2019 Tags: 2012 Hyundai Elantra, 2012 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai									
	Hyundai Elantra	1.6A Elite	\$32,800	\$9,590 /yr	11-Jan-2012	1,591 cc	101,986 km	Sedan	Available
Must View To Believe Showroom Condition Like New Car!									
Mayfair Motoring									
Posted: 10-May-2019 Tags: 2012 Hyundai Elantra, 2012 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai									
	Filtro Plus Carbon Aircon Filter (Mitsubishi Lancer)								
Carbon Aircon Filter for Mitsubishi Lancer 1.6 2012-on.									
Find out more!									
	Hyundai Elantra	1.6A Elite	\$34,800	\$9,650 /yr	29-Mar-2012	1,591 cc	-	Sedan	Available
Accredited Company! Low Interest Rate! Accident-Free, High COE, High Rebate, Low Mileage Done, Low-Interest Rate. In-house Financing Options Available. Buy With A Peace Of Mind. Well Maintained. Guara...									
Fu Yip Motor Trading									
Posted: 10-May-2019 Tags: 2012 Hyundai Elantra, 2012 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai									
	Hyundai Elantra	1.6A Elite	\$38,800	\$10,050 /yr	06-Jul-2012	1,591 cc	-	Sedan	Available
Evaluated By VICOM, Free 6 Months Maintenance And 1 Grooming.									
Yong Lee Seng Motor									
Posted: 04-May-2019 Tags: 2012 Hyundai Elantra, 2012 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai									

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/05/2019 13:10
Date Of Accident	10/05/2019 11:35
Exact Location Of Accident	PIE TOWARDS JURONG (NEAR PAYA LEBAR EXIT)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKF8438G
Insured/Policyholder	
Name Of Registered Owner	LOW CHEE KEAN
NRIC No	S6909766I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81869228
Alternative Phone No	OFFICE-81869228

Vehicle Particulars

Manufacturer	HYUNDAI
Model	ELANTRA 1.6 AT ABS D/AB 2WD 4DR

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	80458949 QMY
Cover Note Number	

Driver

Name of Driver	LOW CHEE KEAN
NRIC No	S6909766I
Date Of Birth	26/03/1969
Occupation	INDOOR
Date Of Driving Pass	22/11/1994
Driving Experience	24 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81869228
Fax Number	
Contact Number	OFFICE-81869228
EMail Address	NOEMAIL

Address	BLK 246 SIMEI STREET 5 #10-62
Postcode	520246
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS DRIVING ALONG PIE TOWARDS JURONG, ON LANE 1. AS I WAS DRIVING, SUDDENLY THE CAR(SMD5734H) IN FRONT OF ME APPLIED THE BRAKE. I APPLIED MY BRAKE TOO BUT STILL HIT ONTO THE REAR OF THE SAID CAR.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMD5734H
Vehicle Make/Model/Colour	TOYOTA COROLLA ALTIS 1.6 AUTO
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claim history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulatory, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time

10 MAY 2019

Driver's Signature

(If driver is not the policyholder)

Date & Time

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4

Singapore 415933


Tel: 67416697 Fax: 67492305

Email: feedback@singnet.com.sg

Name:

NRIC/IN No:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer

L-File

DECLARATION

(We declare the foregoing particulars are true to every respect)

Policyholder's Signature
Date & Time

10 MAY 2019

Driver's Signature
(If driver is not the policyholder)
Date & Time

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: yackb@singnet.com.sg

Reporting Centre Personnel's Signature
Name:
Date & Time

NPH Auto Service
#01-246/254,Block 9005,
Tampines Street 93
528839

Claim Reference: OD0037/05/19
Assessment number: 005040
Version: 1810
Date calculated: 14/05/2019 10:55 AM

Full Report
Registration: SKF8438G
Printed: 14/05/2019 10:55 AM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	MSIG Insurance (Singapore) Pte Ltd
Printed by:	NG POH HUAT	Currency:	SGD
Claim Reference:	OD0037/05/19	Date of Incident:	10/05/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	HYUNDAI
Model:	ELANTRA (MD11)
Sub Model:	BASE MODEL
Model Sheet Number:	30 32 01
Registration:	SKF8438G
VIN number:	KMHDH41CMCU572158
Odometer:	111945

Model Specs

AIR CONDITIONING	1.6 LTR 97KW	AUTO GEARBOX 6 SPEED 4-DOOR
------------------	--------------	-----------------------------



Not Allowed
when
the pre-booking
4 days.
Excess @ 500
tel: 62563561

[Signature]
16/5/19

NPH Auto Service
#01-246/254,Block 9005,
Tampines Street 93
528839

Claim Reference: OD0037/05/19
Assessment number: 005040
Version: 1810
Date calculated: 14/05/2019 10:55 AM

Full Report
Registration: SKF8438G
Printed: 14/05/2019 10:55 AM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
86510R00	RENEW COMPLETE FRONT BUMPER INCLUDES: FRONT BUMPER AND SUPPORT RENEW FRONT BUMPER RAD GRILLE AND ATTACHED PARTS ASSEMBLE IF NECESSARY RENEW		7.0	35.00
92000R0B	REMOVE/REFIT BOTH HEADLIGHT UNITS INCLUDES: SET HEADLIGHT BEAMS		3.0	15.00
81182R00	R + R BONNET LOCK CABLE		2.0	10.00
NO NUMBER	R + R FRONT PANEL CPL		15.0	75.00
81130R00	R + R BONNET LOCK		2.0	10.00
96600R00)	R + R HORN		1.0	5.00
97606R00)	R + R AIR CONDITIONING CONDENSER		1.0	5.00
28100R00	R + R AIR CLEANER CPL		3.0	15.00
25300R00)	R + R RADIATOR INCLUDES: R + R RADIATOR SHROUD, PIPES AND NECESSARY ATTACHED PARTS,		10.0	50.00

NPH Auto Service
#01-246/254,Block 9005,
Tampines Street 93
528839

Claim Reference: OD0037/05/19
 Assessment number: 005040
 Version: 1810
 Date calculated: 14/05/2019 10:55 AM

Full Report
 Registration: SKF8438G
 Printed: 14/05/2019 10:55 AM

Code	Description	WU	Price SGD
25300RA4	DRAIN + REFILL COOLANT	1.0	5.00
09760A00	ADD/TIME FOR AUTOMATIC GEARBOX	5.0	25.00
0471	DRAIN + REFILL AIR CONDITIONING	10.0*	50.00
1201	BONNET REPAIR	5.0*11	25.00
1202	L/F SIDE MEMBER REPAIR	5.0*11	25.00
1002	R/F SIDE MEMBER REPAIR		25.00*
1003	CHK WIRING SYSTEM. CHK WIRING		100.00*
7761	VAC & TOP UP GAS VAC & TOP	5.0*	25.00
	RADIATOR CHECK		
Labour Cost		Hrs	WU
Panel / Mechanical Labour		7.50	75.0
Fixed Rate			125.00
Total of Labour			500.00

Paint

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description	WU Price SGD
	FRT BUMPER SUPPORT SURFACE PAINT	4.0
	FRONT BUMPER NEW PART PAINT K1G/P	24.0
	BONNET REPAIR PAINTING >50%	30.0
	L/F SIDE MEMBER SURFACE PAINT	4.0
	R/F SIDE MEMBER SURFACE PAINT	4.0

Paint Material Per Part

Code	Description	Price SGD
0340	FRT BUMPER SUPPORT SURFACE PAINT	1.76
0283	FRONT BUMPER NEW PART PAINT K1G/P	83.38
0471	BONNET REPAIR PAINTING >50%	40.13
1201	L/F SIDE MEMBER SURFACE PAINT	2.82
1202	R/F SIDE MEMBER SURFACE PAINT	2.82

Labour Cost - Paint

Factor	50.00 SGD/h	Hrs	WU	Price SGD
Time Paint			66.0	
Preparation Main Work Metal		1.70	17.0	85.00
Preparation Comp. Work Plastic		0.60	6.0	30.00
Total	10 WU/h	8.90	89.0	445.00

NPH Auto Service
#01-246/254,Block 9005,
Tampines Street 93
528839

Claim Reference: OD0037/05/19
 Assessment number: 005040
 Version: 1810
 Date calculated: 14/05/2019 10:55 AM

Full Report
 Registration: SKF8438G
 Printed: 14/05/2019 10:55 AM

Material Cost - Paint	Price SGD
New Part Painting - Plastic K1G/PUR	83.38
Repair Painting	40.13
Surface-/Blend Paint	7.40
Material-constant Metal	18.10
Material-constant Plastic	12.70
Total	161.71

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01 Price SGD
0283	FRONT BUMPER	865113X020 ✓		180.00 ✓
0299	FRT BUMPER AIR GRILL	865603X000		80.00 X
0315	FRONT IMPACT DAMPER	865203X000 ✓		50.00 ✓
0340	FRT BUMPER SUPPORT	865303X200		125.00 X
0410	GRILLE	863503X000 ✓		70.00 ✓
1009	FRONT PANEL CPL	641013X002 ✓		270.00 ✓
4465	AIR CON CONDENSER	976063X000 ✓		300.00 X
1000	GRILLE CLIPx6	GRILLE CLIPx6		9.00 ✓
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			1,084.00
u: Used parts	Addition(+10.00%)			108.40
	Total			1,192.40

Extras

Code	Description	Price SGD
1001	F/NO.PLATE W CASE F/No.Plate	45.00*
	Total Extras	45.00

NPH Auto Service
#01-246/254,Block 9005,
Tampines Street 93
528839

Claim Reference: OD0037/05/19
 Assessment number: 005040
 Version: 1810
 Date calculated: 14/05/2019 10:55 AM

Full Report
Registration: SKF8438G
Printed: 14/05/2019 10:55 AM

Final Calculation

	SGD	SGD
Parts	1,084.00	
Addition(+10.00%)	108.40	
Total Parts		1,192.40
Labour Time Base 10 WU/h		
Total 75.0 WU X 50.00 SGD/h	375.00	
Fixed Rate	125.00	
Total of Labour		500.00
Total Of Extras		45.00
Paint Work Time Base 10 WU/h		
Labour Cost 89.0 WU X 50.00 SGD/h	445.00	
Material Cost	161.71	
Total Paint Including Material		606.71
Repair Cost Excludes GST	2440.31	2,344.11
GST (+7.0%)		164.09
Repair Cost Included GST		2,508.20

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

NPH Auto Service
#01-246/254,Block 9005,
Tampines Street 93
528839

Claim Reference: OD0037/05/19
Assessment number: 005040
Version: 1810
Date calculated: 21/05/2019 5:06 PM

Full Report
Registration: SKF8438G
Printed: 21/05/2019 5:06 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	MSIG Insurance (Singapore) Pte Ltd
Printed by:	NG POH HUAT	Currency:	SGD
Claim Reference:	OD0037/05/19	Date of Incident:	10/05/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	HYUNDAI
Model:	ELANTRA (MD11)
Sub Model:	BASE MODEL
Model Sheet Number:	30 32 01
Registration:	SKF8438G
VIN number:	KMHDH41CMCU572158
Odometer:	111945

Model Specs

AIR CONDITIONING	1.6 LTR 97KW	AUTO GEARBOX 6 SPEED 4-DOOR
------------------	--------------	-----------------------------

NPH Auto Service
#01-246/254,Block 9005,
Tampines Street 93
528839

Claim Reference: OD0037/05/19
Assessment number: 005040
Version: 1810
Date calculated: 21/05/2019 5:06 PM

Full Report
Registration: SKF8438G
Printed: 21/05/2019 5:06 PM

Vehicle Condition


Vehicle Status

Pre-Accident Damage:

Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
86512R00	RENEW FRONT BUMPER INCLUDES: GRILLE AND REQUIRED ATTACHED PARTS RENEW		7.0	35.00
86530R00)	R + R FRT BUMPER SUPP (BUMPER REMOVED)		2.0	10.00
92000R0B	REMOVE/REFIT BOTH HEADLIGHT UNITS INCLUDES: SET HEADLIGHT BEAMS		3.0	15.00
81182R00	R + R BONNET LOCK CABLE		2.0	10.00
NO NUMBER	R + R FRONT PANEL CPL		15.0	75.00
81130R00	R + R BONNET LOCK		2.0	10.00
96600R00)	R + R HORN		1.0	5.00
97606R00)	R + R AIR CONDITIONING CONDENSER		1.0	5.00
28100R00	R + R AIR CLEANER CPL		3.0	15.00
25300R00)	R + R RADIATOR INCLUDES: R + R RADIATOR SHROUD, PIPES AND NECESSARY ATTACHED PARTS, DRAIN + REFILL COOLANT		10.0	50.00

NPH Auto Service
#01-246/254,Block 9005,
Tampines Street 93
528839

Claim Reference: OD0037/05/19
 Assessment number: 005040
 Version: 1810
 Date calculated: 21/05/2019 5:06 PM

Full Report
 Registration: SKF8438G
 Printed: 21/05/2019 5:06 PM

Code	Description	WU	Price SGD
25300RA4	ADD/TIME FOR AUTOMATIC GEARBOX	1.0	5.00
09760A00	DRAIN + REFILL AIR CONDITIONING	5.0	25.00
0340	FRT BUMPER SUPPORT REPAIR	10.0*	50.00
0471	BONNET REPAIR	10.0*	50.00
1002	CHK WIRING SYSTEM. CHK WIRING		25.00*
1003	VAC & TOP UP GAS VAC & TOP		100.00*
7761	RADIATOR CHECK	5.0*	25.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		7.70	77.0
Fixed Rate			125.00
Total of Labour			510.00

Paint

Paint Work		SYSTEM AZT	Time Basis 10WU/h
Code	Description	WU	Price SGD
	FRONT BUMPER NEW PART PAINT K1G/P	24.0	
	BONNET REPAIR PAINTING >50%	30.0	
	FRT BUMPER SUPPORT SURFACE PAINT	4.0	
	L/F SIDE MEMBER SURFACE PAINT	4.0	
	R/F SIDE MEMBER SURFACE PAINT	4.0	

Paint Material Per Part

Code	Description	Price SGD
0283	FRONT BUMPER NEW PART PAINT K1G/P	83.38
0471	BONNET REPAIR PAINTING >50%	40.13
0340	FRT BUMPER SUPPORT SURFACE PAINT	1.76
1201	L/F SIDE MEMBER SURFACE PAINT	2.82
1202	R/F SIDE MEMBER SURFACE PAINT	2.82

Labour Cost - Paint		Hrs	WU	Price SGD
Factor				
Time Paint			66.0	
Preparation Main Work Metal		1.70	17.0	85.00
Preparation Comp. Work Plastic		0.60	6.0	30.00
Total		10 WU/h	8.90	89.0

NPH Auto Service
#01-246/254,Block 9005,
Tampines Street 93
528839

Claim Reference: OD0037/05/19
 Assessment number: 005040
 Version: 1810
 Date calculated: 21/05/2019 5:06 PM

Full Report
 Registration: SKF8438G
 Printed: 21/05/2019 5:06 PM

Material Cost - Paint	Price SGD
New Part Painting - Plastic K1G/PUR	83.38
Repair Painting	40.13
Surface-/Blend Paint	7.40
Material-constant Metal	18.10
Material-constant Plastic	12.70
Total	161.71

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01 Price SGD
0283	FRONT BUMPER	865113X020		180.00
0315	FRONT IMPACT DAMPER	865203X000		50.00
0410	GRILLE	863503X000		70.00
1009	FRONT PANEL CPL	641013X002		270.00
1000	GRILLE CLIPx6	GRILLE CLIPx6		9.00
1004	L/CONDENSER GARNISH	CONDENSER GNISH		15.00
1005	R/CONDENSER GARNISH	CONDENSER GNISH		15.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			609.00
u: Used parts	Addition(+10.00%)			60.90
	Total			669.90

Extras

Code	Description	Price SGD
1001	F/NO.PLATE W CASE F/No.Plake	45.00*
1006	RIVET x6 RIVET x6	12.00*
	Total Extras	57.00

NPH Auto Service
#01-246/254,Block 9005,
Tampines Street 93
528839

Claim Reference: OD0037/05/19
 Assessment number: 005040
 Version: 1810
 Date calculated: 21/05/2019 5:06 PM

Full Report
 Registration: SKF8438G
 Printed: 21/05/2019 5:06 PM

Final Calculation

	SGD	SGD
Parts	609.00	
Addition(+10.00%)	60.90	
Total Parts		669.90
Labour Time Base 10 WU/h		
Total 77.0 WU X 50.00 SGD/h	385.00	
Fixed Rate	125.00	
Total of Labour		510.00
Total Of Extras		57.00
Paint Work Time Base 10 WU/h		
Labour Cost 89.0 WU X 50.00 SGD/h	445.00	
Material Cost	161.71	
Total Paint Including Material		606.71
Repair Cost Excludes GST		1,843.61
GST (+7.0%)		129.05
Repair Cost Included GST		1,972.66

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS



NPH AUTO SERVICE

Branch: 100/15 Tampines Street 91 #01-246/251 Singapore 528839 Tel: 67540003/4 Fax: 67540002
 GST Reg No: M06080903 NO Business Reg No: 2067713/MD
 Email: nphauto@nphauto.net.sg



(SUPPLEMENTARY)

INSURER: **MSIG insurance (Singapore) Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	80458949	Date of Loss:	10/05/2019
Vehicle Reg. No.:	SKF8438G	Driveable?	
Driver Age/Info:	50 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LOW CHEE KEAN	Contact No:	+6581869228
Driver:	LOW CHEE KEAN		
Make/Model:	HYUNDAI ELANTRA, 1.6 ABS D/AB 2WD 4DR (A)	Vehicle Reg. Date:	10/07/2012
Vehicle Colour:	SILVER		
Engine No:	G4FGCU580127	Chassis No:	KMHDH41CMCU572158
Odometer:	111945 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair 4 (day)			
Description of Accident/Loss	SKF8438G INVOLVED IN AN ACCIDENT WITH SMD5734H		
Present Location:	NPH AUTO SERVICE (HQ)		

COST OF CLAIMS

	Amount
Parts	46.20
Miscellaneous Items	0.00
Labour	50.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	96.20
+ GST 7.00% (S\$)	6.73
Nett Amount (S\$)	102.93
+ Previous Estimates (S\$)	1,973.20
Claim Total (S\$)	2,076.13

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 22 May 2019)

Parts: 143 HYUNDAI ELANTRA 1.6 ABS D/AB 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKF8438G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*AIR-CON CONDENSER STAND GARNISH L & R x2 @\$15	0.00	0.00	*30.00 F
2	1		*RIVET x6 \$2	0.00	0.00	*12.00 F
Sub Total (S\$)						42.00
+ Margin on L,N Items 10.00% (S\$)						4.20
Total Parts (S\$)						46.20

F=Franchise part.

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	FRT BUMPER SUPPORT REPAIR	New	50.00
Gross Labour Cost (\$\$)			50.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Veron Chen (LKKAUTO)

From: Mark <mark@nphauto.com>
Sent: Wednesday, 22 May 2019 3:25 PM
To: SUR
Subject: Emailing: SKF8438G G (2), SKF8438G G (3), SKF8438G G (4), SKF8438G G (5), SKF8438G RG (1), SKF8438G RG (2), SKF8438G RG (3), SKF8438G RG (4), SKF8438G RG (5), SKF8438G RG (6), SKF8438G RG (7), SKF8438G G (1)
Attachments: SKF8438G G (2).jpg; SKF8438G G (3).jpg; SKF8438G G (4).jpg; SKF8438G G (5).jpg; SKF8438G RG (1).jpg; SKF8438G RG (2).jpg; SKF8438G RG (3).jpg; SKF8438G RG (4).jpg; SKF8438G RG (5).jpg; SKF8438G RG (6).jpg; SKF8438G RG (7).jpg; SKF8438G G (1).jpg; SKMBT_C224e19052215090.pdf

Dear Marcus,

Attached photos and estimate with invoice and supplementary.

COR:\$1843.61 before gst.

Regards,
Roy

TAX INVOICE

INVOICE NO. 8147434

DATE	15/05/2019	PAGE	1
TERM	7 Days	SALESMAN	Tan Poo Huat
CUSTOMER REF.	SKF8438G	OUR REF.	40611

GST REG. NO.: M2-0090482-6 CO REG. NO.: 198905613E

ACCOUNT NUMBER: NPH AUTO SERVICE

NPH AUTO SERVICE
BLK 9005, TAMPINES STREET 93,
#01-246, TAMPINES IND PARK A,
SINGAPORE 528839

Telephone No : 67840663

ROUTE:
TAMP2

DELIVER TO :

NPH AUTO SERVICE
BLK 9005, TAMPINES STREET 93,
#01-246, TAMPINES IND PARK A,
SINGAPORE 528839==URGENT==URGENT




PART NO.	PARTICULARS	LOC	QUANTITY	UNIT PRICE	AMOUNT
1 HY86511-3X020	COVER-FR BUMPER	4E-03F	1 PC	180.00	180.00
2 HY86520-3X100	ABSORBER-FR BUMPER ENERGY	3P-02I	1 PC	50.00	50.00
3 HY86350-3X000	GRILLE ASSY-RADIATOR(CHROME	2I-06C	1 PC	70.00	70.00
4 HY64101-3X002	FRT SUPPPORT PANEL	2C-02A	1 PC	270.00	270.00
5 HY86590-28000 H	CLIP-BUMPER	1L-10C	6 PCS	1.50	9.00
6 HY29134-3X000	AIR GUARD RH	1L-04L	1 PC	15.00	15.00
7 HY29136-3X000	AIR GUARD LH	1S-1EE	1 PC	15.00	15.00

GOODS RECEIVED IN GOOD ORDER AND CONDITION.

*GOODS SOLD ARE NOT RETURNABLE.
*OVERDUE ACCOUNTS SHALL BEAR INTEREST AT UOB'S PREVALING LENDING RATE
*CASH INVOICE MUST BE PAID WITHIN 7 DAYS FROM DATE OF INVOICE.

Exclusive Distributor



Payment via telegraphic transfer to
Name of Bank: United Overseas Bank
Account Name: Min Ghee Auto Pte Ltd
Branch Code: 046
Account No.: 503-309-511-3
*Please send a screen shot of your payment/transfer confirmation to
account@minghee.com

TOTAL	SIN	609.00
ADD GST	7%	42.63
AMOUNT DUE	SIN	651.63

SIGN & COMPANY'S STAMP



DATE
ALL CHEQUES MUST BE MADE PAYABLE TO
MIN GHEE AUTO PTE LTD.

For MIN GHEE AUTO PTE. LTD.



8, Jalan Lembah Kallang, #01-01 Min Ghee Building Singapore 339564
Main Tel: 6298 3888 Fax: 6291 2172, 6294 1450 Accounts Tel: 6291 6119 Accounts Fax: 6297 0863
Email: info@minghee.com (Main), account@minghee.com (Accounts)
Website: http://www.minghee.com

PRO-FORMA INVOICE

PROFORMA INVOICE NO. **16760**

DATE	24/05/2019	PAGE	1
TERM	7 Days	SALESMAN	Tan Poo Huat
CUSTOMER REF.		OUR REF.	12041

GST REG. NO.: M12-0090482-6 CO REG. NO.: 198905613E

ACCOUNT NUMBER: NPHAUTO1 TIME:11:41

NPH AUTO SERVICE
BLK 9005, TAMPINES STREET 93,
#01-246, TAMPINES IND PARK A,
SINGAPORE 528839

Telephone No : 67840663

ROUTE

DELIVER TO :

NPH AUTO SERVICE
BLK 9005, TAMPINES STREET 93,
#01-246, TAMPINES IND PARK A,
SINGAPORE 528839



PART NO.	PARTICULARS	LOC	QUANTITY	UNIT PRICE	AMOUNT
1 HY14160-03080	RIVET BLIND	1W-01D	6 PCS	2.00	12.00

GOODS RECEIVED IN GOOD ORDER
AND CONDITION.

*GOODS SOLD ARE NOT RETURNABLE.
*OVERDUE ACCOUNTS SHALL BEAR INTEREST AT UOB'S
PREVAILING LENDING RATE
*CASH INVOICE MUST BE PAID WITHIN 7 DAYS
FROM DATE OF INVOICE.

Exclusive Distributor

HDK

Stockists

Payment via telegraphic transfer to
Name of Bank: United Overseas Bank
Account Name: Min Ghee Auto Pte Ltd
Branch Code: 045
Account No.: 501 309 531-3
*Please send a screenshot of your payment/
transfer confirmation to
account@minghee.com.

SIGN & COMPANY'S STAMP

DATE

ALL CHEQUES MUST BE MADE PAYABLE TO
MIN GHEE AUTO PTE LTD.



For MIN GHEE AUTO PTE. LTD.

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: OD0037/05/19
Assessment number: 005040
Version: 1810
Date calculated: 28/05/2019 3:41 PM

Full Report
Registration: SKF8438G
Printed: 28/05/2019 3:41 PM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	MSIG Insurance (Singapore) Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:	OD0037/05/19	Date of Incident:	10/05/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle		
Manufacturer:	HYUNDAI	
Model:	ELANTRA (MD11)	
Sub Model:	BASE MODEL	
Model Sheet Number:	30 32 01	
Registration:	SKF8438G	
VIN number:	KMHDH41CMCU572158	
Odometer:	111945	
Model Specs		
AIR CONDITIONING	1.6 LTR 97KW	AUTO GEARBOX 6 SPEED 4-DOOR

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: OD0037/05/19
 Assessment number: 005040
 Version: 1810
 Date calculated: 28/05/2019 3:41 PM

Full Report
 Registration: SKF8438G
 Printed: 28/05/2019 3:41 PM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
 Date of Inspection:

Damage Areas

All ☐
 Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
86512R00	RENEW FRONT BUMPER INCLUDES: GRILLE AND REQUIRED ATTACHED PARTS RENEW		7.0	35.00
86530R00)	R + R FRT BUMPER SUPP (BUMPER REMOVED)		2.0	10.00
92000R0B	REMOVE/REFIT BOTH HEADLIGHT UNITS INCLUDES: SET HEADLIGHT BEAMS		3.0	15.00
81182R00	R + R BONNET LOCK CABLE		2.0	10.00
NO NUMBER	R + R FRONT PANEL CPL		15.0	75.00
81130R00	R + R BONNET LOCK		2.0	10.00
96600R00)	R + R HORN		1.0	5.00
97606R00)	R + R AIR CONDITIONING CONDENSER		1.0	5.00
28100R00	R + R AIR CLEANER CPL		3.0	15.00
25300R00)	R + R RADIATOR INCLUDES: R + R RADIATOR SHROUD, PIPES AND NECESSARY ATTACHED PARTS, DRAIN + REFILL COOLANT		10.0	50.00

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: OD0037/05/19
 Assessment number: 005040
 Version: 1810
 Date calculated: 28/05/2019 3:41 PM

Full Report
 Registration: SKF8438G
 Printed: 28/05/2019 3:41 PM

Code	Description	WU	Price SGD
25300RA4	ADD/TIME FOR AUTOMATIC GEARBOX	1.0	5.00
09760A00	DRAIN + REFILL AIR CONDITIONING	5.0	25.00
0340	FRT BUMPER SUPPORT REPAIR	10.0*	50.00
0471	BONNET REPAIR	10.0*	50.00
1003	VAC & TOP UP GAS VAC & TOP		50.00*
Labour Cost		Hrs	WU
Panel / Mechanical Labour		7.20	72.0
Fixed Rate			50.00
Total of Labour			410.00

Paint

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description	WU Price SGD
	FRONT BUMPER NEW PART PAINT K1G/P	24.0
	BONNET REPAIR PAINTING >50%	30.0
	FRT BUMPER SUPPORT SURFACE PAINT	4.0
	L/F SIDE MEMBER SURFACE PAINT	4.0
	R/F SIDE MEMBER SURFACE PAINT	4.0

Paint Material Per Part

Code	Description	Price SGD
0283	FRONT BUMPER NEW PART PAINT K1G/P	83.38
0471	BONNET REPAIR PAINTING >50%	40.13
0340	FRT BUMPER SUPPORT SURFACE PAINT	1.76
1201	L/F SIDE MEMBER SURFACE PAINT	2.82
1202	R/F SIDE MEMBER SURFACE PAINT	2.82

Labour Cost - Paint	Hrs	WU	Price SGD
Factor	50.00 SGD/h		
Time Paint		66.0	
Preparation Main Work Metal	1.70	17.0	85.00
Preparation Comp. Work Plastic	0.60	6.0	30.00
Total	10 WU/h	89.0	445.00

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: OD0037/05/19
 Assessment number: 005040
 Version: 1810
 Date calculated: 28/05/2019 3:41 PM

Full Report
 Registration: SKF8438G
 Printed: 28/05/2019 3:41 PM

Material Cost - Paint	Price SGD
New Part Painting - Plastic K1G/PUR	83.38
Repair Painting	40.13
Surface-/Blend Paint	7.40
Material-constant Metal	18.10
Material-constant Plastic	12.70
Total	161.71

Spare Parts

				prices as at 2015-06-01
Code	Description	Part Number	Supplier	Price SGD
0283	FRONT BUMPER	865113X020		180.00
0315	FRONT IMPACT DAMPER	865203X000		50.00
0410	GRILLE	863503X000		70.00
1009	FRONT PANEL CPL	641013X002		270.00
1000	GRILLE CLIPx6	GRILLE CLIPx6		9.00
1004	L/CONDENSER GARNISH	CONDENSER GNISH		15.00
1005	R/CONDENSER GARNISH	CONDENSER GNISH		15.00
f: OEM Parts				Savings 0.00
n: Non-OEM Parts				Subtotal 609.00
u: Used parts				Addition(+10.00%) 60.90
Total				669.90

Extras

Code	Description	Price SGD
1001	F/NO.PLATE W CASE F/No.Plate	35.00*
1006	RIVET x6 RIVET x6	12.00*
Total Extras		47.00

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: OD0037/05/19
Assessment number: 005040
Version: 1810
Date calculated: 28/05/2019 3:41 PM

Full Report
Registration: SKF8438G
Printed: 28/05/2019 3:41 PM

Final Calculation

	SGD	SGD
Parts	609.00	
Addition(+10.00%)	60.90	
Total Parts		669.90
Labour Time Base 10 WU/h		
Total 72.0 WU X 50.00 SGD/h	360.00	
Fixed Rate	50.00	
Total of Labour		410.00
Total Of Extras		47.00
Paint Work Time Base 10 WU/h		
Labour Cost 89.0 WU X 50.00 SGD/h	445.00	
Material Cost	161.71	
Total Paint Including Material		606.71
Repair Cost Excludes GST		1,733.61
GST (+7.0%)		121.35
Repair Cost Included GST		1,854.96

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 29 May 2019 5:49 PM
To: Mark; SUR
Subject: RE: Hyundai Elantra-SKF 8438G

Dear Roy,

Noted with thanks.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mark <mark@nphauto.com>
Sent: Wednesday, 29 May 2019 10:52 AM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: Hyundai Elantra

Dear Veron,

Please confirm and submit. Please arrange merimen offer to close from MSIG.

Regards,
Roy

From: Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]
Sent: Tuesday, 28 May 2019 4:10 PM
To: Mark <mark@nphauto.com>; SUR <sur@lkkauto.com>
Subject: RE: Hyundai Elantra

Dear Roy,

Finalise amount \$1733.61 before excess \$500

Please check and confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mark <mark@nphauto.com>
Sent: Friday, 24 May 2019 3:36 PM
To: SUR <sur@lkkauto.com>
Subject: Hyundai Elantra

Dear Marcus,

As spoken.

Regards,
Roy47

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 May 2019 11:03 Send Back Est	14 May 2019 11:20 S\$2,344.11	15 May 2019 10:55 Edit Adj Rpt	S\$1,733.61 Edit Estimates	S\$1,733.61 View Rpt		Pending for Survey Report Cancel Case
Supp #1	22 May 2019 14:36	22 May 2019 15:08 S\$96.20	22 May 2019 15:08			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: LOW CHEE KEAN , ID: S6909766I, Tel: +6581869228, Email: NOEMAIL									
Vehicle Reg. No.: SKF8438G		Date of Loss: 10/05/2019 11:00 - :59 [82 Months From LTA Reg Date (Man Yr)]							
Claim Type: OD / 593120		Policy/Cover Note No.: 80458949 (Comprehensive) Coverage: 10/07/2018 - 09/07/2019							
		Excess: S\$500.00							
Repairer: NPH Auto Service (HQ) Blk 9005 Tampines Steet 93, #01-246/254, 528839 Tampines - Tel: 6784 0663									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jocelyn Ng Shin Bun]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 14/06/2019]									
Driver/Custodian: LOW CHEE KEAN (50 / Male) , NRIC: S6909766I, Tel: +6581869228 Email: NOEMAIL									
Adj Ass. Remarks: Please revert.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- MSIG_SG (29/05/2019): Alert - Adj Mandate Approved (S\$1733.61) - SKF8438G - Claim Handler: Jocelyn Ng ... - MSIG_SG (16/05/2019): Alert - Adj Mandate Approved (S\$1728.61) - SKF8438G - Claim Handler: Jocelyn Ng ...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SKF8438G (593120)
OD
May 10 2019 11:00AM
[LOW CHEE KEAN]
NPH Auto Service

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Assessment Reports

1 per page

No	Finalized On	VAC (Kaki Bukit)		Thumbnail	Print
1	10/05/19 13:21	Accident Statement		Load HTM	
No	Finalized On	NPH Auto Service (HQ)		Thumbnail	Print
1	14/05/19 11:20	Repairer Estimates		Load HTM	
2	22/05/19 15:08	Repairer Estimates Suppl. #1		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	15/05/19 17:34	Adjuster Immediate Advice		Load HTM	
2	29/05/19 11:07	Adjuster Immediate Advice		Load HTM	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	15/05/19 18:04	Chassis Number		Load JPG	
2	15/05/19 18:04	Odometer Reading		Load JPG	
3	15/05/19 18:04	General View		Load JPG	
4	15/05/19 18:04	General View		Load JPG	
5	15/05/19 18:04	General View		Load JPG	
6	15/05/19 18:04	General View		Load JPG	
7	15/05/19 18:04	General View		Load JPG	
8	15/05/19 18:04	General View		Load JPG	
9	15/05/19 18:04	General View		Load JPG	
10	15/05/19 18:04	General View		Load JPG	
11	15/05/19 18:04	General View		Load JPG	
12	15/05/19 18:04	General View		Load JPG	
13	15/05/19 18:04	General View		Load JPG	
14	15/05/19 18:04	General View		Load JPG	
15	15/05/19 18:04	General View		Load JPG	
16	15/05/19 18:04	General View		Load JPG	
17	15/05/19 18:04	General View		Load JPG	
18	15/05/19 18:04	General View		Load JPG	
19	15/05/19 18:04	General View		Load JPG	
20	15/05/19 18:04	General View		Load JPG	
21	15/05/19 18:04	General View		Load JPG	
22	15/05/19 18:04	General View		Load JPG	
23	15/05/19 18:04	General View		Load JPG	
24	15/05/19 18:04	General View		Load JPG	
25	15/05/19 18:04	General View		Load JPG	
26	15/05/19 18:04	General View		Load JPG	
27	15/05/19 18:04	General View		Load JPG	
28	15/05/19 18:04	General View		Load JPG	
29	15/05/19 18:04	General View		Load JPG	
30	15/05/19 18:04	General View		Load JPG	

Assessment Reports			1 per page	☒
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
31	15/05/19 18:04	General View	 Load JPG	☒
32	15/05/19 18:04	General View	 Load JPG	☒
33	15/05/19 18:04	General View	 Load JPG	☒
34	15/05/19 18:04	General View	 Load JPG	☒
35	15/05/19 18:04	General View	 Load JPG	☒
36	15/05/19 18:04	General View	 Load JPG	☒
37	15/05/19 18:04	General View	 Load JPG	☒
38	15/05/19 18:04	General View	 Load JPG	☒
39	15/05/19 18:04	General View	 Load JPG	☒
40	15/05/19 18:04	General View	 Load JPG	☒
41	15/05/19 18:04	General View	 Load JPG	☒
42	15/05/19 18:04	General View	 Load JPG	☒
43	15/05/19 18:04	General View	 Load JPG	☒
44	15/05/19 18:04	General View	 Load JPG	☒
45	15/05/19 18:04	General View	 Load JPG	☒
46	15/05/19 18:04	General View	 Load JPG	☒
47	15/05/19 18:04	General View	 Load JPG	☒
48	16/05/19 18:24	Reinspection Photo	 Load JPG	☒
49	16/05/19 18:24	Reinspection Photo	 Load JPG	☒
50	16/05/19 18:24	Reinspection Photo	 Load JPG	☒
51	16/05/19 18:24	Reinspection Photo	 Load JPG	☒
52	16/05/19 18:24	Reinspection Photo	 Load JPG	☒
53	16/05/19 18:24	Reinspection Photo	 Load JPG	☒
54	16/05/19 18:24	Reinspection Photo	 Load JPG	☒
55	16/05/19 18:24	Reinspection Photo	 Load JPG	☒
56	16/05/19 18:24	Reinspection Photo	 Load JPG	☒
57	16/05/19 18:24	Reinspection Photo	 Load JPG	☒
58	16/05/19 18:24	Reinspection Photo	 Load JPG	☒
59	16/05/19 18:24	Reinspection Photo	 Load JPG	☒
60	16/05/19 18:24	Reinspection Photo	 Load JPG	☒
61	16/05/19 18:24	Reinspection Photo	 Load JPG	☒
62	16/05/19 18:24	Reinspection Photo	 Load JPG	☒
63	16/05/19 18:24	Reinspection Photo	 Load JPG	☒
64	16/05/19 18:24	Reinspection Photo	 Load JPG	☒
65	16/05/19 18:24	Reinspection Photo	 Load JPG	☒
66	16/05/19 18:24	Reinspection Photo	 Load JPG	☒
67	16/05/19 18:24	Reinspection Photo	 Load JPG	☒
68	16/05/19 18:24	Reinspection Photo	 Load JPG	☒
69	16/05/19 18:24	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	14/05/19 17:01	PARF COE	 Load PDF	
2	14/05/19 17:01	Transfer Fee Details	 Load PDF	
3	14/05/19 17:02	TP GIA Report - SMD5734H	 Load PDF	
No	Finalized On	NPH Auto Service (HQ)	Thumbnail	Print
1	14/05/19 11:20	Audatex Report	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/05/19 17:35	ESTIMATE.pdf	 Load PDF	
2	29/05/19 11:10	SUPPLEMENTARY	 Load PDF	
3	31/05/19 09:14	Parts Invoice	 Load PDF	

Linked Accident Report Documents

				View	View in Browser
Assessment Reports				1 per page	☒
No	Finalized On	VAC (Kaki Bukit)		Thumbnail	Print
1	10/05/19 13:21	Accident Statement		Load HTM	
2	13/05/19 12:43	Addendum Sheet		Load TIF	
3	13/05/19 12:43	Accident Statement Addm. #1		Load HTM	
Photos/Images				3 per page	☒
No	Finalized On	VAC (Kaki Bukit)		Thumbnail	Print
1	10/05/19 13:18	Accident Photo		Load JPG	☒
2	10/05/19 13:18	Accident Photo		Load JPG	☒
3	10/05/19 13:18	Accident Photo		Load JPG	☒
4	10/05/19 13:18	Accident Photo		Load JPG	☒
5	10/05/19 13:18	Accident Photo		Load JPG	☒
6	10/05/19 13:18	Accident Photo		Load JPG	☒
7	10/05/19 13:18	Accident Photo		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	VAC (Kaki Bukit)		Thumbnail	Print
1	10/05/19 13:16	Sketch Plan		Load TIF	
2	10/05/19 13:16	Sketch Plan #2		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG19008587/UVD3E2

Date: 31/05/2019

REFERENCE

Insured/Claimant:	LOW CHEE KEAN	Policy No:	80458949	Claim No:	593120
Date of Loss:	10/05/2019	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKF8438G		Engine No:	G4FGCU580127
Make & Model:	HYUNDAI ELANTRA, 1.6 ABS D/AB 2WD 4DR (A)		Chassis No:	KMHDH41CMCU572158
Reg. Date:	10/07/2012 (Man. Year: 2012)		Odometer:	111971 km
Colour:	Silver			
Engine Capacity:	1591 cc			
Market Value/New Car Price:	S\$34,000.00			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55Z R16	Rear Tyre Size:	205/55Z R16
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,238.60	681.90	556.70	44.95
Miscellaneous Items	45.00	35.00	10.00	22.22
Paintwork Materials	161.71	161.71	0.00	0.00
Labour	550.00	410.00	140.00	25.45
Paintwork Labour	445.00	445.00	0.00	0.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,440.31	1,733.61	706.70	28.96
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	1,940.31	1,233.61	706.70	36.42
+ GST 7.00/7.00% (S\$)	135.82	86.35	49.47	36.42
Nett Amount (S\$)	2,076.13	1,319.96	756.17	36.42

INSPECTION

Date of Assignment:	15/05/2019 Present Location:	NPH Auto Service (HQ)
Date Inspected:	15/05/2019 Inspected At:	NPH Auto Service (HQ)
		Blk 9005 Tampines Steet 93, #01-246/254
		Singapore 528839
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 May 2019)
Parts:	143	HYUNDAI ELANTRA 1.6 ABS D/AB 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKF8438G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SPARE PARTS (WCP)		1,084.00 F	*579.00 F
Supplementary #1						
2	1		*AIR-CON CONDENSER STAND GARNISH L & R x2 @\$15 (WCP)	Torn	30.00 F	*30.00 F
3	1		*RIVET x6 \$2	Necessary	12.00 F	*12.00 FS
F=Franchise part. S=SpcNett.						
Sub Total (\$\$)					1,126.00	621.00
+ Margin on L,N Items 10.00/10.00% (\$\$)					112.60	60.90
Total Parts (\$\$)					1,238.60	681.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Materials</u>				
1	1	PAINTWORK MATERIALS	161.71	161.71
<u>Miscellaneous Items</u>				
2	1	EXTRAS	45.00	35.00
Sub Total (S\$)			206.71	196.71

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	PAINTWORK LABOUR	New	445.00	445.00
<u>Labour Items</u>				
2	PANEL/MECHANICAL LABOUR	New	500.00	360.00
<u>Supplementary #1</u>				
<u>Labour Items</u>				
3	FRT BUMPER SUPPORT REPAIR	New	50.00	50.00
Gross Labour Cost (S\$)			995.00	855.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >