

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 28 May 2019 4:27 PM
To: 'HUPHUP WORKSHOP'
Cc: SUR
Subject: RE: GBB 6185B MSIG (OD) DOA - 03/05/2019

Dear Ms. Wong,

As instructed by our client, please proceed at repair cost not exceeding \$ 8,500.00 (inclusive check, supplementary items & Excess) to repair the insured vehicle **GBB 6185B** (Excess \$ 750/-) on lump Sum basis.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: HUPHUP WORKSHOP [mailto:hupwshop@hotmail.com]
Sent: Thursday, 16 May 2019 5:27 PM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Subject: Re: GBB 6185B MSIG (OD) DOA - 03/05/2019

Hi Shirley,

Shall we raise up the Repair Costs to Lump Sum \$ 8500/= Just be able to cover our costs.

Thanks & Best regards
Wong (Ms)
Hup Hup Workshop
Tel: 6265 1966

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, May 16, 2019 12:07 PM
To: hupwshop@hotmail.com

Cc: SUR

Subject: GBB 6185B MSIG (OD) DOA - 03/05/2019

Hi Ms. Wong,

Kindly check the repair cost limit whether you are able to repair the vehicle not exceeding \$ 7,400.00 on lump sum basis.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)