

ASS. REC. BY:

REF:

CS/FCI19008589/Utd3

Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person):

Kerentan

of

FCI

Date/Time:

4.53pm @ 14/5/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SJT 9837U

Insured:

SHD 4966X

at Workshop m/s

Progressive

Tel:

67415336

of

Bllc 3022A Ubi Rd 1 #01-48/46

Policy No.:

Claim No.:

D19003178 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

12/5/2019

CA / REV / REP. / REV 24 HRS

DS

15/5/19

H.O.D. Endorsement:

Date/Time:

5.41pm @ 14/5/19

Person Contacted:

Pei weh

Vehicle

IN/OUT

Date/Time	Action/Instruction
	Johnnie (✓)
	SJT 9837U - X
	SHD 4966X - X
15/5 - 11:49am	Revised preli advise via email

REF: FCI

ASSIGNMENT

From:

Date: 15/5/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SJ798374

at Workshop m/s:

Progressive

of

Blk 3022A ubi Rd L # 01-45

Insured:

Policy No.:

Claims No.:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

11 am
(waiting)

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

\$ 11k.

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lump Sum:

20

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

100

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SJ798374

Veh Regn:

12/11/09

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA 1

Make:

Hyundai Avante

C.C.

159/

Colour:

Red

A/C:

Insured / Std / Nil / NA

Sp. Reading:

146611

T/Radio: Insured / Std / Nil / NA

Eng/No:

G/No:

KMH DU 413 MAY 893771

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

205/55-R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

12/5/19

D.O.A.

15/5/19

Survey held at

Des. of Damages: Frt / Rear / O/S / W/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time

Action / Instruction

15/5/19

1/5 \$ 4400 confirmed with windy. (red: 4051.94, 47%)
Summit

16/5 - Check with Marcus Submit.

MV: 11,000/-
LTA: 6552/-
NV: 4448

RECEIVED 16 MAY 2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Survey Fee:

Transportation:

: \$ + RS. \$1

: Photos

: Others

TOTAL

160

50

50

92

352

Report Format :

Lump Sum / L.B.E (\$)

Your Ref: D19003178MFSH

Date: 16/5/2019

Our Ref: CS/FCI19008589/Utd3


The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SJT 9837UPlease be informed that we had conducted the inspection of the abovementioned vehicle
16/05/2019 at the premises of M/s Progressive have the following to report: -

Workshop Estimate Amount	: S\$	<u>8,451.94</u>
Revised Estimate Amount	: S\$	<u>5,706.53</u>
"Check" Items Amount	: S\$	<u>0.00</u>
Market Value	: S\$	<u> </u>
LTA Reimbursement Value	: S\$	<u> </u>
Nett Value	: S\$	<u> </u>

Description of Damage:

The vehicle sustained damages at the
front portion.**Comments/ Present Status:**

Damages Consistent.

Yours faithfully

Marcus

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	14-05-2019	Our Ref No. D19003178MFSH
Accident Date	12-05-2019	Claim Type. Third Party
Insured Vehicle	SHD4966X	Third Party Vehicle. SJT9837U
Survey Location	BLK 3022A UBI ROAD #01-45/46	
Contact Person.	PEI WEN NG	
Contact No.	67415336/ 0	Fax No. 67417208
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PROGRESSIVE CAR CARE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Thursday, 16 May 2019 11:49 AM
To: Admin-D (LKKAUTO); 'CWS Motor Claims'; assignments
Cc: 'Karen Tan'; SUR
Subject: RE: SURVEY ASSESSMENT - D19003178MFSH/1
Attachments: PRELI ADVISED SJT 9837U.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SJT 9837U**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 14 May 2019 5:52 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19003178MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that repairer agreed survey on 15/05/2019.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 14 May 2019 4:53 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19003178MFSH/1



Why pay more? Save with Independent Specialists!
 Find the independent speciality workshops for your Car Make and enjoy great savings.



Hyundai Avante

Price Range

Depreciation

2009

Vehicle Type

Submit

Advanced Search

Home » Used Cars » Wheels Singapore Pte Ltd » Hyundai Avante 1.6A S Sunroof

Hyundai Avante 1.6A S Sunroof

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

PREMIUM AD

Price \$11,888

Depreciation N.A.

Reg Date 28-Oct-2009
(5mths 12days COE left)

Mileage 129,563 km (13.6k /yr)

Manufactured 2009

Road Tax \$738 /yr

Transmission Auto

Dereg Value \$5,627 as of today (change)

OMV \$11,254

COE N.A.

ARF \$11,254

Engine Cap 1,591 cc

Power 89.7 kW (120 bhp)

Curb Weight 1,264 kg

No. of Owners 2

Type of Vehicle Mid-Sized Sedan

Features

Served Him Well Throughout The Years Problem Free. Much Has Been Spent On Maintenance And Owner Wash The Car Himself Every Sunday. Very Reluctant Sale View specs of the Hyundai Avante (2007-2011)

Accessories

Regularly Serviced And If Workshop Finds Anything That Requires Doing, He Will Do Without A 2nd Thought. Talk About Commitment!

Description

Price Dropped! Sunroof S Model, Owner Seldom Drive Now That He Has Shifted To His New House, MRT Downstairs Only, Direct To His Workplace 5 MRT Stops Away! Superbly Well Kept, Owner Spared No Expense In Upkeeping His Baby. Reluctant Sale, Best Kept And Clean Avante In Singapore, I Believe! Come And Buy Today, When COE Drops At Year End, Renew The COE! Call For Appt, View At Owner's House At MSCP.

Category

PARF Car, Premium Ad Car

Status

Available

Resources



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Location Map

Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

Company	Wheels Singapore Pte Ltd	
	* dealer's pricelist	
	* 87 vehs sold 52 vehs available	
Address	10 Kaki Bukit Road 2 #01-30	
	Search cars nearby this location	
Location	First East Centre	
Office No	66815662	
Contact Person(s)	Jacson	87881825
	Mr Ng	86857799

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 8152F

Vehicle Details

Vehicle No.: SJT9837U

Vehicle to be Exported: No

Intended Deregistration Date: 15 May 2019

Vehicle Make: HYUNDAI

Vehicle Model: AVANTE 1.6 AT ABS D/AB 2WD 4DR

Primary Colour: Red

Manufacturing Year: 2009

Engine No.: G4FC9U747011

Chassis No.: KMH DU41BMAU893771

Maximum Power Output: 89.7 kW (120 bhp)

Open Market Value: \$11,465.00

Original Registration Date: 12 Nov 2009

First Registration Date: 12 Nov 2009

Transfer Count: 1

Actual ARF Paid: \$11,465.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 11 Nov 2019

PARF Rebate Amount: \$5,732.00

Intended COE Rebate Details

COE Expiry Date: 11 Nov 2019

COE Category: A - Car (1600cc & below)

COE Period(Years): 10

QP Paid: \$16,747.00

COE Rebate Amount: \$820.00

Total Rebate Amount: \$6,552.00

The information contained herein is correct as at 15 May 2019

OK

Supplementary information submitted to Traffic Police.

Thank you

Your feedback will be valuable input which we can use to constantly improve our range of services.

Our officers will be in contact with you should you expect a reply from us.

Reference Number: SR/20190513/6020



Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST: 201006949C RCB NO: 201006949C

M/S : LAU WAI KEAT
BLK 635 BEDOK RESERVOIR ROAD #10-21
SINGAPORE 410635

ATTN: FIRST CAPITAL

Your Ref No: TP 0519-5523
Claim Type: Third Party
Accident Date: 12/05/2019
TP Veh Reg No: SHD 4966 X

Estimate No: EST1504867
Date: 13 May 2019
Policy No: MT/00555704
Veh Reg No: SJT9837U
Make/Model: HYUNDAI AVANTE 1.6
AT ABS D/AB 2WD 4DR
Chassis No: KMHDU41BMAU893771
Engine No: G4FC9U747011
Reg. Date: 12/11/2009

Estimate Repair Cost to Vehicle No :SJT9837U

Description	U/Price	Quantity	Price	Amount
			SS	SS
List Price				
1 FRONT BUMPER	461.4000	1 PC	Das 461.40	---
2 FRONT BUMPER CLIPS	3.0000	10 PC	nee 30.00	---
3 FRONT BUMPER SIDE HOLDER - LH	18.7000	1 PC	sup 18.70	---
4 FRONT BUMPER SIDE HOLDER - RH	18.7000	1 PC	st 18.70	---
5 FRONT BUMPER FOAM	113.4000	1 PC	Ton 113.40	---
6 FRONT BUMPER REINFORCEMENT	254.0000	1 PC	sup 254.00	---
7 FRONT BUMPER CENTRE LOWER GRILLE	47.0000	1 PCS	De 47.00	---
8 FRONT BUMPER FOG LAMP - LH	141.7000	1 PC	cm 141.70	---
9 FRONT BUMPER FOG LAMP - RH	141.7000	1 PC	17 141.70	X
10 GRILLE ASSY	73.0000	1 PCS	Cno 73.00	---
11 GRILLE LOGO	23.3000	1 PCS	12c 23.30	---
12 GRILLE CLIPS	3.0000	10 PCS	17 30.00	X
13 GRILLE TOP CHROME	51.0000	1 PCS	scr 51.00	---
14 HEADLAMP - RH	480.0000	1 PCS	17 480.00	X
15 HEADLAMP LOWER RETAINER - RH	29.8000	1 PCS	17 29.80	X
16 HEADLAMP - LH	480.0000	1 PCS	Cno 480.00	---
17 HEADLAMP LOWER RETAINER - LH	29.8000	1 PCS	scr 29.80	---
18 SUPPORT PANEL ASSY W/BRACE PANEL	791.3000	1 PCS	sup/cro 791.30	---
19 BONNET	1,885.600	1 PC	Buc 1,885.60	---
20 BONNET LOCK	44.8000	1 PC	ton 44.80	---
21 BONNET HINGE - LH	55.7000	1 PC	17 55.70	X
22 BONNET HINGE - RH	55.7000	1 PC	17 55.70	X
23 BONNET INSULATOR	230.1000	1 PC	17 230.10	X
24 BONNET INSULATOR CLIPS	3.0000	12 PC	17 36.00	X
25 BONNET RUBBER	15.0000	1 PC	ner 15.00	---
26 FRONT FENDER - LH	521.2000	1 PC	3rd/3rd 521.20	---
27 FRONT FENDER VVT WORDING - LH	18.2000	1 PCS	un 18.20	---
28 FRONT FENDER COWLING - LH	48.0000	1 PC	17 48.00	X
29 FRONT FENDER COWLING CLIPS - RH/LH	3.0000	20 PC	17 60.00	X
30 RADIATOR	588.7000	1 PC	Pur 588.70	---
31 CONDENSER	990.9000	1 PC	Al/Pur 990.90	---
32 GRILLE MOUNTING - LH (1ST)	39.5800	1 PCS	17 39.58	X
33 GRILLE MOUNTING - RH (1ST)	39.8000	1 PCS	17 39.80	X
34 GRILLE MOUNTING - LH (2ND)	39.8000	1 PCS	17 39.80	X
35 GRILLE MOUNTING - RH (2ND)	39.8000	1 PCS	17 39.80	X
36 GRILLE MOUNTING LOWER	47.5000	1 PCS	17 47.50	X

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

Estimate No:	EST1504867
Date:	13 May 2019
Policy No:	MT/00555704
Veh Reg No:	SJT9837U
Make/Model:	HYUNDAI AVANTE 1.6 AT ABS D/AB 2WD 4DR
Chassis No:	KMH DU41BMAU893771
Engine No:	G4FC9U747011
Reg. Date:	12/11/2009



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19008589/Utd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 21-05-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 4966X	Veh. Inspected	SJT 9837U	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19003178MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	14/05/2019	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI AVANTE (A)	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	KMH DU41BMAU893771	Colour	RED	
Odometer	146611	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	PIRELLI	6 mm	
L/H Front Tyre	205/55 R16	PIRELLI	6 mm	
R/H Rear Tyre	205/55 R16	PIRELLI	6 mm	
L/H Rear Tyre	205/55 R16	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/05/2019	Inspection Date	15/05/2019	
Survey held at	PROGRESSIVE CAR CARE PTE LTD BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJT 9837U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	DISTORTED	461.40	461.40
10	FRONT BUMPER CLIPS @\$3.00	NECESSARY	30.00	30.00
1	FRONT BUMPER SIDE HOLDER-LH	BENT	18.70	18.70
1	FRONT BUMPER SIDE HOLDER-RH	BENT	18.70	18.70
1	FRONT BUMPER FOAM	TORN	113.40	113.40
1	FRONT BUMPER REINFORCEMENT	BENT	254.00	254.00
1	FRONT BUMPER CENTRE LOWER GRILLE	DEFORMED	47.00	47.00
1	FRONT BUMPER FOG LAMP-LH	CRACKED	141.70	141.70
1	FRONT BUMPER FOG LAMP-RH	NOT NECESSARY	141.70	-
1	GRILLE ASSY	CRACKED	73.00	73.00
1	GRILLE LOGO	NECESSARY	23.30	23.30
10	GRILLE CLIPS @\$3.00	NOT NECESSARY	30.00	-
1	GRILLE TOP CHROME	SCRATCHED	51.00	51.00
1	HEADLAMP-RH	NOT NECESSARY	480.00	-
1	HEADLAMP LOWER RETAINER-RH	NOT NECESSARY	29.80	-
1	HEADLAMP-LH	CRACKED	480.00	480.00
1	HEADLAMP LOWER RETAINER-LH	BENT	29.80	29.80
1	SUPPORT PANEL ASSY W/BRACE PANEL	BUCKLED / CRACKED	791.30	791.30
1	BONNET	BUCKLED	1,885.60	1,885.60
1	BONNET LOCK	TWISTED	44.80	44.80
1	BONNET HINGE-LH	TO REPAIR SEE LABOUR	55.70	-
1	BONNET HINGE-RH	TO REPAIR SEE LABOUR	55.70	-
1	BONNET INSULATOR	NOT NECESSARY	230.10	-
12	BONNET INSULATOR CLIPS @\$3.00	NOT NECESSARY	36.00	-
1	BONNET RUBBER	NECESSARY	15.00	15.00
1	FRONT FENDER-LH	BENT / BUCKLED	521.20	521.20
1	FRONT FENDER VVT WORDING-LH	NECESSARY	18.20	18.20
1	FRONT FENDER COWLING-LH	NOT NECESSARY	48.00	-
20	FRONT FENDER COWLING CLIPS-RH/LH @\$3.00	NOT NECESSARY	60.00	-

Report Ref No. CS/FCI19008589/Utd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RADIATOR	PUNCTURE	588.70	588.70
1	CONDENSER	BENT / PUNCTURE	990.90	990.90
1	GRILLE MOUNTING-LH (1ST)	NOT NECESSARY	39.58	-
1	GRILLE MOUNTING-RH (1ST)	NOT NECESSARY	39.80	-
1	GRILLE MOUNTING-LH (2ND)	NOT NECESSARY	39.80	-
1	GRILLE MOUNTING-RH (2ND)	NOT NECESSARY	39.80	-
1	GRILLE MOUNTING LOWER	NOT NECESSARY	47.50	-
	LESS 20% DISCOUNT		-1,594.24	-1,319.54
			6,376.94	5,278.16
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE WITH CASING (SN)	DAMAGED	35.00	35.00
1	LIT COOLANT (SN)	NECESSARY	20.00	20.00
			55.00	55.00
	<u>LABOUR</u>			
	TO KNOCK OUT DENTS,CUT/WELD,SUPPORT PANEL,REMOVE,REPLACE ACCIDENT PARTS.INCLUSIVE OF THE REPAIR OF BONNET HINGE-LH AND BONNET HINGE-RH.		900.00	800.00
	TO RESPRAY PAINT ON ACCIDENT PORTIONS.		900.00	850.00
	TO CHECK WIRING.		20.00	20.00
	TO REMOVE,REPLACE CONDENSER AND REFILL GAS.		100.00	100.00
	TO TUFF-KOTE.		100.00	30.00
			2,020.00	1,800.00
	GRAND TOTAL		8,451.94	7,133.16
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,400.00

Report Ref No. CS/FC19008589/Utd3n2

MARKET VALUE: \$11,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$6,552.00=NETT VALUE: \$4,448.00

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.