

ASS. REC. BY:

REF: CS/TM1190085961 Dvd3n2 Special Instruction:

Survivor: Bryan

## ASSIGNMENT (Office)

From (Person): Jeffrey Tay of TM1 Date/Time: 15.5.19 12.04 p.m.

Estimated Cost: Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHB 4449H Insured: XD 7542B

at Workshop m/s Chinni Motor work Tel: 64836016

of Bk10 # 01-05/06 AMT Autopoint

Policy No: ME 000845 Claim No: M1903386

Sum Insured: Excess:

Make of Veh: D.O.A. 8/5/2019  
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 15.5.19 12.57pm Person Contacted: Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHB 4449H - CS/MSG 17621212/KRBE2
	XD 7542B - X

05/10/14

REF:

Summer

## ASSIGNMENT

CBE March 2024

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs: 13 # days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHB 4449 H

Yr Regn:

2016 March

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai I40

C.C

1685

Colour:

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

447349

T/Radio: Insured / Std / NI / NA

Eng/No:

D4FDFU605718

C/No:

KMHLB41UMGU086646

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60 R16

R:

— 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

P/Bal.

S

mm

R/Bal.

S

mm

L/Bal.

S

mm

L/Bal.

S

mm

D.O.A.

08/15/2019

D.O.L

16/05/2019

Survey held at

Chunni AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

0/8 Rev y 0/3 Body y 0/3 Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Tokio XD 7542B

03/07/19

Jinayn 2/5 13500/- - 13 days 2/19

(Red 11, 479-12, 469)

RECEIVED 04 JUL 2019

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2) 4/7 - typist

Report Format :

merimen

Lump Sum / I.B.I: (\$

13,500/-)

Days Of Repair:

13

Resurvey No. of Trip:

2

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation,

S + RS, \$

Photos

Others

TOTAL

550  
11

561

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 May 2019		15 May 2019 12:04 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

## CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	RONG DE LOGISTIC PTE LTD, Co. Reg. No.: 200009392E		
Main Claimant:	COMFORT TRNSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Vehicle Reg. No.:	SHB4449H	Date of Loss:	08/05/2019 18:00 - :59
Claim Type:	TP / M1903386	Policy/Cover Note No.:	ME000845 (Comprehensive) Coverage: 26/08/2018 - 25/08/2019
Vehicle Reg. No. (Insured):	XD7542B	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Chunni Motor Work Pte Ltd - Amk (HQ) Blk 10 #01-05/06, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64836016		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Jeffrey Tay - 65926413]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 27/05/2019]		
Driver/Custodian (Insured):	NG CHEE LEONG (), NRIC: S1371210G, Tel: +6596384927 Email:		

## ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.



## ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

MCD619062484 / ComfortDolGro Engineering Pte Ltd - Layan  
 ENTRY DATE & TIME: 14/05/2019 12:00  
 SUBMITTED BY: Huang XiaoYan

Your NCD will be affected due to late reporting  
 Actual e-Filing Submission Date & Time: 14/05/2019 12:12

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date Of Report 14/05/2019 12:00  
 Date Of Accident 08/05/2019 18:30  
 Exact Location Of Accident PIONEER ROAD TWDS TUAS  
 Country/State of Loss SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number SHB4449H  
 Insured/Policyholder  
 Name Of Registered Owner COMFORT TRANSPORTATION PTE LTD  
 Co Reg No 199303821R  
 Email Address FLEETSAFETY@CDGTAXI.COM.SG  
 Mobile Phone No  
 Alternative Phone No OFFICE-65508768  
 Vehicle Particulars  
 Manufacturer HYUNDAI  
 Model I40  
 Exact Purpose for which vehicle was being used at time of accident  
 Are you claiming under your own insurance policy for repair to your vehicle? NO  
 If No, Please state action to be taken THIRD PARTY  
 Vehicle Category TAXI  
 Insurance Company  
 Name of Insurance Company MS FIRST CAPITAL INSURANCE LTD  
 Type Of Coverage THIRD PARTY FIRE AND/OR THEFT  
 Fleet Policy YES  
 Policy Number D-18088936MFSH  
 Cover Note Number  
 Driver  
 Name of Driver NG BENG KIM PETER  
 NRIC No S0227318G  
 Date Of Birth 02/03/1954  
 Occupation OUTDOOR  
 Date Of Driving Pass 09/07/1974  
 Driving Experience 44 YEARS AND 9 MONTHS  
 Gender MALE  
 Mobile Number (LOCAL) +65-97544524  
 Fax Number  
 Contact Number  
 Email Address NOEMAIL

Address BLK 531 BUKIT BATOK STREET 51 #07-138  
 Postcode 650531  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident SIDE SWIPE  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) involved in the accident 2  
 Was any body injured in the Accident? YES  
 Was any injured conveyed to hospital by ambulance? YES  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? YES  
 If Yes, Please state which Police Station  
 POLICE STATION NAME [OTHER] BUKIT BATOK N.P.C  
 Was notice of Intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

PLS REFER TO ATTACHED / POLICE REPORT : T/20190509/2018

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? YES  
 Remarks/ Reasons: -  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number XD7542B  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category COMMERCIAL VEHICLE  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name TOKIO MARINE INSURANCE SINGAPORE LTD  
 Nature Of Damage FRT LEFT  
 No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name	NG BENG KIM PETER
Approximate Age	
Injuries Sustain	NECK, SHOULDER AND BACK PAIN. ON 4 DAYS MC.
Injured person in which vehicle?	SHB4449H
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

**SKETCH PLAN****IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(Including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 10.05.2019  
@ 1600 hrs

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



Along Pioneer Road-TWDS Tuas

[illegible]

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

Date &amp; Time:

(If driver is not the policyholder)

Date & Time: 10.05.2019  
@ 1600 hrs

Name:

NRIC/FIN No.:





# SINGAPORE POLICE FORCE



T/20190509/2018

1 of 3

Police Station Of Origin:  
Bukit Batok N.P.C  
21 Bukit Batok East Avenue 4 SINGAPORE  
659840  
Tel No: 1800-6659999

Report No. T/20190509/2018

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 09/05/2019 03:52	Vide Report No.:	Station Diary No.: 23
--	------------------	--------------------------

## Informant's Particulars

Name of Informant: NG BENG KIM			Address: APT BLK 531 BUKIT BATOK STREET 51 #07-138 SINGAPORE 650531		
ID Type / ID No.: NRIC NO / S0227318G			Contact No.: Home/Office:		

## General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 08/05/2019 18:30	Type of Location: Straight Road
Location: Along Road 1 PIONEER ROAD				
Pioneer Road towards Tuas after Pioneer Crescent				
Weather: Cloudy		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: No Traffic
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

## Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHB4449H	Car	HYUNDAI	i40	Blue	Seriously Damaged	0

## Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

**SINGAPORE  
POLICE FORCE**

T/20190509/2018

2 of 3

Police Station Of Origin:  
Bukit Batok N.P.C  
21 Bukit Batok East Avenue 4 SINGAPORE  
659840  
Tel No: 1800-6659999

Report No. T/20190509/2018

## CONTINUATION OF REPORT

Driver			
Name	NG BENG KIM	ID No.	S0227318G
Related Vehicle	SHB4449H (Car)	Contact No.	97544524
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	08/05/2019	Date Discharge	08/05/2019
No. of Days granted Medical Leave	04	Degree of Injury	Slight

**Brief Details.**

On 08/05/2019 at about 1830hrs, I was driving my vehicle, a blue color comfort taxi, Hyundai i40 along Pioneer road towards Tuas. Just after Pioneer Crescent, my vehicle was rear end by a lorry trailer which I recall is blue in color.

My vehicle was pushed from the rear till it skidded to the right. The end result, the driver side of my car was being push by the front of the lorry trailer. When the ambulance came, the truck was directed to be reversed. I was helped by the paramedics to exit from my vehicle. I was then conveyed straight away to Ng Teng Fong Hospital. Traffic Police was at scene too.

I was subsequently given 4 days of MC from 08/05/2019 to 11/05/2019. I sustained muscle strain on the right side of my neck area. My hospital treatment bill added up to S\$120/-/

**SINGAPORE  
POLICE FORCE**

T/20190509/2018

3 of 3

Report No. T/20190509/2018

Police Station Of Origin:

Bukit Batok N.P.C

21 Bukit Batok East Avenue 4 SINGAPORE  
659840

Tel No: 1800-6659999

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /

Sgt 3 MUHAMMAD AMIRUL HASIF BIN  
MOHAMED YUNOS

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /

Staff Sgt MOHAMED HUSNUL TAUFIQ BIN MD  
SOF

Contact No.: 65476358

SN 114

Authentication Stamp

Signature Of Informant:

Date/Time:

09/05/2019 03:52

Classification Of Case:

Singapore Police Force

Officer- In -Charge  
Investigation Section  
Traffic Police  
No. 10 Ubi Avenue 3  
Singapore 408865

Name : Ng Beng Kim  
NRIC :S0227318G  
Address:Blk 53 Bt Batok St 51  
#07-138  
Singapore ( 650531 )  
Tel : 97544524


**TRAFFIC ACCIDENT AMMENDMENT REPORT**


ACCIDENT INVOLVING SHB4449H and XD7542B

ALONG Pioneer road towards Tuas after Pioneer Crescent  
ON 08/05/2019 @ 1830hrs

With reference to the above, I have on 010/02/2019 (date) at 1513hrs (time)  
make a Traffic accident amendment police report at Tampines North NPP (Name of  
police station / NPP) vide T/20190509/2018.

I would just like to add that the other vehicle involved is XD7542B

  
Signature

If a police officer records this amendment, please complete the following;	
Name / Rank No:Ssgt T02016 Abdul Ghani	Station Diary No. 11
Signature 	

**Tampines North NPP**  
Block 461 Tampines St 44  
#01-56 Singapore 52046  
Tel: 1800-7818999

**CHUNNI MOTOR WORK PTE LTD****REPAIR ESTIMATE\***

To Survey by (Kk)

VEHICLE NO : SHB 4449H

DATE : 13.05.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

Tokio Marine

MODEL : HYUNDAI I40		FAX : 0342 603		CITY : MARRAKECH	
Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Fender (RH) <i>Dented</i>			\$	663.00
	Front Fender Apron Panel (RH) <i>NH</i>			\$	637.00
	Front Fender Shield (RH) <i>NH</i>			\$	174.90
	Rear Bumper <i>ent / NH</i>			\$	553.00
	Rear Bumper Clip 10 pcs <i>Nec</i>			\$	22.00
	Rear Fender With Housing (RH) <i>Buc</i>			\$	4,736.90
	Rear Fender Inner Lining (RH) <i>distorted</i>			\$	169.30
	Rear Windscreen Moulding <i>Nec</i>			\$	28.30
	Rear Door (RH) <i>Buc</i>			\$	2,201.10
	Rear Door Rubber (RH) <i>distorted</i>			\$	280.50
	Rear Door Gear/Regulator (RH) <i>NH</i>			\$	242.80
	Rear Door Power Motor (RH) <i>NH</i>			\$	158.60
	Rear Door Hinge Upper (RH) <i>NH</i>			\$	45.90
	Rear Door Hinge Lower (RH) <i>NH</i>			\$	45.90
	Rear Door Check (RH) <i>NH</i>			\$	62.90
	Rear Door Trim Board (RH) <i>NH</i>			\$	808.70
	Front Door (RH) <i>Dented</i>			\$	2,256.40
	Front Door Gear / Regulator (RH) <i>NH</i>			\$	250.60
	Front Door Hinge Upper (RH) <i>NH</i>			\$	36.10
	Front Door Hinge Lower (RH) <i>NH</i>			\$	36.10
	Front Door Check (RH) <i>NH</i>			\$	39.20
	Front Door Mirror Assy (RH) <i>broken</i>			\$	670.00
	Front Door Power Motor, RH <i>NH</i>			\$	296.40
	Front Door Trim Board (RH) <i>NH</i>			\$	973.50
	Door Centre Pillar Outer (RH) <i>Dented</i>			\$	2,527.80
	Rocker Panel Outer Garnish (RH) <i>broken / ent</i>			\$	341.40
	Rear Tyre Rim (RH) <i>NH</i>			\$	325.30
	Rear Wheel Hub-Cap (RH) <i>ent</i>			\$	107.10
	Rear Wheelbearing IN & Hub <i>&amp; Dam</i>			\$	362.00
	Rear Trailing Arm (RH) <i>&amp; distorted</i>			\$	192.00
	Rear Assist (RH) <i>&amp; distorted</i>			\$	145.70
	Rear Shock Absorber (RH) <i>&amp; distorted</i>			\$	276.30
	Rear Shock Absorber Mounting (RH) <i>NH</i>			\$	81.30
	Rear Crossmember <i>NH</i>			\$	1,021.50
	Stabilizer Bar <i>NH</i>			\$	199.60
	Stabilizer Link <i>NH</i>			\$	85.90
	Rear Upper Arm (RH) <i>&amp; distorted</i>			\$	335.75
	Rear Lower Arm (RH) <i>&amp; distorted</i>			\$	353.80
	Rear Knuckle Arm (RH) <i>&amp; distorted</i>			\$	545.60
			16767.95		
			1341436		
	SUB TOTAL			\$	22,290.15
	LESS 20%			\$	4,458.03
	DISCOUNTED TOTAL			\$	17,832.12

SEB 4449H

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper Rubber Mat N/C			\$ 50.00
	Rear Windscreen Sealant N/C			\$ 46.00
	Rear Door Comfortdelgro & Apps Sticker (RH) N/C			\$ 80.00
	Front Door Coloured Comfort Logo (RH) N/C			\$ 75.00
	Front Door Advertisement Logo (RH) N/C			\$ 100.00
	Rear Tyre (RH) N/A		351.00	\$ 216.00
				<b>\$ 567.00</b>
	<b>Labour Charge</b>			
	Panel Beating			\$ 2,500.00
	Spray Painting Charge			\$ 1,200.00
	Wiring Charge			\$ 100.00
	Tuff Kote			\$ 100.00
	Towing Charge			\$ 50.00
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00
	Remove/Refix Rear Windscreen Glass			\$ 120.00
	Remove/Refix Reverse Sensor			\$ 120.00
	Transfer of Door	\$ 120.00		\$ 240.00
	Remove/Refix Undercarriage (RR)			\$ 200.00
	Rear Wheel Alignment	320.00		\$ 120.00
	Re-set Rear ABS System			\$ 200.00
	Re-set Frt & Rear Power Window System	\$ 200.00		\$ 400.00
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00
	<b>TOTAL LABOUR</b>			<b>\$ 6,580.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 24,979.12</b>
	16/05/2019 @ 0900am N/A Andrew 2pm 13 days Ryan J KK Auto		1688536 4/5 13500/-	
			LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company  Acknowledged by Repairer Signature:	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAME  
ADDRESS

Home Tel.:

VIN:

Registration: SHB 4449 H

Technician:

Mileage: 447349

Time Printed 16.5.19 9:40 AM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
-0°37'		-3°00' 3°00'
4°17'		-0°19' 5°41'
0°29'		-1°30' 1°30'
14°27'		
13°50'		

Camber  
Caster  
Toe  
SAI  
Included Angle  
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
-0°32'		-3°00' 3°00'
4°02'		-0°19' 5°41'
-3°50'		-1°30' 1°30'
18°20'		
17°48'		

Front

Cross Camber  
Cross Caster  
Cross SAI  
Total Toe  
Cross Turn Diff.

Actual	BEFORE	Specified Range
-0°05'		-3°00' 3°00'
0°15'		-3°00' 3°00'
-3°53'		-3°00' 3°00'
-3°21'		-3°00' 3°00'

Rear : Left

Actual	BEFORE	Specified Range
-2°01'		-3°30' 2°30'
0°09'		-1°30' 1°30'

Camber  
Toe

Rear : Right

Actual	BEFORE	Specified Range
-1°59'		-3°30' 2°30'
3°11'		-1°30' 1°30'

Rear

Cross Camber  
Total Toe  
Thrust Angle

Actual	BEFORE	Specified Range
-0°02'		-3°00' 3°00'
3°20'		-3°00' 3°00'
-1°31'		-3°00' 3°00'



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI19008596/DVD3N2

Date: 11/07/2019

## REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	ME000845
Claimant Vehicle No :	SHB4449H	Insured Vehicle No :	XD7542B
Date of Loss:	08/05/2019	Nature of Claim:	TP
		Claim No:	M1903386

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SHB4449H		
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Engine No:	D4DFDU605718
Reg. Date:	24/03/2016 (Man. Year: 2015)	Chassis No:	KMHLB41UMGU086646
Colour:	Blue	Odometer:	447349 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	18,399.12	13,765.36	4,633.76	25.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,580.00	3,120.00	3,460.00	52.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>24,979.12</b>	<b>16,885.36</b>	<b>8,093.76</b>	<b>32.40</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>13,500.00</b>		
<b>(S\$)</b>	<b>24,979.12</b>	<b>13,500.00</b>	<b>11,479.12</b>	<b>45.95</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,748.54</b>	<b>945.00</b>	<b>803.54</b>	<b>45.95</b>
<b>Nett Amount (S\$)</b>	<b>26,727.66</b>	<b>14,445.00</b>	<b>12,282.66</b>	<b>45.95</b>

## INSPECTION

Date of Assignment:	15/05/2019	
Date Inspected:	16/05/2019	Inspected At: Chunni Motor Work Pte Ltd - Amk (HQ) Blk 10 #01-05/06, AMK Autopoint Singapore 568047
Estimated Period of Repair:	13.0 days	

Adjuster: BRYAN TANI

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

*knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 11 Jul 2019)
<b>Parts:</b>	143	HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHB4449H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER (RH)	Dented	663.00 FL	*663.00 FL
2	1		*FRONT FENDER APRON PANEL (RH)	Not Necessary	637.00 FL	*- FL
3	1		*FRONT FENDER SHIELD (RH)	Not Necessary	174.90 FL	*- FL
4	1		*REAR BUMPER	Cut/Bent	553.00 FL	*553.00 FL
5	10		*REAR BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
6	1		*REAR FENDER WITH HOUSING (RH)	Buckled	4,736.90 FL	*4,736.90 FL
7	1		*REAR FENDER INNER LINING (RH)	Deformed	169.30 FL	*169.30 FL
8	1		*REAR WINDSCREEN MOULDING	Necessary	28.30 FL	*28.30 FL
9	1		*REAR DOOR (RH)	Buckled	2,201.10 FL	*2,201.10 FL
10	1		*REAR DOOR RUBBER (RH)	Deformed	280.50 FL	*280.50 FL
11	1		*REAR DOOR GEAR/REGULATOR (RH)	Not Necessary	242.80 FL	*- FL
12	1		*REAR DOOR POWER MOTOR (RH)	Not Necessary	158.60 FL	*- FL
13	1		*REAR DOOR HINGE UPPER (RH)	Not Necessary	45.90 FL	*- FL
14	1		*REAR DOOR HINGE LOWER (RH)	Not Necessary	45.90 FL	*- FL
15	1		*REAR DOOR CHECK (RH)	Not Necessary	62.90 FL	*- FL
16	1		*REAR DOOR TRIM BOARD (RH)	Not Necessary	808.70 FL	*- FL
17	1		*FRONT DOOR (RH)	Dented	2,256.40 FL	*2,256.40 FL
18	1		*FRONT DOOR GEAR/REGULATOR (RH)	Not Necessary	250.60 FL	*- FL
19	1		*FRONT DOOR HINGE UPPER (RH)	Not Necessary	36.10 FL	*- FL
20	1		*FRONT DOOR HINGE LOWER (RH)	Not Necessary	36.10 FL	*- FL
21	1		*FRONT DOOR CHECK (RH)	Not Necessary	39.20 FL	*- FL
22	1		*FRONT DOOR MIRROR ASSY (RH)	Broken	670.00 FL	*670.00 FL
23	1		*FRONT DOOR POWER MOTOR,RH	Not Necessary	296.40 FL	*- FL
24	1		*FRONT DOOR TRIM BOARD (RH)	Not Necessary	973.50 FL	*- FL
25	1		*DOOR CENTRE PILLAR OUTER (RH)	Dented	2,527.80 FL	*2,527.80 FL
26	1		*ROCKER PANEL OUTER GARNISH (RH)	Broken/Cut	341.40 FL	*341.40 FL
27	1		*REAR TYRE RIM (RH)	Not Necessary	325.30 FL	*- FL
28	1		*REAR WHEEL HUP-CAP (RH)	Cut	107.10 FL	*107.10 FL
29	1		*REAR WHEELBEARING ING & HUB	Damaged	362.00 FL	*362.00 FL
30	1		*REAR TRAILING ARM (RH)	Distorted	192.00 FL	*192.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
31	1		*REAR ASSIST (RH)	Distorted	145.70 FL	*145.70 FL
32	1		*REAR SHOCK ABSORBER (RH)	Distorted	276.30 FL	*276.30 FL
33	1		*REAR SHOCK ABSORBER MOUNTING (RH)	Not Necessary	81.30 FL	*- FL
34	1		*REAR CROSSMEMBER	Not Necessary	1,021.50 FL	*- FL
35	1		*STABILIZER BAR	Not Necessary	199.60 FL	*- FL
36	1		*STABILIZER LINK	Not Necessary	85.90 FL	*- FL
37	1		*REAR UPPER ARM (RH)	Distorted	335.75 FL	*335.75 FL
38	1		*REAR LOWER ARM (RH)	Distorted	353.80 FL	*353.80 FL
39	1		*REAR KNUCKLE ARM (RH)	Distorted	545.60 FL	*545.60 FL
40	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 FS	*50.00 FS
41	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS
42	1		*REAR DOOR COMFORTDELGRO & APPS STICKER (RH)	Necessary	80.00 FS	*80.00 FS
43	1		*FRONT DOOR COLOURED COMFORT LOGO (RH)	Necessary	75.00 FS	*75.00 FS
44	1		*FRONT DOOR ADVERTISEMENT LOGO (RH)	Necessary	100.00 FS	*100.00 FS
45	1		*REAR TYRE (RH)	Not Necessary	216.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>22,857.15</b>	<b>17,118.95</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>4,458.03</b>	<b>3,353.59</b>
<b>Total Parts (\$\$)</b>	<b>18,399.12</b>	<b>13,765.36</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	2,500.00	1,200.00
2	SPRAY PAINTING CHARGE	New	1,800.00	1,200.00
3	WIRING CHARGE	New	100.00	0.00
4	TUFF KOTE	New	100.00	40.00
5	TOWING CHARGE	New	50.00	0.00
6	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
7	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	80.00
8	REMOVE/REFIX REVERSE SENSOR	New	120.00	40.00
9	TRANSFER OF DOOR	New	240.00	120.00
10	REMOVE/REFIX UNDERCARRIAGE (RR)	New	200.00	150.00
11	REAR WHEEL ALIGNMENT	New	120.00	60.00
12	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE }	New	480.00	150.00
13	RE-SET REAR ABS SYSTEM }	New	200.00	0.00
14	RE-SET FRT & REAR POWER WINDOW SYSTEM }	New	400.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>6,580.00</b>	<b>3,120.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >