

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Mega@Woodlands, 39 Woodlands Close #01-12

Singapore 737856

Tel: 62562281 Fax: Email: YTMG

INSURER : EQ INSURANCE COMPANY LTD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	YTMG/TP/1905/004
Policy No:	5070638368-04	Date of Loss:	06/05/2019
Vehicle Reg. No.:	GBD6352A	Driveable?	no
Driver Age:		Third Party Vehicle No.:	GZ565S , GBE515G
Any Injuries?	no	Contact No:	62590423
Insured/Claimant:	POWER SOLUTION ELECTRICAL ENGINEERING PTE LTD	Driver:	CHIN KENG HANG

Make/Model:	Nissan, Urvan	Vehicle Reg. Date:	19/01/2005
Vehicle Colour:	GREY	Engine Number:	ZD30045760
Chassis No:	JN1MG4E25Z0712478	Odometer:	
Total Loss?	NO	Est. Duration of Repair(Day)	

Description of Accident/loss COLLISION - MAJOR/MINOR RD
 Remarks:
 Present Location: Yew Tee Automobile Tech Pte Ltd (Mega)-YTMG

COST OF CLAIMS

	Amount
Parts	16,920.74
Miscellaneous Items	775.00
Labour	3,420.00
Paintwork Labour	2,185.00
Towing	0.00
Gross Total(S\$):	23,300.74
GST 7.00%(S\$):	1,631.05
Nett Amount(S\$):	24,931.79

This claim is handled by: Lai Yee Meng

REPAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	FRONT BUMPER DEF /	0.00	622.80	-30.00	435.96
2	1	FRONT BUMPER BRACKET LH nnc /	0.00	104.70	-10.00	94.23
3	1	FRONT BUMPER BRACKET RH nnc	0.00	104.70	-10.00	94.23
4	1	FRONT BUMPER FOG LAMP LH mis /	0.00	258.00	-10.00	232.20
5	1	FRONT BUMPER FOG LAMP GARNISH LH mis /	0.00	78.60	-10.00	70.74
6	1	FRONT BUMPER REINFORCEMENT BT /	0.00	451.20	-30.00	315.84
7	1	FRONT BUMPER LOWER GRILLE DEF /	0.00	270.00	-10.00	243.00
8	1	FRONT HEADLAMP LH CRA /	0.00	395.50	-10.00	355.95
9	1	FRONT HEADLAMP RH nnc	0.00	395.50	-10.00	355.95
10	1	FRONT SIDE LAMP LH CRA /	0.00	126.10	-10.00	113.49
11	1	FRONT SIDE LAMP RH nnc	0.00	126.10	-10.00	113.49
12	1	FRONT GRILLE nnc	0.00	430.90	-30.00	301.63
13	1	FRONT GRILLE CHROME MOULDING nnc	0.00	0.00	-10.00	0.00
14	1	BONNET nnc	0.00	0.00	0.00	0.00
15	1	FRONT CORNER PANEL LH Buc /	0.00	578.00	-10.00	520.20
16	1	RADIATOR nnc	0.00	761.10	-30.00	532.77
17	1	RADIATOR FAN COWLING nnc	0.00	470.00	-10.00	423.00
18	1	RADIATOR FAN MOTOR nnc	0.00	380.00	-10.00	342.00
19	1	RADIATOR FAN BLADE nnc	0.00	155.00	-10.00	139.50
20	2	RADIATOR BRACKET nnc	0.00	110.00	-10.00	99.00
21	1	FRONT DOOR LH Buc /	0.00	1,116.40	-30.00	781.48
22	2	FRONT DOOR HINGES LH BT /	0.00	136.00	-10.00	122.40
23	1	FRONT DOOR PILLAR LH nnc	0.00	2,236.50	-30.00	1,565.55
24	1	FRONT DOOR INNER BOARD LH DEF /	0.00	755.70	-30.00	528.99
25	1	FRONT DOOR GLASS REGULATOR LH nnc	0.00	203.60	-10.00	183.24
26	1	FRONT DOOR GLASS REGULATOR MOTOR LH nnc	0.00	576.90	-10.00	519.21
27	1	FRONT DOOR LOCK LH Jam /	0.00	310.20	-10.00	279.18
28	1	FRONT DOOR LOCK CATCH LH nnc	0.00	67.60	-10.00	60.84
29	1	FRONT DOOR RUBBER LH nnc	0.00	130.00	-10.00	117.00
30	1	FRONT DOOR GLASS LH CRA /	0.00	716.90	-30.00	501.83
31	1	FRONT DOOR GLASS CHANNEL LH nnc	0.00	122.00	-10.00	109.80
32	1	FRONT DOOR INNER RUBBER LH nnc	0.00	145.00	-10.00	130.50
33	1	FRONT DOOR STEP PANEL LH Buc /	0.00	398.00	-10.00	358.20
34	1	FRONT DOOR STEP GARNISH LH DEF /	0.00	110.00	-10.00	99.00
35	1	FRONT CHASSIS SIDE MEMBER LH Buc /	0.00	581.70	-10.00	523.53
36	1	FRONT CHASSIS MEMBER LH nnc	0.00	2,200.00	-30.00	1,540.00
37	1	FRONT WASHER TANK Buc /	0.00	257.80	-10.00	232.02
38	1	FRONT WASHER TANK MOTOR nnc CRA /	0.00	155.00	-10.00	139.50
39	1	FRONT FENDER LH Repair x	0.00	1,800.00	-30.00	1,260.00
40	1	FRONT WHEEL ARCH INNER PROTECTOR LH nnc	0.00	135.10	-10.00	121.59
41	1	FRONT FENDER INNER SHIELD LH nnc	0.00	247.50	-10.00	222.75
42	1	FRONT UPPER ARM LH nnc	0.00	382.70	-10.00	344.43
43	1	FRONT LOWER ARM LH nnc	0.00	271.40	-10.00	244.26
44	1	FRONT KNUCKLE ARM LH nnc	0.00	342.40	-10.00	308.16
45	1	SLIDING DOOR LH Repair x	0.00	0.00	0.00	0.00
46	1	REAR FENDER LH Repair x	0.00	1,896.70	-30.00	1,327.69
47	1	REAR BUMPER nnc	0.00	683.60	-30.00	478.52
48	1	REAR BUMPER BRACKET LH nnc	0.00	42.10	-10.00	37.89

Total Parts (\$\$)

16,920.74

Estimates of Miscellaneous Items

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	FRONT DOOR INNER BOARD CLIPS <i>rec</i>	0.00	45.00	0.00	45.00 <i>30</i>
2	1	FRONT WHEEL RIM LH <i>Repair x</i>	0.00	550.00	0.00	550.00
3	1	FRONT TYRE (DEPRECIATION) LH <i>nr x</i>	0.00	180.00	0.00	180.00
Sub Total (S\$)						775.00

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	70.00	70.00	0.00	70.00 <i>40</i>
2	1	To Dismantle and Refit Front Undercarriage.	180.00	180.00	0.00	180.00 <i>100</i>
3	1	To Do Up Interior Cleaning and Chemical Wash.	200.00	200.00	0.00	200.00 <i>50</i>
4	1	To Dismantle & Refit Front Dashboard & related wire harness & related parts.	350.00	350.00	0.00	350.00 <i>x</i>
5	1	To Pressure Test Air Con Condenser and Radiator For Leakage.	120.00	120.00	0.00	120.00 <i>40</i>
6	1	To Transfer Sliding Door.	80.00	80.00	0.00	80.00 <i>x</i>
7	1	To Transfer Door.	60.00	60.00	0.00	60.00 <i>50</i>
8	1	To Remove & Refit air-con compressor, air-con motor, condenser, pipes & vacuum, including refilling of gas.	180.00	180.00	0.00	180.00 <i>x</i>
9	1	To Conduct Computer Wheel Alignment.	80.00	80.00	0.00	80.00 <i>160</i>
10	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	2,100.00	2,100.00	0.00	2,100.00 <i>1400</i>

Gross Labour Cost (S\$) 3,420.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	60.00	60.00	0.00	60.00 <i>40</i>
2	1	To Supply Spray Terostat Sealant On The Cutting Areas.	45.00	45.00	0.00	45.00 <i>30</i>
3	1	To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.	80.00	80.00	0.00	80.00 <i>40</i>
4	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	2,000.00	2,000.00	0.00	2,000.00 <i>1300</i>

Gross Labour Cost (S\$) 2,185.00

Total - \$7300

< END OF ESTIMATES >

- LKK Auto Consult is the
the following:
- To resurvey before after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Hwee Jia - LKK

14/5/19

4/5 8days.

[Signature]