

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Mega@Woodlands, 39 Woodlands Close #01-12
Singapore 737856

Tel: 62562281 Fax: Email: YTMG

INSURER : EQ INSURANCE COMPANY LTD

PARTICULARS OF CLAIM

Claim Type:	TP	Ref. No:	YTMG/TP/1905/004
Policy No:	5070638368-04	Date of Loss:	06/05/2019
Vehicle Reg. No.:	GBD6352A	Driveable?	no
Driver Age:		Third Party Vehicle No.:	GZ565S , GBE515G
Any Injuries?	no	Contact No:	62590423
Insured/Claimant:	POWER SOLUTION ELECTRICAL ENGINEERING PTE LTD	Driver:	CHIN KENG HANG
Make/Model:	Nissan, Urvan	Vehicle Reg. Date:	19/01/2005
Vehicle Colour:	GREY	Engine Number:	ZD30045760
Chassis No:	JN1MG4E25Z0712478	Odometer:	
Total Loss?	NO	Est. Duration of Repair(Day)	

Description of Accident/loss COLLISION - MAJOR/MINOR RD
Remarks:
Present Location: Yew Tee Automobile Tech Pte Ltd (Mega)-YTMG

COST OF CLAIMS

	Amount
Parts	16,920.74
Miscellaneous Items	775.00
Labour	3,420.00
Paintwork Labour	2,185.00
Towing	0.00
Gross Total(S\$):	23,300.74
GST 7.00%(S\$):	1,631.05
Nett Amount(S\$):	24,931.79

This claim is handled by: Lai Yee Meng

REPAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	FRONT BUMPER	0.00	622.80	-30.00	435.96
2	1	FRONT BUMPER BRACKET LH	0.00	104.70	-10.00	94.23
3	1	FRONT BUMPER BRACKET RH	0.00	104.70	-10.00	94.23
4	1	FRONT BUMPER FOG LAMP LH	0.00	258.00	-10.00	232.20
5	1	FRONT BUMPER FOG LAMP GARNISH LH	0.00	78.60	-10.00	70.74
6	1	FRONT BUMPER REINFORCEMENT	0.00	451.20	-30.00	315.84
7	1	FRONT BUMPER LOWER GRILLE	0.00	270.00	-10.00	243.00
8	1	FRONT HEADLAMP LH	0.00	395.50	-10.00	355.95
9	1	FRONT HEADLAMP RH	0.00	395.50	-10.00	355.95
10	1	FRONT SIDE LAMP LH	0.00	126.10	-10.00	113.49
11	1	FRONT SIDE LAMP RH	0.00	126.10	-10.00	113.49
12	1	FRONT GRILLE	0.00	430.90	-30.00	301.63
13	1	FRONT GRILLE CHROME MOULDING	0.00	0.00	-10.00	0.00
14	1	BONNET	0.00	0.00	0.00	0.00
15	1	FRONT CORNER PANEL LH	0.00	578.00	-10.00	520.20
16	1	RADIATOR	0.00	761.10	-30.00	532.77
17	1	RADIATOR FAN COWLING	0.00	470.00	-10.00	423.00
18	1	RADIATOR FAN MOTOR	0.00	380.00	-10.00	342.00
19	1	RADIATOR FAN BLADE	0.00	155.00	-10.00	139.50
20	2	RADIATOR BRACKET	0.00	110.00	-10.00	99.00
21	1	FRONT DOOR LH	0.00	1,116.40	-30.00	781.48
22	2	FRONT DOOR HINGES LH	0.00	136.00	-10.00	122.40
23	1	FRONT DOOR PILLAR LH	0.00	2,236.50	-30.00	1,565.55
24	1	FRONT DOOR INNER BOARD LH	0.00	755.70	-30.00	528.99
25	1	FRONT DOOR GLASS REGULATOR LH	0.00	203.60	-10.00	183.24
26	1	FRONT DOOR GLASS REGULATOR MOTOR LH	0.00	576.90	-10.00	519.21
27	1	FRONT DOOR LOCK LH	0.00	310.20	-10.00	279.18
28	1	FRONT DOOR LOCK CATCH LH	0.00	67.60	-10.00	60.84
29	1	FRONT DOOR RUBBER LH	0.00	130.00	-10.00	117.00
30	1	FRONT DOOR GLASS LH	0.00	716.90	-30.00	501.83
31	1	FRONT DOOR GLASS CHANNEL LH	0.00	122.00	-10.00	109.80
32	1	FRONT DOOR INNER RUBBER LH	0.00	145.00	-10.00	130.50
33	1	FRONT DOOR STEP PANEL LH	0.00	398.00	-10.00	358.20
34	1	FRONT DOOR STEP GARNISH LH	0.00	110.00	-10.00	99.00
35	1	FRONT CHASSIS SIDE MEMBER LH	0.00	581.70	-10.00	523.53
36	1	FRONT CHASSIS MEMBER LH	0.00	2,200.00	-30.00	1,540.00
37	1	FRONT WASHER TANK	0.00	257.80	-10.00	232.02
38	1	FRONT WASHER TANK MOTOR	0.00	155.00	-10.00	139.50
39	1	FRONT FENDER LH	0.00	1,800.00	-30.00	1,260.00
40	1	FRONT WHEEL ARCH INNER PROTECTOR LH	0.00	135.10	-10.00	121.59
41	1	FRONT FENDER INNER SHIELD LH	0.00	247.50	-10.00	222.75
42	1	FRONT UPPER ARM LH	0.00	382.70	-10.00	344.43
43	1	FRONT LOWER ARM LH	0.00	271.40	-10.00	244.26
44	1	FRONT KNUCKLE ARM LH	0.00	342.40	-10.00	308.16
45	1	SLIDING DOOR LH	0.00	0.00	0.00	0.00
46	1	REAR FENDER LH	0.00	1,896.70	-30.00	1,327.69
47	1	REAR BUMPER	0.00	683.60	-30.00	478.52
48	1	REAR BUMPER BRACKET LH	0.00	42.10	-10.00	37.89

Total Parts (\$\$)

16,920.74

Estimates of Miscellaneous Items						
No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	FRONT DOOR INNER BOARD CLIPS	0.00	45.00	0.00	45.00
2	1	FRONT WHEEL RIM LH	0.00	550.00	0.00	550.00
3	1	FRONT TYRE (DEPRECIATION) LH	0.00	180.00	0.00	180.00
Sub Total (\$\$)						775.00

Estimates On Labour						
No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	70.00	70.00	0.00	70.00
2	1	To Dismantle and Refit Front Undercarriage.	180.00	180.00	0.00	180.00
3	1	To Do Up Interior Cleaning and Chemical Wash.	200.00	200.00	0.00	200.00
4	1	To Dismantle & Refit Front Dashboard & related wire harness & related parts.	350.00	350.00	0.00	350.00
5	1	To Pressure Test Air Con Condenser and Radiator For Leakage.	120.00	120.00	0.00	120.00
6	1	To Transfer Sliding Door.	80.00	80.00	0.00	80.00
7	1	To Transfer Door.	60.00	60.00	0.00	60.00
8	1	To Remove & Refit air-con compressor, air-con motor, condenser, pipes & vacuum, including refilling of gas.	180.00	180.00	0.00	180.00
9	1	To Conduct Computer Wheel Alignment.	80.00	80.00	0.00	80.00
10	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	2,100.00	2,100.00	0.00	2,100.00
Gross Labour Cost (\$\$)						3,420.00

Estimates On Paint Work Labour						
No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	60.00	60.00	0.00	60.00
2	1	To Supply Spray Terostat Sealant On The Cutting Areas.	45.00	45.00	0.00	45.00
3	1	To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.	80.00	80.00	0.00	80.00
4	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	2,000.00	2,000.00	0.00	2,000.00
Gross Labour Cost (\$\$)						2,185.00

< END OF ESTIMATES >