

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0611/2019/TF
Date : 10-May-19

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Xia Xinming Sam
Address : Blk 75A Redhill Road
Singapore 151075
Telephone : HP +65 91293966
Type of Claim : Third Party Claim
Policy No. : 1800133353
Vehicle No : **SMF 5310 L**
Model Code : Audi A3 SEDAN 1.4 TFSI
Model / Year : 15/11/2019
Engine No : CZE 846409
Chassis No : WAUZZZ8V8K1003952
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 26-Apr-19
Place of Accident : Golden Mile Tower Carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMF 5310 L

<u>S/n</u>	<u>Nature of Jobs</u>	<u>Estimated Charges</u>	<u>Surveyor's Recommendation</u>
1	To remove and transfer front wire harness for headlights, horns, outside tempature sensor and headlight washer assy.	S/N \$ 360.00 ✓	
2	To dismantle and renew front bumper. Re-organise rear crash management components. Reinstall all parts removed.	\$ 1,050.00 500	
3	To respray front bumper	\$ 900.00 550	
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ <u>2,502.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SMF 5310 L

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>Repair</i>	\$ 1,830.00	+
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 170.00	+
3	FRONT BUMPER GRILLE - CENTER <i>new</i>	\$ 146.00	+
4	FRONT BUMPER CLOSING ELEMENT - LH / RH <i>new</i>	\$ 540.00	+
5	FRONT BUMPER COVER TRIM - LH / RH <i>new</i>	\$ 296.00	+
6	RADIATOR GRILLE <i>Carbed</i>	\$ 1,301.00	✓
7	FRONT BUMPER CLOSING ELEMENT -CENTER <i>new</i>	\$ 174.00	+
8	FRONT BUMPER AIR GRILLE - LH / RH <i>new</i>	\$ 342.00	+
9	FRONT BUMPER REINFORCEMENT <i>new</i>	\$ 660.00	+
10	FOAM FILLER PIECE <i>new</i>	\$ 172.00	+
11	FRONT BUMPER REINFORCEMENT COVER <i>new</i>	\$ 111.00	+
12	A/C STICKER <i>new</i>	\$ 7.00	+
13	CAUTION STICKER <i>new</i>	\$ 13.00	+
14	FRONT NO. PLATE <i>Best</i>	S/N \$ 40.00	✓
15	SUNDRIES <i>?</i>	\$ 300.00	?
TOTAL SPARE PARTS		\$ 6,102.00	
TOTAL LABOUR CHARGES		\$ 2,502.00	
GRAND TOTAL		\$ 8,604.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

me :
Name : Adrian King
Inspected Date : 24/05/19.
Surrendered Date :
Authorised Cost :
Excess :
Liability :
Remarks : Not Authorised, 03 Days.
Remarks :

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant