

INS. CASE OWNER:

CC 6/ AL61900 8602, Ueas

LKK:
IDAC

Situation:

MAY 19

DOI:

ASSIGNMENT

15/5/19

Date / Time:

15/5/19

Registered in Merimen:

15/5/19

Pre-assign / CCU / FTE

SLN 56418



Insured Vehicle No.:

Claim No.:

Name of Insured:

Lim Leng Long, Singapore.

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A.:

15/5/19

Place of Accident:

Is driver the owner?

(YES) / NO

Nature of Accident:

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: % Final? Yes / No

FB88628 C



INSRS:

WSP:

Tel:

Liability:

RMKS:

b44



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

FB88628 C

SLN 56418 - NA/INC 1900 7857 / 03 1004 415/19

- NA/INC 1900 7857 / 03 1004 415/19

* Please verify D.O.A. TP-15/5/19; 01-415/19

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

23-05-19

EMAIL WSP LIABILITY CLEAR, TO REQUEST TO PREPARE GRS REPORT.

8/10/19 - FILE PAS TO HML TO CLOSE

* LTA search date is diff w D.O.A.

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time: 2/10/19

Confirm with Raymond

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

nil.

If NO or B 28, Ass. Lia:

Repair Cost: (w/hst)

S\$ 1016.50

C/D TR 3. PREP. VER.

Loss of Rental (LOR):

S\$ -

(

days)

Loss of Use (LOU):

S\$ 80.00

(\$ 20 x 4 days)

Loss of Income (LOI):

S\$ -

(\$ x days)

LOR only ☐ LOU only ☒LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$ 2.00

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

Total:

S\$ 1098.50

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$ 1098.50

Name 1:

Ban Hock Hin Co Pte Ltd

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: FBB862fc
 at Workshop m/s: 3H11
 of _____
 Insured: SLNS641B
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: 20 % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS L1A 1980
 Date: _____ Person Contacted: 1344A
 Vehicle: IN / OUT

Veh No: FBB862fc Yr Regn: P, 07
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Yamaha FINO c.c. 114
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 63715 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: 4D0558177
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Order / Jammed / Leaked / Burnt or ok
 Brake: Order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 80-90-14
 R: 90-80-14
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Timsum
 Front: _____ Rear: 6
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. _____ mm L/Bal. _____ mm
 D.O.A. 5/5/19 D.O.I. 15/5/19
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear, n/s, o/s Body
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
we 22-8-2022 3453 hrs.

L1 - \$950 (Red \$366.50 / 281)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Report Format :

Lump Sum / I.B.I. (\$) _____)

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)

) \$ + RS. \$ _____

) Photos

) Others

TOTAL



BAN HOCK HIN
Co., Pte Ltd

Co. Reg No: 187000298N
MOTORCYCLE ACCESSORIES / SERVICE CENTRE
MODIFICATIONS / SPRAY PAINTING AND BODY WORK / METAL
WORKS / LEASING & RENTALS / FLEET SALES / INSURANCE SALES

QUOTATION

Customer

NO. : 34135

- Rev. 1

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120
MOTOR CLAIMS DEPT

DATE : 10/05/2019

CLAIM NO. : 11335

POLICY NO. :

FROM : RAYMOND

VEHICLE NO : FBB8628C
MAKE/MODEL : YAM / FINO

*not Alvin
near
1/5 950
stay
15/5/19
to be pre Alvin*

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	BALL BEARING P/N: 62247	REPLACE	1.00	\$18.50	18.50
2	BALL BEARING RETAINER P/N: 52980	REPLACE	1.00	\$17.50	17.50
3	BALL RACE 1 P/N: 50822	REPLACE	1.00	\$11.50	11.50
4	BALL RACE 2 P/N: 50823	REPLACE	1.00	\$11.50	11.50
5	COVER LOWER P/N: 38557	REPLACE	1.00	\$41.50	41.50
6	COVER SIDE LH P/N: 38540	REPLACE	1.00	\$68.00	68.00
7	COVER SIDE RH P/N: 38541	REPLACE	1.00	\$68.00	68.00
8	EMBLEM LH (FINO) P/N: 38576	REPLACE	1.00	\$41.50	41.50
9	EMBLEM RH (FINO) P/N: 38542	REPLACE	1.00	\$41.50	41.50
10	FENDER FRONT P/N: 38543	REPLACE	1.00	\$47.50	47.50
11	FENDER REAR	REPLACE	1.00	\$35.50	35.50
12	FORK FRONT ASSY P/N: 52318	REPLACE	1.00	\$275.00	275.00
13	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED		1.00	\$280.00	280.00



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2909, (Accounts) +65 6281 6759

CERT. NO. 2280-4-0000
01/01/2019

677.50

S/N	Description	Action	Qty	Unit Price	Amount
14	LEG SHIELD 2 P/N 52328	REPLACE	1.00	\$73.00	73.00
15	LEVER BRAKE RH P/N 38548	REPLACE	1.00	\$12.00	12.00
16	PANEL FRONT P/N 38551	REPLACE	1.00	\$82.00	82.00
17	PLATE DISC BRAKE RH P/N 52322	REPLACE	1.00	\$53.00	53.00
18	PLATE NUMBER REAR (6.5 INCH X 9 INCH) P/N 26951	REPLACE	1.00	\$12.00	12.00
19	RACE BALL 2 P/N 52330	REPLACE	1.00	\$11.50	11.50
20	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N 32921	REPLACE	1.00	\$12.00	12.00
21	TAIL LIGHT ASSY	REPLACE	1.00	\$68.50	68.50
22	TRANSPORT CHARGES P/N 07169		1.00	\$35.00	35.00
SUB TOTAL					\$1,316.50
GST @ 7 %					\$92.16
GRAND TOTAL					\$1,408.66

50% deposit required before ordering of parts.

Validity: 30 days

Accident quotation

For & on Behalf of

BAN HOCK HIN CO PTE LTD



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature

Acknowledge & Accepted By

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

977.50
1.2
879.75

305





BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 34135

- Rev. 2

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120
MOTOR CLAIMS DEPT

DATE : 10/05/2019

CLAIM NO. : 11335

POLICY NO. :

FROM : RAYMOND

VEHICLE NO. : FBB8628C
MAKE/MODEL : YAM / FINO

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	BALL BEARING P/N: 62247	REPLACE	1.00	\$18.50 Disc %: 10.00	16.65
2	BALL BEARING RETAINER P/N: 52980	REPLACE	1.00	\$17.50 Disc %: 10.00	15.75
3	BALL RACE 1 P/N: 50622	REPLACE	1.00	\$11.50 Disc %: 10.00	10.35
4	BALL RACE 2 P/N: 50623	REPLACE	1.00	\$11.50 Disc %: 10.00	10.35
5	COVER LOWER P/N: 38557	REPLACE	1.00	\$41.50 Disc %: 10.00	37.35
6	COVER SIDE LH P/N: 38540	REPLACE	1.00	\$68.00 Disc %: 10.00	61.20
7	COVER SIDE RH P/N: 38541	REPLACE	1.00	\$68.00 Disc %: 10.00	61.20
8	EMBLEM LH (FINO) P/N: 38576	REPLACE	1.00	\$41.50 Disc %: 10.00	37.35
9	EMBLEM RH (FINO) P/N: 38542	REPLACE	1.00	\$41.50 Disc %: 10.00	37.35
10	FENDER FRONT P/N: 38543	REPLACE	1.00	\$47.50 Disc %: 10.00	42.75
11	FENDER REAR	REPLACE	1.00	\$35.50 Disc %: 10.00	31.95
12	FORK FRONT ASSY P/N: 52318	REPLACE	1.00	\$275.00 Disc %: 10.00	247.50
13	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED		1.00	\$250.00	250.00



bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 200244180
ISO 9001:2015

S/N	Description	Action	Qty	Unit Price	Amount
14	LEG SHIELD 2 P/N: 52328	REPLACE	1.00	\$73.00 Disc %: 10.00	65.70
15	LEVER BRAKE RH P/N: 38548	REPLACE	1.00	\$12.00 Disc %: 10.00	10.80
16	PANEL FRONT P/N: 38551	REPLACE	1.00	\$82.00 Disc %: 10.00	73.80
17	PLATE DISC BRAKE RH P/N: 52322	REPLACE	1.00	\$53.00	53.00
18	PLATE NUMBER REAR (6.5 INCH X 9 INCH) P/N: 26951	REPLACE	1.00	\$10.00	10.00
19	RACE BALL 2 P/N: 52330	REPLACE	1.00	\$11.50 Disc %: 10.00	10.35
20	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921	REPLACE	1.00	\$10.00	10.00
21	TAIL LIGHT ASSY	REPLACE	1.00	\$68.50 Disc %: 10.00	61.65
22	TRANSPORT CHARGES P/N: 07169		1.00	\$35.00	35.00

SUB TOTAL

\$1,190.05

GST @ 7 %

\$83.30

GRAND TOTAL

\$1,273.35

50% deposit required before ordering of parts.

Validity: 30 days

Accident quotation

For & on Behalf of

BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By

**RAYMOND**

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

bizSAFE₃

[Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	1344A

Vehicle Details

Vehicle No.:	FBB8628C
Vehicle to be Exported:	No
Intended Deregistration Date:	15 May 2019
Vehicle Make:	YAMAHA
Vehicle Model:	FINO 114 A
Primary Colour:	Beige
Manufacturing Year:	2007
Engine No.:	4D0558177
Chassis No.:	4D0558177
Maximum Power Output:	-
Open Market Value:	\$1,806.00
Original Registration Date:	23 Aug 2007
First Registration Date:	23 Aug 2007
Transfer Count:	2
Actual ARF Paid:	\$271.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	22 Aug 2022
COE Category:	D - Motorcycle
COE Period(Years):	5
PQP Paid:	\$3,030.00
COE Rebate Amount:	\$1,980.00
Total Rebate Amount:	\$1,980.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 15 May 2019

OK



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000268K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer:

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120
MOTOR CLAIMS DEPT

NO. : 34135

- Rev. 1

DATE : 10/05/2019
CLAIM NO. : 11335
POLICY NO. :

FROM : RAYMOND

VEHICLE NO. : FBB8628C
MAKE/MODEL : YAM / FINO

*not Alvin
15/5/19
the pre Atk up*

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	BALL BEARING P/N: 62247	REPLACE	1.00	\$18.50	18.50
2	BALL BEARING RETAINER P/N: 52980	REPLACE	1.00	\$17.50	17.50
3	BALL RACE 1 P/N: 50622	REPLACE	1.00	\$11.50	11.50
4	BALL RACE 2 P/N: 50623	REPLACE	1.00	\$11.50	11.50
5	COVER LOWER P/N: 38557	REPLACE	1.00	\$41.50	41.50
6	COVER SIDE LH P/N: 38540	REPLACE	1.00	\$68.00	68.00
7	COVER SIDE RH P/N: 38541	REPLACE	1.00	\$68.00	68.00
8	EMBLEM LH (FINO) P/N: 38576	REPLACE	1.00	\$41.50	41.50
9	EMBLEM RH (FINO) P/N: 38542	REPLACE	1.00	\$41.50	41.50
10	FENDER FRONT P/N: 38543	REPLACE	1.00	\$47.50	47.50
11	FENDER REAR	REPLACE	1.00	\$35.50	35.50
12	FORK FRONT ASSY P/N: 52318	REPLACE	1.00	\$275.00	275.00
13	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED		1.00	\$280.00	280.00



S/N	Description	Action	Qty	Unit Price	Amount
14	LEG SHIELD 2 P/N: 52328	REPLACE	1.00	\$73.00	73.00 ?
15	LEVER BRAKE RH P/N: 38548	REPLACE	1.00	\$12.00	12.00 <i>scr</i>
16	PANEL FRONT P/N: 38551	REPLACE	1.00	\$82.00	82.00 <i>one</i>
17	PLATE DISC BRAKE RH P/N: 52322	REPLACE	1.00	\$53.00	53.00 <i>1.1</i> X
18	PLATE NUMBER REAR (6.5 INCH X 9 INCH) P/N: 26951	REPLACE	1.00	\$12.00	12.00 <i>Self</i> 105
19	RACE BALL 2 P/N: 52330	REPLACE	1.00	\$11.50	11.50 7
20	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921	REPLACE	1.00	\$12.00	12.00 <i>Self</i> 105
21	TAIL LIGHT ASSY	REPLACE	1.00	\$68.50	68.50 <i>one</i>
22	TRANSPORT CHARGES P/N: 07169		1.00	\$35.00	35.00

SUB TOTAL

\$1,316.50

GST @ 7 %

\$92.16

GRAND TOTAL

\$1,408.66

50% deposit required before ordering of parts.

Validity: 30 days

Accident quotation


For & on Behalf of

BAN HOCK HIN CO PTE LTD



RAYMOND

Acknowledge & Accepted By



This quotation is sent via email / LAN-Fax and will bear a computer generated signature.



Enquire Transfer Fee

Vehicle Details

Vehicle No.:	FBB8628C
Vehicle Type:	P00 - Passenger Motorcycle/Autocycle/Moped
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	YAMAHA
Vehicle Model:	FINO 114 A
Chassis No.:	4D0558177
Propellant:	Petrol
Engine No.:	4D0558177
Engine Capacity:	114 cc
Maximum Power Output:	-
Maximum Laden Weight:	-
Unladen Weight:	91 kg
Year Of Manufacture:	2007
Original Registration Date:	23 Aug 2007
Lifespan Expiry Date:	-
COE Category:	D - Motorcycle
PQP Paid:	\$3,030.00
COE Expiry Date:	22 Aug 2022
Road Tax Expiry Date:	22 Aug 2019
Inspection Due Date:	22 Aug 2019
Intended Transfer Date:	15 May 2019
CO2 Emission:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Total Amount Payable:			25.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

You may print this page for reference.

OK

Print



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000268K
MOTORCYCLE ACCESSORIES / SERVICE CENTRE
MODIFICATIONS / SPRAY PAINTING AND BODY WORK / METAL
WORKS / LEASING & RENTALS / FLEET SALES / INSURANCE SALES

31 JUL 2019

Your Ref : SLN5641B
Our Ref : TP/11335/FBB8628C/SLN5641B

BY EMAIL & HAND

AIG Asia Pacific Insurance Pte Ltd
CHARTIS BUILDING
78 Shenton Way
#07-16
Singapore 079120

ATTN: MOTOR CLAIMS DEPT

Dear Sir / Madam,,

Accident Involving FBB8628C & SLN5641B on 04/05/2019

We refer to the above-mentioned matter.

As instructed by our client, we proceed to quantify our claim as itemized below:

1. Cost of Repair (Inc 7% GST)	\$1,016.50
2. Loss of Use (4 days x \$20)	\$ 80.00
3. GIA Vehicle Insurance Search Fee	\$ 2.00
TOTAL	<u>\$1,098.50</u>

We attached our Tax Invoice and GIA Search Invoice for your perusal.

Please acknowledge receipt.

If you require any further clarification, please do not hesitate to contact Mr Raymond at 6281 6520 ext.220.

Thank you.

BAN HOCK HIN CO PTE LTD

Raymond Tan
Manager/Insurance Dept



Jia Le (LKK Auto)

From: Jia Le (LKK Auto)
Sent: Thursday, 29 August 2019 2:16 PM
To: agustinelim@yahoo.com.sg
Subject: ACCIDENT INVOLVING SLN 5641B & FBB 8628C ALONG/AT BLK 329 ANCHORVALE ST MSCP ON 04/05/2019

Our Ref: CC6/AIG19008602/Uda3

LIM LENG LONG, AGUSTINE
APT BLK 327C ANCHORVALE ROAD
#13-300
SINGAPORE 543327

Dear Sir/Madam,

ACCIDENT INVOLVING SLN 5641B & FBB 8628C ALONG/AT BLK 329 ANCHORVALE ST MSCP ON 04/05/2019

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from FBB 8628C against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in your favour as your vehicle collided onto Third Party motorbike. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Best Regards,

Carlor Chan | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LETTER OF AUTHORISATION

31 JUL 2019

Your Ref : SLN5641B
Our Ref : TP/11335/FBB8628C/SLN5641B

BY EMAIL & HAND

AIG Asia Pacific Insurance Pte Ltd
CHARTIS BUILDING
78 Shenton Way
#07-16
Singapore 079120

ATTN: MOTOR CLAIMS DEPT

Dear Sir / Madam,,

Accident Involving FBB8628C & SLN5641B on 04/05/2019

AUTHORIZATION LETTER

I / We refer to the above-mentioned matter.

I / We, Chew Kian Lye, Desmond hereby irrevocably authorize Ban Hock Hin Co., Pte Ltd to act on our behalf to file a 3rd Party Claim against your insured SLN5641B.

I / We further authorize M/s AIG Asia Pacific Insurance Pte Ltd to release the claim and payment to M/s Ban Hock Hin Co., Pte Ltd in consideration of their allowing me to take possession of my motorcycle FBB8628C upon completion of repairs.

If you need any verification from us, kindly direct all enquiries and correspondences to M/s Ban Hock Hin Co., Pte Ltd.

Yours faithfully

Witness


.....
Claimant (Signature & Company Stamp)


.....
Witness Signature

Chew Kian Lye, Desmond / S8411344A
.....
Name & NRIC No

Tan Choo Loon / 67715235R
.....
Name & NRIC No

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, **BAN HOCK HIN CO PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$1,016.50** (Repair Cost), **S\$80.00** (Loss of Use/Rental), **S\$2.00** (Disbursement) for vehicle no. **FBB 8628C** that was damaged pursuant to the accident which occurred on **04/05/2019** (date) along **ANCHORVALE ST BLK 329 LEVEL 2A LOT 41** (location) involving vehicle no/s **SLN 5641B**. This is pursuant to the inspection conducted on **15/05/2019** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **CHEW KIAN LYE, DESMOND** ("the third party claimant") of vehicle no. **FBB 8628C** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **FBB 8628C** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 07th (day) of October (month) 2019 (year)



CKS

Signed by appointed surveyor



Signed by "the workshop" (with chop)



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 19700268K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

TAX INVOICE

GST Reg No. : M2-0010542-7

Customer :

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120
MOTOR CLAIMS DEPT

Invoice No. : DLCR40101435-I11335
Invoice Date : 26/07/2019
Payment Due Date : 25/08/2019

CLAIM NO. : 11335
POLICY NO. :
VEHICLE NO. : FBB8628C
MAKE/MODEL : YAM / FINO

S/N	Description	Amount
1	LUMPSUM REPAIR	\$950.00
SUB TOTAL		\$950.00
GST @ 7 %		\$66.50
GRAND TOTAL		\$1,016.50

Validity: 30 days

Accident quotation

For & on Behalf of

BAN HOCK HIN CO PTE LTD



Printed by : RAYMOND

bizSAFE₃



Address: No. 6, Delu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 5759

CERT NO: 202-1-0303
ISO 9001:2015

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-19-076451
Date of Request: 14/05/2019

Your Ref No: Online Purchase

Ban Hock Hin Co. Pte Ltd
No. 6 Defu Lane 4
Singapore 539410

Dear Sir/Madam,

Enquiry Date: 14/05/2019
Enquiry By: Tan Chok Lok
TP Vehicle No.: SLN5641B
Accident Date: 05/05/2019

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLN5641B	AIG Asia Pacific Insurance Pte. Ltd.	09/05/2018-08/05/2019	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 May 2019 Edit Reg		15 May 2019 00:00 Edit Adj Rpt	\$950.00 Edit Estimates	\$950.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LIM LENG LONG, AGUSTINE , ID: S8034812F								
Main Claimant:	CHEW KIAN LYE, DESMOND , ID: S8411344A								
Vehicle Reg. No.:	FBB8628C	Date of Loss:	04/05/2019 07:00 - :59 [140 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 2932250886SG	Policy/Cover Note No.:	1700003754 (Comprehensive) Coverage: 09/05/2018 - 08/05/2019						
Vehicle Reg. No. (Insured):	SLN5641B	Policy No. (Claimant):	MC/00408409						
		Excess:							
Repairer:	Ban Hock Hin Co. Pte Ltd (HQ) No. 6 Defu Lane 4, 539410 Defu Lane - Tel: 62816520								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com								
Claimant's Insurer:	Direct Asia Insurance (Singapore) Pte Ltd (HQ) - Tel: 65322888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 27/05/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (23/05/2019): Re: Conflicting DOA - AIG_SG (23/05/2019): Re: Conflicting DOA - AIG_SG (22/05/2019): Conflicting DOA - AIG_SG (17/05/2019): Re: [SLN5641B] - Conflicting DOA - AIG_SG (17/05/2019): Re: [SLN5641B] - Conflicting DOA - AIG_SG (16/05/2019): Request To Upload TP GIA Report - AIG_SG (16/05/2019): Conflicting DOA									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBB8628C (2932250886SG)
[SLN5641B]

TP
CHEW KIAN LYE, DESMOND
May 4 2019 7:00AM
[LIM LENG LONG, AGUSTINE]
Ban Hock Hin Co. Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser	
----------------------------------	--	-------------------------------	------------------------------------	------------------------------	------------------------------	---	--

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown		Edit	

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	15/05/19 18:00	General View		Load JPG	☒
2	15/05/19 18:00	General View		Load JPG	☒
3	15/05/19 18:00	General View		Load JPG	☒
4	15/05/19 18:00	General View		Load JPG	☒
5	15/05/19 18:00	General View		Load JPG	☒
6	15/05/19 18:00	General View		Load JPG	☒
7	15/05/19 18:00	General View		Load JPG	☒
8	15/05/19 18:00	General View		Load JPG	☒
9	15/05/19 18:00	General View		Load JPG	☒
10	15/05/19 18:00	General View		Load JPG	☒
11	15/05/19 18:00	General View		Load JPG	☒
12	15/05/19 18:00	General View		Load JPG	☒
13	15/05/19 18:00	General View		Load JPG	☒
14	15/05/19 18:00	General View		Load JPG	☒
15	15/05/19 18:00	General View		Load JPG	☒
16	15/05/19 18:00	General View		Load JPG	☒
17	15/05/19 18:00	General View		Load JPG	☒
18	15/05/19 18:00	General View		Load JPG	☒
19	15/05/19 18:00	General View		Load JPG	☒
20	15/05/19 18:00	General View		Load JPG	☒
21	15/05/19 18:00	General View		Load JPG	☒
22	15/05/19 18:00	General View		Load JPG	☒
23	15/05/19 18:00	General View		Load JPG	☒
24	15/05/19 18:00	General View		Load JPG	☒
25	15/05/19 18:00	General View		Load JPG	☒
26	15/05/19 18:00	General View		Load JPG	☒
27	15/05/19 18:00	General View		Load JPG	☒
28	15/05/19 18:00	General View		Load JPG	☒
29	15/05/19 18:00	General View		Load JPG	☒
30	15/05/19 18:00	General View		Load JPG	☒
31	15/05/19 18:00	General View		Load JPG	☒
32	15/05/19 18:00	General View		Load JPG	☒
33	15/05/19 18:00	General View		Load JPG	☒
34	15/05/19 18:00	General View		Load JPG	☒
35	15/05/19 18:00	General View		Load JPG	☒
36	15/05/19 18:00	General View		Load JPG	☒
37	15/05/19 18:00	General View		Load JPG	☒
38	15/05/19 18:00	General View		Load JPG	☒
39	15/05/19 18:00	General View		Load JPG	☒
40	15/05/19 18:00	General View		Load JPG	☒

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
					☒
41	15/05/19 18:00	General View		Load JPG	☒
42	15/05/19 18:00	General View		Load JPG	☒
43	15/05/19 18:00	General View		Load JPG	☒
44	15/05/19 18:00	General View		Load JPG	☒
45	15/05/19 18:00	General View		Load JPG	☒
46	15/05/19 18:00	General View		Load JPG	☒
47	15/05/19 18:00	General View		Load JPG	☒
48	15/05/19 18:00	General View		Load JPG	☒
49	15/05/19 18:00	General View		Load JPG	☒
50	15/05/19 18:00	General View		Load JPG	☒
51	15/05/19 18:00	General View		Load JPG	☒
52	15/05/19 18:00	General View		Load JPG	☒
53	15/05/19 18:00	General View		Load JPG	☒
54	15/05/19 18:00	General View		Load JPG	☒
55	15/05/19 18:00	General View		Load JPG	☒
56	15/05/19 18:00	General View		Load JPG	☒
57	15/05/19 18:00	General View		Load JPG	☒
58	15/05/19 18:00	General View		Load JPG	☒
59	15/05/19 18:00	General View		Load JPG	☒
60	15/05/19 18:00	General View		Load JPG	☒
61	15/05/19 18:00	General View		Load JPG	☒
62	15/05/19 18:00	General View		Load JPG	☒
63	15/05/19 18:00	General View		Load JPG	☒
64	15/05/19 18:00	General View		Load JPG	☒
65	26/07/19 17:02	Reinspection Photo		Load JPG	☒
66	26/07/19 17:02	Reinspection Photo		Load JPG	☒
67	26/07/19 17:02	Reinspection Photo		Load JPG	☒
68	26/07/19 17:02	Reinspection Photo		Load JPG	☒
69	26/07/19 17:02	Reinspection Photo		Load JPG	☒
70	26/07/19 17:02	Reinspection Photo		Load JPG	☒
71	26/07/19 17:02	Reinspection Photo		Load JPG	☒
72	26/07/19 17:02	Reinspection Photo		Load JPG	☒
73	26/07/19 17:02	Reinspection Photo		Load JPG	☒
74	26/07/19 17:02	Reinspection Photo		Load JPG	☒
75	26/07/19 17:02	Reinspection Photo		Load JPG	☒
76	26/07/19 17:02	Reinspection Photo		Load JPG	☒
77	26/07/19 17:02	Reinspection Photo		Load JPG	☒
78	26/07/19 17:02	Reinspection Photo		Load JPG	☒
79	27/07/19 09:15	Reinspection Photo		Load JPG	☒
80	27/07/19 09:15	Reinspection Photo		Load JPG	☒
81	27/07/19 09:15	Reinspection Photo		Load JPG	☒
82	27/07/19 09:15	Reinspection Photo		Load JPG	☒
83	27/07/19 09:15	Reinspection Photo		Load JPG	☒
84	27/07/19 09:15	Reinspection Photo		Load JPG	☒
85	27/07/19 09:15	Reinspection Photo		Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	16/05/19 20:38	TP ESTIMATE - MARKED		Load PDF	
2	16/05/19 20:38	TP GIA REPORT		Load PDF	
3	08/10/19 19:48	FBB8628C_Amended GIA		Load PDF	
4	16/10/19 12:07	WORKSHOP INVOICE		Load PDF	
5	16/10/19 12:07	AUTHORISATION TO ACT FORM		Load PDF	
6	16/10/19 12:07	Release Voucher		Load PDF	
7	16/10/19 12:07	GIA SEARCH		Load PDF	
8	16/10/19 12:07	LOD		Load PDF	
9	16/10/19 12:07	LETTER TO OI		Load PDF	

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	17/05/19 08:40	OI GIA report		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST				Reset	Save	Print
There are no document checklists configured.						

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 	
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.	

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLN5641B (Insd veh)	Model:	YAMAHA FINO 114CC (A)
	FBB8628C (TP veh)		
Date of Accident:	04/05/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	1,408.66
Final Repair Cost	:	\$	1,016.50
Loss of Use	:	\$	80.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	1,098.50

4.00 days at \$20.00 per day
days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop:** Agreed Liability ____ 100 ____ (%)

B) For **GIA Registered Workshop:** BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Ban Hock Hin Co. Pte Ltd	:	\$ 1,098.50
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

16 Oct
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19008602/UDA3Q2

Date: 16/10/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700003754
 Claimant Vehicle No: FBB8628C Insured Vehicle No: SLN5641B
 Date of Loss: 04/05/2019 Nature of Claim: TP Claim No: 2932250886SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBB8628C
 Make & Model: YAMAHA FINO, 114cc (A) Engine No: 4D0558177
 Reg. Date: 23/08/2007 (Man. Year: 2007) Chassis No: 4D0558177
 Colour: White Odometer: 63715 km
 Engine Capacity: 114 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 80-90-14 Rear Tyre Size: 90-80-14
 Front Left Side: Timsun 6 mm Rear Left Side: Timsun 6 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,001.50	899.75	101.75	10.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	315.00	285.00	30.00	9.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,316.50	1,184.75	131.75	10.01
Approved Total (Overridden) (S\$)		950.00		
(S\$)	1,316.50	950.00	366.50	27.84
+ GST 7.00/7.00% (S\$)	92.16	66.50	25.66	27.84
Nett Amount (S\$)	1,408.66	1,016.50	392.16	27.84
+ Loss of Use (4.0 x S\$20.00/day) (S\$)		80.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,098.50		

INSPECTION

Date of Assignment: 15/05/2019
 Date Inspected: 15/05/2019 Inspected At: Ban Hock Hin Co. Pte Ltd (HQ)
 No. 6 Defu Lane 4
 Singapore 539410
 Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BALL BEARING	Necessary	18.50 F	*18.50 FL
2	1		*BALL BEARING RETAINER	Necessary	17.50 F	*17.50 FL
3	1		*BALL RACE 1	Necessary	11.50 F	*11.50 FL
4	1		*BALL RACE 2	Necessary	11.50 F	*11.50 FL
5	1		*COVER LOWER	Cut	41.50 F	*41.50 FL
6	1		*COVER SIDE LH	Cut	68.00 F	*68.00 FL
7	1		*COVER SIDE RH	Cut	68.00 F	*68.00 FL
8	1		*EMBLEM LH (FINO)	Necessary	41.50 F	*41.50 FL
9	1		*EMBLEM RH (FINO)	Necessary	41.50 F	*41.50 FL
10	1		*FENDER FRONT	Cut	47.50 F	*47.50 FL
11	1		*FENDER REAR	Cracked	35.50 F	*35.50 FL
12	1		*FORK FRONT ASSY	Bent / Twisted	275.00 F	*275.00 FL
13	1		*LED SHIELD 2	Cracked	73.00 F	*73.00 FL
14	1		*LEVER BRAKE RH	Scratched	12.00 F	*12.00 FL
15	1		*PANEL FRONT	Cracked	82.00 F	*82.00 FL
16	1		*PLATE DISC BRAKE RH	Bent	53.00 F	*53.00 FL
17	1		*TAIL LIGHT ASSY	Cracked	68.50 F	*68.50 FL
18	1		*PLATE NUMBER REAR (6.5 INCH X 9 INCH)	Bent	12.00 FS	*10.00 FS
19	1		*RACE BALL 2	Necessary	11.50 F	*11.50 FL
20	1		*STICKER NUMBER PLATE FRONT (BLACK)	Scratched	12.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,001.50	997.50
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	97.75
Total Parts (\$\$)	1,001.50	899.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TRANSPORT CHARGES	New	35.00	35.00
2	LABOUR-FOR DISMANTLE AND ASSEMBLING OF PARTS QUOTED	New	280.00	250.00
Gross Labour Cost (S\$)			315.00	285.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >