



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com
Tel: 6286 6060 , FAX: 6286 7060

VEHICLE NUM:	SMK 2724 U
MAKE & MODEL:	OPEL INSIGNIA
MILEAGE:	4773
TYRE:	
CHASSIS NUM:	W0VZM6EF5K1035180

ATTN:			
NO.	DESCRIPTION - PARTS	QTY	PRICE
1	REAR WINDSCREEN MOULDING X		
2	THIRD BRAKE LAMP X		
3	BOOT LID X R		
4	BOOT LID LOGO (OPEL) / AEC		
5	BOOT LID EMBLEM (INSIGNIA) / AEC		
6	BOOT LID EMBLEM (TURBO) / AEC		
7	BOOT LID EMBLEM (D) / AEC		
8	BOOT LID LOCK X		
9	BOOT LID CATCH X		
10	BOOT LID LAMP (L+R) X		
11	BOOT LID LAMP PANEL (L+R) X		
12	BOOT LID BOARD (CENTER) X		
14	BOOT LID BOARD (L+R) X		
15	BOOT LID HANDLE X		
16	BOOT LID DAMPER (L+R) X		
17	BOOT LID HINGE (L+R) X		
18	BOOT LID WIRE PROTECTOR RUBBER (L+R) X		
19	BOOT LID STOPPER (L+R) X		
20	BOOT LID INNER BOARD X		
21	BOOT LID WEATHER STRIP / CR4		
22	TAIL LAMP (L+R) LH ? RH X		
23	TAIL LAMP PANEL (L+R) LH ? RH X		
24	REAR BUMPER / DD		
25	REAR BUMPER RETAINER (L+R) / BR		
26	REAR BUMPER CARPLATE LAMP (L+R) ?		
27	REAR BUMPER TOWING CAP (L+R) 1 pc (RH) / CR4		
28	REAR BUMPER REFLECTOR (L+R) / LH - RH CAT		
29	REAR BUMPER REINFORCEMENT BAR ?		
30	REAR BUMPER BEAM ?		
31	REAR BUMPER SPONGE ?		
32	REAR BUMPER BRACKET (L+R) ?		
33	REAR FENDER (L+R) X		
34	REAR FENDER INNER TRIM (L+R) X		
35	REAR FENDER COWLING (L+R) X		
36	END PANEL ?		
37	END PANEL TOP GARNISH ?		
38	SPAREWHEEL PANEL X / DD		
39	SPAREWHEEL PANEL TOP BOARD X / TN		
40	SPAREWHEEL PANEL TOP BOARD TOP MAT X		
41	SPAREWHEEL PANEL TOOL BOX ?		

[illegible]

		PARTS TOTAL	\$	-
		SPECIAL NETT	QTY	PRICE
1	REAR WINDSCREEN SEALANT ✕		1	\$ 120.00
2	BOOT LID LAMP CLIP (L+R) ✕ <i>NEC</i>		10	\$ 100.00
3	BOOT LID BOARD CLIP (CENTER) ✕		10	\$ 100.00
4	BOOT LID BOARD CLIP (L+R) ✕		10	\$ 100.00
5	BOOT LID INNER BOARD CLIP ✕		10	\$ 100.00
6	BOOT LID LAMP CLIP (L+R) ✕		10	\$ 100.00
7	TAIL LAMP CLIP (L+R) / <i>NEC</i>		10	\$ 100.00
8	REAR BUMPER CLIP / <i>NEC</i>		10	\$ 100.00
9	REAR CARPLATE / <i>NR</i>		1	\$ 120.00
10	REVERSE CAMERA / <i>MIS</i>		1	\$ 850.00
11	REAR FENDER SEALANT (L+R) ✕		1	\$ 120.00
12	REAR FENDER COWLING CLIP (L+R) ✕		10	\$ 100.00
13	REAR FENDER INNER TRIM CLIP (L+R) ✕		10	\$ 100.00
14	END PANEL SEALANT / <i>NEC</i>		1	\$ 120.00
15	SPAREWHEEL SEALANT / <i>NEC</i>		1	\$ 120.00
16	BONNET INNER TRIM CLIP / <i>NEC</i>		10	\$ 100.00
17	HEAD LAMP CLIP (L+R) ?		10	\$ 100.00
18	FRONT BUMPER CLIP / <i>NEC</i>		10	\$ 100.00
19	FRONT BUMPER SENSOR (L+R) ?		6	\$ 900.00
20	FRONT BUMPER FOG LAMP CLIP (L+R) ✕		10	\$ 100.00
21	FRONT FENDER SEALANT (L+R) ✕		1	\$ 120.00
22	AIRCON GAS ?		1	\$ 120.00
		SPECIAL NETT TOTAL		\$ 3,890.00
LABOUR		QTY	PRICE	
	TO RNR ACCIDENT DAMAGE PARTS,CUT/WELD ,KNOCK&REALIGN <i>1300-1500</i>		\$ 5,200.00	
	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA <i>1150</i>		\$ 3,200.00	
	TO RUST PROOF ACCIDENT AFFECTED AREA		\$ 200.00	
	TO RNR REAR WINDSCREEN		\$ 400.00	
	TO RNR FRONT WINDSCREEN		\$ 400.00	
	TO RNR REAR BOOT MECHANISM		\$ 120.00	
	TO RNR UPHOSTERY,GARNISH AND ATTACHMENT PARTS	<i>100</i>	\$ 400.00	
	TO RNR REVERSE SENSOR & CHECK FUNCTION.		\$ 120.00	
	TO RNR FRONT SENSOR & CHECK FUNCTION		\$ 120.00	
	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	<i>80</i>	\$ 120.00	
	TO RNR A/C CONDENSOR ASSY AND REFILL GAS ?		\$ 120.00	
	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS		\$ 120.00	
	TO CHECK WIRING LAYOUT AND TAIL LAMP FUNCTION		\$ 120.00	
	TO DO DIAGNOSIS AND RESET , REPROGRAM OR CODING FAULT CODE.		\$ 400.00	
	TO DO WATER LEAK TEST .		\$ 80.00	
	TO RNR RADIATOR ASSY AND HOSES TO ASSIST WORK LOAD ?		\$ 120.00	
	TO RNR FUEL TANK TO ASSIST WORK LOAD		\$ 250.00	
	TO CHECK CHASSIS ALIGNMENT		\$ 600.00	

		TOTAL	\$ 12,090.00
		GRAND TOTAL COST	\$ 15,980.00

PAGE 2 OF 2

Steve (LKK)
832 2 8813

wh 12
16/5/19, 3:30 pm
chys
L/S
Ry AL spg

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: