

2/20/2012

SS. REC. BY:

REF:

CS/MSG19008608/TISD362

Special Instruction:

Surveyor: Taufiqh

ASSIGNMENT (Office)

From (Person): Ong Zi Hui

of

MSK

Date/Time:

15/5/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SKK 9183H

Insured:

SLX 8784A

at Workshop m/s

NOVA

Tel:

67623377

of

FAN YOUNG

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

11/5/19

CA / REV / REP. / REV 24 HRS

Date/Time:

15/5/19

Person Contacted:

Nabilah

H.O.D. Endorsement:

Vehicle IN/OUT

| Date/Time | Action/Instruction (✓) Estimate |
|-----------|---------------------------------|
|           | SKK 9183H x                     |
|           | SLX 8784A x                     |
| 16/5/19   | @ 13:33 pm received IA to       |
|           |                                 |
|           |                                 |
|           |                                 |

REF:

MS14

## ASSIGNMENT

From:

Date:

15.5.19

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

\$77K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

"wp"

Date:

Person Contacted:

Vehicle: IN / OUT

B.illy

Veh No:

SKK9183H

Vr Regn:

2013, April

Type: M.Cap / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 520T

G.C. 1997

Colour:

Buwze

A/C: Insured / Std / NI / NA

Sp. Reading

108759

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBA XG 120 X 019 X 53 408

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/55 R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

C

mm

L/Bal.

6

mm

L/Bal.

C

mm

D.O.A.

D.O.I.

15/5/19 2:50pm

Survey held at

Mova Fan Jory

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

16/5

\$22K repair limit, e-mail to Billy

04/07/19

Confirmed ~~the~~ HS \$22,000.00 / 12 days with Taufik  
( \$15,951.59 Red - 42% )

RECEIVED 9 JUL 2019

Taufik

P.L.S. see my remarks



4/7/2019

Date/Time, File Pass to?

09/07/19

1)

Typist



: Preli. Report



: Final Report

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$ 22,000/- 4/5)

Days Of Repair:

12

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S + RS, \$

Photos

Others

TOTAL

250

11

261

## Nivitha (LKK Auto)

**From:** Ong Zi Hui <zihui\_ong@sg.msig-asia.com>  
**Sent:** Wednesday, 15 May 2019 2:40 PM  
**To:** assignments@lkkauto.com; admin-d@lkkauto.com  
**Cc:** Crystal Lee  
**Subject:** Survey Request - Manual Assigned

**TP Claim - SKK9183H - DOA : 11/05/2019 (URGENT) TO SURVEY ON 150519 (MORNING) REQUESTED BY WORKSHOP. OUR REF: SLX8784A**

### Manual Assigned

Dear LKK

Refer to the email below, please survey the vehicle by TODAY.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment.

Thank you.

Ong Zi Hui  
Admin Officer, Claims Services  
D: +65 6643 1320 | F: +65 6225 7402 | [zihui\\_ong@sg.msig-asia.com](mailto:zihui_ong@sg.msig-asia.com)



**MSIG**

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

**From:** Venessa Chan  
**Sent:** Wednesday, 15 May, 2019 2:19 PM  
**To:** Nabilah <nabilah@mova.com.sg>  
**Cc:** Nabilah Rasol <nabilah\_rasol@sg.msig-asia.com>; 'Billy' <billy@mova.com.sg>; 'Enny' <enny@mova.com.sg>; 'Nitha' <nitha@mova.com.sg>; Jasmine Lok Kheng Kwei <jasmine\_lok@sg.msig-asia.com>; Ong Zi Hui <zihui\_ong@sg.msig-asia.com>; Crystal Lee <crystal\_lee@sg.msig-asia.com>  
**Subject:** TP Claim - SKK9183H - DOA : 11/05/2019 (URGENT) TO SURVEY ON 150519 (MORNING) REQUESTED BY WORKSHOP. OUR REF: SLX8784A

Dear Nabilah,

Thank you for your selection of LKK Auto Consultants.

We will proceed to appoint LKK Auto Consultants via Merimen at our end and update you upon confirmation.

Please do not contact them directly to prevent confusion.

Please be informed that our surveyor will also be conducting a post repair inspection within the stipulated timeline under the protocol

Thank you.

Have A Great Week Ahead!

*Venessa Chan*

Admin Officer, Claims Services (Motor)

Direct line +65 6594 2470 | Direct fax +65 6225 7402 | [venessa\\_chan@sg.msig-asia.com](mailto:venessa_chan@sg.msig-asia.com)



Insurer Claims  
Team of the Year  
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

**From:** Nabilah [<mailto:nabilah@mova.com.sg>]

**Sent:** Wednesday, 15 May, 2019 1:04 PM

**To:** Venessa Chan <[venessa\\_chan@sg.msig-asia.com](mailto:venessa_chan@sg.msig-asia.com)>

**Cc:** Nabilah Rasol <[nabilah\\_rasol@sg.msig-asia.com](mailto:nabilah_rasol@sg.msig-asia.com)>; Jasmine Lok Kheng Kwei <[jasmine\\_lok@sg.msig-asia.com](mailto:jasmine_lok@sg.msig-asia.com)>; 'Billy' <[billy@mova.com.sg](mailto:billy@mova.com.sg)>; 'Enny' <[enny@mova.com.sg](mailto:enny@mova.com.sg)>; 'Nitha' <[nitha@mova.com.sg](mailto:nitha@mova.com.sg)>

**Subject:** RE: TP Claim - SKK9183H - DOA : 11/05/2019 (URGENT) TO SURVEY ON 150519 (MORNING) REQUESTED BY WORKSHOP. OUR REF: SLX8784A

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

**Your Ref : SLX8784A**

Dear Venessa,

Thank you for your reply.

Kindly assist to arrange LKK Auto Consultants Pte Ltd for the survey.

Meanwhile, kindly assist to advise on the liability of accident.

Thank you.

**Best Regards,**

**Nabilah Senin**

MOVA Automotive Pte Ltd

15 Fan Yoong Road

Singapore 629792

Tel: +65 6262 3377

Fax: +65 6264 3151



Connect with us on  

**From:** Venessa Chan [[mailto:venessa\\_chan@sg.msig-asia.com](mailto:venessa_chan@sg.msig-asia.com)]

**Sent:** Wednesday, 15 May 2019 12:18 PM

**To:** [nabilah@mova.com.sg](mailto:nabilah@mova.com.sg)

**Cc:** Nabilah Rasol; Jasmine Lok Kheng Kwei

**Subject:** TP Claim - SKK9183H - DOA : 11/05/2019 (URGENT) TO SURVEY ON 150519 (MORNING) REQUESTED BY WORKSHOP. OUR REF: SLX8784A

Dear Nabilah,

For future cases, please email to [motorsurvey@sg.msig-asia.com](mailto:motorsurvey@sg.msig-asia.com) to avoid any delay.

We refer to your email on 15.05.19, we are unable to assign our In House Surveyor to survey vehicle today.

Please choose one surveyor from the list that you wish for us to appoint to conduct the pre-repair inspection:

- 1) LKK Auto Consultants Pte Ltd
- 2) Formteam Consultancy Pte Ltd
- 3) Automobile Inspection Services Pte Ltd
- 4) STA Inspection Pte Ltd
- 5) **MSIG In-House Surveyors (unable to survey today 15.05.19)**

To facilitate an expeditious claim settlement, we hope you are agreeable for the above surveyor to be the SJE (Single Joint Expert).

If not, you may wish to nominate any of the 10 surveyors listed below as the SJE, depending on their availability:

- 1 Calvin Ang
- 2 Kenneth Kong
- 3 Marcus Chua
- 4 Henry Ng
- 5 Lau Kwok Kwong
- 6 Frankie Pang
- 7 Ng You Han
- 8 Gary Soon
- 9 Chow Bo Xiong
- 10 Axel Lee

NB:

- (a) \*Fast-Lane Settlement is not applicable for cases that liability is in dispute\*
- (b) If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

We have created a dedicated motor survey mailbox for your motor survey request and pre-repair inspection. Please contact us (MSIG) by clicking this link: [motorsurvey@sg.msig-asia.com](mailto:motorsurvey@sg.msig-asia.com)

Thank you

Have A Great Week Ahead!

*Venessa Chan*

Admin Officer, Claims Services (Motor)



Insurer Claims  
Team of the Year  
2016

**MSIG Insurance (Singapore) Pte Ltd** 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581

| T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

**From:** Nabilah <[nabilah@movacom.sg](mailto:nabilah@movacom.sg)>  
**Sent:** Wednesday, 15 May 2019 10:15 AM  
**To:** Claims <[claims@sg.msig-asia.com](mailto:claims@sg.msig-asia.com)>  
**Cc:** 'Billy' <[billy@movacom.sg](mailto:billy@movacom.sg)>; 'Enny' <[enny@movacom.sg](mailto:enny@movacom.sg)>; 'Nitha' <[nitha@movacom.sg](mailto:nitha@movacom.sg)>  
**Subject:** RE: TP Claim - SKK9183H - DOA : 11/05/2019  
**Importance:** High

**EXTERNAL EMAIL:** Be careful when you click any links or open any attachment(s).

Your Ref : SLX8784A

Dear Sir/Mdm,

Kindly assist to arrange survey on 15/05/2019 (Wednesday) morning at Movacom (Fan Yoong).

Please advise on the officer-in-charge and revert on the liability of accident.

Vehicle is in since 13/05/2019.

Thank you.

Best Regards,  
Nabilah Senin  
MOVA Automotive Pte Ltd  
15 Fan Yoong Road  
Singapore 629792  
Tel: +65 6262 3377  
Fax: +65 6264 3151



Connect with us on

**From:** Nabilah [<mailto:nabilah@movacom.sg>]  
**Sent:** Tuesday, 14 May 2019 4:30 PM  
**To:** 'claims@sg.msig-asia.com'  
**Cc:** 'Billy'; 'Enny'; 'Nitha'  
**Subject:** TP Claim - SKK9183H - DOA : 11/05/2019  
**Importance:** High

Your Ref : SLX8784A

Dear Sir/Mdm,

Kindly assist to arrange survey on 15/05/2019 (Wednesday) morning at Mova (Fan Yoong).

We're in the midst of preparing the estimate.

Vehicle is in since 13/05/2019.

Thank you.

Best Regards,  
Nabilah Senin  
MOVA Automotive Pte Ltd  
15 Fan Yoong Road  
Singapore 629792  
Tel: +65 6262 3377  
Fax: +65 6264 3151



Connect with us on 

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

9183C

### Vehicle Details

Vehicle No.:

SKK9183H

Vehicle to be Exported:

No

Intended Deregistration Date:

14 May 2019

Vehicle Make:

B.M.W.

Vehicle Model:

520I 2.0L AT D/AB 2WD 4DR GAS/D NAV

Primary Colour:

Brown

Manufacturing Year:

2013

Engine No.:

A4290442N20B20B

Chassis No.:

WBAXG120X0DX53408

Maximum Power Output:

135.0 kW (181 bhp)

Open Market Value:

\$42,008.00

Original Registration Date:

26 Apr 2013

First Registration Date:

26 Apr 2013

Transfer Count:

0

Actual ARF Paid:

\$45,812.00

### Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

25 Apr 2023

PARF Rebate Amount:

\$29,777.00

### Intended COE Rebate Details

COE Expiry Date:

25 Apr 2023

COE Category:

E - Open Category

COE Period(Years):

10

QP Paid:

\$62,000.00

COE Rebate Amount:

\$24,472.00

**Total Rebate Amount:**

**\$54,249.00**

The information contained herein is correct as at 14 May 2019

OK

MARKET VALUE \$11800.00

sgCARMART.COM

Login Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

## Free Car Valuation

Unsure of how much your car is worth?

Let us tell you how much is the value - no charges &amp; no obligations!

Post an Advertisement  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

Honda CRZ Hybrid 1.5M



Manual Drive, under 100km, One  
Owner, Good Condition And  
Perfect For CDE Residents.  
Direct Owner - Star Ad



Browse by Category

Sort by Date Posted 20 results/page

16 vehicles

5 Series 520i

Advanced Search Submit

| Image                                                                                                                                                                                                        | Model                      | Price         | Depreciation | Reg Date    | Eng Cap  | Mileage       | Veh Type | Status       |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------|---------------|--------------|-------------|----------|---------------|----------|--------------|
| Search Selection                                                                                                                                                                                             |                            | 5 Series 520i | Any          | Any         | 2013     | Any           | Any      | Available    |
|                                                                                                                             | BMW 5 Series 520i          | \$92,888      | \$15,590 /yr | 30-Aug-2013 | 1,997 cc | 120,000 km    | Luxury   | Available    |
| Facelifted LED Instrument Cluster. 100% Accident Free PML Unit- Agent Maintained Till Oct 2018. Genuine Mileage. All Wear & Tear Replaced With Receipt To Prove Car In Mint Condition With New Glossy P...   |                            |               |              |             |          |               |          | Consistent   |
| MV Auto                                                                                                                                                                                                      |                            |               |              |             |          |               |          |              |
| Posted: 13 May 2019 Tags: 2013 BMW 520i, 2013 bmw 520i, BMW 520i, bmw 520i, BMW 520i, Used BMW                                                                                                               |                            |               |              |             |          |               |          |              |
|                                                                                                                            | BMW 5 Series 520i          | \$69,300      | \$13,550 /yr | 31-Jan-2013 | 1,997 cc | -             | Luxury   | Available    |
| Low Interest Rate Just At 1.98%! Very Well Maintained, Only 1 Owner And 2 Years Warranty/Service By Platinum Motoring In House Workshop. New Paint Color Of Your Choice And New Pure Leather Seats. Hu...    |                            |               |              |             |          |               |          | Premium      |
| Posted: 12 May 2019 Tags: 2013 BMW 520i, 2013 bmw 520i, BMW 520i, bmw 520i, BMW 520i, Used BMW                                                                                                               |                            |               |              |             |          |               |          |              |
|                                                                                                                           | BMW 5 Series 520i          | \$90,800      | \$14,270 /yr | 29-Nov-2013 | 1,997 cc | 78,000 km     | Luxury   | Available    |
| Very Well Taken Care Unit. Regularly Serviced. Original Black Paintwork With Classy Brown Interiors. Low Mileage Done, Under Utilized. Superb Condition! Trade In And Flexible Loan Available! Call Now ...  |                            |               |              |             |          |               |          |              |
| 360 VR Cars                                                                                                                                                                                                  |                            |               |              |             |          |               |          |              |
| Posted: 10 May 2019 Tags: 2013 BMW 520i, 2013 bmw 520i, BMW 520i, bmw 520i, BMW 520i, Used BMW                                                                                                               |                            |               |              |             |          |               |          |              |
|                                                                                                                           | BMW 5 Series 520i          | \$77,000      | \$13,970 /yr | 28-Mar-2013 | 1,997 cc | 76,675 km     | Luxury   | Available    |
| Well Maintained. Good Condition. Smooth, Silent, Comfortable And Responsive. One Owner. Elegant Black. A Good Choice Buy. Trade In And Financing Available. Buy With Peace Of Mind.                          |                            |               |              |             |          |               |          |              |
| Posted: 10 May 2019 Tags: 2013 BMW 520i, 2013 bmw 520i, BMW 520i, bmw 520i, BMW 520i, Used BMW                                                                                                               |                            |               |              |             |          |               |          |              |
| Car Buying                                                                                                                                                                                                   |                            |               | Car Selling  |             |          | Car Ownership |          |              |
| Car Aftermarket                                                                                                                                                                                              |                            |               | On The Move  |             |          | Lifestyle     |          |              |
| <a href="#">Buy Tyres Online</a><br><a href="#">Latest Special Offers from Tyresport</a>                                                                                                                     |                            |               |              |             |          |               |          |              |
|                                                                                                                           | BMW 5 Series 520i Highline | \$78,800      | \$14,430 /yr | 29-Mar-2013 | 1,997 cc | 85,000 km     | Luxury   | Available    |
| Latest Addition! 1 Owner! Bidded Number Inclusive. Agent Unit Highline Model! Low Mileage Of 13,500km Per Year! Smooth And Quiet Engine. i-Drive, Bluetooth Connectivity, Navigation, Paddle Shifter, Pa...  |                            |               |              |             |          |               |          |              |
| Posted: 06 May 2019 Tags: 2013 BMW 520i, 2013 bmw 520i, BMW 520i, bmw 520i, BMW 520i, Used BMW                                                                                                               |                            |               |              |             |          |               |          |              |
|                                                                                                                           | BMW 5 Series 520i          | \$77,000      | \$13,780 /yr | 17-Apr-2013 | 1,997 cc | 113,488 km    | Luxury   | Available    |
| PML Unit. All Services Performed At PML From Day 1. Careful Owner. Pri Stine Condition. All Accessories Are Factory Fitted. Powerful And Comfortable Ride. Sophisto Grey Exterior With Beige Leather Int...  |                            |               |              |             |          |               |          | Direct Owner |
| Posted: 05 May 2019 Tags: 2013 BMW 520i, 2013 bmw 520i, BMW 520i, bmw 520i, BMW 520i, Used BMW                                                                                                               |                            |               |              |             |          |               |          |              |
|                                                                                                                           | BMW 5 Series 520i          | \$78,800      | \$13,920 /yr | 28-May-2013 | 1,997 cc | 97,303 km     | Luxury   | Available    |
| 1 (Director) Owner! Low Depreciation! High Loan Are Available At Low Interest Rate! Fully Agent (PML) Servicing Records Since Days 1. Extended Premium Warranty Can Be Arrange! Stock Condition! High Tra... |                            |               |              |             |          |               |          |              |
| Starise Automobile                                                                                                                                                                                           |                            |               |              |             |          |               |          |              |
| Posted: 04 May 2019 Tags: 2013 BMW 520i, 2013 bmw 520i, BMW 520i, bmw 520i, BMW 520i, Used BMW                                                                                                               |                            |               |              |             |          |               |          |              |
|                                                                                                                           | BMW 5 Series 520i          | \$75,700      | \$13,270 /yr | 09-May-2013 | 1,997 cc | -             | Luxury   | Available    |
| 1 Owner. Genuinely Well Maintained BMW F10 520i! Outstanding Handling, Engine Performance And Built Quality Among Its Class. High Trade In, Attractive Financing Available. Call To Arrange For Viewing A... |                            |               |              |             |          |               |          |              |
| Pang's Motor Trading Pte Ltd                                                                                                                                                                                 |                            |               |              |             |          |               |          |              |
| Posted: 29 Apr 2019 Tags: 2013 BMW 520i, 2013 bmw 520i, BMW 520i, bmw 520i, BMW 520i, Used BMW                                                                                                               |                            |               |              |             |          |               |          |              |



**BMW 5 Series 520i** \$73,800 \$13,270 /yr 19-Apr-2013 1,997 cc 95,000 km Luxury Available  
 PML Maintained With Receipts. Upgraded Audio System, Rear LCD. 100% Accident Free. Highest Trade-In. Std Bank Loan, Balloon Loan, In-House Loan, 100% Loan Available. Test Drive Today.

Posted: 25-Apr-2019 Tags: 2013 BMW 520i, 2013 bmw 520i, BMW 520i, bmw 520i, BMW 520i, Used BMW



**BMW 5 Series 520i** \$77,800 \$14,000 /yr 19-Apr-2013 1,997 cc 67,000 km Luxury Available  
 (Fully PML Serviced), 1 Owner, Facelifted Model, Low Mileage, Low Depreciation, Low Interest Rate, High Loan Package Available, Mint Condition, Hurry Call Now.

Hamilton Autohub Pte Ltd

Posted: 24-Apr-2019 Tags: 2013 BMW 520i, 2013 bmw 520i, BMW 520i, bmw 520i, BMW 520i, Used BMW



#### Audio Upgrade for Any Budget

Want more than what your stock in-car entertainment system can offer? With 400 head units choose from, you'll definitely find "the one" that suits your needs. Prices from just \$170!

Find out more!



**BMW 5 Series 520i** \$83,666 \$14,480 /yr 30-May-2013 1,997 cc 80,000 km Luxury Available  
 1 Owner, Low Mileage Done. 6 Months Warranty. 100 % Loan & PHV Loan Available, High Paper Value. Trade In Welcome. Call Now

Privilege Motors Pte Ltd

Posted: 24-Apr-2019 Tags: 2013 BMW 520i, 2013 bmw 520i, BMW 520i, bmw 520i, BMW 520i, Used BMW



**BMW 5 Series 520i** \$77,800 \$14,170 /yr 29-Mar-2013 1,997 cc 93,000 km Luxury Available  
 Single Owner Unit. Exclusive 1 Year Warranty And 1 Year Free Servicing. Elegant Silver On Beige Interior For Its Classy Look. Very Well Maintained By A Meticulous Ex-Owner. Trade In / STA Inspection / ...

Posted: 23-Apr-2019 Tags: 2013 BMW 520i, 2013 bmw 520i, BMW 520i, bmw 520i, BMW 520i, Used BMW



**BMW 5 Series 520i** \$77,900 \$13,370 /yr 21-Jun-2013 1,997 cc 107,000 km Luxury Available  
 Look No Further! Most Reasonably Priced Unit In Town And Full Service Records At PML. Direct Owner's 2013 BMW 520 With Luxurious Saddle Brown Leather Upholstery Owned By 1 Family Owner Selling Due To ...

Posted: 06-Apr-2019 Tags: 2013 BMW 520i, 2013 bmw 520i, BMW 520i, bmw 520i, BMW 520i, Used BMW



**BMW 5 Series 520i Highline** \$93,800 \$16,270 /yr 30-Aug-2013 1,997 cc 95,800 km Luxury Available  
 Maintained By MBM Workshop! Comes With 1 Year Warranty By MBM And 3 Times Free Servicing! Well Maintained By Meticulous Owner! Drive With A Peace Of Mind! Non Consignment Unit! Trade In Are Welcome. F...

Posted: 30-Mar-2019 Tags: 2013 BMW 520i, 2013 bmw 520i, BMW 520i, bmw 520i, BMW 520i, Used BMW



**BMW 5 Series 520i Luxury** \$75,500 \$13,450 /yr 28-Mar-2013 1,997 cc 138,000 km Luxury Available  
 1 Owner Only. New Tyres, Engine Mounting, Transmission Mounting, Brake Pads, Engine Oil Sump Gasket, Flywheel Oil Seal, Wheel Alignment Done. All Good To Go. Viewing By Appointment Only. Call To Arran...

Singapore Automobile.com

Posted: 18-Mar-2019 Tags: 2013 BMW 520i, 2013 bmw 520i, BMW 520i, bmw 520i, BMW 520i, Used BMW



**BMW 5 Series 520i** \$79,800 \$14,030 /yr 11-Jun-2013 1,997 cc - Luxury Available  
 Just Arrived, 1 Owner, Well Maintained By Previous Owner! Loan With High Trade In Available. Price Negotiable. Call Now Or Visit Our Showroom Today.

Posted: 13-Mar-2019 Tags: 2013 BMW 520i, 2013 bmw 520i, BMW 520i, bmw 520i, BMW 520i, Used BMW

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads.

20 results/page

Home New Cars Used Cars Sell My Car Directory Products Insurance Article Forum Resources

sgCarMart is the number one car classifieds for parallel import cars. Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons. SUV, MPV, hatchback, to CDE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used 5 Series 520i, 5 Series 520i Singapore, used 5 Series 520i Singapore, used 5 Series 520i, used vehicles Singapore or even buy used 5 Series 520i Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, motor, car performance parts, car discussion, forum discussion, commercial vehicle leasing & CDE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

About Us Careers Contact Us Sitemap Terms of Service Privacy Policy Personal Data Protection Statement

Compare

©2004-2019 sgCarMart. All rights reserved.

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Tuesday, 9 July 2019 1:53 PM  
**To:** 'Billy'; Taufikh (LKKAuto)  
**Cc:** SUR; CS A Team  
**Subject:** RE: SKK9183H

Dear Billy,

Confirmed final fig \$ 22,000.00 (lump sum) @ 12 days of repairs before GST.

Final invoice and all supporting documents sent over to MSIG Insurance (Singapore) Pte. Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Billy [mailto:billy@moval.com.sg]  
**Sent:** Monday, 1 July 2019 12:00 PM  
**To:** 'Taufikh (LKKAuto)' <Taufikh@lkkauto.com>  
**Cc:** sur@lkkauto.com; cs-a@lkkauto.com  
**Subject:** Re:SKK9183H

Hi Sir,

Damaged parts photos and after repair. Thank You.

Best Regard's  
**Billy Liaw**

**MOVA Automotive Pte Ltd**  
Tel: +65 62623377  
Fax: +65 62643151



Connect with us on



**Shirley Hiew (LKK Auto)**

---

**From:** Taufikh (LKKAuto) <Taufikh@lkkauto.com>  
**Sent:** Thursday, 16 May 2019 3:08 PM  
**To:** Shirley Hiew (LKK Auto)  
**Subject:** FW: SKK9183H REPAIR LIMIT

---

**From:** Taufikh (LKK Auto) [mailto:taufikh@lkkauto.com]  
**Sent:** Thursday, 16 May 2019 8:59 AM  
**To:** 'Billy'  
**Subject:** SKK9183H REPAIR LIMIT

Hi Billy,

Please take note repair limit for this car is \$22,000.

Regards  
Taufikh  
Lkk Auto

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Jasmine Lok Kheng Kwei

Date: 16 May 2019

**Preliminary Advice**

|                    |                                                                                                              |                         |              |
|--------------------|--------------------------------------------------------------------------------------------------------------|-------------------------|--------------|
| Insured Vehicle No | : SLX8784A                                                                                                   | Accident Date           | : 11/05/2019 |
| TP Vehicle No      | : SKK9183H                                                                                                   | Assignment Date         | : 16/05/2019 |
| Make               | : BMW 520I                                                                                                   | Est. Duration of Repair | : 12 days    |
| Date of Inspection | : 15/05/2019                                                                                                 |                         |              |
| Inspection At      | : Mova Automotive Pte Ltd (Bukit Merah)<br>Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3<br>Singapore 159722 |                         |              |

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front & rear portion and parts claimed are consistent to the accident.

|                             |      |           |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 35,911.18 |
| Revised Amount              | :S\$ | 20,893.22 |
| Check Items (Estimated)     | :S\$ | 12,824.50 |
| Total                       | :S\$ | 33,717.72 |

Lump Sum Repair :S\$

**Total Loss Consideration**

|                    |      |
|--------------------|------|
| New for Old Value  | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate  | :S\$ |
| Salvage Value      | :S\$ |
| Margin for Repair  | :S\$ |

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                                              |
|----------------------------|----------------------------------------------|
| Date Of Report             | 13/05/2019 12:37                             |
| Date Of Accident           | 11/05/2019 17:15                             |
| Exact Location Of Accident | PIE TOWARDS CHANGI AIRPORT (NEAR EUNOS EXIT) |
| Country/State of Loss      | SINGAPORE                                    |

### DETAILS OF OWN VEHICLE

|                             |                       |
|-----------------------------|-----------------------|
| Vehicle Registration Number | SKK9183H              |
| <b>Insured/Policyholder</b> |                       |
| Name Of Registered Owner    | SEET KENG KIM HERBERT |
| NRIC No                     | S1089183C             |
| Email Address               | NOEMAIL               |
| Mobile Phone No             | (LOCAL) +65-97226068  |
| Alternative Phone No        | OTHERS-97226068       |

### Vehicle Particulars

|                                                                              |                                     |
|------------------------------------------------------------------------------|-------------------------------------|
| Manufacturer                                                                 | BMW                                 |
| Model                                                                        | 520I 2.0L AT D/AB 2WD 4DR GAS/D NAV |
| Exact Purpose for which vehicle was being used at time of accident           |                                     |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO                                  |
| If No, Please state action to be taken                                       | THIRD PARTY                         |
| Vehicle Category                                                             | PRIVATE CAR                         |

### Insurance Company

|                           |                                        |
|---------------------------|----------------------------------------|
| Name of Insurance Company | NTUC INCOME INSURANCE CO-OPERATIVE LTD |
| Type Of Coverage          | COMPREHENSIVE                          |
| Fleet Policy              | NO                                     |
| Policy Number             |                                        |
| Cover Note Number         |                                        |

### Driver

|                      |                           |
|----------------------|---------------------------|
| Name of Driver       | DAMIAN ZEPHANIAH SEET     |
| NRIC No              | S8947149D                 |
| Date Of Birth        | 27/12/1989                |
| Occupation           | INDOOR                    |
| Date Of Driving Pass | 24/12/2009                |
| Driving Experience   | 9 YEARS AND 4 MONTHS      |
| Gender               | MALE                      |
| Mobile Number        | (LOCAL) +65-96634063      |
| Fax Number           |                           |
| Contact Number       |                           |
| Email Address        | DAMIANZEPHANIAH@GMAIL.COM |

|                                                     |                 |
|-----------------------------------------------------|-----------------|
| Address                                             | 167 LOYANG RISE |
| Postcode                                            | 507434          |
| Was driver an employee of the Insured's Company     | NO              |
| If No, Relationship of the Driver with the Insured  | CHILDREN        |
| Vehicle Registration Number of Driver's Own Vehicle | -               |
| Insurance Company of Driver's Own Vehicle           | -               |

#### General Information of the Accident

|                    |                 |
|--------------------|-----------------|
| Type Of Accident   | CHAIN COLLISION |
| Weather Conditions | CLEAR           |
| Road Surface       | DRY             |

#### Other Information

|                                                                                             |     |
|---------------------------------------------------------------------------------------------|-----|
| Was any foreign vehicle involved in this accident?                                          | NO  |
| Number of vehicles (including own vehicle) involved in the accident                         | 4   |
| Was any body injured in the Accident?                                                       | NO  |
| Was any injured conveyed to hospital by ambulance?                                          |     |
| Was any other material or property damaged?                                                 | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO  |
| Number of Passengers (Including Driver)                                                     | 1   |

#### Details of Police Action

|                                           |    |
|-------------------------------------------|----|
| Was the accident reported to the police?  | NO |
| If Yes, Please state which Police Station |    |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom?                     |    |

#### Circumstances of Accident

REFER TO SKETCH PLAN

#### Attachment(s)

|                                               |     |
|-----------------------------------------------|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera?   | NO  |
| Was there any audio recorded?                 | NO  |

#### DETAILS OF OTHER VEHICLE PROPERTY 1

|                                     |             |
|-------------------------------------|-------------|
| Vehicle Registration Number         | SKZ287Y     |
| Vehicle Make/Model/Colour           |             |
| Details Of Properties               |             |
| Vehicle Category                    | PRIVATE CAR |
| Name of Driver                      |             |
| NRIC/Passport Number                |             |
| Contact Number                      |             |
| Address                             |             |
| Postcode                            |             |
| Insurance Company Name              |             |
| Nature Of Damage                    |             |
| No. Of Passenger (Including Driver) |             |

#### DETAILS OF OTHER VEHICLE PROPERTY 2

|                             |          |
|-----------------------------|----------|
| Vehicle Registration Number | SLX8784A |
|-----------------------------|----------|

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

### DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

SLL9282M

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

|                                                                                                                                                                                                |                                           |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------|
| LICENSE PLATE: SKK 9183H                                                                                                                                                                       | ACCIDENT DATE & TIME: 11 May 2019, 1715   |
| CONTACT NUMBER: 9663 4063                                                                                                                                                                      | E-MAIL ADDRESS: DAMIANZEPHANIAH@GMAIL.COM |
| LOCATION: PIE towards Changi Airport near Euros Exit                                                                                                                                           |                                           |
| <p>car in front of car 1 made a sudden stop.</p> <p>car 1 made an e-brake. Car 2, 3 and 4 e-brake</p> <p>but were unsuccessful resulting in the chain collision</p>                            |                                           |
| <p>NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE CHECK YOUR POLICY FOR MORE INFORMATION</p>              |                                           |
| Please state:                                                                                                                                                                                  |                                           |
| <input type="checkbox"/> Claim Own Policy <input checked="" type="checkbox"/> Claim Third Party <input type="checkbox"/> Claim OD/TP at other workshop <input type="checkbox"/> Reporting Only |                                           |

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

**Main Office:**

Mova Building  
No. 22, Jalan Kilang,  
Singapore 159419  
Tel: (65) 6476 3333  
Fax: (65) 6271 5891  
www.mova.com.sg

**Workshop Dept:**

Block 1008,  
Bukit Merah Lane 3,  
#01-04/06/08/94  
Singapore 159722

Tel: (65) 6272 3892  
Fax: (65) 6270 8314

Co. Reg. 198904033G  
GST Reg. M2-0088864-2

# Estimate

14/05/2019

**MSIG INSURANCE (S) PTE LTD (SGX CENTRE)**  
**16, RAFFLES QUAY**  
**#24-01 HONG LEONG BUILDING**  
**SINGAPORE 048581.**

Attention :- XA013

Page # :- 1

Veh # :- SKK9183H

Veh Model :- BMW 520I 2.0L AT D/AB 2WD

Estimate# :- CK419150

Claim # :-

ACC. Date :- 11/05/19

Terms :- C.O.D Days

Remarks :-

| No.                 | Description                         | Qty    | U.Price  | Amounts S\$ |
|---------------------|-------------------------------------|--------|----------|-------------|
| <b>LIST ITEMS :</b> |                                     |        |          |             |
| 1.                  | BOOT LID                            | 1 PC   | 1,642.45 | 1,642.45    |
| 2.                  | BOOT LID LOGO                       | 1 PC   | 71.25    | 71.25       |
| 3.                  | BOOT LID EMBLEM - 520I              | 1 PC   | 64.10    | 64.10       |
| 4.                  | BOOT LID REFLECTOR LH               | 1 PC   | 360.25   | 360.25      |
| 5.                  | BOOT LID LOCK                       | 1 PC   | 425.35   | 425.35      |
| 6.                  | BOOT LID WEATHERSTRIP               | 1 PC   | 106.60   | 106.60      |
| 7.                  | TAIL LAMP ASSY LH                   | 1 PC   | 609.95   | 609.95      |
| 8.                  | REAR END PANEL                      | 1 PC   | 817.30   | 817.30      |
| 9.                  | REAR END PANEL TOP COVER            | 1 PC   | 115.55   | 115.55      |
| 10.                 | REAR BUMPER                         | 1 PC   | 1,563.35 | 1,563.35    |
| 11.                 | REAR CHASSIS MEMBER LH (REPAIR)     | 1 PC   |          |             |
| 12.                 | REAR BUMPER REINFORCEMENT           | 1 PC   | 772.05   | 772.05      |
| 13.                 | REAR BUMPER RETAINER RH & LH        | 1 PCS  | 155.90   | 155.90      |
| 14.                 | REAR BUMPER REFLECTOR LH            | 1 PC   | 36.80    | 36.80       |
| 15.                 | REAR BUMPER LOWER GARNISH           | 1 PC   | 60.45    | 60.45       |
| 16.                 | REAR BUMPER CLIPS                   | 10 PCS | 5.00     | 50.00       |
| 17.                 | REAR TOW COVER RH & LH              | 2 PCS  | 47.60    | 95.20       |
| 18.                 | REVERSE SENSOR INNER RH & LH        | 2 PCS  | 236.85   | 473.70      |
| 19.                 | REVER SENSOR OUTER LH               | 1 PC   | 236.85   | 236.85      |
| 20.                 | REAR EXHAUST PIPE                   | 1 PC   | 1,270.90 | 1,270.90    |
| 21.                 | BONNET                              | 1 PC   | 2,325.25 | 2,325.25    |
| 22.                 | BONNET HINGE RH & LH                | 2 PCS  | 92.75    | 185.50      |
| 23.                 | BONNET RUBBER                       | 1 PC   | 38.85    | 38.85       |
| 24.                 | BONNET OPENER                       | 1 PC   | 88.20    | 88.20       |
| 25.                 | RIVET                               | 2 PCS  | 5.00     | 10.00       |
| 26.                 | BONNET CATCH RH & LH                | 2 PCS  | 68.60    | 137.20      |
| 27.                 | BONNET LOCK RH & LH                 | 2 PCS  | 188.60   | 377.20      |
| 28.                 | BONNET LOCK TOP RH & LH             | 2 PCS  | 88.40    | 176.80      |
| 29.                 | BONNET INSULATOR                    | 1 PC   | 222.00   | 222.00      |
| 30.                 | BONNET DAMPER RH & LH               | 2 PCS  | 141.70   | 283.40      |
| 31.                 | HEADLAMP ASSY RH & LH               | 2 PCS  | 2,649.65 | 5,299.30    |
| 32.                 | HEADLAMP MODULE LH                  | 1 PC   | 763.70   | 763.70      |
| 33.                 | HEADLAMP LED CONTROL LH             | 1 PC   | 395.75   | 395.75      |
| 34.                 | HEADLAMP CONTROL UNIT LH            | 1 PC   | 867.85   | 867.85      |
| 35.                 | HEADLAMP NOZZLE JET LH              | 1 PC   | 133.40   | 133.40      |
| 36.                 | HEADLAMP NOZZLE COVER LH            | 1 PC   | 47.60    | 47.60       |
| 37.                 | HEADLAMP WASHER NOZZLE HOSE         | 1 PC   | 48.70    | 48.70       |
| 38.                 | FRONT BUMPER                        | 1 PC   | 1,335.40 | 1,335.40    |
| 39.                 | FRONT BUMPER LOGO                   | 1 PC   | 71.25    | 71.25       |
| 40.                 | FRONT BUMPER GRILLE RH & LH         | 2 PCS  | 133.30   | 266.60      |
| 41.                 | FRONT BUMPER LOWER GARNISH - CENTER | 1 PC   | 68.80    | 68.80       |
| 42.                 | FRONT BUMPER LOWER GARNISH LH       | 1 PC   | 72.20    | 72.20       |
| 43.                 | FRONT BUMPER SPONGE                 | 1 PC   | 48.70    | 48.70       |
| 44.                 | FRONT BUMPER REINFORCEMENT          | 1 PC   | 715.90   | 715.90      |
| 45.                 | FRONT BUMPER BEAM                   | 1 PC   | 165.65   | 165.65      |
| 46.                 | FRONT BUMPER BRACKET RH & LH        | 2 PCS  | 24.05    | 48.10       |
| 47.                 | FRONT BUMPER RETAINER LH            | 1 PC   | 30.80    | 30.80       |
| 48.                 | FRONT BUMPER RETAINER PLATE LH      | 1 PC   | 20.60    | 20.60       |
| 49.                 | FRONT BUMPER CLIPS                  | 10 PCS | 5.00     | 50.00       |
| 50.                 | FRONT BUMPER SENSOR INNER RH & LH   | 2 PCS  | 236.85   | 473.70      |
| 51.                 | FRONT BUMPER SENSOR OUTER LH        | 1 PC   | 236.85   | 236.85      |

**Main Office:**  
 Mova Building  
 No. 22, Jalan Kilang,  
 Singapore 159419  
 Tel: (65) 6476 3333  
 Fax: (65) 6271 5891  
 www.mova.com.sg

**Workshop Dept:**  
 Block 1008,  
 Bukit Merah Lane 3,  
 #01-04/06/08/94  
 Singapore 159722

Tel: (65) 6272 3892  
 Fax: (65) 6270 8314

Co. Reg. 198904033G  
 GST Reg. M2-0088864-2

# Estimate

14/05/2019

**MSIG INSURANCE (S) PTE LTD (SGX CENTRE)**  
**16, RAFFLES QUAY**  
**#24-01 HONG LEONG BUILDING**  
**SINGAPORE 048581.**

Attention :- **XA013**

Page # :- 1 134932  
 Veh # :- SKK9183H  
 Veh Model :- BMW 520I 2.0L AT D/AB 2WD  
 Estimate# :- CK419150  
 Claim # :-  
 ACC. Date :- 11/05/19  
 Terms :- C.O.D Days  
 Remarks :-

| No.                                                                                                                                                                                                      | Description                      | Qty   | U.Price  | Amounts S\$    |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------|-------|----------|----------------|
| 52.                                                                                                                                                                                                      | FOG LAMP LH                      | 1 PC  | 276.25   | 276.25 ✓       |
| 53.                                                                                                                                                                                                      | FRONT NUMBER PLATE GARNISH       | 1 PC  | 58.20    | 58.20 ✓        |
| 54.                                                                                                                                                                                                      | TOP PANEL                        | 1 PC  | 162.90   | 162.90 ✓       |
| 55.                                                                                                                                                                                                      | TOP PANEL REINFORCEMENT          | 1 PC  | 197.30   | 197.30 ✓       |
| 56.                                                                                                                                                                                                      | HEADLAMP PANEL RH & LH           | 2 PCS | 195.50   | 391.00 ✓       |
| 57.                                                                                                                                                                                                      | HEADLAMP GARNISH RH & LH         | 2 PCS | 33.30    | 66.60 ✓        |
| 58.                                                                                                                                                                                                      | FRONT V-BAR RH & LH              | 2 PCS | 18.90    | 37.80 ✓        |
| 59.                                                                                                                                                                                                      | AIR GUIDE                        | 1 PC  | 335.45   | 335.45 ✓       |
| 60.                                                                                                                                                                                                      | AIR CON CONDENSER                | 1 PC  | 1,028.35 | 1,028.35 ✓     |
| 61.                                                                                                                                                                                                      | AIR CON DISCHARGE PIPE           | 1 PC  | 311.10   | 311.10 ✓       |
| 62.                                                                                                                                                                                                      | AIR CON ALUMINIUM PIPE           | 1 PC  | 261.30   | 261.30 ✓       |
| 63.                                                                                                                                                                                                      | INTERCOOLER - CHECK              | 1 PC  | ?        | ?              |
| 64.                                                                                                                                                                                                      | RADIATOR ASSY                    | 1 PC  | 1,092.75 | 1,092.75 ✓     |
| 65.                                                                                                                                                                                                      | RADIATOR FAN ASSY                | 1 PC  | 1,324.10 | 1,324.10 ✓     |
| 66.                                                                                                                                                                                                      | RADIATOR TOP COVER RH & LH       | 2 PCS | 35.35    | 70.70 ✓        |
| 67.                                                                                                                                                                                                      | FRONT FENDER LH                  | 1 PC  | 894.90   | 894.90 ✓       |
| 68.                                                                                                                                                                                                      | FRONT FENDER TOP GARNISH LH & RH | 2 PCS | 227.05   | 454.10 ✓       |
| 69.                                                                                                                                                                                                      | FRONT FENDER COWLING FRONT LH    | 1 PC  | 128.20   | 128.20 ✓       |
| 70.                                                                                                                                                                                                      | FRONT FENDER BRACKET LH          | 1 PC  | 84.25    | 84.25 ✓        |
| LIST TOTAL S\$                                                                                                                                                                                           |                                  |       |          | 31,264.40      |
| 5% DISCOUNT S\$                                                                                                                                                                                          |                                  |       |          | -1,563.22      |
|                                                                                                                                                                                                          |                                  |       |          | 29,701.18      |
| <b>SPECIAL NET ITEMS :</b>                                                                                                                                                                               |                                  |       |          |                |
| 1.                                                                                                                                                                                                       | FRONT NUMBER PLATE               | 1 PC  | 40.00    | 40.00 ✓        |
| 2.                                                                                                                                                                                                       | COOLANT                          | 1 PC  | 30.00    | 30.00 ✓        |
| SPECIAL NET TOTAL S\$                                                                                                                                                                                    |                                  |       |          | 70.00          |
| <b>LABOUR :</b>                                                                                                                                                                                          |                                  |       |          |                |
| TOWING CHARGE (KING TROLLY)                                                                                                                                                                              |                                  |       |          | 120. 180.00    |
| TO CUT/WELD REAR END PANEL, KNOCK AND STRAIGHTEN REAR BODY MEMBERS, SPARE WHEEL PANEL, FRONT BODY MEMBER, FRONT FENDER INNER PANEL LH. REMOVE AND REPLACE ACCIDENT DAMAGED PARTS. REALIGN ALL CONNECTION |                                  |       |          | 1600. 2,500.00 |
| SPRAY PAINT BONNET, FRONT FENDERS RH & LH, FRONT BUMPER, BOOT LID, REAR END PANEL, SPARE WHEEL PANEL, REAR FENDER, REAR BUMPER                                                                           |                                  |       |          | 1400. 2,000.00 |
| REMOVE & REINSTALL AIR CON CONDENSER, PIPE, HOSE AND RECHARGE AIR CON GAS                                                                                                                                |                                  |       |          | ✓ 120.00       |
| RE-PROGRAMME / INSTATE HEADLAMP ASSY                                                                                                                                                                     |                                  |       |          | 180. 280.00    |
| REMOVE & REFIT LUGGAGE COMPARTMENT INNER TRIM. GARNISH, COVERING                                                                                                                                         |                                  |       |          | 60. 100.00     |

# Estimate

14/05/2019

**MSIG INSURANCE (S) PTE LTD (SGX CENTRE)**  
16, RAFFLES QUAY  
#24-01 HONG LEONG BUILDING  
SINGAPORE 048581.

Attention :- **XA013**

Page # :- 1 134932  
Veh # :- SKK9183H  
Veh Model :- BMW 520I 2.0L AT D/AB 2WD  
Estimate# :- CK419150  
Claim # :-  
ACC. Date :- 11/05/19  
Terms :- C.O.D Days  
Remarks :-

**Main Office:**  
Mova Building  
No. 22, Jalan Kilang,  
Singapore 159419  
Tel : (65) 6476 3333  
Fax : (65) 6271 5891  
www.mova.com.sg  
**Workshop Dept:**  
Block 1008,  
Bukit Merah Lane 3,  
#01-04/06/08/94  
Singapore 159722  
Tel : (65) 6272 3892  
Fax : (65) 6270 8314  
Co. Reg. 198904033G  
GST Reg. M2-008864-2

| No. | Description                                        | Qty | U.Price             | Amounts S\$ |
|-----|----------------------------------------------------|-----|---------------------|-------------|
|     | REMOVE & REFIT EXHAUST PIPE, HEAT COVER, MOUNTINGS |     | 60.                 | 100.00      |
|     | DIAGNOSE AND RESET VEHICLE SETTING AFTER REPAIR    |     | 150                 | 280.00      |
|     | CHECK CHASSIS ALIGNMENT ON LASER LOCK MACHINE      |     | Report + photo 300? | 380.00 ✓    |
|     | CHECK WIRING & FOCUS HEADLIGHT                     |     | 30.                 | 50.00       |
|     | RUST PROOF AFFECTED AREA                           |     | 60.                 | 150.00      |
|     | LABOUR TOTAL S\$                                   |     |                     | 6,140.00    |

E. & O.E

NON-TAX AMOUNT S 37951.59  
AMOUNT S\$ 35,911.18  
GST @ 7 % 2,513.78  
AMOUNT DUE S\$ 38,424.96

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Tanfer 97495749  
15/5/19 R4  
Lumpsum / partly part.  
Resurvey before / after paint.  
12 days  
Surrendered to check repair limit

**Main Office:**

Mova Building  
No. 22, Jalan Kilang,  
Singapore 159419  
Tel: (65) 6476 3333  
Fax: (65) 6271 5891  
www.mova.com.sg

**Workshop Dept:**

Block 1008,  
Bukit Merah Lane 3,  
#01-04/06/08/94  
Singapore 159722  
Tel: (65) 6272 3892  
Fax: (65) 6270 8314  
Co. Reg. 198904033G  
GST Reg. M2-0088864-2

# SUPPLEMENTARY

MSIG INSURANCE (S) PTE LTD (SGX CENTRE)  
16 RAFFLES QUAY  
#24-01 HONG LEONG BUILDING  
SINGAPORE 048581

Page : 1  
Veh No : SKK9183H  
Model : BMW 520I  
Acc Date : 11-May-19  
Incharge : BILLY

| No                           | Description                          | Qty | U.Price   | Amt \$                |
|------------------------------|--------------------------------------|-----|-----------|-----------------------|
| <b>LIST ITEMS:</b>           |                                      |     |           |                       |
| 1                            | FRONT SEAT BULKER RH                 | 1   | \$ 324.40 | \$324.40 ✓ aut A      |
| 2                            | FRONT SEAT REST REPAIR KIT — photo 2 | 2   | \$ 179.20 | \$358.40 ✓ aut X A my |
| 3                            | HEADLAMP NOZZLE JET RH               | 1   | \$ 50.65  | \$50.65 ✓ dis A       |
| 4                            | RESONATOR ASSY                       | 1   | \$ 232.00 | \$232.00 ✓ de A       |
| 5                            | RESONATOR HOSE                       | 1   | \$ 226.70 | \$226.70 ✓ dis A      |
| 6                            | REAR UNDER COVER RH                  | 1   | \$ 165.00 | \$165.00 ✓ de A       |
| 7                            | GEAR BOX MOUNTING                    | 2   | \$ 68.00  | \$135.00 ✓ de A       |
| <b>PARTS WITHOUT PRICE :</b> |                                      |     |           |                       |
| 1                            | INTERCOOLER                          | 1   | \$ 655.65 | \$655.65              |
| LIST TOTAL S\$               |                                      |     |           | \$2,147.80            |
| 5% DISCOUNT S\$              |                                      |     |           | \$107.39              |
|                              |                                      |     |           | <u>\$2,040.41</u>     |

NON-TAX AMOUNTS  
GST @ 7%  
AMOUNT DUE

\$2,040.41  
\$142.83  
\$2,183.24

Customer's Signature/Co.Stamp

  
MOVA AUTOMOTIVE PTE LTD

**Main Office:**

Mova Building  
No. 22, Jalan Kilang,  
Singapore 159419  
Tel: (65) 6476 3333  
Fax: (65) 6271 5891  
www.mova.com.sg

**Workshop Dept:**

Block 1008,  
Bukit Merah Lane 3,  
#01-04/05/08/94  
Singapore 159722

Tel: (65) 6272 3892  
Fax: (65) 6270 8314

Co. Reg. 198904033G  
GST Reg. M2-0088864-2

# Estimate

14/05/2019

**MSIG INSURANCE (S) PTE LTD (SGX CENTRE)**  
**16, RAFFLES QUAY**  
**#24-01 HONG LEONG BUILDING**  
**SINGAPORE 048581.**

Attention :- XA013

Page # :- 1

Veh # :- SKK9183H

Veh Model :- BMW 520I 2.0L AT D/AB 2WD

Estimate# :- CK419150

Claim # :-

ACC. Date :- 11/05/19

Terms :- C.O.D Days

Remarks :-

| No.                 | Description                         | Qty | U.Price      | Amounts S\$ |
|---------------------|-------------------------------------|-----|--------------|-------------|
| <b>LIST ITEMS :</b> |                                     |     |              |             |
| 1.                  | BOOT LID                            | 1   | PC 1,642.45  | 1,642.45 ✓  |
| 2.                  | BOOT LID LOGO                       | 1   | PC 71.25     | 71.25 ✓     |
| 3.                  | BOOT LID EMBLEM - 520I              | 1   | PC 64.10     | 64.10 ✓     |
| 4.                  | BOOT LID REFLECTOR LH               | 1   | PC 360.25    | 360.25 ✓    |
| 5.                  | BOOT LID LOCK                       | 1   | PC 425.35    | 425.35 ✓    |
| 6.                  | BOOT LID WEATHERSTRIP               | 1   | PC 106.60    | 106.60 ✓    |
| 7.                  | TAIL LAMP ASSY LH                   | 1   | PC 609.95    | 609.95 ✓    |
| 8.                  | REAR END PANEL                      | 1   | PC 817.30    | 817.30 ✓    |
| 9.                  | REAR END PANEL TOP COVER            | 1   | PC 115.55    | 115.55 ✓    |
| 10.                 | REAR BUMPER                         | 1   | PC 1,563.35  | 1,563.35 ✓  |
| 11.                 | REAR CHASSIS MEMBER LH (REPAIR)     | 1   | PC 772.05    | 772.05 ✓    |
| 12.                 | REAR BUMPER REINFORCEMENT           | 2   | PCS 155.90   | 311.80 ✓    |
| 13.                 | REAR BUMPER RETAINER RH & LH        | 1   | PC 36.80     | 36.80 ✓     |
| 14.                 | REAR BUMPER REFLECTOR LH            | 1   | PC 60.45     | 60.45 ✓     |
| 15.                 | REAR BUMPER LOWER GARNISH           | 10  | PCS 5.00     | 50.00 ✓     |
| 16.                 | REAR BUMPER CLIPS                   | 2   | PCS 47.60    | 95.20 ✓     |
| 17.                 | REAR TOW COVER RH & LH              | 2   | PCS 236.85   | 473.70 ✓    |
| 18.                 | REVERSE SENSOR INNER RH & LH        | 1   | PC 236.85    | 236.85 ✓    |
| 19.                 | REVER SENSOR OUTER LH               | 1   | PC 1,270.90  | 1,270.90 ✓  |
| 20.                 | REAR EXHAUST PIPE                   | 1   | PC 2,325.25  | 2,325.25 ✓  |
| 21.                 | BONNET                              | 2   | PCS 92.75    | 185.50 ✓    |
| 22.                 | BONNET HINGE RH & LH                | 1   | PC 38.85     | 38.85 ✓     |
| 23.                 | BONNET RUBBER                       | 1   | PC 88.20     | 88.20 ✓     |
| 24.                 | BONNET OPENER                       | 2   | PCS 5.00     | 10.00 ✓     |
| 25.                 | RIVET                               | 2   | PCS 68.60    | 137.20 ✓    |
| 26.                 | BONNET CATCH RH & LH                | 2   | PCS 188.60   | 377.20 ✓    |
| 27.                 | BONNET LOCK RH & LH                 | 2   | PCS 88.40    | 176.80 ✓    |
| 28.                 | BONNET LOCK TOP RH & LH             | 1   | PC 222.00    | 222.00 ✓    |
| 29.                 | BONNET INSULATOR                    | 2   | PCS 141.70   | 283.40 ✓    |
| 30.                 | BONNET DAMPER RH & LH               | 2   | PCS 2,649.65 | 5,299.30 ✓  |
| 31.                 | HEADLAMP ASSY RH & LH               | 1   | PC 763.70    | 763.70 ✓    |
| 32.                 | HEADLAMP MODULE LH                  | 1   | PC 395.75    | 395.75 ✓    |
| 33.                 | HEADLAMP LED CONTROL LH             | 1   | PC 867.85    | 867.85 ✓    |
| 34.                 | HEADLAMP CONTROL UNIT LH            | 1   | PC 133.40    | 133.40 ✓    |
| 35.                 | HEADLAMP NOZZLE JET LH              | 1   | PC 47.60     | 47.60 ✓     |
| 36.                 | HEADLAMP NOZZLE COVER LH            | 1   | PC 48.70     | 48.70 ✓     |
| 37.                 | HEADLAMP WASHER NOZZLE HOSE         | 1   | PC 1,335.40  | 1,335.40 ✓  |
| 38.                 | FRONT BUMPER                        | 1   | PC 71.25     | 71.25 ✓     |
| 39.                 | FRONT BUMPER LOGO                   | 2   | PCS 133.30   | 266.60 ✓    |
| 40.                 | FRONT BUMPER GRILLE RH & LH         | 1   | PC 68.80     | 68.80 ✓     |
| 41.                 | FRONT BUMPER LOWER GARNISH - CENTER | 1   | PC 72.20     | 72.20 ✓     |
| 42.                 | FRONT BUMPER LOWER GARNISH LH       | 1   | PC 48.70     | 48.70 ✓     |
| 43.                 | FRONT BUMPER SPONGE                 | 1   | PC 715.90    | 715.90 ✓    |
| 44.                 | FRONT BUMPER REINFORCEMENT          | 1   | PC 165.65    | 165.65 ✓    |
| 45.                 | FRONT BUMPER BEAM                   | 2   | PCS 24.05    | 48.10 ✓     |
| 46.                 | FRONT BUMPER BRACKET RH & LH        | 1   | PC 30.80     | 30.80 ✓     |
| 47.                 | FRONT BUMPER RETAINER LH            | 1   | PC 20.60     | 20.60 ✓     |
| 48.                 | FRONT BUMPER RETAINER PLATE LH      | 10  | PCS 5.00     | 50.00 ✓     |
| 49.                 | FRONT BUMPER CLIPS                  | 2   | PCS 236.85   | 473.70 ✓    |
| 50.                 | FRONT BUMPER SENSOR INNER RH & LH   | 1   | PC 236.85    | 236.85 ✓    |
| 51.                 | FRONT BUMPER SENSOR OUTER LH        |     |              |             |

# Estimate

14/05/2019

MSIG INSURANCE (S) PTE LTD (SGX CENTRE)  
16, RAFFLES QUAY  
#24-01 HONG LEONG BUILDING  
SINGAPORE 048581.

Attention :- XA013

Page # :- 1 134932  
Veh # :- SKK9183H  
Veh Model :- BMW 520I 2.0L AT D/AB 2WD  
Estimate# :- CK419150  
Claim # :-  
ACC. Date :- 11/05/19  
Terms :- C.O.D Days  
Remarks :-

**Main Office:**  
Mova Building  
No. 22, Jalan Kilang,  
Singapore 159419  
Tel: (65) 6476 3333  
Fax: (65) 6271 5891  
www.mova.com.sg  
**Workshop Dept:**  
Block 1008,  
Bukit Merah Lane 3,  
#01-04/06/08/94  
Singapore 159722  
Tel: (65) 6272 3892  
Fax: (65) 6270 8314  
Co. Reg. 198904033G  
GST Reg. M2-0088864-2

| No.                                                                                                                                                                                                      | Description                      | Qty   | U.Price  | Amounts S\$          |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------|-------|----------|----------------------|
| 52.                                                                                                                                                                                                      | FOG LAMP LH                      | 1 PC  | 276.25   | 276.25 ✓             |
| 53.                                                                                                                                                                                                      | FRONT NUMBER PLATE GARNISH       | 1 PC  | 58.20    | 58.20 ✓              |
| 54.                                                                                                                                                                                                      | TOP PANEL                        | 1 PC  | 162.90   | 162.90 ✓             |
| 55.                                                                                                                                                                                                      | TOP PANEL REINFORCEMENT          | 1 PC  | 197.30   | 197.30 ✓             |
| 56.                                                                                                                                                                                                      | HEADLAMP PANEL RH & LH           | 2 PCS | 195.50   | 391.00 ✓             |
| 57.                                                                                                                                                                                                      | HEADLAMP GARNISH RH & LH         | 2 PCS | 33.30    | 66.60 ✓              |
| 58.                                                                                                                                                                                                      | FRONT V-BAR RH & LH ~ photo.     | 2 PCS | 18.90    | 37.80 ✓              |
| 59.                                                                                                                                                                                                      | AIR GUIDE                        | 1 PC  | 335.45   | 335.45 ✓             |
| 60.                                                                                                                                                                                                      | AIR CON CONDENSER ~ photo.       | 1 PC  | 1,028.35 | 1,028.35 ✓           |
| 61.                                                                                                                                                                                                      | AIR CON DISCHARGE PIPE           | 1 PC  | 311.10   | 311.10 ✓             |
| 62.                                                                                                                                                                                                      | AIR CON ALUMINIUM PIPE           | 1 PC  | 261.30   | 261.30 ✓             |
| 63.                                                                                                                                                                                                      | INTERCOOLER - CHECK - 655.65 ✓   | 1 PC  | ?        | 655.65 ✓             |
| 64.                                                                                                                                                                                                      | RADIATOR ASSY                    | 1 PC  | 1,092.75 | 1,092.75 ✓           |
| 65.                                                                                                                                                                                                      | RADIATOR FAN ASSY                | 1 PC  | 1,324.10 | 1,324.10 ✓           |
| 66.                                                                                                                                                                                                      | RADIATOR TOP COVER RH & LH       | 2 PCS | 35.35    | 70.70 ✓              |
| 67.                                                                                                                                                                                                      | FRONT FENDER LH                  | 1 PC  | 894.90   | 894.90 ✓             |
| 68.                                                                                                                                                                                                      | FRONT FENDER TOP GARNISH LH & RH | 2 PCS | 227.05   | 454.10 ✓             |
| 69.                                                                                                                                                                                                      | FRONT FENDER COWLING FRONT LH    | 1 PC  | 128.20   | 128.20 ✓             |
| 70.                                                                                                                                                                                                      | FRONT FENDER BRACKET LH          | 1 PC  | 84.25    | 84.25 ✓              |
| LIST TOTAL S\$                                                                                                                                                                                           |                                  |       |          | 28,815.80 31,264.40  |
| 5% DISCOUNT S\$                                                                                                                                                                                          |                                  |       |          | - 1,440.79 -1,563.22 |
| SPECIAL NET ITEMS :                                                                                                                                                                                      |                                  |       |          |                      |
| 1.                                                                                                                                                                                                       | FRONT NUMBER PLATE               |       |          |                      |
| 2.                                                                                                                                                                                                       | COOLANT                          |       |          |                      |
| SPECIAL NET TOTAL S\$                                                                                                                                                                                    |                                  |       |          | 29,701.18            |
| LABOUR :                                                                                                                                                                                                 |                                  |       |          |                      |
| TOWING CHARGE (KING TROLLY)                                                                                                                                                                              |                                  |       |          | 120.00               |
| TO CUT/WELD REAR END PANEL, KNOCK AND STRAIGHTEN REAR BODY MEMBERS, SPARE WHEEL PANEL, FRONT BODY MEMBER, FRONT FENDER INNER PANEL LH, REMOVE AND REPLACE ACCIDENT DAMAGED PARTS. REALIGN ALL CONNECTION |                                  |       |          | 2,500.00             |
| SPRAY PAINT BONNET, FRONT FENDERS RH & LH, FRONT BUMPER, BOOT LID, REAR END PANEL, SPARE WHEEL PANEL, REAR FENDER, REAR BUMPER                                                                           |                                  |       |          | 2,000.00             |
| REMOVE & REINSTALL AIR CON CONDENSER, PIPE, HOSE AND RECHARGE AIR CON GAS                                                                                                                                |                                  |       |          | 120.00               |
| RE-PROGRAMME / INSTATE HEADLAMP ASSY                                                                                                                                                                     |                                  |       |          | 280.00               |
| REMOVE & REFIT LUGGAGE COMPARTMENT INNER TRIM, GARNISH, COVERING                                                                                                                                         |                                  |       |          | 100.00               |

# Estimate

14/05/2019

MSIG INSURANCE (S) PTE LTD (SGX CENTRE)  
16, RAFFLES QUAY  
#24-01 HONG LEONG BUILDING  
SINGAPORE 048581.

Attention :- XA013

Page # :- 1 134932  
Veh # :- SKK9183H  
Veh Model :- BMW 520i 2.0L AT D/AB 2WD  
Estimate# :- CK419150  
Claim # :-  
ACC. Date :- 11/05/19  
Terms :- C.O.D Days  
Remarks :-

**Main Office:**  
Mova Building  
No. 22, Jalan Kilang,  
Singapore 159419  
Tel: (65) 6476 3333  
Fax: (65) 6271 5891  
www.mova.com.sg  
**Workshop Dept:**  
Block 1008,  
Bukit Merah Lane 3,  
#01-04/06/08/94  
Singapore 159722  
Tel: (65) 6272 3892  
Fax: (65) 6270 8314  
Co. Reg. 198904033G  
GST Reg. M2-0088864-2

| No. | Description                                          | Qty | U.Price | Amounts S\$         |
|-----|------------------------------------------------------|-----|---------|---------------------|
|     | REMOVE & REFIT EXHAUST PIPE, HEAT COVER, MOUNTINGS   |     | 60.     | 100.00              |
|     | DIAGNOSE AND RESET VEHICLE SETTING AFTER REPAIR      |     | 150     | 280.00              |
|     | CHECK CHASSIS ALIGNMENT ON LASER LOCK MACHINE        |     | ?       | 300.00              |
|     | CHECK WIRING & FOCUS HEADLIGHT                       |     | 30.     | 50.00               |
|     | RUST PROOF AFFECTED AREA                             |     | 60.     | 150.00              |
|     | LABOUR TOTAL S\$                                     |     |         | 3) 4000.00 6,140.00 |
|     | Suspension Rod: R & L Front Strut Head Bolt 14 x 1.4 |     | 300.00  |                     |

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$

35,911.18

GST @ 7 %

2,513.78

AMOUNT DUE S\$

38,424.96

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD

1) PAID 25934.22  
2) 9/11/17 70.00  
3) LABOUR 4000.00  
4) Suspension Rod 2053.62  
5) Supp. Labor 300.00  
32357.84  
- 6471.56 12% GST  
25886.27

Lump Sum \$25850.00

Please advice.  
Thank You RUTH LIM.

Tanfer 97445749

WP  
15/5/19 R4

Lumpsum / partly part.  
Resum before / after part.

12 days

Supp. Labor  
To check repair limit



Automotive Pte Ltd


Date: June 04, 2019 Time: 11:43 AM

Customer.....: SKK9183H, BMWS20I  
Vehicle.....: 2013-BMW-BMW520i  
VIN: .....: VBAXG120X05X6408  
Work Order #: 23407  
Technician.....: 11111  
Odometer.....: 11111

Height

415  
415

415  
415



Length

From

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING |             |               |                                                      |                                                       |                                                 |            |                                                                 |
|--------------------------|-------------|---------------|------------------------------------------------------|-------------------------------------------------------|-------------------------------------------------|------------|-----------------------------------------------------------------|
| Case                     | Notified    | Est Submitted | Adj Assigned                                         | Adj Rpt                                               | Adj Submitted                                   | Ins Auth'd | Status                                                          |
| Main                     | 15 May 2019 |               | 16 May 2019<br>10:35<br><a href="#">Edit Adj Rpt</a> | <b>S\$22,000.00</b><br><a href="#">Edit Estimates</a> | <b>S\$22,000.00</b><br><a href="#">View Rpt</a> |            | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

| Main                                                                                                                                                                          | Reference                                                                                                                        | Claim Details          | Documents                                                                    | Show All |         |             |              |            |       |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------|------------------------|------------------------------------------------------------------------------|----------|---------|-------------|--------------|------------|-------|
| <b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>                                                                                        |                                                                                                                                  |                        |                                                                              |          |         |             |              |            |       |
| Insured:                                                                                                                                                                      | HITACHI CAPITAL ASIA PACIFIC PTE LTD, Co. Reg. No.: 199400399N                                                                   |                        |                                                                              |          |         |             |              |            |       |
| Main Claimant:                                                                                                                                                                | SEET KENG KIM HERBERT, ID: S1089183C                                                                                             |                        |                                                                              |          |         |             |              |            |       |
| Vehicle Reg. No.:                                                                                                                                                             | SKK9183H                                                                                                                         | Date of Loss:          | 11/05/2019 17:00 - :59<br>[72 Months and 15 Days From LTA Reg Date (Man Yr)] |          |         |             |              |            |       |
| Claim Type:                                                                                                                                                                   | TP / MSC/V/19-000555                                                                                                             | Policy/Cover Note No.: | MSD/VPCP/19-000336-00 (Comprehensive)<br>Coverage: 16/04/2019 - 15/04/2020   |          |         |             |              |            |       |
| Vehicle Reg. No. (Insured):                                                                                                                                                   | SLX8784A                                                                                                                         | Policy No. (Claimant): |                                                                              |          |         |             |              |            |       |
|                                                                                                                                                                               |                                                                                                                                  | Excess:                |                                                                              |          |         |             |              |            |       |
| Repairer:                                                                                                                                                                     | Mova Automotive Pte Ltd (Bukit Merah) Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3, 159722 Bukit Merah - Tel: 62723892/64763333 |                        |                                                                              |          |         |             |              |            |       |
| Handling Insurer:                                                                                                                                                             | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]               |                        |                                                                              |          |         |             |              |            |       |
| Claimant's Insurer:                                                                                                                                                           | NTUC Income Insurance Co-operative Ltd (HQ) - Tel:                                                                               |                        |                                                                              |          |         |             |              |            |       |
| Adjuster:                                                                                                                                                                     | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 15/06/2019]        |                        |                                                                              |          |         |             |              |            |       |
| Driver/Custodian (Insured):                                                                                                                                                   | KONDO TAKA AKI (51 / Male), NRIC: G6061638N Email:                                                                               |                        |                                                                              |          |         |             |              |            |       |
| Adj Asg. Remarks:                                                                                                                                                             | on WP. (MANUAL ASSIGNED) SURVEY AGREE ON SJE - REQ TO ASSIGN LKK. LIABILITY: 100% CONTACT: NABILAH 6262 3377                     |                        |                                                                              |          |         |             |              |            |       |
| <b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>                                                 |                                                                                                                                  |                        |                                                                              |          |         |             |              |            |       |
| There are no mail for this case.                                                                                                                                              |                                                                                                                                  |                        |                                                                              |          |         |             |              |            |       |
| <b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span> |                                                                                                                                  |                        |                                                                              |          |         |             |              |            |       |
| Due Date                                                                                                                                                                      | Priority                                                                                                                         | Type                   | Task Group                                                                   | Subject  | Handler | Assigned By | Completed On | Created On | Done? |
| No results.                                                                                                                                                                   |                                                                                                                                  |                        |                                                                              |          |         |             |              |            |       |

## Claim Documents

\*SKK9183H (MSC/V/19-000555)  
[SLX8784A]  
TP  
SEET KENG KIM HERBERT  
May 11 2019 5:00PM  
[HITACHI CAPITAL ASIA PACIFIC PTE LTD]  
Mova Automotive Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

**View** View in Browser

1 per page

☒

| Assessment Reports |                |                                       | Thumbnail | Print                               |
|--------------------|----------------|---------------------------------------|-----------|-------------------------------------|
| No                 | Finalized On   | Mova Automotive Pte Ltd (Bukit Merah) |           |                                     |
| 1                  | 13/05/19 13:32 | Accident Statement                    | Load HTM  | <input checked="" type="checkbox"/> |
| No                 | Finalized On   | LKK Auto Consultants Pte Ltd (HQ)     |           |                                     |
| 1                  | 16/05/19 13:33 | Adjuster Immediate Advice             | Load HTM  | <input checked="" type="checkbox"/> |

3 per page

☒

| Photos/Images |                 |                                   | Thumbnail | Print                               |
|---------------|-----------------|-----------------------------------|-----------|-------------------------------------|
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) |           |                                     |
| 1             | 04/07/19 15:57  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 2             | 04/07/19 15:57  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 3             | 04/07/19 15:57  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 4             | 04/07/19 15:57  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 5             | 04/07/19 15:57  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 6             | 04/07/19 15:57  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 7             | 04/07/19 15:57  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 8             | 04/07/19 15:57  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 9             | 04/07/19 15:57  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 10            | 04/07/19 15:57  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 11            | 04/07/19 15:57  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 12            | 04/07/19 15:57  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 13            | 04/07/19 15:57  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 14            | 04/07/19 15:57  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 15            | 04/07/19 15:57  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 16            | 04/07/19 15:57  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 17            | 04/07/19 15:57  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 18            | 04/07/19 15:57  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 19            | 04/07/19 15:57  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 20            | 04/07/19 15:57  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 21            | 04/07/19 15:57  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 22            | 04/07/19 15:57  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 23            | 04/07/19 15:57  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 24            | 04/07/19 15:57  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 25            | 04/07/19 15:57  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 26            | 04/07/19 15:57  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 27            | 04/07/19 15:57  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 28            | 04/07/19 15:57  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 29            | 04/07/19 15:57  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 30            | 04/07/19 15:57  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 31            | 04/07/19 15:57  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 32            | 04/07/19 15:57  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |

| Assessment Reports |                |                                       | 1 per page                                                                                     | <input checked="" type="checkbox"/> |
|--------------------|----------------|---------------------------------------|------------------------------------------------------------------------------------------------|-------------------------------------|
| No                 | Finalized On   | Mova Automotive Pte Ltd (Bukit Merah) | Thumbnail                                                                                      | Print                               |
| 33                 | 04/07/19 15:57 | General View                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 34                 | 04/07/19 15:57 | General View                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 35                 | 04/07/19 15:57 | General View                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 36                 | 04/07/19 15:57 | General View                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 37                 | 04/07/19 15:57 | General View                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 38                 | 04/07/19 15:57 | General View                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 39                 | 04/07/19 15:57 | General View                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 40                 | 04/07/19 15:57 | General View                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 41                 | 04/07/19 15:57 | General View                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 42                 | 04/07/19 15:57 | General View                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 43                 | 04/07/19 15:57 | General View                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 44                 | 04/07/19 15:57 | General View                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 45                 | 04/07/19 15:57 | General View                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 46                 | 04/07/19 15:57 | General View                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 47                 | 04/07/19 15:57 | General View                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 48                 | 04/07/19 15:57 | General View                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 49                 | 04/07/19 15:57 | General View                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 50                 | 04/07/19 15:57 | General View                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 51                 | 04/07/19 15:57 | General View                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 52                 | 04/07/19 15:57 | General View                          |  Load JPG  | <input checked="" type="checkbox"/> |
| 53                 | 04/07/19 15:57 | General View                          |  Load JPG | <input checked="" type="checkbox"/> |
| 54                 | 04/07/19 15:57 | General View                          |  Load JPG | <input checked="" type="checkbox"/> |
| 55                 | 04/07/19 15:57 | General View                          |  Load JPG | <input checked="" type="checkbox"/> |
| 56                 | 04/07/19 15:57 | General View                          |  Load JPG | <input checked="" type="checkbox"/> |
| 57                 | 04/07/19 15:57 | General View                          |  Load JPG | <input checked="" type="checkbox"/> |
| 58                 | 04/07/19 15:57 | General View                          |  Load JPG | <input checked="" type="checkbox"/> |
| 59                 | 04/07/19 15:57 | General View                          |  Load JPG | <input checked="" type="checkbox"/> |
| 60                 | 04/07/19 15:57 | General View                          |  Load JPG | <input checked="" type="checkbox"/> |
| 61                 | 04/07/19 15:57 | General View                          |  Load JPG | <input checked="" type="checkbox"/> |
| 62                 | 04/07/19 15:57 | General View                          |  Load JPG | <input checked="" type="checkbox"/> |
| 63                 | 04/07/19 15:57 | General View                          |  Load JPG | <input checked="" type="checkbox"/> |
| 64                 | 04/07/19 15:57 | General View                          |  Load JPG | <input checked="" type="checkbox"/> |
| 65                 | 04/07/19 15:57 | General View                          |  Load JPG | <input checked="" type="checkbox"/> |
| 66                 | 04/07/19 15:57 | General View                          |  Load JPG | <input checked="" type="checkbox"/> |
| 67                 | 04/07/19 15:57 | General View                          |  Load JPG | <input checked="" type="checkbox"/> |
| 68                 | 04/07/19 15:57 | General View                          |  Load JPG | <input checked="" type="checkbox"/> |
| 69                 | 04/07/19 15:57 | General View                          |  Load JPG | <input checked="" type="checkbox"/> |
| 70                 | 04/07/19 15:57 | General View                          |  Load JPG | <input checked="" type="checkbox"/> |
| 71                 | 04/07/19 15:57 | General View                          |  Load JPG | <input checked="" type="checkbox"/> |
| 72                 | 04/07/19 15:57 | General View                          |  Load JPG | <input checked="" type="checkbox"/> |
| 73                 | 04/07/19 15:57 | General View                          |  Load JPG | <input checked="" type="checkbox"/> |
| 74                 | 04/07/19 15:57 | General View                          |  Load JPG | <input checked="" type="checkbox"/> |
| 75                 | 04/07/19 15:57 | General View                          |  Load JPG | <input checked="" type="checkbox"/> |
| 76                 | 04/07/19 15:57 | General View                          |  Load JPG | <input checked="" type="checkbox"/> |
| 77                 | 04/07/19 15:57 | General View                          |  Load JPG | <input checked="" type="checkbox"/> |
| 78                 | 04/07/19 15:57 | General View                          |  Load JPG | <input checked="" type="checkbox"/> |
| 79                 | 04/07/19 15:57 | General View                          |  Load JPG | <input checked="" type="checkbox"/> |
| 80                 | 04/07/19 15:57 | General View                          |  Load JPG | <input checked="" type="checkbox"/> |
| 81                 | 04/07/19 15:57 | General View                          |  Load JPG | <input checked="" type="checkbox"/> |
| 82                 | 04/07/19 15:57 | General View                          |  Load JPG | <input checked="" type="checkbox"/> |

| Assessment Reports |                |                                       | 1 per page                                                                                     | <input checked="" type="checkbox"/> |
|--------------------|----------------|---------------------------------------|------------------------------------------------------------------------------------------------|-------------------------------------|
| No                 | Finalized On   | Mova Automotive Pte Ltd (Bukit Merah) | Thumbnail                                                                                      | Print                               |
| 83                 | 04/07/19 15:57 | General View                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 84                 | 04/07/19 15:57 | General View                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 85                 | 04/07/19 15:57 | General View                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 86                 | 04/07/19 15:57 | General View                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 87                 | 04/07/19 15:57 | General View                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 88                 | 04/07/19 15:57 | General View                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 89                 | 04/07/19 15:57 | General View                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 90                 | 04/07/19 15:57 | General View                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 91                 | 04/07/19 15:57 | General View                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 92                 | 04/07/19 15:57 | General View                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 93                 | 04/07/19 15:57 | General View                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 94                 | 04/07/19 15:57 | General View                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 95                 | 04/07/19 15:57 | General View                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 96                 | 04/07/19 15:57 | General View                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 97                 | 04/07/19 15:57 | General View                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 98                 | 04/07/19 15:57 | General View                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 99                 | 04/07/19 15:57 | General View                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 100                | 04/07/19 15:57 | General View                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 101                | 04/07/19 15:57 | General View                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 102                | 04/07/19 15:57 | General View                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 103                | 04/07/19 15:57 | General View                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 104                | 04/07/19 15:57 | General View                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 105                | 04/07/19 15:57 | General View                          |  Load JPG  | <input checked="" type="checkbox"/> |
| 106                | 04/07/19 15:57 | General View                          |  Load JPG | <input checked="" type="checkbox"/> |
| 107                | 04/07/19 15:57 | General View                          |  Load JPG | <input checked="" type="checkbox"/> |
| 108                | 04/07/19 15:57 | General View                          |  Load JPG | <input checked="" type="checkbox"/> |
| 109                | 04/07/19 15:57 | General View                          |  Load JPG | <input checked="" type="checkbox"/> |
| 110                | 04/07/19 15:57 | General View                          |  Load JPG | <input checked="" type="checkbox"/> |
| 111                | 04/07/19 15:57 | General View                          |  Load JPG | <input checked="" type="checkbox"/> |
| 112                | 04/07/19 15:57 | General View                          |  Load JPG | <input checked="" type="checkbox"/> |
| 113                | 04/07/19 15:57 | General View                          |  Load JPG | <input checked="" type="checkbox"/> |
| 114                | 04/07/19 15:57 | General View                          |  Load JPG | <input checked="" type="checkbox"/> |
| 115                | 04/07/19 15:57 | General View                          |  Load JPG | <input checked="" type="checkbox"/> |
| 116                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 117                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 118                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 119                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 120                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 121                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 122                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 123                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 124                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 125                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 126                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 127                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 128                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 129                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 130                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 131                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 132                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |

| Assessment Reports |                |                                       | 1 per page                                                                                     | <input checked="" type="checkbox"/> |
|--------------------|----------------|---------------------------------------|------------------------------------------------------------------------------------------------|-------------------------------------|
| No                 | Finalized On   | Mova Automotive Pte Ltd (Bukit Merah) | Thumbnail                                                                                      | Print                               |
| 133                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 134                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 135                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 136                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 137                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 138                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 139                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 140                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 141                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 142                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 143                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 144                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 145                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 146                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 147                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 148                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 149                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 150                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 151                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 152                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 153                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 154                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG  | <input checked="" type="checkbox"/> |
| 155                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 156                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 157                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 158                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 159                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 160                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 161                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 162                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 163                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 164                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 165                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 166                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 167                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 168                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 169                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 170                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 171                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 172                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 173                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 174                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 175                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 176                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 177                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 178                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 179                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 180                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 181                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 182                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |

| Assessment Reports |                |                                       | 1 per page                                                                                     | <input checked="" type="checkbox"/> |
|--------------------|----------------|---------------------------------------|------------------------------------------------------------------------------------------------|-------------------------------------|
| No                 | Finalized On   | Mova Automotive Pte Ltd (Bukit Merah) | Thumbnail                                                                                      | Print                               |
| 183                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 184                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 185                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 186                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 187                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 188                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 189                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 190                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 191                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 192                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 193                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 194                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 195                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 196                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 197                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 198                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 199                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 200                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 201                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 202                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 203                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 204                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 205                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 206                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 207                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 208                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 209                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 210                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 211                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 212                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 213                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 214                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 215                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 216                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 217                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 218                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 219                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 220                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 221                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 222                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 223                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 224                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 225                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 226                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 227                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 228                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 229                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 230                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 231                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |
| 232                | 04/07/19 16:00 | Reinspection Photo                    |  Load JPG | <input checked="" type="checkbox"/> |

| Assessment Reports |                 |                                                          | 1 per page                                                                                     | <input checked="" type="checkbox"/> |
|--------------------|-----------------|----------------------------------------------------------|------------------------------------------------------------------------------------------------|-------------------------------------|
| No                 | Finalized On    | Mova Automotive Pte Ltd (Bukit Merah)                    | Thumbnail                                                                                      | Print                               |
| 233                | 04/07/19 16:00  | Reinspection Photo                                       |  Load JPG   | <input checked="" type="checkbox"/> |
| 234                | 04/07/19 16:00  | Reinspection Photo                                       |  Load JPG   | <input checked="" type="checkbox"/> |
| 235                | 04/07/19 16:00  | Reinspection Photo                                       |  Load JPG   | <input checked="" type="checkbox"/> |
| 236                | 04/07/19 16:00  | Reinspection Photo                                       |  Load JPG   | <input checked="" type="checkbox"/> |
| 237                | 04/07/19 16:00  | Reinspection Photo                                       |  Load JPG   | <input checked="" type="checkbox"/> |
| 238                | 04/07/19 16:00  | Reinspection Photo                                       |  Load JPG   | <input checked="" type="checkbox"/> |
| 239                | 04/07/19 16:00  | Reinspection Photo                                       |  Load JPG   | <input checked="" type="checkbox"/> |
| 240                | 04/07/19 16:00  | Reinspection Photo                                       |  Load JPG   | <input checked="" type="checkbox"/> |
| 241                | 04/07/19 16:00  | Reinspection Photo                                       |  Load JPG   | <input checked="" type="checkbox"/> |
| 242                | 04/07/19 16:00  | Reinspection Photo                                       |  Load JPG   | <input checked="" type="checkbox"/> |
| 243                | 04/07/19 16:00  | Reinspection Photo                                       |  Load JPG   | <input checked="" type="checkbox"/> |
| 244                | 04/07/19 16:00  | Reinspection Photo                                       |  Load JPG   | <input checked="" type="checkbox"/> |
| 245                | 04/07/19 16:00  | Reinspection Photo                                       |  Load JPG   | <input checked="" type="checkbox"/> |
| 246                | 04/07/19 16:00  | Reinspection Photo                                       |  Load JPG   | <input checked="" type="checkbox"/> |
| 247                | 04/07/19 16:00  | Reinspection Photo                                       |  Load JPG   | <input checked="" type="checkbox"/> |
| 248                | 04/07/19 16:00  | Reinspection Photo                                       |  Load JPG   | <input checked="" type="checkbox"/> |
| 249                | 04/07/19 16:00  | Reinspection Photo                                       |  Load JPG   | <input checked="" type="checkbox"/> |
| 250                | 04/07/19 16:00  | Reinspection Photo                                       |  Load JPG   | <input checked="" type="checkbox"/> |
| 251                | 04/07/19 16:00  | Reinspection Photo                                       |  Load JPG   | <input checked="" type="checkbox"/> |
| 252                | 04/07/19 16:00  | Reinspection Photo                                       |  Load JPG   | <input checked="" type="checkbox"/> |
| 253                | 04/07/19 16:00  | Reinspection Photo                                       |  Load JPG   | <input checked="" type="checkbox"/> |
| 254                | 04/07/19 16:00  | Reinspection Photo                                       |  Load JPG  | <input checked="" type="checkbox"/> |
| Documentation      |                 |                                                          | 1 per page                                                                                     | <input checked="" type="checkbox"/> |
| No                 | Finalized On    | MSIG Insurance (Singapore) Pte. Ltd. (HQ)                | Thumbnail                                                                                      | Print                               |
| 1                  | 15/05/19 17:52  | E-FILE REPORT (SKZ287Y)                                  |  Load PDF |                                     |
| 2                  | 15/05/19 17:52  | E-FILE REPORT (SLL9282M)                                 |  Load PDF |                                     |
| 3                  | 15/05/19 17:55  | E-FILE REPORT (SLX8784A)                                 |  Load PDF |                                     |
| 4                  | 15/05/19 18:15  | TP EST BILL                                              |  Load PDF |                                     |
| 5                  | 16/05/19 09:21  | SURVEY AGREE ON SJE - REQ TO ASSIGN LKK                  |  Load PDF |                                     |
| No                 | Finalized On    | MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor) | Thumbnail                                                                                      | Print                               |
| 1                  | 16/05/19 10:33  | email - manual assign                                    |  Load PDF |                                     |
| No                 | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)                        | Thumbnail                                                                                      | Print                               |
| 1                  | 18/07/19 16:10  | Supplementary                                            |  Load PDF |                                     |

## Linked Accident Report Documents

| Assessment Reports |                |                                       | 1 per page                                                                                     | <input checked="" type="checkbox"/> |
|--------------------|----------------|---------------------------------------|------------------------------------------------------------------------------------------------|-------------------------------------|
| No                 | Finalized On   | Mova Automotive Pte Ltd (Bukit Merah) | Thumbnail                                                                                      | Print                               |
| 1                  | 13/05/19 13:32 | Accident Statement                    |  Load HTM |                                     |
| Photos/Images      |                |                                       | 3 per page                                                                                     | <input checked="" type="checkbox"/> |
| No                 | Finalized On   | Mova Automotive Pte Ltd (Bukit Merah) | Thumbnail                                                                                      | Print                               |
| 1                  | 13/05/19 13:32 | Accident Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 2                  | 13/05/19 13:32 | Accident Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 3                  | 13/05/19 13:32 | Accident Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 4                  | 13/05/19 13:32 | Accident Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 5                  | 13/05/19 13:32 | Accident Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 6                  | 13/05/19 13:32 | Accident Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 7                  | 13/05/19 13:32 | Accident Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 8                  | 13/05/19 13:32 | Accident Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 9                  | 13/05/19 13:32 | Accident Photo                        |  Load JPG | <input checked="" type="checkbox"/> |

|                           |                |                                       |                                                                                              |                                     |
|---------------------------|----------------|---------------------------------------|----------------------------------------------------------------------------------------------|-------------------------------------|
| <b>Assessment Reports</b> |                |                                       | 1 per page                                                                                   | <input type="checkbox"/>            |
| No                        | Finalized On   | Mova Automotive Pte Ltd (Bukit Merah) | Thumbnail                                                                                    | Print                               |
| <b>Documentation</b>      |                |                                       | 1 per page                                                                                   | <input checked="" type="checkbox"/> |
| No                        | Finalized On   | Mova Automotive Pte Ltd (Bukit Merah) | Thumbnail                                                                                    | Print                               |
| 1                         | 13/05/19 13:24 | Sketch Plan                           |  Load TIF |                                     |

## Documents Checklist

|                                                                   |       |      |       |
|-------------------------------------------------------------------|-------|------|-------|
| <b>DOCUMENTS CHECKLIST</b>                                        | Reset | Save | Print |
| There are no document checklists configured.                      |       |      |       |
| <b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>  |       |      |       |
| <div></div>                                                       |       |      |       |
| <b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer |       |      |       |
| Note: Remarks are private unless you show it to other parties.    |       |      |       |

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19008608/T1SD3E2  
Date: 18/07/2019

## REFERENCE

|                       |                                      |                      |                       |
|-----------------------|--------------------------------------|----------------------|-----------------------|
| Handling Insurer:     | MSIG Insurance (Singapore) Pte. Ltd. | Policy No:           | MSD/VPCP/19-000336-00 |
| Claimant Vehicle No : | SKK9183H                             | Insured Vehicle No : | SLX8784A              |
| Date of Loss:         | 11/05/2019                           | Nature of Claim:     | TP                    |
|                       |                                      | Claim No:            | MSC/V/19-000555       |

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

|                             |                                          |             |                   |
|-----------------------------|------------------------------------------|-------------|-------------------|
| Reg No:                     | <b>SKK9183H</b>                          |             |                   |
| Make & Model:               | BMW 520I, 2.0 D/AB 2WD 4DR GAS/D NAV (A) | Engine No:  | A4290442N20B20B   |
| Reg. Date:                  | 26/04/2013 (Man. Year: 2013)             | Chassis No: | WBAXG120X0DX53408 |
| Colour:                     | Bronze                                   | Odometer:   | 108759 km         |
| Engine Capacity:            | 1997 cc                                  |             |                   |
| Market Value/New Car Price: | N/A                                      |             |                   |
| Sum Insured (\$\$):         | <b>Market Value/New Car Price</b>        |             |                   |

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

## CONDITION OF TYRES

|                   |              |                  |              |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size:  | 225/55 R17   | Rear Tyre Size:  | 225/55 R17   |
| Front Left Side:  | Pirelli 6 mm | Rear Left Side:  | Pirelli 6 mm |
| Front Right Side: | Pirelli 6 mm | Rear Right Side: | Pirelli 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                            | Repairer's       | Adjuster's       | Difference       | Diff %       |
|-------------------------------------------|------------------|------------------|------------------|--------------|
| Parts                                     | 31,811.59        | 27,262.78        | 4,548.81         | 14.30        |
| Miscellaneous Items                       | 0.00             | 0.00             | 0.00             |              |
| Labour                                    | 6,140.00         | 4,000.00         | 2,140.00         | 34.85        |
| Paintwork Labour                          | 0.00             | 0.00             | 0.00             |              |
| Towing                                    | 0.00             | 0.00             | 0.00             |              |
| <b>Calculated Gross Total (\$\$)</b>      | <b>37,951.59</b> | <b>31,262.78</b> | <b>6,688.81</b>  | <b>17.62</b> |
| <b>Approved Total (Overridden) (\$\$)</b> |                  | <b>22,000.00</b> |                  |              |
| <b>(\$\$)</b>                             | 37,951.59        | 22,000.00        | 15,951.59        | 42.03        |
| <b>+ GST 7.00/7.00% (\$\$)</b>            | 2,656.61         | 1,540.00         | 1,116.61         | 42.03        |
| <b>Nett Amount (\$\$)</b>                 | <b>40,608.20</b> | <b>23,540.00</b> | <b>17,068.20</b> | <b>42.03</b> |

## INSPECTION

|                             |            |                                       |
|-----------------------------|------------|---------------------------------------|
| Date of Assignment:         | 16/05/2019 |                                       |
| Date Inspected:             | 15/05/2019 | Inspected At:                         |
|                             |            | Mova Automotive Pte Ltd (Bukit Merah) |
|                             |            | 15 FAN YONG ROAD                      |
|                             |            | SINGAPORE 629792                      |
| Estimated Period of Repair: | 12.0 days  |                                       |

---

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

|                            |                                                                                                                                                                              |
|----------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Part Source:</b> MRM-SG | Version: 1.0 (Last Synchronised: 18 Jul 2019)                                                                                                                                |
| <b>Parts:</b> 143          | BMW 520I 2.0 D/AB 2WD 4DR GAS/D NAV (A) (Catalogue:Merimen Singapore 1.0)                                                                                                    |
| <b>Labour:</b> Repairer's  | (Price-denominated Standard List)                                                                                                                                            |
| <b>Print Code:</b>         | (Unsubmitted, no print-code for SKK9183H)                                                                                                                                    |
| <b>Validity:</b>           | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| <b>Further Info:</b>       | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |

## Recommended Parts

| No. | Qty | Part No. | Particulars                   | Condition                    | Repairer's  | Amount       |
|-----|-----|----------|-------------------------------|------------------------------|-------------|--------------|
| 1   | 1   |          | *BOOT LID                     | Bent                         | 1,642.45 FL | *1,642.45 FL |
| 2   | 1   |          | *BOOT LID LOGO                | Necessary                    | 71.25 FL    | *71.25 FL    |
| 3   | 1   |          | *BOOT LID EMBLEM - 520I       | Necessary                    | 64.10 FL    | *64.10 FL    |
| 4   | 1   |          | *BOOT LID REFLECTOR LH        | Not Necessary                | 360.25 FL   | *- FL        |
| 5   | 1   |          | *BOOT LID LOCK                | Bent                         | 425.35 FL   | *425.35 FL   |
| 6   | 1   |          | *BOOT LID WEATHERSTRIP        | Deformed                     | 106.60 FL   | *106.60 FL   |
| 7   | 1   |          | *TAIL LAMP ASSY LH            | Not Necessary                | 609.95 FL   | *- FL        |
| 8   | 1   |          | *REAR END PANEL               | Bent                         | 817.30 FL   | *817.30 FL   |
| 9   | 1   |          | *REAR END PANEL TOP COVER     | Not Necessary                | 115.55 FL   | *- FL        |
| 10  | 1   |          | *REAR BUMPER                  | Cracked                      | 1,563.35 FL | *1,563.35 FL |
| 11  | 1   |          | *REAR CHASSIS MEMBER LH (NPA) | Repair                       | 0.00 FL     | *- FL        |
| 12  | 1   |          | *REAR BUMPER REINFORCEMENT    | Bent                         | 772.05 FL   | *772.05 FL   |
| 13  | 1   |          | *REAR BUMPER RETAINER RH & LH | N/SNecessary/O/SNotNecessary | 311.80 FL   | *155.90 FL   |
| 14  | 1   |          | *REAR BUMPER REFLECTOR LH     | Cracked                      | 36.80 FL    | *36.80 FL    |
| 15  | 1   |          | *REAR BUMPER LOWER GARNISH    | Cracked                      | 60.45 FL    | *60.45 FL    |
| 16  | 10  |          | *REAR BUMPER CLIPS            | Necessary                    | 50.00 FL    | *50.00 FL    |
| 17  | 2   |          | *REAR TOW COVER RH & LH       | Missing                      | 95.20 FL    | *95.20 FL    |
| 18  | 2   |          | *REVERSE SENSOR INNER RH & LH | Not Working                  | 473.70 FL   | *473.70 FL   |
| 19  | 1   |          | *REVER SENSOR OUTER LH        | Not Working                  | 236.85 FL   | *236.85 FL   |
| 20  | 1   |          | *REAR EXHAUST PIPE            | Bent                         | 1,270.90 FL | *1,270.90 FL |
| 21  | 1   |          | *BONNET                       | Bent                         | 2,325.25 FL | *2,325.25 FL |
| 22  | 2   |          | *BONNET HINGE RH & LH         | Repair                       | 185.50 FL   | *- FL        |
| 23  | 1   |          | *BONNET RUBBER                | Cut                          | 38.85 FL    | *38.85 FL    |
| 24  | 1   |          | *BONNET OPENER                | Distorted                    | 88.20 FL    | *88.20 FL    |
| 25  | 2   |          | *RIVET                        | Necessary                    | 10.00 FL    | *10.00 FL    |
| 26  | 2   |          | *BONNET CATCH RH & LH         | Bent                         | 137.20 FL   | *137.20 FL   |
| 27  | 2   |          | *BONNET LOCK RH & LH          | Bent                         | 377.20 FL   | *377.20 FL   |
| 28  | 2   |          | *BONNET LOCK TOP RH & LH      | Deformed                     | 176.80 FL   | *176.80 FL   |
| 29  | 1   |          | *BONNET INSULATOR             | Deformed                     | 222.00 FL   | *222.00 FL   |
| 30  | 2   |          | *BONNET DAMPER RH & LH        | Not Necessary                | 283.40 FL   | *- FL        |
| 31  | 2   |          | *HEADLAMP ASSY RH & LH        | N/S Cracked/O/S Distorted    | 5,299.30 FL | *5,299.30 FL |
| 32  | 1   |          | *HEADLAMP MODULE LH           | Distorted                    | 763.70 FL   | *763.70 FL   |
| 33  | 1   |          | *HEADLAMP LED CONTROL LH      | Distorted                    | 395.75 FL   | *395.75 FL   |
| 34  | 1   |          | *HEADLAMP CONTROL UNIT LH     | Distorted                    | 867.85 FL   | *867.85 FL   |
| 35  | 1   |          | *HEADLAMP NOZZLE JET LH       | Distorted                    | 133.40 FL   | *133.40 FL   |
| 36  | 1   |          | *HEADLAMP NOZZLE COVER LH     | Deformed                     | 47.60 FL    | *47.60 FL    |
| 37  | 1   |          | *HEADLAMP WASHER NOZZLE HOSE  | Distorted                    | 48.70 FL    | *48.70 FL    |
| 38  | 1   |          | *FRONT BUMPER                 | Deformed                     | 1,335.40 FL | *1,335.40 FL |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                          | Condition     | Repairer's  | Amount       |
|-----|-----|----------|--------------------------------------|---------------|-------------|--------------|
| 39  | 1   |          | *FRONT BUMPER LOGO                   | Necessary     | 71.25 FL    | *71.25 FL    |
| 40  | 2   |          | *FRONT BUMPER GRILLE RH & LH         | Cracked       | 266.60 FL   | *266.60 FL   |
| 41  | 1   |          | *FRONT BUMPER LOWER GARNISH - CENTER | Deformed      | 68.80 FL    | *68.80 FL    |
| 42  | 1   |          | *FRONT BUMPER LOWER GARNISH LH       | Deformed      | 72.20 FL    | *72.20 FL    |
| 43  | 1   |          | *FRONT BUMPER SPONGE                 | Deformed      | 48.70 FL    | *48.70 FL    |
| 44  | 1   |          | *FRONT BUMPER REINFORCEMENT          | Bent          | 715.90 FL   | *715.90 FL   |
| 45  | 1   |          | *FRONT BUMPER BEAM                   | Not Necessary | 165.65 FL   | *- FL        |
| 46  | 2   |          | *FRONT BUMPER BRACKET RH & LH        | Necessary     | 48.10 FL    | *48.10 FL    |
| 47  | 1   |          | *FRONT BUMPER RETAINER LH            | Deformed      | 30.80 FL    | *30.80 FL    |
| 48  | 1   |          | *FRONT BUMPER RETAINER PLATE LH      | Deformed      | 20.60 FL    | *20.60 FL    |
| 49  | 10  |          | *FRONT BUMPER CLIPS                  | Necessary     | 50.00 FL    | *50.00 FL    |
| 50  | 2   |          | *FRONT BUMPER SENSOR INNER RH & LH   | Distorted     | 473.70 FL   | *473.70 FL   |
| 51  | 1   |          | *FRONT BUMPER SENSOR OUTER LH        | Distorted     | 236.85 FL   | *236.85 FL   |
| 52  | 1   |          | *FOG LAMP LH                         | Distorted     | 276.25 FL   | *276.25 FL   |
| 53  | 1   |          | *FRONT NUMBER PLATE GARNISH          | Deformed      | 58.20 FL    | *58.20 FL    |
| 54  | 1   |          | *TOP PANEL                           | Bent          | 162.90 FL   | *162.90 FL   |
| 55  | 1   |          | *TOP PANEL REINFORCEMENT             | Bent          | 197.30 FL   | *197.30 FL   |
| 56  | 2   |          | *HEADLAMP PANEL RH & LH              | Repair        | 391.00 FL   | *- FL        |
| 57  | 2   |          | *HEADLAMP GARNISH RH & LH            | Deformed      | 66.60 FL    | *66.60 FL    |
| 58  | 2   |          | *FRONT V-BAR RH & LH                 | Bent          | 37.80 FL    | *37.80 FL    |
| 59  | 1   |          | *AIR GUIDE                           | Bent          | 335.45 FL   | *335.45 FL   |
| 60  | 1   |          | *AIR CON CONDENSER                   | Bent          | 1,028.35 FL | *1,028.35 FL |
| 61  | 1   |          | *AIR CON DISCHARGE PIPE              | Not Necessary | 311.10 FL   | *- FL        |
| 62  | 1   |          | *AIR CON ALUMINIUM PIPE              | Not Necessary | 261.30 FL   | *- FL        |
| 63  | 1   |          | *INTERCOOLER                         | Bent          | 655.65 FL   | *655.65 FL   |
| 64  | 1   |          | *RADIATOR ASSY                       | Bent          | 1,092.75 FL | *1,092.75 FL |
| 65  | 1   |          | *RADIATOR FAN ASSY                   | Distorted     | 1,324.10 FL | *1,324.10 FL |
| 66  | 2   |          | *RADIATOR TOP COVER RH & LH          | Deformed      | 70.70 FL    | *70.70 FL    |
| 67  | 1   |          | *FRONT FENDER LH                     | Buckled       | 894.90 FL   | *894.90 FL   |
| 68  | 2   |          | *FRONT FENDER TOP GARNISH LH & RH    | Cracked       | 454.10 FL   | *454.10 FL   |
| 69  | 1   |          | *FRONT FENDER COWLING FRONT LH       | Deformed      | 128.20 FL   | *128.20 FL   |
| 70  | 1   |          | *FRONT FENDER BRACKET LH             | Bent          | 84.25 FL    | *84.25 FL    |
| 71  | 1   |          | *FRONT NUMBER PLATE                  | Bent          | 40.00 FS    | *40.00 FS    |
| 72  | 1   |          | *COOLANT                             | Necessary     | 30.00 FS    | *30.00 FS    |
| 73  | 1   |          | *FRONT SEAT BULKER RH                | Activated     | 324.40 FL   | *324.40 FL   |
| 74  | 2   |          | *FRONT SEAT REST REPAIR KIT          | Not Necessary | 358.40 FL   | *- FL        |
| 75  | 1   |          | *HEADLAMP NOZZLE JET RH              | Distorted     | 50.65 FL    | *50.65 FL    |
| 76  | 1   |          | *RESONATOR ASSY                      | Deformed      | 232.00 FL   | *232.00 FL   |
| 77  | 1   |          | *RESONATOR HOSE                      | Distorted     | 226.70 FL   | *226.70 FL   |
| 78  | 1   |          | *REAR UNDER COVER RH                 | Deformed      | 165.00 FL   | *165.00 FL   |
| 79  | 2   |          | *GEAR BOX MOUNTING                   | Deformed      | 135.00 FL   | *135.00 FL   |

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 33,482.20 30,284.20  
 - List Item Discount on L Items 5.00/10.00% (\$\$) 1,670.61 3,021.42

Total Parts (\$\$) 31,811.59 27,262.78

|                                               |
|-----------------------------------------------|
| Report was unsubmitted during this print-out. |
|-----------------------------------------------|

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                                                                                                                                                                | Lab.Type | Repairer's      | Amount          |
|---------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                                                                                                                                                                                            |          |                 |                 |
| 1                               | TOWING CHARGE (KING TROLLY)                                                                                                                                                                                | New      | 180.00          | 120.00          |
| 2                               | TO CUT / WELD REAR END PANEL, KNOCK AND STRAIGHTEN REAR BODY MEMBERS, SPARE WHEEL PANEL, FRONT BODY MEMBER, FRONT FENDER INNER PANEL LH. REMOVE AND REPLACE ACCIDENT DAMAGED PARTS. REALIGN ALL CONNECTION | New      | 2,500.00        | 1,600.00        |
| 3                               | SPRAY PAINT BONNET, FRONT FENDERS RH & LH, FRONT BUMPER, BOOT LID, REAR END PANEL, SPARE WHEEL PANEL, REAR FENDER, REAR BUMPER                                                                             | New      | 2,000.00        | 1,400.00        |
| 4                               | REMOVE & REINSTALL AIR CON CONDENSER, PIPE, HOSE AND RECHARGE AIR CON GAS                                                                                                                                  | New      | 120.00          | 120.00          |
| 5                               | RE-PROGRAMME / INSTATE HEADLAMP ASSY                                                                                                                                                                       | New      | 280.00          | 100.00          |
| 6                               | REMOVE & REFIT LUGGAGE COMPARTMENT INNER TRIM, GARNISH, COVERING                                                                                                                                           | New      | 100.00          | 60.00           |
| 7                               | REMOVE & REFIT EXHAUST PIPE, HEAT COVER, MOUNTINGS                                                                                                                                                         | New      | 100.00          | 60.00           |
| 8                               | DIAGNOSE AND RESET VEHICLE SETTING AFTER REPAIR                                                                                                                                                            | New      | 280.00          | 150.00          |
| 9                               | CHECK CHASSIS ALIGNMENT ON LASER LOCK MACHINE                                                                                                                                                              | New      | 380.00          | 300.00          |
| 10                              | CHECK WIRING & FOCUS HEADLIGHT                                                                                                                                                                             | New      | 50.00           | 30.00           |
| 11                              | RUST PROOF AFFECTED AREA                                                                                                                                                                                   | New      | 150.00          | 60.00           |
| <b>Gross Labour Cost (\$\$)</b> |                                                                                                                                                                                                            |          | <b>6,140.00</b> | <b>4,000.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >