

ASS. REC. BY:

REF: CS/FCL19008611/Gvd3m2

Special Instruction:

SUBJECT: GA ASSIGNMENT (Office)From (Person): Henry Kao of FCL Date/Time: 15.5.19 3.01pm

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: EK 1018B Insured: SHC 7979Vat Workshop m/s K. Kim Hin Auto Tel: 64527018 Mang Huatof 160 Sa Ming Drive #02-20 9717 6881Policy No: \_\_\_\_\_ Claim No: D19003173MFCH

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 11-5-2019  
(Client's Record)CA / REV / REP. / REV 24 HRS "19" H.O.D. Endorsement: \_\_\_\_\_Date/Time: 15.5.19 3.05pm Person Contacted: Sandra Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>EK1018B - X</u>
	<u>SHC 7979V - CS/FCL17004074/TIGH312</u> <u>DOA - 03/03/2017</u>
<u>16/5/19</u>	<u>Email preli revised to FCL</u>
<u>18/7/19</u>	<u>LS \$4500 confirmed by email (Recd 6819.04, 60/6)</u>





Auto  
Consultants  
Pte Ltd

Company Registration No. 199607188R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19003173MFSH

Our ref: CS/FCI19008611/Gvd3

Date: 16/5/2019

The Motor Claims Department  
MS FIRST CAPITAL INSURANCE LIMITED

WITHOUT PREJUDICE

Dear Sir/Madam,

**INITIAL INSPECTION REPORT OF VEHICLE NO. EK 1018B**


We thank you for your instruction on 15/5/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 15/5/2019 at the premises of M/s K KIM HIN AUTO PTE LTD and have the following to report:-

Workshop Estimate Amount	:S\$11,319.04
Revised Estimate Amount	:S\$4,689.90
"Check" Items Amount	:S\$4,404.44
Market Value	:S\$
LTA Reimbursement Value	:S\$
Nett Value	:S\$

**Description of Damage:**

The vehicle sustained damages at the front and rear portion.



**Comments/Present Status:**

Damages Consistent

Yours faithfully,

XING GUO QIANG (HP 8288 0282)  
M.MATAL, AMSAE-A  
Automotive Assessor

**MOTOR SURVEY ASSIGNMENT**

Date	14-05-2019	Our Ref No. D19003173MFSH
Accident Date	11-05-2019	Claim Type. Third Party
Insured Vehicle	SHC7979U	Third Party Vehicle. EK1018B
Survey Location	160 SIN MING DRIVE #02-20SIN MING AUTOCITY	
Contact Person.	SANDRA	
Contact No.	64527018/ 96222116	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

Cc : Workshop	K. KIM HIN AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

**Veron Chen (LKKAuto)**

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Thursday, 18 July 2019 9:56 AM  
**To:** survey@kkimhin.com.sg; SUR; Guo Qiang (LKKAuto)  
**Cc:** sandrakhong@gmail.com; 'Simon'  
**Subject:** RE: EK1018B TP-MS FIRST QUESTION MARK ITEM

Dear Meng Huat,

WITHOUT PREJUDICE

Confirmed Lump Sum \$4500/- @ 4 working days

**Kindly send Final invoice and all supporting documents directly to First Capital Ins Ltd.**

Best Regards,  
Veron Chen | Case Handler  
LKK Auto Consultants Pte Ltd  
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: survey@kkimhin.com.sg <survey@kkimhin.com.sg>  
Sent: Wednesday, 17 July 2019 11:17 AM  
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; Guo Qiang (LKKAuto) <GuoQiang@lkkauto.com>  
Subject: EK1018B TP-MS FIRST QUESTION MARK ITEM

Hi All,

Enclosed your attention.  
Thank you.

Regard  
Meng Huat  
K.Kim Hin Auto

## Veron Chen (LKKAuto)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Thursday, 16 May 2019 1:38 PM  
**To:** 'CWS Motor Claims'; SUR  
**Cc:** 'Henry Kao Cai Jie'  
**Subject:** RE: SURVEY ASSESSMENT - D19003173MFSH/1, EK 1018B  
**Attachments:** EK 1018B PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle EK 1018B  
Date of survey: 15/5/2019  
Number of days : 4 days

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Wednesday, 15 May 2019 3:01 PM  
**To:** 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>  
**Cc:** 'Henry Kao Cai Jie' <HenryKao@msfirstcapital.com.sg>  
**Subject:** RE: SURVEY ASSESSMENT - D19003173MFSH/1

Dear Sir/Madam,

Thank you for the assignment.

Best Regards,

**Summer Lee** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]  
**Sent:** Wednesday, 15 May, 2019 2:39 PM  
**To:** ASSIGNMENTS@LKKAUTO.COM  
**Cc:** CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao Cai Jie <HenryKao@msfirstcapital.com.sg>  
**Subject:** PRI: SURVEY ASSESSMENT - D19003173MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

**Note: All the accident reports are uploaded into CWS for your perusal.**

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**

## ▶ Jetta Used Vehicle List (9 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availability
<b>Volkswagen Jetta 1.4A TSI</b>	<b>\$28,800</b>	\$9,220 /yr	18-Apr-2011	1,390 cc	150,000 km	Hua Yang Credit Pte Ltd	Available
Very Pristine Condition Short Term Drive Car For Grab/Rental. 100% Loan Available, NO Repair Needed, Hurry Call Our Sales For Further Discount And Enquiry. Office No. - 64625111 Sky - 84371619   Miss Tan - 86864198							
<b>Volkswagen Jetta Sport 1.4A TSI</b>	<b>\$27,090</b>	\$8,210 /yr	28-Apr-2011	1,390 cc	-	Apex Automotive	Available
No Repairs Needed. Car Is In Pristine Condition. High Loan Available! Low Mileage! Hurry Call Our Friendly Salesman Today! Office No. - 62513972 Kelvin Sim - 97278548   Dion Tan - 88625982   Tan - 93547280							
<b>Volkswagen Jetta 1.4A TSI</b>	<b>\$29,800</b>	\$9,560 /yr	01-May-2011	1,390 cc	90,900 km	Hong Heng Co. Pte Ltd	Available
Mileage Done Only 58k. Excellent Condition. Ultimate Driving Pleasure. Powerful And Give Good Road Handling. Great Family Sedan Than Give Driving A Good Feeling. View To Believe. No Gimmick. Call Us F... Office No. - 64521112 Mr Ho - 96563239   David Ang - 92376357							
<b>Volkswagen Jetta Sport 1.4A TSI</b>	<b>\$28,800</b>	\$9,080 /yr	09-May-2011	1,390 cc	-	Cosmo Automobiles	Available
Purchase From An Award Winning Dealership! 1 Year Comprehensive Warranty Inclusive! STA Certified Accident-Free Quality Pre-Owned With Low Mileage For Peace Of Mind. 100% Loan Approval With Our Flexib... Office No. - 64651090 Leonard - 83337808   Andy - 98502116   Dennis - 92234854   Kevin - 97976757							
<b>Volkswagen Jetta Sport 1.4A TSI</b>	<b>\$40,800</b>	\$12,700 /yr	23-Aug-2011	1,390 cc	-	Grande Auto Credit	Available
New Sports Model With Sporty White. Nice Bidded Number 6777. High \$25k Paper Value. Accident Free. Very Well Maintained With Services Record Proven. Flexible High Loan Available. Office No. - 63650065 Calvin - 90303900   Joseph - 96690065							
<b>Volkswagen Jetta 1.4A TSI</b>	<b>\$34,500</b>	\$9,750 /yr	29-Aug-2011	1,390 cc	-	MyBro Garage Pte Ltd	Available
Servicing Done By Our Own Garage Plus Complimentary Oil Servicing Package. Don't Miss This Powerful, Yet Economical Ride! Office No. - - HX - 90625785							
<b>Volkswagen Jetta Sport 1.4A TSI</b>	<b>\$35,500</b>	\$9,970 /yr	22-Sep-2011	1,390 cc	110,000 km	Autorol Pte Ltd	Available
Car Is In Immaculate Condition! Well Maintained By Previous Owner! Comfort And Smooth Driving! Responsive Drive, Spacious Cabin, Yet Fuel Efficient 1.4L Family Sedan! Drive With Passion! Trade In And ... Office No. - - Hari - 94594812   Roland Lim - 97666881							
<b>Volkswagen Jetta Sport 1.4A TSI</b>	<b>\$35,900</b>	\$9,520 /yr	17-Nov-2011	1,390 cc	95,024 km	Iterly Motor Pte Ltd	Available
1 Owner With Genuine Low Mileage, Original Condition, Agent Regular Maintain, Tax Nov 19, Stable And Well Handled Sedan. Price Negotiable. Office No. - 64893113 Eddy - 96168680							
<b>Volkswagen Jetta Sport 1.4A TSI</b>	<b>\$33,500</b>	\$8,550 /yr	18-Nov-2011	1,390 cc	190,000 km	Asia Motorsports Solution Pte Ltd	Available
Highest Spec Jetta At An Unbelievable Price And Lowest Depreciation. Sporty Red With Original 18" Sport Rims. All-New Michelin Pilot Sport Tyres Replaced Less Than 1 Year Ago. Extremely Well Maintaine... Office No. - 67453811 Loo - 96220160							

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	5838G
Vehicle No.:	EK1018B
Vehicle to be Exported:	No
Intended Deregistration Date:	15 May 2019
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	JETTA 1.4 TSI AT 1623Q5
Primary Colour:	Silver
Manufacturing Year:	2011
Engine No.:	CAV291948
Chassis No.:	WVWZZZ16ZBM106075
Maximum Power Output:	118.0 kW (158 bhp)
Open Market Value:	\$24,364.00
Original Registration Date:	12 Aug 2011
First Registration Date:	12 Aug 2011
Transfer Count:	1
Actual ARF Paid:	\$24,364.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Aug 2021
PARF Rebate Amount:	\$14,618.00
COE Expiry Date:	11 Aug 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$56,002.00
COE Rebate Amount:	\$12,540.00
<b>Total Rebate Amount:</b>	<b>\$27,158.00</b>

The information contained herein is correct as at 15 May 2019

OK

> [Back to OneMotoring](#)

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5838G
Vehicle Details	
Vehicle No.:	EK1018B
Vehicle to be Exported:	Yes
Intended Deregistration Date:	14 May 2019
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	JETTA 1.4 TSI AT 1623Q5
Primary Colour:	Silver
Manufacturing Year:	2011
Engine No.:	CAV291948
Chassis No.:	WVWZZZ16ZBM106075
Maximum Power Output:	118.0 kW (158 bhp)
Open Market Value:	\$24,364.00
Original Registration Date:	12 Aug 2011
First Registration Date:	12 Aug 2011
Transfer Count:	1
Actual ARF Paid:	\$24,364.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Aug 2021
PARF Rebate Amount:	\$14,618.00
Intended COE Rebate Details	
COE Expiry Date:	11 Aug 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$56,002.00
COE Rebate Amount:	\$12,555.00
<b>Total Rebate Amount:</b>	<b>\$27,173.00</b>

The information contained herein is correct as at 14 May 2019

OK

**金興(龔)汽車私人有限公司**

160 Sin Ming Drive, #02-18/19/20/21,  
 Sin Ming AutoCity, Singapore 575722  
 Tel: 6452 7018 Fax: 6458 3895  
 Email: service@kkimhin.com.sg

(IN) TP: FIRST

Vehicle Insured : SLA 6597 H  
 Accident Date : 11-May-2019

No. : 30453  
 Date : 14-May-2019

Our Ref : 190246 (MS FIRST) / MH

PAGE : 1

KOK WEE KOK  
 Singapore

ESTIMATED COST OF REPAIR FOR VOLKSWAGEN JETTA 1.4 TSI (2011) EK1018B

1 pc	front number plate base	Re	187.50
	garnish		
1 pc	front bumper	cut.	1,360.00
1 pc	front bumper spoiler	NN	487.50
2 pcs	front bumper side retainer	@ S\$ 45.00	90.00
	(lh & rh)		
1 pc	front bumper centre bracket	CMA	271.50
1 pc	front bumper lower centre grille	NN	375.00
2 pcs	front bumper foglamp (lh/rh)	@ S\$201.90	403.80
2 pcs	front bumper foglamp cover	@ S\$195.50	391.00
	(lh/rh)		
1 pc	front bumper towing cover	NN	55.00
1 pc	front bumper sponge	NN	145.60
1 pc	front bumper reinforcement	BT	555.10
1 pc	front grille	NN	441.90
2 pcs	headlamp assy (lh/rh)	@ S\$725.00	1,450.00
1 pc	rear bumper	cut.	1,100.10
1 pc	rear bumper spoiler	cut.	555.90
2 pcs	rear bumper side retainer	@ S\$ 55.00	110.00
	(lh/rh)		
2 pcs	rear bumper side bracket	@ S\$ 45.00	90.00
	(lh/rh)		
1 pc	rear bumper centre bracket	NN	175.00
10 pcs	rear bumper rivet	@ S\$ 5.00	50.00
1 pc	rear bumper sponge	NN	145.00
1 pc	rear bumper reinforcement	NN	725.00
1 pc	bootlid logo		95.00
1 pc	bootlid 'JETTA' emblem		110.70
1 pc	bootlid 'TSI' emblem		95.00
			9,465.60
Less 10% :			-946.56
			8,519.04

**金興(龔)汽車私人有限公司**

160 Sin Ming Drive, #02-18/19/20/21,  
Sin Ming AutoCity, Singapore 575722  
Tel: 6452 7018 Fax: 6458 3895  
Email: service@kkimhin.com.sg

Vehicle Insured : SLA 6597 H  
Our Ref : 190246

Page : 2  
No. : 30453

1 pc front number plate	✓ CDA	40.00	sn
1 pc reverse sensor	✗ X NN	220.00	sn

To remove, cut out damaged parts,  
panel beating, welding, align,  
refix and to renew affected parts.

✓ 400 1,000.00

To focus Headlamps and Taillamps. }  
To check front and rear lighting  
operation and rewiring

NN ✗ ? 60.00

To remove aircon condenser, pipes  
and driers. Vaccum and recharge gas

✗ ? 100.00

To remove and refit reverse sensor  
assy.

40 80.00

To putty and respray on affected  
portions.

600 1,300.00

Total : S\$11,319.04  
=====

Singapore Dollars Eleven Thousand Three Hundred  
and Nineteen and Cents Four Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

*[Signature]*  
15/5/19  
4 Days.  
Lumpsum repair.  
After repair photos.  
Guo Qiang - 8288 0282  
15/5/19.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:  
Signature:  
Date:



金興(龔)汽車私人有限公司  
 160 Sin Ming Drive, #02-18/19/20/21,  
 Sin Ming AutoCity, Singapore 575722  
 Tel: 6452 7018 Fax: 6458 3895  
 Email: service@kkimhin.com.sg

(IN) TP: FIRST

Vehicle Insured : SLA 6597 H  
 Accident Date : 11-May-2019

No. : 30453  
 Date : 14-May-2019

Our Ref : 190246 (MS FIRST) / MH

PAGE : 1

KOK WEB KOK  
 Singapore

ESTIMATED COST OF REPAIR FOR VOLKSWAGEN JETTA 1.4 TSI (2011) EK1018B  
 =====

1 pc front number plate base garnish		187.50	/
1 pc front bumper	<i>mis repair - cut.</i>	1,360.00	/
1 pc front bumper spoiler	X	<del>487.50</del>	X
2 pcs front bumper side retainer (lh & rh)	<i>PH - ee. LH/X</i>	<del>90.00</del>	<i>45.00</i> /
1 pc front bumper centre bracket		271.50	/
1 pc front bumper lower centre grille	<i>?</i>	<del>375.00</del>	X
2 pcs front bumper foglamp (lh/rh)	<i>CRA.</i>	403.80	/
2 pcs front bumper foglamp cover (lh/rh)	<i>LH - cut. RH X</i>	<del>391.00</del>	<i>195.50</i> /
1 pc front bumper towing cover	X	<del>55.00</del>	X
1 pc front bumper sponge	<i>?</i>	<del>145.60</del>	X
1 pc front bumper reinforcement	<i>?</i>	555.10	/
1 pc front grille	<i>?</i>	<del>441.90</del>	X
2 pcs headlamp assy (lh/rh)	<i>? X</i>	<del>1,450.00</del>	X
1 pc rear bumper	<i>cut. cut.</i>	<del>1,100.10</del>	/
1 pc rear bumper spoiler		555.90	/
2 pcs rear bumper side retainer (lh/rh)	X	<del>110.00</del>	X
2 pcs rear bumper side bracket (lh/rh)	X	<del>90.00</del>	X
1 pc rear bumper centre bracket	<i>?</i>	<del>175.00</del>	X
10 pcs rear bumper rivet	<i>acc</i>	50.00	/
1 pc rear bumper sponge	<i>?</i>	<del>145.00</del>	X
1 pc rear bumper reinforcement	<i>?</i>	<del>725.00</del>	X
1 pc bootlid logo		95.00	/
1 pc bootlid 'JETTA' emblem		110.70	/
1 pc bootlid 'TSI' emblem		95.00	/
		9,465.60	
Less 10% :		<del>-946.56</del>	
		8,519.04	



金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-18/19/20/21,  
Sin Ming AutoCity, Singapore 575722  
Tel: 6452 7018 Fax: 6458 3895  
Email: service@kkimhin.com.sg

Vehicle Insured : SLA 6597 H  
Our Ref : 190246

Page : 2  
No. : 30453

1 pc front number plate ✓ 40.00 sn ✓  
1 pc reverse sensor ? 220.00 sn X

To remove, cut out damaged parts,  
panel beating, welding, align,  
refix and to renew affected parts. 400 1,000.00

To focus Headlamps and Taillamps.

To check front and rear lighting  
operation and rewiring ? 60.00 X

To remove aircon condenser, pipes  
and driers. Vaccum and recharge gas ? 100.00 X

To remove and refit reverse sensor  
assy. 400 80.00

To putty and respray on affected  
portions. 600 1,300.00

Total : S\$11,319.04

Singapore Dollars Eleven Thousand Three Hundred  
and Nineteen and Cents Four Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

4 Days.  
Lumpsum repair.  
After repair photos.  
Guo Qiang - 8288 0582  
15/5/19.

\$ 5,025.10 - 10%  
-----  
\$ 4,522.59  
\$ 40.00 - 10%  
\$ 1,040.00  
-----  
\$ 5,602.59  
- 20%  
-----  
\$ 4,482.07  
-----  
C/S: \$ 4,500.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19008611/Gvd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 19-07-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 7979U	Veh. Inspected	EK 1018B
Policy No.		Coverage (\$)	0.00
Claim No.	D19003173MFSH	Excess (\$)	0.00
Assign From	HENRY KAO	Assign Date	15/05/2019
2. Vehicle Particulars & Condition			
Make & Model	VOLKSWAGEN JETTA	c.c	1390
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	WVWZZZ16ZBM106075	Colour	SILVER
Odometer	122103	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55 ZR16	MICHELIN	6 mm
L/H Front Tyre	205/55 ZR16	MICHELIN	6 mm
R/H Rear Tyre	205/55 ZR16	MICHELIN	6 mm
L/H Rear Tyre	205/55 ZR16	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	11/05/2019	Inspection Date	15/05/2019
Survey held at	K.KIM HIN AUTOMOTIVE PTE LTD 160 SIN MING DRIVE, #02-20 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>4 Working Days</b>	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. EK 1018B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT NUMBER PLATE BASE GARNISH	DEFORMED	187.50	187.50
1	FRONT BUMPER	CUT	1,360.00	1,360.00
1	FRONT BUMPER SPOILER	NOT NECESSARY	487.50	-
2	FRONT BUMPER SIDE RETAINER (LH/RH) @\$45.00	O/S DEFORMED / N/S NOT NECESSARY	90.00	45.00
1	FRONT BUMPER CENTRE BRACKET	CRACKED	271.50	271.50
1	FRONT BUMPER LOWER CENTRE GRILLE	NOT NECESSARY	375.00	-
2	FRONT BUMPER FOGLAMP (LH/RH) @\$201.90	CRACKED	403.80	403.80
2	FRONT BUMPER FOGLAMP COVER (LH/RH) @\$195.50	N/S CUT / O/S NOT NECESSARY	391.00	195.50
1	FRONT BUMPER TOWING COVER	NOT NECESSARY	55.00	-
1	FRONT BUMPER SPONGE	NOT NECESSARY	145.60	-
1	FRONT BUMPER REINFORCEMENT	BENT	555.10	555.10
1	FRONT GRILLE	NOT NECESSARY	441.90	-
2	HEADLAMP ASSY (LH/RH) @\$725.00	NOT NECESSARY	1,450.00	-
1	REAR BUMPER	CUT	1,100.10	1,100.10
1	REAR BUMPER SPOILER	CUT	555.90	555.90
2	REAR BUMPER SIDE RETAINER (LH/RH) @\$45.00	NOT NECESSARY	110.00	-
2	REAR BUMPER SIDE BRACKET (LH/RH) @\$45.00	NOT NECESSARY	90.00	-
1	REAR BUMPER CENTRE BRACKET	NOT NECESSARY	175.00	-
10	REAR BUMPER RIVET @\$5.00	NECESSARY	50.00	50.00
1	REAR BUMPER SPONGE	NOT NECESSARY	145.00	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	725.00	-
1	BOOTLID LOGO	NECESSARY	95.00	95.00
1	BOOTLID "JETTA" EMBLEM	NECESSARY	110.70	110.70
1	BOOTLID "TSI" EMBLEM	NECESSARY	95.00	95.00
	LESS 10% DISCOUNT		-948.56	-502.51
			<b>8,519.04</b>	<b>4,522.59</b>
<b>SPECIAL NETT ITEMS</b>				
1	FRONT NUMBER PLATE (SN)	CRACKED	40.00	40.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REVERSE SENSOR (SN)	NOT NECESSARY	220.00	-
			260.00	40.00
	<b>LABOUR</b>			
	TO REMOVE,CUT OUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW AFFECTED PARTS.		1,000.00	400.00
	TO CHECK FRONT AND REAR LIGHTING OPERATION AND REWIRING. )	NOT NECESSARY	60.00	-
	TO FOCUS HEADLAMPS AND TAILLAMPS. )		-	-
	TO REMOVE AIRCON CONDENSER,PIPES AND DRIERS.VACCUM AND RECHARGE GAS.	NOT NECESSARY	100.00	-
	TO REMOVE AND REFIT REVERSE SENSOR ASSY.		80.00	40.00
	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.		1,300.00	600.00
			2,540.00	1,040.00
<b>GRAND TOTAL</b>			<b>11,319.04</b>	<b>5,602.59</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>4,500.00</b>

Report Ref No. CS/FC119008611/Gvd3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.