

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 4419 H

S/N	Parts Description	c/f	<u>Damage Parts & Prices</u>	
			<u>S/NETT</u>	<u>REMARKS</u>
			\$	3,323.52
21	HORN BRACKET - LH / RH		\$ 52.00	
22	BONNET		\$ 2,554.00	\$ 2,043.20
23	BONNET ATTACHMENT PARTS		\$ 111.00	
24	BONNET HINGE- LH / RH		\$ 554.00	
25	BONNET IMPACT PROTECTION	3	\$ 75.00	\$ 59.44
26	FRONT WIPER COWLING RUBBER		\$ 53.00	
27	BONNET GAS FILLED STRUT		\$ 217.00	
28	BONNET STRIKER- LH / RH		\$ 92.00	
29	BONNET LOCK	2	\$ 391.00	
30	LOCKING MECHANISM CONNECTOR HOUSING	2	\$ 24.00	
31	CONNECTOR HOUSING BRACKET	2	\$ 18.00	
32	BONNET BOWDEN CABLE	2	\$ 106.00	\$ 41.68
33	BOWDEN CABLE COVER		\$ 9.00	
34	BONNET RELEASE LEVER		\$ 12.00	
35	BONNET LOCK CABLE		\$ 67.00	
36	FRONT WIPER COWLING		\$ 89.00	
37	BONNET SOUND ABSORBER		\$ 311.00	
38	FRONT WHEEL SPOILER - LH		\$ 66.00	
39	FRONT WHEEL SPOILER TRIM - LH		\$ 32.00	
40	FRONT FENDER STONE CHIP GUARD - LH		\$ 46.00	
SUB TOTAL SPARE PARTS			\$ 4,879.00	\$ 5,467.84

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 4419 H

S/N	Parts Description	c/f	Damage Parts & Prices	
			S/NETT	REMARKS
			\$	5,467.84
41	HEADLIGHT - LH / RH		\$ 14,174.00	\$ 5,669.60
42	HEADLIGHT POWER MODULE		\$ 716.00	
43	HEADLIGHT CONTROL UNIT		\$ 685.00	
44	HEADLIGHT VENTILATION HOSE - LH		\$ 32.00	
45	HEADLIGHT LIFT CYLINDER - LH		\$ 192.00	
46	HEADLIGHT LIFT CYLINDER HOSE	2	\$ 118.00	
47	WATER SESERVOIR		\$ 135.00	
48	LOCK CARRIER		\$ 928.00	
49	RADIATOR SUPPORT - LH		\$ 35.00	
50	A/C CONDENSER		\$ 568.00	
51	A/C REFRIGERANT LINE		\$ 152.00	
52	A/C RECEIVER DRIER		\$ 123.00	
53	RADIATOR		\$ 603.00	
54	ADDITIONAL RADIATOR - LOWER CENTER		\$ 470.00	
55	COOLANT		\$ 84.00	
56	RADIATOR FAN RING		\$ 242.00	
57	RADIATOR FAN CONTROL UNIT		\$ 2,107.00	
58	LOCK CARRIER AIR GUIDE	6	\$ 106.00	\$ 28.16
59	FOAM FILLER PIECE		\$ 113.00	\$ 90.40
60	INTAKE AIR DUCT - RH		\$ 19.00	
SUB TOTAL SPARE PARTS			\$ 21,602.00	\$ 11,256.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 4419 H

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
		c/f	\$ 11,256.00
61	INTAKE AIR DUCT AIR GUIDE - RH	\$ 48.00	
62	AIR FILTER	\$ 352.00	
63	INTAKE HOSE	\$ 85.00	
64	FRONT NO. PLATE	S/N \$ 40.00	\$ 40.00
65	<i>Added parts - see attached</i>	\$ 280.00	\$ 224.00
66	SUNDRIES	\$ 600.00	\$ 57.20
TOTAL SPARE PARTS		\$ 33,569.00	\$ 11,577.20
TOTAL LABOUR CHARGES		\$ 9,152.00	\$ 3,202.00
GRAND TOTAL		\$ 42,721.00	\$ 14,779.20

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0620/2019/DY 21-May-19 Glory Tan 1 of 1 SLS 4419 H Audi A4 Sedan 1.4 TFSI S
Quantity	Description	Unit Price	Amount
<u>Parts</u> 1	Window slot seal with trim strip RHF <i>wt</i>	\$ 280.00	\$ 224.00 ✓
		\$ 280.00	\$ 224.00
<u>LABORS</u> 1	To remove and reinstall RHS front door, trim, and other fittings for replacement slot shield	\$ 300.00	\$ 300.00 ✓
	TOTAL	\$ 580.00	\$ 524.00

For Premium Automobiles Pte Ltd

Adrian Ling
8/5/19

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 6 June 2019 5:45 PM
To: Boo seng yak; Carrine Leong; jiayee.yap@premiumauto.com.sg; Chang Chee Sing; SUR
Subject: RE: FINAL REVISION - SLS4419H - OD AIG - SURVEYED 15 MAY 19

Dear Mr Boo,

Confirm repair cost of \$14,779.20 before excess \$600 and GST @ 6 days of repairs.

Kindly send us invoice and discharge voucher for us to close file.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>

Sent: Thursday, 6 June 2019 1:18 PM

To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg; Chang Chee Sing <claims@premiumauto.com.sg>

Subject: FINAL REVISION - SLS4419H - OD AIG - SURVEYED 15 MAY 19

Hi Adrian and all,

Revised and photographs is attached.

Please confirm repair cost of \$14,779.20 @ 6 days of repairs.

Your early closure is well appreciated.

Best regards - jb

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLS 4419 H

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0620/2019/NS

16 Aug 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

1

total pages

RE: INSURANCE CLAIM FOR SLS 4419 H, Audi A4 SEDAN 1.4 TFSI

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

With reference to the above-mentioned vehicle, no. **SLS 4419 H**, claimant, **Mr. Rajith Mohan** please find the related document per attached.

1. A copy of the Original invoice no. 85014101 – S\$15,171.74.
2. A copy of the Discharge Voucher duly signed by client.

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLS 4419 H

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLS 4419 H

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0620/2019/GW
27 May 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE: CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A4 Sedan 1.4 TFSI
Vehicle Chassis No. : WAUZZZF47JA044453
Vehicle Regn No. : **SLS 4419 H**
Vehicle Mileage : 29985 KM
Vehicle Owner : Mr. Rajith Mohan
Certificate No : 1700055635-01
Own Damage Excess : \$ 642.00 (Inclusive GST)
Accident Date : 12/05/2019
Place : After Exit 3C TPE turning to Pasir Ris
Repair Cost : \$ 15,171.74
WIP No. : 53308
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time : 1000
Date : 28/5/19

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159936
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159936
Main Telephone 6368 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 11:37

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85014101 Date : 14/08/2019 Order : SLS4419H Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No: SLS4419H (V 35375)	Regn Date: 22/09/2017	Mileage: 32147	WIP No.: 53308
Model: A4 SEDAN 1.4 TFSI S tronic	Chassis: WAUZZZF47JA044453	Engine: CVN 049568	Dept: U
You have been assisted by :- UB-Tony Foong (33)			

		Details	Qty	Unit Price	Amount
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE	40.00	1.00	40.00
Q	EXC	M: 8888 Insurance Excess/Liability	-600.00	1.00	-600.00
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	360.00	1.00	360.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER, LHS HEADLIGHTS AND BONNET. REALIGN FRONT LOCK CARRIER TO POSITION. REORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	1250.00	1.00	1,250.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER AND BONNET.	1100.00	1.00	1,100.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
S	BODYWORK	M: TO REMOVE AND REINSTALL RHS FRONT DOOR, TRIM, AND OTHER FITTINGS FOR REPLACEMENT SLOT SHIELD	300.00	1.00	300.00
X	A8W0853651 3FZ	(SK) GRILLE Less 020%	1.00	1053.00	842.40
X	A8W0941773A	HEADLIGHT Less 020%	1.00	7087.00	5,669.60
X	A8W0807771	BRACKET (LAST) Less 020%	1.00	125.00	100.00
X	A8W0807081	(SK) COVER Less 020%	1.00	115.50	92.40
X	A8W0807550A	(GER) FOAM INSER Less 020%	1.00	113.00	90.40
X	A8W0807113	BRACKET (LAST) Less 020%	1.00	732.50	586.00
X	A8W0823029A	HOOD Less 020%	1.00	2554.00	2,043.20
X	A8W0807065C GRU	COVER Less 020%	1.00	1946.00	1,556.80
X	A8W0807333	SUPPORT (LAST) Less 020%	1.00	25.40	20.32
X	A8W0807251A	007239/(V) (SK) FOAM I Less 020%	1.00	15.90	12.72
X	A8W0121673A	AIR DUCT Less 020%	1.00	10.40	8.32
X	A8W0820536	BRACKET Less 020%	1.00	16.30	13.04
X	A8W0823125	007239/(V) (SK) PROTEC Less 020%	1.00	24.90	19.92

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 2 11:37

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120		Invoice: 85014101 Date : 14/08/2019 Order : SLS4419H Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
Regn No: SLS4419H (V 35375) Model: A4 SEDAN 1.4 TFSI S tronic You have been assisted by :- UB-Tony Foong (33)		Regn Date: 22/09/2017 Chassis: WAU2ZZ2F47JA044453	Mileage: 32147 Engine: CVN 049568 WIP No.: 53308 Dept: U

		Details		Qty	Unit Price	Amount
X	A8W0823126	PROTECTION	Less 020%	1.00	24.70	19.76
X	A8W0823529E	(SK)BOWD CABLE	Less 020%	1.00	52.10	41.68
X	A8W0807681B 9B9	GRILL (LAST)	Less 020%	1.00	122.50	98.00
X	A8W0010515A	STICKER	Less 020%	1.00	6.40	5.12
X	A8K0010520A	PLATE	Less 020%	1.00	12.20	9.76
X	A8W0121283AR	(SK)AIR DUCT	Less 020%	1.00	24.80	19.84
X	AN 91093901	RIVET	Less 020%	4.00	0.70	2.24
X	AN 02300311	NUT	Less 020%	4.00	0.50	1.60
X	AN 10036203	BOLT	Less 020%	4.00	12.60	40.32
X	A8W0853284E 2ZZ	WINDOW SLO	Less 020%	1.00	280.00	224.00
X	A8W0823124	PROTECTION	Less 020%	1.00	24.70	19.76

Parts 11,537.20
Labour 0.00
Sublet 3,242.00
Menus 0.00
Lubricant 0.00



Sub-Total	14,179.20
7% GST	992.54
Grand Total	15,171.74

Received by

For & on behalf of
Premium Automobiles Pte Ltd

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 May 2019 15:20		15 May 2019 15:17 Edit Adj Rpt	S\$14,779.20 Edit Estimates	S\$14,779.20 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured: RAJITH MOHAN , ID: S7868235C, Tel: +6590615634, Email: RAJITH.MOHAN@GMAIL.COM									
Vehicle Reg. No.: SLS4419H		Date of Loss: 12/05/2019 09:00 - :59 [19 Months and 20 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / 5518746454SG		Policy/Cover Note No.: 1700055635-01 (Comprehensive)							
		Excess: S\$600.00							
Repairer: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Nadaraja, Deeban] Deeban@nadaraja.nadaraja@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 27/05/2019]									
Driver/Custodian: RAJITH MOHAN (40 / Male) , NRIC: S7868235C, Tel: +6590615634 Email: RAJITH.MOHAN@GMAIL.COM									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
- AIG_SG (16/05/2019): Alert - Adj Mandate Approved (S\$17422.00) - SLS4419H - Claim Handler: Nadaraja, ... - AIG_SG (16/05/2019): SLS4419H / OD / 12/05/2019 / Coverage & Excess update									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLS4419H (5518746454SG)**

OD

May 12 2019 9:10AM

[RAJITH MOHAN]

Premium Automobiles Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/05/19 17:40	Adjuster Immediate Advice	 Load HTM	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/05/19 17:24	General View	 Load JPG	☒
2	15/05/19 17:24	General View	 Load JPG	☒
3	15/05/19 17:24	General View	 Load JPG	☒
4	15/05/19 17:24	General View	 Load JPG	☒
5	15/05/19 17:24	General View	 Load JPG	☒
6	15/05/19 17:24	General View	 Load JPG	☒
7	15/05/19 17:24	General View	 Load JPG	☒
8	15/05/19 17:24	General View	 Load JPG	☒
9	15/05/19 17:24	General View	 Load JPG	☒
10	15/05/19 17:24	General View	 Load JPG	☒
11	15/05/19 17:24	General View	 Load JPG	☒
12	15/05/19 17:24	General View	 Load JPG	☒
13	15/05/19 17:24	General View	 Load JPG	☒
14	15/05/19 17:24	General View	 Load JPG	☒
15	15/05/19 17:24	General View	 Load JPG	☒
16	15/05/19 17:24	General View	 Load JPG	☒
17	15/05/19 17:24	General View	 Load JPG	☒
18	15/05/19 17:24	General View	 Load JPG	☒
19	15/05/19 17:24	General View	 Load JPG	☒
20	15/05/19 17:24	General View	 Load JPG	☒
21	15/05/19 17:24	General View	 Load JPG	☒
22	15/05/19 17:24	General View	 Load JPG	☒
23	15/05/19 17:24	General View	 Load JPG	☒
24	15/05/19 17:24	General View	 Load JPG	☒
25	15/05/19 17:24	General View	 Load JPG	☒
26	15/05/19 17:24	General View	 Load JPG	☒
27	15/05/19 17:24	General View	 Load JPG	☒
28	15/05/19 17:24	General View	 Load JPG	☒
29	15/05/19 17:24	General View	 Load JPG	☒
30	15/05/19 17:24	General View	 Load JPG	☒
31	15/05/19 17:24	General View	 Load JPG	☒
32	15/05/19 17:24	General View	 Load JPG	☒
33	15/05/19 17:24	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
34	15/05/19 17:24	General View	 Load JPG	☒
35	15/05/19 17:24	General View	 Load JPG	☒
36	15/05/19 17:24	General View	 Load JPG	☒
37	15/05/19 17:24	General View	 Load JPG	☒
38	15/05/19 17:24	General View	 Load JPG	☒
39	15/05/19 17:24	General View	 Load JPG	☒
40	06/06/19 16:33	Reinspection Photo	 Load JPG	☒
41	06/06/19 16:33	Reinspection Photo	 Load JPG	☒
42	06/06/19 16:33	Reinspection Photo	 Load JPG	☒
43	06/06/19 16:33	Reinspection Photo	 Load JPG	☒
44	06/06/19 16:33	Reinspection Photo	 Load JPG	☒
45	06/06/19 16:33	Reinspection Photo	 Load JPG	☒
46	06/06/19 16:33	Reinspection Photo	 Load JPG	☒
47	06/06/19 16:33	Reinspection Photo	 Load JPG	☒
48	06/06/19 16:33	Reinspection Photo	 Load JPG	☒
49	06/06/19 16:33	Reinspection Photo	 Load JPG	☒
50	06/06/19 16:33	Reinspection Photo	 Load JPG	☒
51	06/06/19 16:33	Reinspection Photo	 Load JPG	☒
52	06/06/19 16:33	Reinspection Photo	 Load JPG	☒
53	06/06/19 16:33	Reinspection Photo	 Load JPG	☒
54	06/06/19 16:33	Reinspection Photo	 Load JPG	☒
55	06/06/19 16:33	Reinspection Photo	 Load JPG	☒
56	06/06/19 16:33	Reinspection Photo	 Load JPG	☒
57	06/06/19 16:33	Reinspection Photo	 Load JPG	☒
58	06/06/19 16:33	Reinspection Photo	 Load JPG	☒
59	06/06/19 16:33	Reinspection Photo	 Load JPG	☒

Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/05/19 17:23	SLS 4419H GIA.pdf	 Load PDF	
2	15/05/19 17:23	INS CERT & DRIVING .pdf	 Load PDF	
3	15/05/19 17:23	ESTIMATE.pdf	 Load PDF	
4	29/08/19 11:33	DISCHARGE VOUCHER	 Load PDF	
5	29/08/19 11:33	SUPPLEMENTARY	 Load PDF	
6	29/08/19 11:33	WORKSHOP INVOICE	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	13/05/19 13:08	Accident Statement	 Load HTM	

Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	13/05/19 13:01	Accident Photo	 Load JPG	☒
2	13/05/19 13:01	Accident Photo	 Load JPG	☒
3	13/05/19 13:01	Accident Photo	 Load JPG	☒
4	13/05/19 13:01	Accident Photo	 Load JPG	☒
5	13/05/19 13:01	Accident Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
6	13/05/19 13:01	Accident Photo	 Load JPG	☒
7	13/05/19 13:01	Accident Photo	 Load JPG	☒
8	13/05/19 13:01	Accident Photo	 Load JPG	☒
9	13/05/19 13:01	Accident Photo	 Load JPG	☒

Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	13/05/19 12:59	Sketch Plan	 Load JPG	☒
2	13/05/19 12:59	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer				
Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19008612/AVD3S2

Date: 29/08/2019

REFERENCE

Insured/Claimant: RAJITH MOHAN Policy No: 1700055635-01
Date of Loss: 12/05/2019 Nature of Claim: OD Claim No: 5518746454SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLS4419H**
Make & Model: AUDI A4, 1.4 (A)
Reg. Date: 22/09/2017 (Man. Year: 2017)
Colour: Black
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$115,000.00
Sum Insured (S\$): **Market Value/New Car Price**

Engine No: CVN049568
Chassis No: WAUZZZF47JA044453
Odometer: 29985 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	33,513.00	11,577.20	21,935.80	65.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,152.00	3,202.00	5,950.00	65.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	42,665.00	14,779.20	27,885.80	65.36
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	42,065.00	14,179.20	27,885.80	66.29
+ GST 7.00/7.00% (S\$)	2,944.55	992.54	1,952.01	66.29
Nett Amount (S\$)	45,009.55	15,171.74	29,837.81	66.29

INSPECTION

Date of Assignment: 15/05/2019
Date Inspected: 15/05/2019 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Deformed	1,946.00 FS	*1,556.80 FS
2	1		*FIXING PARTS FOR FRONT FENDER	Not Necessary	258.00 FS	*- FS
3	2		*SECURING STRIP FOR FRONT BUMPER	Not Necessary	64.00 FS	*- FS
4	1		*FRONT CENTER LOWER GRILLE	Not Necessary	178.00 FS	*- FS
5	1		*FRONT CLOSING ELEMENT - LOWER CENTER	Not Necessary	191.00 FS	*- FS
6	1		*AIR GUIDE GRILLE FOR FRONT BUMPER - LH	Not Necessary	56.00 FS	*- FS
7	1		*AIR GUIDE GRILLE FOR FRONT BUMPER - RH	Not Necessary	56.00 FS	*- FS
8	1		*RADIATOR GRILLE	Cracked	1,053.00 FS	*842.40 FS
9	1		*FRONT AIR GUIDE GRILLE - LH	Not Necessary	123.00 FS	*98.00 FS
10	1		*FRONT AIR GUIDE GRILLE - RH	Not Necessary	123.00 FS	*- FS
11	1		*FRONT BUMPER CARRIER	Bent	733.00 FS	*586.00 FS
12	1		*FRONT BUMPER BRACKET - LH	Not Necessary	207.00 FS	*- FS
13	1		*FRONT BUMPER GUIDE SECTION - LH/RH	Not Necessary	67.00 FS	*- FS
14	1		*FRONT BUMPER TOP COVER	Deformed	116.00 FS	*92.40 FS
15	1		*FOAM FILLER PIECE	Deformed	16.00 FS	*12.72 FS
16	1		*CAUTION STICKER	Necessary	13.00 FS	*9.76 FS
17	1		*A/C STICKER	Necessary	7.00 FS	*5.12 FS
18	1		*LOCK CARRIER BRACKET	Cracked	125.00 FS	*100.00 FS
19	1		*FRONT BUMPER SUPPORT - LH/RH	N/s Damaged	52.00 FS	*20.32 FS
20	1		*HORN - LH/RH	Not Necessary	299.00 FS	*- FS
21	1		*HORN BRACKET - LH/RH	Not Necessary	52.00 FS	*- FS
22	1		*BONNET	Dented	2,554.00 FS	*2,043.20 FS
23	1		*BONNET ATTACHMENT PARTS	Not Necessary	111.00 FS	*- FS
24	1		*BONNET HINGE - LH/RH	Not Necessary	554.00 FS	*- FS
25	1		*BONNET IMPACT PROTECTION	Necessary	75.00 FS	*59.44 FS
			3pcs			
26	1		*FRONT WIPER COWLING RUBBER	Not Necessary	53.00 FS	*- FS
27	1		*BONNET GAS FILLED STRUT	Not Necessary	217.00 FS	*- FS
28	1		*BONNET STRIKER - LH/RH	Not Necessary	92.00 FS	*- FS
29	2		*BONNET LOCK	Not Necessary	391.00 FS	*- FS
30	2		*LOCKING MECHANISM CONNECTOR HOUSING	Not Necessary	24.00 FS	*- FS
31	2		*CONNECTOR HOUSING BRACKET	Not Necessary	18.00 FS	*- FS
32	2		*BONNET BOWDEN CABLE	Damaged	106.00 FS	*41.68 FS
33	1		*BOWDEN CABLE COVER	Not Necessary	9.00 FS	*- FS
34	1		*BONNET RELEASE LEVER	Not Necessary	12.00 FS	*- FS
35	1		*BONNET CABLE	Not Necessary	67.00 FS	*- FS
36	1		*FRONT WIPER COWLING	Not Necessary	89.00 FS	*- FS
37	1		*BONNET SOUND ABSORBER	Not Necessary	311.00 FS	*- FS
38	1		*FRONT WHEEL SPOILER - LH	Not Necessary	66.00 FS	*- FS
39	1		*FRONT WHEEL SPOILER TRIM - LH	Not Necessary	32.00 FS	*- FS
40	1		*FRONT FENDER STONE CHIP GUARD - LH	Not Necessary	46.00 FS	*- FS
41	1		*HEADLIGHT - LH/RH	N/s Cracked	14,174.00 FS	*5,669.60 FS
42	1		*HEADLIGHT POWER MODULE	Not Necessary	716.00 FS	*- FS
43	1		*HEADLIGHT CONTROL UNIT	Not Necessary	685.00 FS	*- FS
44	1		*HEADLIGHT VENTILATION HOSE - LH	Not Necessary	32.00 FS	*- FS
45	1		*HEADLIGHT LIFT CYLINDER - LH	Not Necessary	192.00 FS	*- FS
46	2		*HEADLIGHT LIFT CYLINDER HOSE	Not Necessary	118.00 FS	*- FS
47	1		*WATER RESERVOIR	Not Necessary	135.00 FS	*- FS
48	1		*LOCK CARRIER	Not Necessary	928.00 FS	*- FS
49	1		*RADIATOR SUPPORT - LH	Not Necessary	35.00 FS	*- FS
50	1		*A/C CONDENSER	Not Necessary	568.00 FS	*- FS
51	1		*A/C REFRIGERANT LINE	Not Necessary	152.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*A/C RECEIVER DRIER	Not Necessary	123.00 FS	*- FS
53	1		*RADIATOR	Not Necessary	603.00 FS	*- FS
54	1		*ADDITIONAL RADIATOR - LOWER CENTER	Not Necessary	470.00 FS	*- FS
55	1		*COOLANT	Not Necessary	84.00 FS	*- FS
56	1		*RADIATOR FAN RING	Not Necessary	242.00 FS	*- FS
57	1		*RADIATOR FAN CONTROL UNIT	Not Necessary	2,107.00 FS	*- FS
58	1		*LOCK CARRIER AIR GUIDE 6pcs	Damaged	106.00 FS	*28.16 FS
59	1		*FOAM FILLER PIECE	Deformed	113.00 FS	*90.40 FS
60	1		*INTAKE AIR DUCT - RH	Not Necessary	19.00 FS	*- FS
61	1		*INTAKE AIR DUCT AIR GUIDE - RH	Not Necessary	48.00 FS	*- FS
62	1		*AIR FILTER	Not Necessary	352.00 FS	*- FS
63	1		*INTAKE HOSE	Not Necessary	85.00 FS	*- FS
64	1		*FRONT NO. PLATE	Bent	40.00 FS	*40.00 FS
65	1		*SUNDRIES	Necessary	600.00 FS	*57.20 FS
66	1		*WINDOW SLOT SEAL WITH TRIM STRIP RHF	Cut	224.00 FS	*224.00 FS
Total Parts (\$\$)					33,513.00	11,577.20

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	New	360.00	360.00
2	TO REMOVE AND RENEW AIRCON CONDENSER, RADIATOR, ADDITIONAL RADIATOR, ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT VACUUM / REGAS AND TO PRESSURE COOLING SYSTEM.	New	1,200.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH HEADLIGHTS AND BONNET. RENEW FRONT LOCK CARRIER AND ALIGN POSITION. RE-ORGANIZE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	4,900.00	1,250.00
4	TO RESPRAY FRONT BUMPER, BONNET AND HINGES.	New	2,200.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
6	TO REMOVE AND REINSTALL RHS FRONT DOOR, TRIM, AND OTHER FITTINGS FOR REPLACEMENT SLOT SHIELD.	New	300.00	300.00
Gross Labour Cost (\$\$)			9,152.00	3,202.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >