



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

WEE HOCK SENG SCHOOL BUS SERVICE

14/05/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP LonPac
Joy.

Accident date: 07/05/2019

Estimated repair cost for vehicle no: CB6841D MITSUBISHI BE639GRMHDEA

CHASSIS: BE639GB00212

3.9 M '02

S/n	Qty	Items	U/price	Amount
1	1	Front Panel <i>Repair</i>		\$3,873.00
2	1	Front Panel Emblem Logo <i>new</i>		\$76.00
3	1	Front Bumper <i>Distorted</i>		\$1,685.00
4	1	Front L/H Head Lamp <i>not new</i>		\$732.00
5	1	Front L/H Head Lamp Top Moulding <i>new</i>		\$123.00
6	1	Front L/H Side Lamp <i>lt</i>		\$251.00
7	1	Front L/H Fender <i>Repair</i>		\$3,039.00
8	1	Front L/H Fender Signal Lamp <i>lt</i>		\$88.00
9	1	Front L/H Fender Moulding <i>new</i>		\$578.00
10	1	Front L/H Fender Body Sticker (Special Nett) <i>new</i>		\$480.00
11	1	Front L/H Fender Glass Sealant <i>new</i>		\$220 150 (SN)
Subtotal :-				\$10,925.00

Labour charges

To check wiring

Tuff kote

Panel beating

Spray painting

To remove fender glass

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

~~\$80.00~~ 30

~~\$150.00~~ 50

~~\$1,400.00~~ 800

~~\$1,400.00~~ 750.

Subtotal :- \$3,030.00

Total:- \$13,955.00

total 3746.75
H/S: 3K
05 Days

3K