

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 7735S

DATE 14/5/2019 11:11

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Fender (LH) <i>X repair</i>			\$ 2,171.40
	Rear Fender Inner Lining (LH) <i>X</i>			\$ 169.30
	Rear Windscreen Moulding <i>X</i>			\$ 28.30
	Rear Door (LH) <i>X repair</i>			\$ 2,201.10
	Rear Tyre Rim (LH) <i>X</i>			\$ 325.30
	<i>Rear wheel cone (LH) ✓</i>			\$ 7.10
	<i>Rear Bumper X repair</i>			\$ 4,895.40
	SUB TOTAL			\$ 979.08
	LESS 20%			\$ 3,916.32
	DISCOUNTED TOTAL			
	Rear Bumper Advertisement Logo ✓			\$ 50.00
	Rear Bumper Rubber Mat <i>X</i>			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH) ✓		\$ 100.00	\$ 200.00
	Rear Windscreen Sealant <i>X</i>			\$ 46.00
	Rear Door Advertisement Logo (LH) ✓			\$ 100.00
	Rear Door Comfortdelgro & Apps Sticker (LH) ✓			\$ 80.00
				\$ 526.00
	Labour Charge			
	Panel Beating			\$ 800.00 <i>400</i>
	Spray Painting Charge			\$ 900.00 <i>600</i>
	Wiring Charge			\$ 50.00 <i>X</i>
	Tuff Kote			\$ 50.00 <i>X</i>
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 <i>X</i>
	Remove/Refix Rear Windscreen Glass			\$ 120.00 <i>X</i>
	Remove/Refix Reverse Sensor			\$ 80.00 <i>X</i>
	Transfer of Door			\$ 80.00 <i>X</i>
	<i>Kali 16/11/14</i>			
	<i>14/5/19 1135L</i>			
	<i>3 Pys</i>			
	<i>45 After Repair photo</i>			
	TOTAL LABOUR			\$ 2,230.00
	ESTIMATE TOTAL			\$ 6,672.32

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary charges must be surveyed and subject to final approval from insurance Company

Acknowledged by Repairer
Signature:
Date: