

03/2003

ASS. REC. BY:

REF: CS/APR11 9008620/ATD3

n2

Special Instruction:

SURVEYOR: Adnan

ASSIGNMENT (Office)

From (Person): Justin Wong

of AAI

Date/Time:

5/5/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMF 67404

Insured:

SJC 55032

at Workshop m/s

ACE AUTOMATION

Tel:

6844 1189

of

KARIM PAKIT

Policy No:

Claim No:

C10003094/JW

Sum Insured:

Excess:

D.O.A. B5. 209

Make of Veh:

(Client's Record)

CA / REV / REP / REV 24 HRS

Date/Time:

5/5/19

Person Contacted:

Jenny

H.O.D. Endorsement:

Vehicle INAOUT

Date/Time	Action/Instruction ( ) Estimate
	SMF 67404 x
	SJC 55032 x
	lump sum \$6500+ (red: 15176.14, 70%)

REF:

AGI

Surrogate

## ASSIGNMENT

From:

Date:

15/1/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMF 6740Y

at Workshop m/s

ACE AUTOMATION

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMF 6740Y

Yr Regn: 2018, Nov

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Elantra.

c.c 1591

Colour:

Red.

A/C: Insured / Std / NI / NA

Sp. Reading

10084.

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KM11D841CMJ4765935

Gen. Cond: Good / Fair / Poor / BurntSteering: Order / Jammed / Leaked / Burnt orBrake: Order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

195/65R15.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Nexen.

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

15/05/19.

Survey held at

Ace Automation.

Des. of Damages: Fit / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP Budget Direct.

RECEIVED 17 MAR 2020

Date/Time, File Pass to?

1) AB Typist

☐

Preli. Report

☒

Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$

TP

6500/-

Days Of Repair:

9

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

450

## Nivitha (LKK Auto)

**From:** Justin Wong <justin.wong@budgetdirect.com.sg>  
**Sent:** Wednesday, 15 May 2019 3:16 PM  
**To:** Admin-D (LKKAuto)  
**Cc:** assignments  
**Subject:** FW: SMF 6740 Y || Claim ref: C10003094/JW  
**Attachments:** TP GIA - SMF6740Y.pdf; OI GIA - SJC5503Z.pdf; 15052019115748-0001.pdf

Hi Team,

We would like to arrange TP Pre-repair Survey for SMF6740Y. Please refer to below email for reference.

Please confirm.

Regards,

**Justin Wong**  
Executive, Claims

T +65 6540 2184  
F +65 6725 0853  
E [Justin.wong@budgetdirect.com.sg](mailto:Justin.wong@budgetdirect.com.sg)



**Customer Care** +65 6221 2111  
**Claims** +65 6221 2199  
**Claims (Int.)** +65 6540 2199

190 Clemenceau Avenue, #03-01  
Singapore Shopping Centre  
Singapore  
239924  
[budgetdirect.com.sg](http://budgetdirect.com.sg)

auto  general

Auto & General Insurance (Singapore) Pte. Limited (Co. Reg. No. 201626103G) trading as **Budget Direct Insurance**.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

**From:** Ace Autolution <admin@aceauto.com.sg>  
**Sent:** Wednesday, 15 May 2019 2:10 PM  
**To:** Julie Mangubat <julie.m@budgetdirect.com.sg>

Cc: Justin Wong <justin.wong@budgetdirect.com.sg>  
Subject: Re: SMF 6740 Y || Claim ref: C10003094/JW

Hi Julie,

We Request Calvin Ang LKK Auto Consultant Pte Ltd .

Thank you.

Regards ,  
Jenny / Shu Wen  
ACE AUTOLUTION PTE LTD  
13 KAKI BUKIT ROAD 4 ,  
#03-29 BARTLEY BIZ CENTRE  
SINGAPORE 417807  
Tel : 6844 1184 / 9657 2134

On Wed, May 15, 2019 at 1:52 PM Julie Mangubat <[julie.m@budgetdirect.com.sg](mailto:julie.m@budgetdirect.com.sg)> wrote:

WITHOUT PREJUDICE

Hi Jenny

As spoken, please find list of surveyors for your consideration.

1. Calvin Ang LKK Auto Consultant Pte Ltd
2. Bryan Ang LKK Auto Consultant Pte Ltd
3. Xing Guo Qiang LKK Auto Consultant Pte Ltd
4. Mohammed Rasul LKK Auto Consultants Pte Ltd
5. Mohamad Taufihk LKK Auto Consultants Pte Ltd
6. Simon Ho LKK Auto Consultants Pte Ltd
7. Pang Kiah Keen (Frankie) FormTeam Adjusters Pte Ltd
8. Chua Soo Teck (Benjamin) FormTeam Adjusters Pte Ltd
9. Lim Say Koon FormTeam Adjusters Pte Ltd
10. Ng You Han FormTeam Adjusters Pte Ltd
11. Soon HanXin (Gary) FormTeam Adjusters Pte Ltd

12. Chow Bo Xiong FormTeam Adjusters Pte Ltd

13. Derrick Quok – In house surveyor

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors.

Thank you,

-Julie

**From:** Ace Autolution <[admin@aceauto.com.sg](mailto:admin@aceauto.com.sg)>

**Sent:** Wednesday, May 15, 2019 11:52 AM

**To:** Customer Care <[help@budgetdirect.com.sg](mailto:help@budgetdirect.com.sg)>

**Subject:** SMF 6740 Y

**ATTEN:Cheryl**

Dear Sir/Mdm,

Please take note of the attached file for your reference

Regards ,

Jenny / Shu Wen

ACE AUTOLUTION PTE LTD

13 KAKI BUKIT ROAD 4 ,

#03-29 BARTLEY BIZ CENTRE

SINGAPORE 417807

Tel : 6844 1184 / 9657 2134

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	14/05/2019 11:16
Date Of Accident	13/05/2019 09:05
Exact Location Of Accident	NICOLL DRIVE CARPARK 4
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMF6740Y
<b>Insured/Policyholder</b>	
Name Of Registered Owner	THAM WEN LI SHINA
NRIC No	S9447072B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90187703
Alternative Phone No	OTHERS-90187703

### Vehicle Particulars

Manufacturer	HYUNDAI
Model	ELANTRA AD 1.6 GLS AT (AMS)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VPA/P2219269
Cover Note Number	

### Driver

Name of Driver	LIM CHOON WHAY
NRIC No	S1705199G
Date Of Birth	04/10/1965
Occupation	INDOOR
Date Of Driving Pass	18/12/1984
Driving Experience	34 YEARS AND 4 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97511097
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	845 TAMPINES STREET 83 #06-168 SPORE 520845
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	PARENT
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	4
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJC5503Z
Vehicle Make/Model/Colour	CHEVROLET SPARK 1.0MT
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLW7697E
-----------------------------	----------



Vehicle Make/Model/Colour	VOLKSWAGEN GOLF TSI TL
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SV71D
Vehicle Make/Model/Colour	B.M.W. 520I 2.0L AT D/AB 2WD 4DR GAS/D NAV
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name: *Sulata mi*  
NRIC/FIN No.: *S20403778*

## Sketch Plan #2

### SKETCH PLAN



Vehicle A: SMF 6740 Y  
 Vehicle B: SJG 5503 Z  
 Vehicle C: SAW 7687 E  
 Vehicle D: SV 71 D

### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 13 May 2019, I was travelling along Nisell Drive at around 9.00 AM.

Vehicle D (SV 71 D) was in front of me and the vehicle suddenly stop. As I follow suit and manage to slow down and stop my vehicle on time. However, Vehicle B (SJG 5503 Z) did not managed to stop and collided with the rear of my vehicle and caused my vehicle to be pushed forward and ended up colliding to Vehicle D (SV 71 D) which was in front of me. When I got out of my vehicle to check on the situation, I realised there were a total of 4 vehicle involved in the accident.

### DECLARATION

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature  
 Date & Time:

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

Reporting Centre Personnel's Signature  
 Name: J. L. L.  
 NRIC/PIN No: J1040378



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29  
Singapore 417807

Tel: 6702 4282 Fax: 6702 4202

TP Budget Direct.  
Denise

KMH D841CMJ4765935

Page No. 1

Vehicle No. SMF6740Y HYUNDAI ELANTRA

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR ADJUSTMENT
<b>PARTS (LIST ITEMS)</b>				
1	FRONT BONNET <i>new</i>		1602.50	+
2	FRONT BONNET HINGE LH & RH @\$121.00 <i>new</i>		242.00	+
1	FRONT BONNET LOCK		185.70	+
1	FRONT BUMPER <i>new</i>		498.00	✓
2	FRONT BUMPER SIDE RETAINER LH & RH @\$65.80 <i>new</i>		131.60	70
2	FRONT BUMPER SIDE BRACKET LH & RH @\$70.30 <i>new</i>		140.60	+
2	FRONT BUMPER FOGLAMP COVER LH & RH @\$211.00 <i>new</i>		422.00	+
1	FRONT BUMPER SPONGE <i>cracked</i>		311.60	125
1	FRONT BUMPER REINFORCEMENT <i>new</i>		715.20	+
1	FRONT BUMPER LOWER AIR GRILLE <i>new</i>		410.20	+
2	FRONT HEADLAMP LH & RH @\$1844.40 <i>new</i>		3688.80	1844.40
1	FRONT GRILLE LOGO <i>new</i>		71.00	✓
1	FRONT CHROME GRILLE <i>new</i>		460.20	✓
2	FRONT FENDER LH & RH @\$456.20		912.40	+
2	FRONT FENDER INNER SHEILD LH & RH @\$110.00 <i>new</i>		220.00	+
1	FRONT SUPPORT PANEL <i>new</i>		959.30	+
1	FRONT RADIATOR		658.00	+
1	FRONT A/C CONDENSER		856.00	+
1	REAR BOOTLID <i>new</i>		1011.00	✓
1	REAR BOOTLID LOGO		61.00	✓
1	REAR BOOTLID "ELANTRA" EMBLEM <i>new</i>		71.00	✓
2	REAR BOOTLID LAMP LH & RH @\$355.00 <i>new</i>		710.00	✓
1	REAR BOOTLID LOCK <i>new</i>		210.00	6758.80
1	REAR BOOTLID INNER TRIM <i>new</i>		193.20	+
1	REAR BOOTLID WEATHERTRIP <i>new</i>		170.50	5407.04
1	REAR BUMPER <i>new</i>		953.70	459.40
1	REAR BUMPER LOWER <i>new</i>		241.00	✓
2	REAR BUMPER SIDE RETAINER LH & RH @\$79.00 <i>new</i>		158.00	75
2	REAR BUMPER BRACKET LH & RH @\$82.60 <i>new</i>		165.20	+
1	REAR BUMPER REINFORCEMENT <i>new</i>		511.10	328
1	REAR BUMPER REINFORCEMENT BRACKET <i>new</i>		281.60	+
1	REAR BUMPER UNDER COVER <i>new</i>		81.00	+
1	REAR BUMPER INNER KEYLESS SENSOR <i>new</i>		228.00	+
1	REAR END PANEL <i>new</i>		816.00	454
1	REAR END PANEL TOP GARNISH <i>new</i>		317.90	69.80
1	REAR SPARE TYRE PANEL <i>new</i>		982.00	+
1	REAR SPARE TYRE PANEL TOP COVER <i>new</i>		271.00	+
			19918.30	
less 20%			3983.66	20%
			15934.64	
<b>SPECIAL NETT ITEMS</b>				
1 SET	FRONT CAR PLATE WITH HOLDER <i>new</i>		70.00	✓
1 SET	FRONT BUMPER CLIPS <i>new</i>		80.00	30

1	FRONT PARKING SENSORS <i>new</i>	1091.50	+
1 SET	FRONT FENDER COWLING CLIPS <i>new</i>	100.00	x
1	REVERSE SENSOR <i>2nd</i>	280.00	-20
1	REVERSE CAMERA <i>new</i>	350.00	+
1 SET	REAR BUMPER CLIPS <i>new</i>	100.00	-30
1	REAR END PANEL SEALANT <i>new</i>	100.00	60
1 SET	REAR END PANEL TOP GARNISH CLIPS <i>new</i>	80.00	-10
1	COOLANT <i>new</i>	100.00	x
Total Parts		18286.14	

400



**ACE AUTOLUTION PTE LTD**

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel: 6702 4282 Fax: 6702 4202

Page No. 2

Vehicle No. SMF6740Y HYUNDAI ELANTRA

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
	<u>LABOUR</u>		
1	To remove the affected parts & fittings to commence repairs and replace damaged parts	<del>1400.00</del>	1000
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	<del>1200.00</del>	1100
3	To remove and refix wiring at damaged areas	<del>100.00</del>	60
4	To perform anti rust treatment on affected areas	<del>200.00</del>	60
5	To remove and replace reverse sensors and check for proper functions	<del>120.00</del>	50
6	To remove and refix rear boot mechanism	150.00	x
7	To top up coolant	120.00	x
8	To tuff coat	<del>100.00</del>	60
Labour Total :		3390.00	
TOTAL (PARTS & LABOUR):		21676.14	

2230

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

total 8137.07  
L/S 6.5K  
09 Days

65K




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL		Ref : CS/AGI19008620/Atd3n2	
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Date : 17-03-2020	
		Code : AGI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJC 5503Z	Veh. Inspected	SMF 6740Y
Policy No.		Coverage (\$)	0.00
Claim No.	C10003094/JW	Excess (\$)	0.00
Assign From	JUSTIN WONG	Assign Date	15/05/2019
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI ELANTRA	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	KMHD841CMJU765935	Colour	RED
Odometer	10084	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	NEXEN	6 mm
L/H Front Tyre	195/65 R15	NEXEN	6 mm
R/H Rear Tyre	195/65 R15	NEXEN	6 mm
L/H Rear Tyre	195/65 R15	NEXEN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	13/05/2019	Inspection Date	15/05/2019
Survey held at	ACE AUTOLUTION PTE LTD 13 KAKI BUKIT ROAD 4 #03-29 BARTLEY BIZ CENTRE SINGAPORE 417807		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMF 6740Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT BONNET	NOT NECESSARY	1,602.50	-
2	FRONT BONNET HINGE LH & RH @\$121.00	NOT NECESSARY	242.00	-
1	FRONT BONNET LOCK	NOT NECESSARY	185.70	-
1	FRONT BUMPER	DEFORMED	498.00	498.00
2	FRONT BUMPER SIDE RETAINER LH & RH @\$65.80	NECESSARY	131.60	70.00
2	FRONT BUMPER SIDE BRACKET LH & RH @\$70.30	NOT NECESSARY	140.60	-
2	FRONT BUMPER FOGLAMP COVER LH & RH @\$211.00	NOT NECESSARY	422.00	-
1	FRONT BUMPER SPONGE	CRACKED	311.60	125.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	715.20	-
1	FRONT BUMPER LOWER AIR GRILLE	NOT NECESSARY	410.20	-
2	FRONT HEADLAMP LH & RH @\$1844.40	O/S CUT	3,688.80	1,844.40
1	FRONT GRILLE LOGO	NECESSARY	71.00	71.00
1	FRONT CHROME GRILLE	CUT	460.20	460.20
2	FRONT FENDER LH & RH @\$456.20	NOT NECESSARY	912.40	-
2	FRONT FENDER INNER SHIELD LH & RH @\$110.00	NOT NECESSARY	220.00	-
1	FRONT SUPPORT PANEL	NOT NECESSARY	959.30	-
1	FRONT RADIATOR	NOT NECESSARY	658.00	-
1	FRONT A/C CONDENSER	NOT NECESSARY	856.00	-
1	REAR BOOTLID	DENTED	1,011.00	1,011.00
1	REAR BOOTLID LOGO	NECESSARY	61.00	61.00
1	REAR BOOTLID "ELANTRA" EMBLEM	NECESSARY	71.00	71.00
2	REAR LAMP LH & RH @\$355.00	CRACKED	710.00	710.00
1	REAR BOOTLID LOCK	DAMAGED	210.00	210.00
1	REAR BOOTLID INNER TRIM	NOT NECESSARY	193.20	-
1	REAR BOOTLID WEATHERSTRIP	NOT NECESSARY	170.50	-
1	REAR BUMPER	DEFORMED	953.70	459.40
1	REAR BUMPER LOWER	DEFORMED	241.00	241.00
2	REAR BUMPER SIDE RETAINER LH & RH @\$79.00	NECESSARY	158.00	75.00
2	REAR BUMPER BRACKET LH & RH @\$82.60	NOT NECESSARY	165.20	-
1	REAR BUMPER REINFORCEMENT	BENT	511.10	328.00
1	REAR BUMPER REINFORCEMENT BRACKET	NOT NECESSARY	281.60	-
1	REAR BUMPER UNDER COVER	NOT NECESSARY	81.00	-
1	REAR BUMPER INNER KEYLESS SENSOR	NOT NECESSARY	228.00	-
1	REAR END PANEL	DENTED	816.00	454.00

Report Ref No. CS/AGI19008620/Atd3n2





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR END PANEL TOP GARNISH	DEFORMED	317.90	69.80
1	REAR SPARE TYRE PANEL	TO REPAIR SEE LABOUR	982.00	-
1	REAR SPARE TYRE PANEL TOP COVER	NOT NECESSARY	271.00	-
	LESS 20% DISCOUNT		-3,983.66	-1,351.76
			15,934.64	5,407.04
	<b>SPECIAL NETT ITEMS</b>			
1	SET FRONT CAR PLATE WITH HOLDER (SN0	DENTED	70.00	70.00
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	80.00	30.00
1	FRONT PARKING SENSORS (SN)	NOT NECESSARY	1,091.50	-
1	SET FRONT FENDER COWLING CLIPS (SN)	NOT NECESSARY	100.00	-
1	REVERSE SENSOR (SN)	DAMAGED	280.00	200.00
1	REVERSE CAMERA (SN)	NOT NECESSARY	350.00	-
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	100.00	30.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	100.00	60.00
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	80.00	10.00
1	COOLANT (SN)	NOT NECESSARY	100.00	-
			2,351.50	400.00
	<b>LABOUR</b>			
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS AND REPLACE DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF REAR SPARE TYRE PANEL.		1,400.00	1,000.00
	TO SUPPLY PAINT MATERIALS,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED.		1,200.00	1,100.00
	TO REMOVE AND REFIX WIRING AT DAMAGED AREAS.		100.00	60.00
	TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS.		200.00	60.00
	TO REMOVE AND REPLACE REVERSE SENSORS AND CHECK FOR PROPER FUNCTIONS.		120.00	50.00
	TO REMOVE AND REFIX REAR BOOT MECHANISM.	NOT NECESSARY	150.00	-
	TO TOP UP COOLANT.	NOT NECESSARY	120.00	-
	TO TUFF COAT.		100.00	60.00
			3,390.00	2,330.00
	<b>GRAND TOTAL</b>		<b>21,676.14</b>	<b>8,137.04</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>6,500.00</b>

Report Ref No. CS/AGI19008620/Atd3n2



Report Ref No. CS/AGI19008620/Atd3n2

**ADRIAN LING WAI PING**

**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**