Payce J. (Sinke if N.A.)

53

Name 3:

Preli. Report.

Final Report.

Photos

Others

TOTAL



# 新福德車廠私人有限公司

# NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883 Website: www.nhtmotor.com Email: admin@nhtmotor.com Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

ONG SOON BOON Blk 1 Kaki Bukit Ave 6 # 01-43 Singapore 417883

TP Eryo

16/05/2019

Nett 5 416.

FRID

JHMFD163075206548

Accident date: 14/05/2019

Estimated repair cost for vehicle no: SGQ5255B HONDA CIVIC 1.8 A '07

		/price	Amount
n Qty Items			\$621.40
1 Rear Boot Lid Distor	Do. of	\$48.00	\$96.00
2 Rear Boot Lid Hinge	Bent	•	\$35.00
1 Rear Boot Lid Emblem			\$38.80
1 Rear Boot Lid Civic Log			\$36.10
<ol> <li>Rear Boot Lid lytec Log</li> </ol>	30 V	\$202.20	\$404.40
2 Rear Boot Lid Side Refl	lector Clacino	,	\$50.00
1 Rear Boot Lid Number	Plate sed	\$83.10	\$166.20
	Plate Lamp Not Nec	<b>J</b>	\$127.60
<ol> <li>Rear Boot Lid Lock Cat</li> </ol>	ole NH NCC		\$194.50
0 1 Rear Boot Lid Inner Lo	ck senc		\$137.60
1 Rear Boot Lid Inner Ru	ibber 💝	\$328.70	\$657.40
2 Rear Tail Lamp Cut		\$6.50	\$26.00
13 4 Rear Tail Lamp Clips	NC .	<b>4</b> 0.50	\$158.30
14 2 Rear Tail Lamp Panel	Denko		\$645.30
15 1 Rear Bumper Dels	~ c	\$6.50	\$65:00
16 10 Kear Bumper City	w	\$33.10	\$66.20
17 2 Rear Bumper Side Ret	Conser (Special Nett) Down	ed	\$350:00
18 1 Rear Bumper Reverse	Sensor (Special Mett)		\$65.10
19 2 Rear Bumper Mud Sh	ield Green	\$6.50	\$78.00
20 12 Rear Bumper Mud Sh	field Clip 4		\$55.20
21 2 Rear Bumper Bracket	Henn		\$318.3
6.6	Devled Devled		\$161.2
23 1 Rear End Panel Top G	Barnish Delay d		\$980.5
24 2 Rear Fender Per	im Board Cranyled	\$232.80	\$465.6
25 2 Rear Fender Inner Tr		\$6.50	\$104.0
26 16 Rear Fender Inner Tr	im Board Clip Xee	,0.00	\$38.0
27 2 Rear Fender Air-Duct			\$1,254.4
28 1 Rear Spare Tyre Pane	el repuis		

29	1	Rear Spare Tyre Panel Top Cover	\$329.96
30	1	Rear Spare Tyre Panel & End Panel Sealant Arthur	\$450.00
31	1	Rear Exhaust	\$728-50-633
32	2	Rear Exhaust Chrome Pipe Sex \$186.0	0 \$372.00 124/14
33	1	Rear Center Exhaust	\$637.50 🗶
34	1	Rear Windscreen Moulding	\$100.80

5167-06 4133-64 \$10,014.86

### Labour charges

To remove & refit rear	cushion		\$280.00 60
To remove & refit reve	rse sensor		\$100.00 50
To remove & refit rear	exhaust		\$280.00 80
To remove & refit rear	windscreen		\$120.00 *
Gum			\$50.00 ×
To remove & refit petro	ol tank		\$280.00 X
To check wiring			\$100,00 30
Tuff kote		2780	\$150,00 30
Towing fee Panel beating	LKK Auto Consultants hence notify the Repairer of the following:  • To resurvey beforefalter spray painting  • To display damaged part(s) during resurvey  • Parts prices are subject to confirmation		\$1,600.00 1200
Spray painting	Thed party survey is on a "Webout Prejudice" basis No Regal modification(s) is allowed Supplementary flam(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:	Subtotal :	\$4,660.00
		1	5958. LY. 58k. 07 Days.

#### > Back to OneMotoring

#### Enquire PARF/COE Rebate for Registered Vehicle

#### Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID

5621.

Vehicle Details

Vehicle No.:

SGQ5255B

Vehicle to be Exported:

Na

Intended Deregistration Date: Vehicle Make:

14 May 2019 HONDA

Vehicle Model:

CIVIC 1.8LA

Primary Colour:

Silver

Manufacturing Year:

2006

Engine No.:

R18A12007962

Chassis No.:

JHMFD163075202548

Maximum Power Output:

103.0 kW (138 bhp)

Open Market Value:

\$20,705.00

Original Registration Date:

18 Jan 2007

First Registration Date:

18 Jan 2007

Transfer Count.

Actual ARF Paid:

\$22,776.00

Intended PARF Rebate Details

PARF Eligibility:

Forfeited

PARF Rebate Amount:

PARF Eligibility Expiry Date:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

17 Jan 2022

COE Category:

B - Car (1601cc & above)

COE Period(Years):

POP Paid:

\$26,330.00

COE Rebate Amount:

\$14,085.00

Total Rebate Amount:

\$14,085.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 14 May 2019

OK



# 新福德車廠私人有限公司

ERGO

### NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883 Email: admin@nhtmotor.com Website: www.nhtmotor.com Tel: 6747 9241 Fax: 6741 7276 UEN: 201718370K

ONG SOON BOON Blk 1 Kaki Bukit Ave 6 # 01-43 Singapore 417883

TP Ergo.

16/05/2019

Nett :5 416.

JAMF D163075206548

Accident date: 14/05/2019

Estimated repair cost for vehicle no: SGQ5255B HONDA CIVIC 1.8 A '07

2	S/n	Qty	Items	U/price	Amount
1   Rear Boot Lid Emblem Logo   \$35.0     1   Rear Boot Lid Civic Logo   \$38.8     1   Rear Boot Lid Vive Logo   \$38.8     1   Rear Boot Lid Vive Logo   \$36.1     2   Rear Boot Lid Side Reflector   \$36.1     3   2   Rear Boot Lid Number Plate   \$50.0     3   2   Rear Boot Lid Number Plate Lamp   \$83.10   \$166.2     4   Rear Boot Lid Lock Cable   \$127.6     5   1   Rear Boot Lid Inner Lock   \$194.5     6   1   Rear Boot Lid Inner Rubber   \$137.6     7   1   Rear Boot Lid Inner Rubber   \$137.6     8   1   Rear Boot Lid Inner Rubber   \$328.70   \$657.4     9   1   Rear Tail Lamp   \$328.70   \$657.4     13   4   Rear Tail Lamp Clips   \$6.50   \$26.0     14   2   Rear Tail Lamp Panel   \$33.10   \$66.2     15   1   Rear Bumper Delay   \$6.50   \$65.0     16   10   Rear Bumper Clip   \$6.50   \$65.0     17   2   Rear Bumper Reverse Sensor (Special Nett)   \$65.0     18   1   Rear Bumper Mud Shield   \$65.1     19   2   Rear Bumper Mud Shield   \$65.1     20   12   Rear Bumper Mud Shield   \$65.1     21   2   Rear Bumper Bracket   \$55.2     22   1   Rear End Panel   \$318.3     23   1   Rear End Panel   \$980.5     24   2   Rear Fender   \$980.5     25   2   Rear Fender   \$980.5     26   16   Rear Fender Inner Trim Board Clip   \$6.50   \$104.0     27   2   Rear Fender Inner Trim Board Clip   \$6.50   \$104.0     27   2   Rear Fender Inner Trim Board Clip   \$6.50   \$104.0     27   2   Rear Fender Inner Trim Board Clip   \$6.50   \$104.0     28   \$38.8   \$38.8     38   \$38.8   \$38.8     38   \$38.8   \$38.8     38   \$38.8   \$38.8     38   \$38.8   \$38.8     38   \$38.8   \$38.8     38   \$38.8   \$38.8     38   \$38.8   \$38.8     38   \$38.8   \$38.8     38   \$38.8   \$38.8     38   \$38.8   \$38.8     38   \$38.8   \$38.8     38   \$38.8     38   \$38.8   \$38.8     38   \$38.	1	1	Rear Boot Lid Distorte d		\$621.40
1   Rear Boot Lid Civic Logo   \$38.8     1   Rear Boot Lid Ivtec Logo   \$36.1     2   Rear Boot Lid Side Reflector   \$202.20   \$404.4     1   Rear Boot Lid Number Plate   \$50.0     3   2   Rear Boot Lid Number Plate Lamp   \$83.10   \$166.2     4   Rear Boot Lid Lock Cable   \$127.6     5   1   Rear Boot Lid Inner Lock   \$194.5     6   1   Rear Boot Lid Inner Rubber   \$137.6     7   1   Rear Boot Lid Inner Rubber   \$137.6     8   1   Rear Boot Lid Inner Rubber   \$137.6     9   1   Rear Boot Lid Inner Rubber   \$137.6     10   1   Rear Boot Lid Inner Rubber   \$137.6     11   1   Rear Boot Lid Inner Rubber   \$137.6     12   2   Rear Tail Lamp   \$158.3     13   4   Rear Tail Lamp Clips   \$6.50   \$26.0     14   2   Rear Bumper Delay   \$6.50   \$65.0     15   1   Rear Bumper Delay   \$6.50   \$65.0     16   10   Rear Bumper Side Retainer   \$33.10   \$66.2     17   2   Rear Bumper Reverse Sensor (Special Nett)   \$6.50   \$78.0     19   2   Rear Bumper Mud Shield   \$65.1     20   12   Rear Bumper Mud Shield   \$65.1     20   12   Rear Bumper Bracket   \$55.2     21   2   Rear End Panel   \$318.3     22   1   Rear End Panel   \$318.3     23   1   Rear End Panel   \$980.5     24   2   Rear Fender   \$980.5     25   2   Rear Fender   \$980.5     26   16   Rear Fender Inner Trim Board   \$232.80   \$465.6     27   2   Rear Fender Inner Trim Board   \$338.0     27   2   Rear Fender Inner Trim Board   \$338.0     28   \$38.0   \$38.0     29   \$38.0   \$38.0     20   \$38.0   \$38.0     20   \$38.0   \$38.0     20   \$38.0   \$38.0     20   \$38.0     20   \$38.0   \$38.0     21   \$38.0   \$38.0     22   \$38.0   \$38.0     23   \$38.0     34   \$38.0     35   \$38.0     35   \$38.0     36   \$38.0     37   \$38.0     38   \$	2	2	Rear Boot Lid Hinge	\$48.00	\$96.00
1   Rear Boot Lid   Number Plate   \$50.0     2   Rear Boot Lid   Number Plate   \$50.0     3   2   Rear Boot Lid   Number Plate   Lamp   \$83.10   \$166.2     4   1   Rear Boot Lid   Number Plate Lamp   \$83.10   \$166.2     5   1   Rear Boot Lid   Lock Cable   Me   \$127.6     6   1   Rear Boot Lid   Inner Lock   \$127.6     7   1   Rear Boot Lid   Inner Lock   \$127.6     8   1   Rear Boot Lid   Inner Rubber   \$137.6     9   1   Rear Boot Lid   Inner Rubber   \$137.6     10   1   Rear Tail Lamp   \$137.6     11   1   Rear Tail Lamp   \$137.6     12   2   Rear Tail Lamp   \$137.6     13   4   Rear Tail Lamp   \$138.3     14   2   Rear Tail Lamp   Panel   \$158.3     15   1   Rear Bumper   \$158.3     16   10   Rear Bumper   \$165.0   \$65.0     17   2   Rear Bumper Side Retainer   \$33.10   \$66.2     18   1   Rear Bumper Reverse Sensor (Special Nett)   \$350.0     19   2   Rear Bumper Mud Shield   \$12   \$12   \$12     10   2   Rear Bumper Mud Shield   \$12   \$138.3     1   2   Rear Bumper Bracket   \$165.0   \$138.3     2   3   1   Rear End Panel   \$161.2     2   2   2   Rear Fender   \$16.50   \$104.0     2   3   3   Rear Fender   \$16.50   \$104.0     2   3   3   Rear Fender   \$10.0   \$10.0     2   3   3   Rear Fender   \$10.0   \$10.0     3   4   6   6   6   6   6   6   6     4   6   7   7   7   7   7   7     5   7   7   7   7   7   7     7   8   7   7   7   7   7   7     8   8   8   8   8   8   8   8     8   8	3	1	Rear Boot Lid Emblem Logo 2		\$35.00
65         2         Rear Boot Lid Side Reflector         \$202.20         \$404.4           7         1         Rear Boot Lid Number Plate         \$50.0           8         2         Rear Boot Lid Number Plate Lamp         \$83.10         \$166.2           9         1         Rear Boot Lid Lock Cable         \$127.6           10         1         Rear Boot Lid Inner Lock         \$194.5           11         1         Rear Boot Lid Inner Rubber         \$137.6           12         2         Rear Tail Lamp         \$328.70         \$657.4           13         4         Rear Tail Lamp Clips         \$6.50         \$26.0           14         2         Rear Bumper Dente         \$158.3           15         1         Rear Bumper Dente         \$6.50         \$65.0           16         10         Rear Bumper Clip         \$6.50         \$65.0           17         2         Rear Bumper Side Retainer         \$33.10         \$66.2           18         1         Rear Bumper Mud Shield         \$350.0           20         2         Rear Bumper Mud Shield Clip         \$6.50         \$78.0           21         2         Rear End Panel         \$318.3           23	4	1	Rear Boot Lid Civic Logo How		\$38.80
1   Rear Boot Lid Number Plate   \$50.0     3   2   Rear Boot Lid Number Plate Lamp   \$83.10   \$166.2     4   1   Rear Boot Lid Lock Cable   \$127.6     5   1   Rear Boot Lid Inner Lock   \$194.5     6   1   Rear Boot Lid Inner Rubber   \$137.6     7   1   Rear Boot Lid Inner Rubber   \$137.6     8   1   Rear Boot Lid Inner Rubber   \$137.6     9   2   Rear Tail Lamp   \$328.70   \$657.4     13   4   Rear Tail Lamp Clips   \$6.50   \$26.0     14   2   Rear Bumper Dente   \$158.3     15   1   Rear Bumper Dente   \$6.50   \$645.3     16   10   Rear Bumper Side Retainer   \$33.10   \$66.2     17   2   Rear Bumper Side Retainer   \$33.10   \$66.2     18   1   Rear Bumper Reverse Sensor (Special Nett)   \$350.0     19   2   Rear Bumper Mud Shield   \$65.1     10   12   Rear Bumper Bracket   \$350.0     11   2   Rear Bumper Bracket   \$350.0     12   3   Rear End Panel   \$318.3     1   3   Rear End Panel   \$318.3     1   3   Rear End Panel   \$318.3     24   2   Rear Fender   \$980.5     25   2   Rear Fender Inner Trim Board   \$232.80   \$465.6     26   16   Rear Fender Inner Trim Board Clip   \$6.50   \$104.0     27   2   Rear Fender Air-Duct   \$338.0     28   \$38.0   \$38.0     29   \$38.0   \$38.0     20   \$38.0   \$38.0     20   \$38.0   \$38.0     20   \$38.0   \$38.0     20   \$38.0   \$38.0     21   \$38.0   \$38.0     22   \$38.0   \$38.0     23   \$38.0     24   \$38.0   \$38.0     25   \$38.0   \$38.0     26   \$38.0   \$38.0     27   \$38.0   \$38.0     38   \$38.0	5	1	Rear Boot Lid Ivtec Logo		\$36.10
Rear Boot Lid Number Plate Lamp	6	2	Rear Boot Lid Side Reflector Conclud	\$202.20	\$404.40
1   Rear Boot Lid Lock Cable	7	1	Rear Boot Lid Number Plate 364		\$50.00
1   Rear Boot Lid Lock Cable	8	2	Rear Boot Lid Number Plate Lamp NJ Nec	\$83.10	\$166.20
11 1 Rear Boot Lid Inner Rubber \$137.6 12 2 Rear Tail Lamp (1) \$328.70 \$657.4 13 4 Rear Tail Lamp Clips (1) \$6.50 \$26.0 14 2 Rear Bumper Panel \$158.3 15 1 Rear Bumper Clip \$6.50 \$65.0 16 10 Rear Bumper Side Retainer (1) \$33.10 \$66.2 17 2 Rear Bumper Side Retainer (1) \$33.10 \$66.2 18 1 Rear Bumper Reverse Sensor (Special Nett) \$33.10 \$66.2 18 1 Rear Bumper Mud Shield (2) \$65.0 19 2 Rear Bumper Mud Shield (2) \$65.0 20 12 Rear Bumper Mud Shield Clip \$6.50 \$78.0 21 2 Rear Bumper Bracket \$55.2 22 1 Rear End Panel \$318.3 23 1 Rear End Panel \$318.3 24 2 Rear Fender Panel \$980.5 25 2 Rear Fender Inner Trim Board (1) \$6.50 \$104.0 26 16 Rear Fender Inner Trim Board Clip \$6.50 \$104.0 27 2 Rear Fender Air-Duct (1) \$33.0	9	1			\$127.60
12       2       Rear Tail Lamp       \$328.70       \$657.4         13       4       Rear Tail Lamp Clips       \$6.50       \$26.0         14       2       Rear Tail Lamp Panel       \$158.3         15       1       Rear Bumper       \$645.3         16       10       Rear Bumper Clip       \$6.50       \$65.0         17       2       Rear Bumper Side Retainer       \$33.10       \$66.2         18       1       Rear Bumper Reverse Sensor (Special Nett)       \$33.10       \$66.2         19       2       Rear Bumper Mud Shield       \$6.50       \$78.0         20       12       Rear Bumper Mud Shield Clip       \$6.50       \$78.0         21       2       Rear Bumper Bracket       \$55.2         22       1       Rear End Panel       \$318.3         23       1       Rear End Panel       \$318.3         24       2       Rear Fender       \$980.5         25       2       Rear Fender Inner Trim Board       \$232.80       \$465.6         26       16       Rear Fender Air-Duct       \$38.0	10	1	Rear Boot Lid Inner Lock Dend		\$194.50
13       4       Rear Tail Lamp Clips       \$6.50       \$26.00         14       2       Rear Tail Lamp Panel       \$158.31         15       1       Rear Bumper       \$645.31         16       10       Rear Bumper Clip       \$6.50       \$65.01         17       2       Rear Bumper Side Retainer       \$33.10       \$66.2         18       1       Rear Bumper Reverse Sensor (Special Nett)       \$350.00         19       2       Rear Bumper Mud Shield       \$65.11         20       12       Rear Bumper Mud Shield Clip       \$6.50       \$78.00         21       2       Rear Bumper Bracket       \$55.2         22       1       Rear End Panel       \$318.3         23       1       Rear End Panel       \$318.3         24       2       Rear Fender       \$980.5         25       2       Rear Fender Inner Trim Board       \$232.80       \$465.6         26       16       Rear Fender Inner Trim Board Clip       \$6.50       \$104.0         27       2       Rear Fender Air-Duct       \$38.0	11	1	Rear Boot Lid Inner Rubber		\$137.60
14       2       Rear Tail Lamp Panel       \$158.3         15       1       Rear Bumper       \$645.3         16       10       Rear Bumper Clip       \$6.50       \$65.0         17       2       Rear Bumper Side Retainer       \$33.10       \$66.2         18       1       Rear Bumper Reverse Sensor (Special Nett)       \$350.0         19       2       Rear Bumper Mud Shield       \$65.1         20       12       Rear Bumper Mud Shield Clip       \$6.50       \$78.0         21       2       Rear Bumper Bracket       \$55.2         22       1       Rear End Panel       \$318.3         23       1       Rear End Panel       \$161.2         24       2       Rear Fender       \$980.5         25       2       Rear Fender Inner Trim Board       \$232.80       \$465.6         26       16       Rear Fender Air-Duct       \$38.0         27       2       Rear Fender Air-Duct       \$38.0	12	2	Rear Tail Lamp Cut	\$328.70	\$657.40
15       1       Rear Bumper       \$645.3         16       10       Rear Bumper Clip       \$6.50       \$65.0         17       2       Rear Bumper Side Retainer       \$33.10       \$66.2         18       1       Rear Bumper Reverse Sensor (Special Nett)       \$33.10       \$66.2         19       2       Rear Bumper Mud Shield       \$65.1       \$65.1         20       12       Rear Bumper Mud Shield Clip       \$6.50       \$78.0         21       2       Rear Bumper Bracket       \$55.2         22       1       Rear End Panel       \$318.3         23       1       Rear End Panel       \$161.2         24       2       Rear Fender       \$980.5         25       2       Rear Fender Inner Trim Board       \$232.80       \$465.6         26       16       Rear Fender Inner Trim Board Clip       \$6.50       \$104.0         27       2       Rear Fender Air-Duct       \$38.0	13	4	Rear Tail Lamp Clips NC	\$6.50	\$26.00
16       10       Rear Bumper Clip       \$6.50       \$65.0         17       2       Rear Bumper Side Retainer       \$33.10       \$66.2         18       1       Rear Bumper Reverse Sensor (Special Nett)       \$350.0         19       2       Rear Bumper Mud Shield       \$65.1         20       12       Rear Bumper Mud Shield Clip       \$6.50       \$78.0         21       2       Rear Bumper Bracket       \$55.2         22       1       Rear End Panel       \$318.3         23       1       Rear End Panel       \$161.2         24       2       Rear Fender       \$980.5         25       2       Rear Fender Inner Trim Board       \$232.80       \$465.6         26       16       Rear Fender Inner Trim Board Clip       \$6.50       \$104.0         27       2       Rear Fender Air-Duct       \$38.0	14	2	Rear Tail Lamp Panel Denied		\$158.30
17       2       Rear Bumper Side Retainer       \$33.10       \$66.2         18       1       Rear Bumper Reverse Sensor (Special Nett)       \$350.0         19       2       Rear Bumper Mud Shield       \$65.1         20       12       Rear Bumper Mud Shield Clip       \$6.50       \$78.0         21       2       Rear Bumper Bracket       \$55.2         22       1       Rear End Panel       \$318.3         23       1       Rear End Panel       \$318.3         24       2       Rear Fender       \$980.5         25       2       Rear Fender Inner Trim Board       \$232.80       \$465.6         26       16       Rear Fender Inner Trim Board Clip       \$6.50       \$104.0         27       2       Rear Fender Air-Duct       \$38.0	15	1	Rear Bumper Deland		\$645.30
18 1 Rear Bumper Reverse Sensor (Special Nett) 500 \$350.00 19 2 Rear Bumper Mud Shield 2 \$65.10 20 12 Rear Bumper Mud Shield Clip \$6.50 \$78.00 21 2 Rear Bumper Bracket \$55.20 22 1 Rear End Panel Develog \$318.30 23 1 Rear End Panel Top Garnish \$161.20 24 2 Rear Fender Per \$980.50 25 2 Rear Fender Inner Trim Board (Completed \$232.80 \$465.60 26 16 Rear Fender Inner Trim Board Clip \$6.50 \$104.00 27 2 Rear Fender Air-Duct \$38.00	16	10	Rear Bumper Clip	\$6.50	\$65.00
19       2       Rear Bumper Mud Shield       2       \$65.10         20       12       Rear Bumper Mud Shield Clip       \$6.50       \$78.00         21       2       Rear Bumper Bracket       \$55.20         22       1       Rear End Panel       \$318.30         23       1       Rear End Panel Top Garnish       \$161.20         24       2       Rear Fender       \$980.50         25       2       Rear Fender Inner Trim Board       \$232.80       \$465.60         26       16       Rear Fender Inner Trim Board Clip       \$6.50       \$104.00         27       2       Rear Fender Air-Duct       \$38.00	17	2	Rear Bumper Side Retainer	\$33.10	\$66.20
12   Rear Bumper Mud Shield Clip   \$6.50   \$78.00     12   Rear Bumper Bracket   \$55.20     13   Rear End Panel   Devel   \$318.30     14   25   Rear Fender   \$980.50     15   26   27   26   Rear Fender Inner Trim Board Clip   \$6.50   \$104.00     16   Rear Fender Air-Duct   \$38.00     17   28   Rear Fender Air-Duct   \$38.00     18   \$38.00   \$38.00     19   \$6.50   \$38.00     10   \$38.00     11   \$6.50   \$38.00     12   \$38.00     13   \$6.50   \$38.00     14   \$6.50   \$38.00     15   \$6.50   \$38.00     16   \$6.50   \$38.00     17   \$6.50   \$38.00     18   \$6.50   \$38.00     19   \$6.50   \$38.00     10   \$6.50   \$38.00     10   \$6.50   \$38.00     10   \$6.50   \$38.00     11   \$6.50   \$38.00     12   \$6.50   \$38.00     13   \$6.50   \$38.00     14   \$6.50   \$38.00     15   \$6.50   \$38.00     16   \$6.50   \$38.00     17   \$6.50   \$38.00     18   \$6.50   \$38.00     19   \$6.50   \$38.00     10   \$6.50   \$38.00     10   \$6.50   \$38.00     10   \$6.50   \$38.00     10   \$6.50   \$38.00     10   \$6.50   \$38.00     10   \$6.50   \$38.00     10   \$6.50   \$38.00     10   \$6.50   \$38.00     10   \$6.50   \$38.00     10   \$6.50   \$38.00     10   \$6.50   \$38.00     10   \$6.50   \$38.00     10   \$6.50   \$38.00     10   \$6.50   \$38.00     10   \$6.50   \$6.50     10   \$6.50	18	1	Rear Bumper Reverse Sensor (Special Nett)	nged	\$350.00
21 2 Rear Bumper Bracket	19	2	Rear Bumper Mud Shield 2	9	\$65.10
22       1       Rear End Panel       \$318.30         23       1       Rear End Panel Top Garnish       \$161.20         24       2       Rear Fender       \$980.50         25       2       Rear Fender Inner Trim Board       \$232.80       \$465.60         26       16       Rear Fender Inner Trim Board Clip       \$6.50       \$104.00         27       2       Rear Fender Air-Duct       \$38.00	20	12	Rear Bumper Mud Shield Clip	\$6.50	\$78.00
1 Rear End Panel Top Garnish \$161.20 24 2 Rear Fender \$980.50 25 2 Rear Fender Inner Trim Board (1997) \$232.80 \$465.60 26 16 Rear Fender Inner Trim Board Clip \$6.50 \$104.00 27 2 Rear Fender Air-Duct \$38.00	21	2	Rear Bumper Bracket		\$55.20
24       2 Rear Fender       \$980.5         25       2 Rear Fender Inner Trim Board       \$232.80       \$465.6         26       16 Rear Fender Inner Trim Board Clip       \$6.50       \$104.0         27       2 Rear Fender Air-Duct       \$38.0	22	1	Rear End Panel Develd		\$318.30
25 2 Rear Fender Inner Trim Board Crayled \$232.80 \$465.60 26 16 Rear Fender Inner Trim Board Clip \$6.50 \$104.00 27 2 Rear Fender Air-Duct 14 444 \$38.00	23	1	Rear End Panel Top Garnish		\$161.20
26 16 Rear Fender Inner Trim Board Clip \$6.50 \$104.00 27 2 Rear Fender Air-Duct 14 44 \$38.00	24	2	Rear Fender Penil		\$980.50
27 2 Rear Fender Air-Duct H M \$38.0	25	2	Rear Fender Inner Trim Board Crayled	\$232.80	\$465.60
Control of the State of the Control	26	16	Rear Fender Inner Trim Board Clip	\$6.50	\$104:00
28 1 Rear Spare Tyre Panel Per \$1,254.4	27	2	Rear Fender Air-Duct He Me		\$38.00
	28	1	Rear Spare Tyre Panel Reput		\$1,254.40

29	1	Rear Spare Tyre Panel Top Cover	\$329.96
30	1	Rear Spare Tyre Panel & End Panel Sealant Arthur	\$450.00
31	1	Rear Exhaust Seat	\$728.50
32	2	Rear Exhaust Chrome Pipe But \$186.00	\$372.00 124
33	1	Rear Center Exhaust	\$637.50 🗡
34	1	Rear Windscreen Moulding	\$100.80

5167-06 4133-64 S.N. ASubtotal:- \$10,014.86

Labour charges			
To remove & refit rear	cushion		\$280.00 60
To remove & refit reve	rse sensor		\$100.00 50
To remove & refit rear	exhaust		\$280.00 80
To remove & refit rear	windscreen		\$120.00 *
Gum			\$50.00 *
To remove & refit petro	ol tank		\$280.00 ×
To check wiring			\$100,0630
Tuff kote		2780	\$150,00 60
Towing fee	LKK Auto Consultants hence notify		\$100.00
Panel beating	the Repairer of the following:  To resurvey before after spray painting:  To display damaged part(s) during resurvey:  Parts prices are subject to confirmation:		\$1,600 00 1200
Spray painting	Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and		\$1,600.00 300
	is subject to final approval from insurance Company  Admowledged by Requirer	Subtotal :-	\$4,660.00
	Signature: Date:	Total:-	\$14,674.86

total 5958. LY.

1/5: 58K.

07 Days.

From: Khanchna (LKK Auto)

Sent: Tuesday, 23 July 2019 2:26 PM

To: Admin nht
Cc: Admin A; Chloe

Subject: RE: YP9511C & SGQ 5255B on 14/05/19 //LKK REF:CC4/EGI19008622/Akb3

Tracking: Recipient Delivery

Admin nht Admin A Chloe

Meikwan@lkkauto.com Delivered: 23/7/2019 2:26 PM olivialau@lkkauto.com Delivered: 23/7/2019 2:26 PM shupei@lkkauto.com Delivered: 23/7/2019 2:26 PM

YOUR REF: SGQ 5255B

Without Prejudice (save as to costs)

Dear Sirs/Mdm.

We refer to the above matter.

We propose settlement at a global sum of \$7,028.93(all-in).

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Khanchna | Case Handler LKK Auto Consultants Pte Ltd

DID: 6841 2360 | email: <u>Khanchna@lkkauto.com</u> Fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin nht <admin@nhtmotor.com>

Sent: Friday, 19 July 2019 11:06 AM

To: Khanchna (LKK Auto) <khanchna@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>; Chloe <chloe@nhtmotor.com>

Subject: Re: YP9511C & SGQ 5255B on 14/05/19 //LKK REF:CC4/EGI19008622/Akb3

Without Prejudice

YOUR REF: SGQ 5255B

From:	Admin nht <admin@nhtmotor.com></admin@nhtmotor.com>
Sent:	Wednesday, 17 July 2019 1:16 PM
To:	Khanchna (LKK Auto)
Cc:	Admin A; Chloe
Subject:	Re: YP9511C & SGQ 5255B on 14/05/19 //LKK REF:CC4/EGI19008622/Akb3
Attachments:	SGQ5255B AMENDED LOD.pdf; PASSENGER INV - 81335982.jpeg
Without Prejudice	
Hi Khanchna	
Thanks for your offer.	
Cor + Lou + Lta Search ok	
그는 1일 이미네이트 지하는데 게 되었다고 하는데 하다 하다 하다 하는 다른다.	was miss out of the medical certificates fees submission as our client passenger would like to
claim back the medical fe	es only.
Enclosed amended LOD a	and medical receipt for your reference.
Hope to receive your rev	ise offer soon.
So sorry for the any incor	nvenience caused.
Best Regards,	
Sukyi Chong	Sallog
New Hock Teck Motor Pt	
	01-43 Autobay @ Kaki Bukit S(417883)
Tel: 6747 9241 Fax: 6	741 7276
×	×

On Wed, Jul 17, 2019 at 1:00 PM Khanchna (LKK Auto) < khanchna@lkkauto.com > wrote:

From:

Khanchna (LKK Auto)

Sent:

Wednesday, 17 July 2019 1:00 PM

To:

Admin nht

Cc:

Admin A; Chloe

Subject:

RE: YP9511C & SGQ 5255B on 14/05/19 //LKK REF:CC4/EGI19008622/Akb3

YOUR REF: SGQ 5255B

Without Prejudice (save as to costs)

Dear Sirs/Mdm.

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair (w/GST)	\$ 6,206.00
2. Loss of Use (8 days x \$ 80.00)	\$ 640.00
3. LTA/GIA Search Fee	\$ 7.45
TOTAL	\$ 6,853.45

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Khanchna| Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841 2360 | email: <u>Khanchna@lkkauto.com|</u> Fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin nht <admin@nhtmotor.com> Sent: Wednesday, 17 July 2019 12:20 PM

To: Khanchna (LKK Auto) <khanchna@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>; Chloe <chloe@nhtmotor.com>

Subject: Re: YP9511C & SGQ 5255B on 14/05/19 //LKK REF:CC4/EGI19008622/Akb3

Without Prejudice

Hi Khanchna

So far for our LOD we never breakdown of loss of use amount x no of days and there was no issue for your side till date.



#### GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00 Singapore 048580 Tel (65) 6224 0010 Fax (65) 6224 0030 Operating Hours : Monday to Friday, 09:00 – 17:00 UEN: 5565500206 / GST Reg. No.: M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

		ADDE	ENDUM	
A)	PARTICULARS OF PE	RSONMAKINGTHEAMENDN	MENTS:	
	Original Report No	:	Vehicle Registration No:	YP 9511C
			N (5) PL_NRIC/FIN/Passport No :	
		ehicle Owner) (*) Please delete		
	Address	SIL 272 Tampines	1 8+ 22 403-06	Singapore(いっとり)
	Contact (Tel)	: 6176 8862	Mobile No.:9>3	27831
	Email Address	finance@alkran - ex	p ion sq	
	Date of Accident	14/05/2019	Time of Accident :	
	Place of Accident	: WESTCOAST HIGHWAY TOWARD	DS ALEXANDRA ROAD	
	Insurance Company	ERGO INSURANCE PTE. LTD.	V.	
	* THE NAME OF DRI	VER SHOULD BE MUHAMMAD H	HAFIZ BIN ISHAK, THAT'S ALLI *	
	117	(10)		
/	Policyholder / Driver	's Signature	Reporting Centre Pers	onnel's Signature

Date: 15 7.19

NRIC/FIN No .:

Date:

From:

Khanchna (LKK Auto)

Sent:

Monday, 15 July 2019 3:15 PM

To:

nphauto@gmail.com

Cc:

Admin A

Subject:

ADDENDUM FORM - ACCIDENT INVOLVING YP9511C & SGQ5255B ALONG/AT

WESTCOAST HIGHWAY TOWARDS ALEXANDRA ROAD ON 14/05/2019

Attachments:

INSURED GIA ADDENDUM.pdf

Dear Sir/Madam,

The above matter refers.

We attach herewith a copy of our Insured's GIA addendum form (amendment on Insured driver's name) for your necessary action.

Thank you.

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: **6841 2360** | email: <u>Khanchna@lkkauto.com|</u> Fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## LETTER OF AUTHORISATION

New Hock Teck Motor Pte Ltd Kaki Bukit Avenue 6 Blk 1 #01-43 Singapore 417883

Dear Sir.	
Accident on	14/05/19, 0840
Involving Vehicles	SGQ1255-B, YP9571C.
Along	WC Highway twas mexandra Rd
I/We, the registered of have involved in the a	owner/driver of vehicle registration no:
I/We hereby authorize forthwith.	New Hock Teck Motor Pte Ltd to commence repairs of the said vehicle
I/We agree to assign solicitor,	the whole proceeds of my/our comprehensive/third party claim to you and out, to act on my/our behalf in respect of the
	applicable, my/our solicitors shall accept this as my/our irrevocable authority to emed compensated direct to you after deduction of their costs on a Solicitor and
I/We undertake to co-	operate fully with you and our solicitors to ensure that claim is successful.
	you to sign all discharge vouchers/indemnity forms and all necessary papers in the claim in my/our absence.
Your kind co-operation	on in this matter will be much appreciated.
Yours truly,	
Owner's Signature	
(Company's stamp if	applicable)
Name:	
NRIC No.:	
Date:	

#### Assignment

To:	New Hock	Teck Mot	or Pte Ltd	(Workshop)
To:	Mem Hock	Leck Mon	OI LIG LIG	(Worksh

I/We further confirm that payment to you only or to any person authorised by you to receive payment shall constitute a good and effectual discharge of the obligations by any party of the aforesaid proceeds of my/our claim(s).

I/We authorise you expressly to give notice of this assignment to the party concerned.

I/We confirm that by this assignment, I/we shall not be entitled in law to receive any payment. If a cheque is sent to me/us, I/we shall return same to the sender as I/we am/are precluded from accepting any payment.

Dated this _		14	day of	05	20	19	
Signature	100		Deller.				
Name	13	0	ng 500 n				
ID No.	2		5772562	11			
Address		_	1				
Witness Signature	33		//_				
Witness Name	1	Ch	iow Yue Yin				
Witness ID	1	Sp	826618H	1			
Witness Address	3	designan	Caki Bukit Ave				



## 新福德車廠私人有限公司

### NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883 Website: www.nhtmotor.com Email: admin@nhtmotor.com Tel: 6747 9241 Fax: 6741 7276 UEN: 201718370K GST Reg No.: 201718370K

## TAX INVOICE

ERGO Insurance Pte. Ltd.

Invoice No :

NPL1907-0062

5 Temasek Boulevard.

Date : 8-Jul-19

#04-01 Suntec Tower Five,

Date of Accident : 14-May-19

Singapore 038985

Vehicle No. : SGQ5255B

Client:

ONG SOON BOON

Model Type : Honda Civic

Descriptions			Amount
Lump Sum Repair Cost			5,800.00
	GST 7%	1:	406.00
	Total	:	6,206.00

SIN DOLLARS: SIX THOUSAND TWO HUNDRED AND SIX ONLY



#### > Back to OneMotoring



Land Transport Authority 10 Sin Ming Drive Singapore 575701

GST Registration No.: M4-0006529-2

Print Date/Time:

14 May 2019 / 12:54:43

Receipt Date/Time: 14 May 2019 / 12:54:43

#### Tax Invoice/Receipt

Receipt No.: ITNET-00000-190514-001570

Previous Receipt No.:

S/N	Business Transaction Reference		Amount Before	GST Amount	Amount After GST
	No.		GST (S\$)	(S\$)	(5\$)
	It of Insurance Enquiry - YP9511C				
	14 May 2019/08:40:00				
(()))	ance Co: ERGO INSURANCE PTE. LT	TD.			
1	Insurance Enquiry - YP9511C Enquiry Fee 20190514125353556745		7.00	0.49	7.49
		Sub-Total	7.00	0.49	7.49
		Total Before Rounding	7.00	0.49	7.49
		Rounding Difference			0.04
		Total Amount Payable			7.45
		Paid By			
		20190514125406697	Direct Debit: eNi	2.9	7.45
		Total			7.45
		Cash Change			0.00
		Tendered Amount			7.45
		Excess Refundable Amount			0.00


#### THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Print Receipt

OK

Save as PDF



#### TAX INVOICE # -

ORIGINAL

GST REG NO M90368910N

KFINCWF / FB / 14 05 2019 1117 hrs / Page 1 of 1

**GUO JIEXIN** 

863 TAMPINES STREET 83

#05-496

SINGAPORE 520863

Patient GUO JIEXIN

Tax Invoice Number 771911150000001

Bill Ref Number 17719111500I-0001-01
Tex Invoice Date 14.05.2019 1117 hrs
Patient NRICHRN 59024542A

Visit Date

14 05.2019 1038 hrs

Visit / Bill Location : HXW24 / KXW24 / OBS

Payment Class PRIVATE Type of Supply

: Cash/Credit

SERVICE CODE	DESCRIPTION	QUANTITY	AMOUNT(55)
	PROFESSIONAL FEES - DOCTOR	Subtotal	128,00
CNW24UC	URGENT CARE CONSULTATION	100	126.00
	X-RAY INVESTIGATIONS	Subtotal	36.0
(RP008Z	U.S. OBS/GYN-ROUTINE SIMPLE SC (CLINICS)	100	36.0
		Subtotal Charges	164.0
		Total Charges Payable	184.0
MOUNT PAYABLE BEFORE TAX			154
MOUNT PAYABLE AFTER TAX			175.
ET AMOUNT PAYABLE			175
YMENT			187
IO JIEXIN	14.05.2019 NETS	575	40 57

## AUTHORISATION LETTER TO CLAIM MEDICAL BILLS

I/We,	GUO JIEX	IN	("the	third	party	claimant")	of
BLK 86	3 TAMPINES S	T 83 #06-49	6 S(520863)			(address),	
owner/driver/pa	ssenger of SG	Q 5255B	(vehicle no.)	hereby au	thorize NI	EW HOCK	
TECK MOTO	R PTE LTD("	he workshop	") to act for	me with	respect to	my claim	
for medical bill	ls ("claim") pursu	ant to the a	ccident which	occurred	14/05/2	2019	
(date) along	WEST COAS	T HIGHWAY	(location	n) invol	lving ve	hicle no/s	
YP9511C	("the accident")						
I/We, also confi	irmed that we will	not be mak	ing any Injur	y claim a	nd will on	ly claim for	
	s related to this ac						
I/We further au	thorize the works	hop to settle	my above me	ntioned ci	laim in a	manner that	
they deem fit ar	d the workshop is	further author	orized to receiv	e paymer	nt further t	o settlement	
of my claim wit	h payment cheque	s being made	in favour of t	he worksh	юр.		
V 0 12 L							
I/We further aci	knowledge that an	y settlement	the workshop	may reach	on my be	shalf is on a	
without prejudio	e and without adr	nission of liab	oility basis inso	ofar as the	driver/ow	ner/insurers	
of the other veh	icle/s is concerned	L					
Dated this	(day) of	67 (n	nonth) 20 <u>19</u> (y	year)	0		
			G III		(STEC)		
				1	(30)	18	
Į.				- 1	(A)	3	
X					en	Sulfi chu	n
the state of the s	hird party claimar	11"	Signed	by the	workshop"	1	/



Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources



### HIGH GLOSS, LIESS MAINTIENANGE, LAST LONGER

Check out the list of Paint Protection Film services available here.



Price Range

▼ Depreciation ▼ > 10 year() ▼ Vehicle Type

#### Used Car Comparison

-- Comparing 4 Vehicles ---

Honda Civic 1.6A VTi (COE till 11/2021)



Honda Civic 1.8A VTI-5 (COE till 07/2021)



Honda Civic 1.8A VTI-5 (COE till 02/2022)



Honda Civic 1.8A VTI-02/2022)



Clear All

Add all to Shortfish

Back to searth result

COE expiry date 2022-02-21

Remarks

Add to Shortlist

Add to Shortlist

COE expiry date

2022-02-21

COE expiry date

2022-02-21

Back to search result				
CAR DETAILS				Les Da
Price	\$19,000	\$21,500	\$23,800	\$22,800
Instalment	N.A.	N.A.	N.A.	N.A.
Registration Date	23-Nov-2006	24-Nov-2006	21-Feb-2007	22-Feb-2007
Manufactured	2006	2006	2006	2006
Mileage	183,000 km	2	137,000 km	144,000 km
Transmission	Auto	Auto	Auto	Auto
Engine Cap	1,595 cc	1,799 cc	1,799 сс	1,799 cc
Road Tax	\$962 /yr	\$1,271 /yr	\$1,174 /yr	\$1,174 /yr
Power	92.0 kW (123 thp)	103.0 kW (138 bhp)	103.0 kW (138 bhp)	103.0 kW (138 b
Curb Weight	1,220 kg	1,219 kg	1,219 kg	1,219 kg
Features	Brand New Aircon. Lowering Springs. Sports Rims, Looks Sporty And Stylish. Engine, Gear Box Runs Smooth. Servicing Done Regularly, Fuel Saving.	1.8L I-VTEC Engine. 5 Speed Auto Transmission, ABS, SRS Airbags. Paddle Shifter, Immobiliser, Climatic Control Aircon.	1.8L 16 Valves I-VTEC Engine, 138 BHP, 5 Speed Automatic With Paddle Shifters, ABS, Airbags, Digital Climatic Aircon Controls.	*
Accessories	New Tires Lasts You Till End Of CDE, DVD Player, Clean Interior, Auto Mirrors, Carbon Fiber Interior, Impossible To Get A Car At This Condition,	Sports Rims, Reverse Sensors And Camera, Pioneer DVD Player With Bluetooth.	Sports Rims, Retractable Side Mirrors, Reverse Sensors.	¥
Description	Selling Due To Last Minute Overseas Posting, Wanted To Keep For Another 3 Years That's Why I Just Changed The Tyres Also. Travel 20Km A Day Only, Stay At AMK Work At Khatib. Excellent Car For 3 Years. Inspection Done And Road Tax Just Renewed, Buy New And Don't Need To Spend Any Money On Repairs For The Next 3 Years.	Consignment Unit, Full Loan Available. Call Or Whatsapp For More Info.	Full Loan Available, Easily One Of The Best Condition Civics In The Market. High Trade In. Buy With Trust And Assure.	Good Engine Cor
COE	\$25,821	\$25,815	\$26,039	\$26,039
ому	\$18,460	\$20,493	\$20,032	\$20,032
ARF	\$20,306	\$22,543	\$22,036	\$18,452
Depreciation	\$7,520 /yr	\$9,710 /yr	\$8,580 /yr	\$8,220 /yr
No. of Owners	4	3	3	5
Type of Vehicle	Sedan	5edan	Sedan	Sedan
Category	CDE Car, Direct Gwner Sale	COE Car	COE Car, Premium Ad Car	COE Car, Descri
Availability	Available	Available	Available	Available

COE expiry date 2022-02-21

#### Nivitha (LKK Auto)

From: Jeannie Cheng <jeannie.cheng@ergo.com.sg>

Sent: Wednesday, 15 May 2019 11:37 AM

To: admin-d@lkkauto.com

Cc: sur@lkkauto.com; Tracy Tan; Survey Report (ERGO Insurance Pte. Ltd.)

Subject: FW: PRS IRO SGQ5255B | OI : YP9511C | DOA: 14/05/2019 | ERGO REF:

YP9511C/SL/jc

Attachments: SGQ5255B GIA.PDF

HI LKK,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and Ergo Insurance Pte Ltd have agreed on your company to be the "Single Joint Expert".

Please conduct this survey request on without prejudice basis and try to finalize with the repairer on the repairs. (Note: No repair estimate was provided to us and our driver has not lodge the accident report to us)

Attached are the necessary documents for your further actions.

Kindly acknowledge receipt of this email.

NOTE: Please assist to quote our ref as the subject matter, when forwarding the Preliminary Reports / Survey Reports.

Thank you.

Warmest Regards. Jeannie Cheng ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five Singapore 038985 DID: +65 6829 9199 x 194 jeannie cheng@ergo.com.sig

**ERGO** 

Veh lu

www.ergo.com.sq

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

#### EMAIL DISCLAIMER

The information contained in this email communication is confidential. You should only read, disclose, re-transmit, copy, distribute, act in reliance on or commercialize the information if you are authorized to do so. If you are not the intended recipient of this email communication, please notify the sender by replying to the email and destroy any electronic or paper copy of this message.

Any views expressed in this email communication are those of the individual sender. ERGO Insurance Pte. Ltd. does not represent, warrant or guarantee that the integrity of this communication has been maintained or that the communication is free of errors, virus or interference.

ERGO Insurance Pte. Ltd. asserts copyright in respect to this email including any attachment. No part may be reproduced by any process or for any purpose without prior written permission.



#### Shu Pei (LKKAuto)

From:

Jeannie Cheng <jeannie.cheng@ergo.com.sg>

Sent:

Tuesday, 28 May 2019 10:36 AM

To:

Shu Pei (LKKAuto)

Cc:

Tracy Tan; Survey Report (ERGO Insurance Pte. Ltd.)

Subject:

RE: PRS IRO SGQ5255B | OI : YP9511C | DOA: 14/05/2019| ERGO REF: YP9511C/SL/jc

Attachments:

YP9511C OLPDF

Dear Shu Pei.

insured have reported the accident. Please see attached.

Thank you.

Wagnest Regards, less me Chong ERGO Insurance Pte, Ltd.

Tomasian Societario, #04-01 Sunted Towar Pive property 050065 ptd. 485 6500 9190 v 104 comas chang@exp.com.sq



EACO is the 67 the major insurance groups in Germany and Europe. Worldwide. ERGO is impresented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.



The endage of the Allectiments are confidential, intended only by the named addresses, and may be provided. If you are not the intermediate recognition of the sendor by return and and deliver the measure. If you are not the resident recognition of the sendor by return and and deliver the measure of the sendor by return and and deliver the measure of the sendor by return and and deliver the measure of the sendor by return and and deliver the measure of the sendor by return and and deliver the measure of the sendor by return and the sendor by

From: Shu Pei (LKKAuto) [mailto:shupei@lkkauto.com]

Sent: Tuesday, May 28, 2019 10:34 AM

To: Jeannie Cheng; Tracy Tan; Survey Report (ERGO Insurance Pte. Ltd.)

Subject: RE: PRS IRO SGQ5255B | OI : YP9511C | DOA: 14/05/2019| ERGO REF: YP9511C/SL/jc

#### WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

Kindly advice whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Thank you.

Best Regards.

Shu Pei Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: <a href="mailto:inupei@likkauto.com">inupei@likkauto.com</a> | fax: 6741-4108 Bik 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | \$(408933)

From: Shu Pei (LKKAuto)

Sent: Thursday, 16 May 2019 4:30 PM

To: jeannie.cheng@ergo.com.sg; Tracy Tan < tracy.tan@ergo.com.sg>; Survey Report (ERGO Insurance Pte. Ltd.

<Survey.Report@ergo.com.sg>

Cc: Admin A <admin-a@lkkauto.com>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>

Subject: RE: PRS IRO SGQ5255B | OI : YP9511C | DOA: 14/05/2019 | ERGO REF: YP9511C/SL/jc

#### WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle SGQ 5255B at M/s New Hock Teck Motor Pte Ltd on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:

TP GIA report

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Kindly take note that the case handler in-charge is Asher and she can be contacted at DID: 6841 6051.

Thank you.

Best Regards,

Shu Pel | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: <u>shupqi@lkkuuto.com</u> | fax: 6741-4108 Illk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | 5(408933)

From: Jeannie Cheng [mailto:jeannie.cheng@ergo.com.sg]

Sent: Wednesday, 15 May, 2019 11:37 AM

To: admin-d@lkkauto.com

Cc: sur@lkkauto.com; Tracy Tan <tracy.tan@ergo.com.sg>; Survey Report (ERGO Insurance Pte. Ltd.)

<Survey.Report@ergo.com.sg>

Subject: FW: PRS IRO SGQ5255B | OI: YP9511C | DOA: 14/05/2019 | ERGO REF: YP9511C/SL/jc

HI LICK.

to compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and Ergo Insurance Pte Ltd have agreed on your company to be the "Single Joint Expert".

Please conduct this survey request on without prejudice basis and try to finalize with the repairer on the repairs.

(Note: No repair estimate was provided to us and our driver has not lodge the accident report to us)

Attached are the necessary documents for your further actions.

Kindly acknowledge receipt of this email.

NOTE: Please assist to quote our ref as the subject matter, when forwarding the Preliminary Reports / Survey Reports.

Thank you.

Warmost Regards, Jeannie Chong ERGO Insurance Pie, Ltd.

Industrial Superior States Town Francisco Commission
 Industrial States States



- ULOVE 60

EHOCH is one of the major historical groups in Commany and Europe. Worldwide. EROC is impresented in more than 20 countries and concentrated an area and Aria. EROC in part of Marrier Re (Group), one of the world's leading his content.

#### EMAIL DISCLAIMER

The information contained in this email communication is confidential. You should only read, disclose, re-transmit, copy, distribute, act in reliance on or commercialize the information if you are authorized to do so. If you are not the intended recipient of this email communication, please notify the sender by replying to the email and destroy any electronic or paper copy of this message.

Any views expressed in this email communication are those of the individual sender. ERGO Insurance Pte. Ltd. does not represent, warrant or guarantee that the integrity of this communication has been maintained or that the communication is free of errors, virus or interference.

ERGC insurance Pte, Ltd. asserts copyright in respect to this email including any attachment. No part may be reproduced by any process or for any purpose without prior written permission.



The services and as adjustments are completed, effected only for the named authorises and may be previously. If you are not the intended recipient, you are not the intended recipient, process made for personal and delete the measure. By a service of the intended recipient, process made and you agree that ENGO intervative Plants will not be a recipient as interval of the intended process. The residual interval of the intended process and you agree that ENGO intervalve Plants will not be a recipient to the interval of the

From: Jeannie Cheng

Sent: Wednesday, May 15, 2019 11:34 AM

To: 'Admin nht'

Cc: Chloe; Tracy Tan; Survey Report (ERGO Insurance Pte. Ltd.)
Subject: RE: SG05255B CLAIMING AGAINST YP9511C DOA:14.05.19

WITHOUT PREJUDICE

Dear Sukyi,

We will assign the selected surveyor accordingly.

Thank you.

Warmest Regards, January Cheng ERGO Insurance Pte. Ltd.

III Tombuch Southering, #D4-D1 Bunter Tower Five
Tower Visions
Tower Vis

**ERGO** 

-----

TABLES one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentration on Datace and Asia. ERGO is part of Munich Re (Group), one of the world's feeding risk centers:



The manager and as approximate and correction accounted only to the manufacturers and may be provided if you are not be effected in the control of the contr

From: Admin nht [mailto:admin@nhtmotor.com]
Sent: Wednesday, May 15, 2019 9:03 AM

To: ERGO Insurance Pte. Ltd. (Claims Department)

Cc: Chloe; Jeannie Cheng; Tracy Tan

Subject: Re: SGQ5255B CLAIMING AGAINST YP9511C DOA:14.05.19

Without Prejudice

Hi Jeannie

We has yet receive the GIA from reporting center, once we have it will forward to you, thanks.

Please arrange for :-

6 LKK Auto Consultants Pte Ltd

Please take note this claim is under "New Hock Teck Motor Pte Ltd" "\*\*\*


Best Regards,

Sukvi Chong

New Hock Teck Motor Pte Ltd

| Kaki Bukit Ave 6 Blk C #01-43 Autobay @ Kaki Bukit S(417883)

Tel: 6747 9241 Fax: 6741 7276



On Wed, May 15, 2019 at 8:56 AM ERGO Insurance Pte. Ltd. (Claims Department) < claims@ergo.com.sg> wrote:

#### WITHOUT PREJUDICE

Dear Sukyi,

We acknowledged receipt of your email for the PRS request as below.

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below.

1	AIS	Automobile Inspection Services Pte Ltd	
2	FTA	FormTeam Consultancy Pte Ltd	
3	IAS	Infiniti Appraisal Service	
4:	JPK	JP Knights Pte Ltd	
5	LBS	L.B.S Auto Consultants Pte Ltd	
6	LKK	LKK Auto Consultants Pte Ltd	
7	PS PS	Priority Services	
8	VAC	Vicom Ltd	
9	AJAX	AJAX Inspection Services Pte Ltd	

- · Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy
- · Your request for inspection does not have your client's GIA report, kindly forward a copy
- Our Insured's driver has not reported the accident to us todate.

Kindly let us have your reply on the selection of the surveyor. Thank you. ERGO Insurance Ptr. Ltd. calmic chehd@exps.com.sg **ERGO** 

ED DID to coll of the responseshed groups in Germany and Europe. Worldwide: EFFOQ is represented in more than 30 countries and concentrative and and Assa ENFO is part of Munich Re (Group) one of the world's leading risk conners.

[II] E3

The impact of all allocations are confidented another being the named addresses, and may be presented if you are not the impact of the communication of you are not the mended property assume the sentent by when considered delivered the communication of you are not the mended property assume the sentent by when considered delivered the constant of the constant in the constant of t the any such a distance thereby caused

From: Admin nht [mailto:admin@nhtmotor.com]

Sent: Tuesday, May 14, 2019 1:16 PM

To: ERGO Insurance Pte. Ltd. (Claims Department)

Subject: SGQ5255B CLAIMING AGAINST YP9511C DOA:14.05.19
Without Prejudice
Hi Motor Claim Dept
S22 N
Please send us your surveyor list,thanks.
*** Please take note this claim is under "New Hock Teck Motor Pte Ltd" "****
Best Regards,
Sukyi Chang
New Hock Teck Motor Pte Ltd
1 Kaki Bukit Ave 6 Blk C #01-43 Autobay @ Kaki Bukit S(417883)
Tel: 6747 9241 Fax: 6741 7276

Assignment

To:	New Hock Teck Motor Pte Ltd	(Workshop)
-----	-----------------------------	------------

In consideration for your agreement to repair my motor vehicle registration no. 

SGODUSB

and to defer demanding for payment of the cost of repair, I/we the undersigned do hereby irrevocably assign absolutely to you all the proceeds of my/our claim(s) including damages, interest, costs and expenses (including legal costs / disbursements payable on a party and party basis which are to be paid to the parties so entitled including solicitors, vehicle appraisers and other experts / consultants).

I/We further confirm that payment to you only or to any person authorised by you to receive payment shall constitute a good and effectual discharge of the obligations by any party of the aforesaid proceeds of my/our claim(s).

I/We authorise you expressly to give notice of this assignment to the party concerned.

I/We confirm that by this assignment, I/we shall not be entitled in law to receive any payment. If a cheque is sent to me/us, I/we shall return same to the sender as I/we am/are precluded from accepting any payment.

Dated this _		day of	2	20	20	19	-
Signature	Ť	Dolo					
Name	12	ongso	ON BOOK	7			
ID No.	3	57725	16215				
Address	2		7	-			
Witness Signature		-/1					
Witness Name	6	Chew Yue Y	în				
Witness ID		S8826618H	1				
Witness Address	()	1 Kaki Buki Singapore 41		#01-43			

From:

lvy Yong <ivy.yong@ergo.com.sg>

Sent:

Thursday, 18 July 2019 9:30 AM

To:

Khanchna (LKK Auto)

Cc:

ERGO Insurance Pte. Ltd. (Claims Department); Phoebe Xie

Subject:

RE: Direct settlement - SGQ5255B | OI : YP9511C | DOA: 14/05/2019 | ERGO REF:

YP9511C/SL/ic

Attachments:

TP PASSENGER MEDICAL INVOICE JPEG: TP LOD.PDF

Hi Khanchna,

Yes, please

Data Classification: Confidential, C3

Warmest Regards, Ivy Yong

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-05 Suntec Tower Five Singapore 038985 DID. +65 6829 9197 ivv.yong@ergo.com.sg

**ERGO** 

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

#### EMAIL DISCLAIMER

The information contained in this email communication is confidential. You should only read, disclose, re-transmit, copy, distribute, act in reliance on or commercialize the information if you are authorized to do so. If you are not the intended recipient of this email communication, please notify the sender by replying to the email and destroy any electronic or paper copy of this message.

Any views expressed in this email communication are those of the individual sender. ERGO Insurance Pte. Ltd. does not represent, warrant or guarantee that the integrity of this communication has been maintained or that the communication is free of errors, virus or interference.

ERGO Insurance Pte. Ltd. asserts copyright in respect to this email including any attachment. No part may be reproduced by any process or for any purpose without prior written permission.

in f

Disclaimer. This message and its attachments are confidential, intended only for the named addresses, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd. will not be liable for any loss or damage thereby caused.

From: Khanchna (LKK Auto) [mailto:khanchna@lkkauto.com]

Sent: Thursday, 18 July, 2019 9:29 AM

To: ERGO Insurance Pte. Ltd. (Claims Department)

Cc: Ivy Yong

Subject: Direct settlement - SGQ5255B | OI: YP9511C | DOA: 14/05/2019 | ERGO REF: YP9511C/SL/jc

YOUR REF: YP9511C/SL/jc

From:

Khanchna (LKK Auto)

Sent:

Thursday, 18 July 2019 9:29 AM

To:

ERGO Insurance Pte. Ltd. (Claims Department)

Cc:

Ivy Yong

Subject:

Direct settlement - SGQ5255B | OI : YP9511C | DOA: 14/05/2019| ERGO REF:

YP9511C/SL/jc

Attachments:

TP PASSENGER MEDICAL INVOICE.jpeg; TP LOD.pdf

YOUR REF: YP9511C/SL/jc

Dear Sir/Madam,

The above matter and the attachment herein refers.

Kindly be informed that the Third party's passenger would also like to claim for medical expenses incurred at the date of accident.

Please advise as to whether we can proceed to offer for the said claim or not if the global claim amount is still within the mandate of \$8,000.00.

Thank you.

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

# NEW HOCK TECK MOTOR PTE LTD

Our Ref : NPLT1907-0062/SGQ52558

Your Ref : YP9511C

Date : 08th July 2019

1 Kaki Bukit Avenue 6 Blk C #01-43 Autobay@KB

WITHOUT PREJUDICE

Singapore 417883

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five,

Singapore 038985

Dear Sirs,

# RE: ACCIDENT INVOLVING SGQ5255B & YP9511C AT WEST COAST HIGHWAY TOWARDS ALEXANDRA ROAD ON 14.05.2019, 08:40AM

We are instructed by ONG SOON BOON to claim damages and losses against you in connection with the above captioned road traffic accident which our client's vehicle SGQ5255B was damaged by vehicle YP9511C driven by your insured at the material time.

We are instructed that the said accident was caused by your insured's negligent driving and/or management of the vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expenses, particulars of which are as follows:

	\$ 6,206.00
1) Repair Costs (7% GST)	\$ 800.00
2) Loss of Use for 08 days (7 + 1 Weekend)	\$ 175.48
3) Medical Certificates Fees	\$ 7.45
4) LTA Search Fees	\$ 7,188.93

A copy each of the following supporting document is enclosed:

- 1) Final Repair Bill
- 2) LTA Receipt

Please let us have your cheque for the sum \$7,188.93 made payable to us, NEW HOCK TECK MOTOR PTE LTD in the next 14 days.

Yours faithfully,

NEW HOCK TECK MOTOR PTE LTD

From:

Khanchna (LKK Auto)

Sent

Monday, 3 June 2019 11:57 AM

To:

ACCIDENT INVOLVING YP9511C & SGQ5255B ALONG/AT WESTCOAST HIGHWAY

Subject:

TOWARDS ALEXANDRA ROAD ON 14/05/2019

Attachments:

GIA-addendumform YP9511C.pdf

Our Ref: CC4/EGI19008622/Akb3

ALKADRI EXPRESS TRANSPORTATION (S) PTE LTD 115 AIRPORT CARGO ROAD CARGO AGENT BLDG C #01-36 SINGAPORE 819466

Attn: Ms. Hafiza

Dear Sir/Madam,

## ACCIDENT INVOLVING YP9511C & SGQ5255B ALONG/AT WESTCOAST HIGHWAY TOWARDS ALEXANDRA ROAD ON 14/05/2019

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, ERGO INSURANCE COMPANY LIMITED to deal with the third party claim against your policy.

We have received a claim from SGQ5255B against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in your favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Kindly fill up the GIA addendum form and e-mail them back to us for our further action.

Please call us if you have further queries.

Thank you.

Best Regards, Khanchna| Case Handler LKK Auto Consultants Pte Ltd DID: 6841 2360| email: <u>Khanchna@lkkauto.com|</u>Fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## LETTER OF AUTHORISATION

New Hock Teck Motor Pte Ltd

Date:

Kaki Bukit Avenue 6 Blk 1 #01-43 Singapore 417883 Dear Sir. Accident on Involving Vehicles Along I/We, the registered owner/driver of vehicle registration no: have involved in the above accident. I/We hereby authorize New Hock Teck Motor Pte Ltd to commence repairs of the said vehicle forthwith. I/We agree to assign the whole proceeds of my/our comprehensive/third party claim to you and our \_\_\_\_, to act on my/our behalf in respect of the above matter. And if applicable, my/our solicitors shall accept this as my/our irrevocable authority to pay the amount as deemed compensated direct to you after deduction of their costs on a Solicitor and client basis. I/We undertake to co-operate fully with you and our solicitors to ensure that claim is successful. I/We also authorize you to sign all discharge vouchers/indemnity forms and all necessary papers in relation with the above claim in my/our absence. Your kind co-operation in this matter will be much appreciated, Yours truly, Owner's Signature (Company's stamp if applicable) Name: NRIC No.:

# AUTHORISATION LETTER TO CLAIM MEDICAL BILLS

owner/dri	ver/nassenger of	ES ST 83 #06-49	OR S(520863)			
TECK N	ver/passenger of		00 0(020000)			(address),
for medic	MOTOR PTE L	TD("the workshop	o") to act for	me with	respect to	my claim
(date) a YP951	long WEST C	pursuant to the account of the accou	Y (location	occurred n) invo		nicle no/s
	o confirmed that cal bills related to	we will not be ma this accident.	king any Inju	ry claim :	and will on	ly claim for
they deer	m fit and the work	workshop to settleshop is further aut cheque/s being ma	horized to rece	ive payme	nt further t	manner that o settlement
without	prejudice and with her vehicle/s is co		iability basis in	sofar as th	ch on my b	ehalf is on a vner/insurers
Dated the	by "the third party	y claimant"			e workshop	Suffi chang



# 新福德車廠私人有限公司

## NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883 Website: www.nhtmotor.com Email: admin@nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276 UEN: 201718370K GST Reg No.: 201718370K

## TAX INVOICE

**ERGO Insurance Pte. Ltd.** 

5 Temasek Boulevard, #04-01 Suntec Tower Five,

Singapore 038985

Client:

ONG SOON BOON

Invoice No :

NPL1907-0062

Date: 8-Jul-19

Date of Accident : 14-May-19

Vehicle No. : SGQ5255B

Model Type :

Honda Civic

Descriptions			Amount
Lump Sum Repair Cost			5,800.00
	GST 7%	:	406.00
	Total	:	6,206.00

SIN DOLLARS: SIX THOUSAND TWO HUNDRED AND SIX ONLY



#### > Back to OneMotoring

Land Transport Authority 10 Sin Ming Drive Singapore 575701

GST Registration No.: M4-0006529-2

Print Date/Time:

14 May 2019 / 12:54:43

Receipt Date/Time: 14 May 2019 / 12:54:43

## Tax Invoice/Receipt

Receipt No.: ITNET-00000-190514-001570

Previ	ous Receipt No.		Taxani da maray		
S/N	Item Description/ Business Transaction Reference No.		Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Asa	ult of Insurance Enquiry - YP9511C t 14 May 2019/08:40:00 rance Co: ERGO INSURANCE PTE. L'	TD.			
1	Insurance Enquiry - YP9511C Enquiry Fee 20190514125353556745		7.00	0.49	7.49
	20190514125353550745	Sub-Total	7.00	0.49	7.49
		Total Before Rounding	7.00	0.49	7.49
		Rounding Difference			0.04
		Total Amount Payable			7.45
		Paid By			
		20190514125406697	Direct Debit: eN (Internet Bankin		7.45
		Total			7.45
		Cash Change			0.00
		Tendered Amount			7.45
		Excess Refundable Amount			0.00

#### THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Print Receipt

OK

Save as PDF



#### TAX INVOICE .

ORIGINAL

GST REG NO: M90368910N

KFINCWF / FB / 14.05.2019 1117 hrs / Page 1 of 1

**GUO JIEXIN** 

Tax Invoice Number:771911150010001

863 TAMPINES STREET 83

Bill Ref Number

:77191115001-0001-01

#06-496

Patient NRIC/HRN :S9024842A

Tax Invoice Date :14.05.2019 1117 hrs

SINGAPORE 520863

Visit Date

:14.05.2019 1038 hrs

Patient : GUO JIEXIN

Visit / Bill Location :KXW24 / KXW24 / OBS

Payment Class

:PRIVATE

Type of Supply

: Cash/Credit

SERVICE CODE	DESCRIPTION		QUANTITY	AMOUNT(S\$)
POULET IN THE PROPERTY OF THE	PROFESSIONAL FEES - DOCTOR	1	Subtotal	128.00
CNW24UC	URGENT CARE CONSULTATION		1	128.00
	X-RAY INVESTIGATIONS		Subtotal	36.00
XRP008Z	U/S, OBS/GYN-ROUTINE SIMPLE	SC (CLINICS)	1	36.00
			Subtotal Charges	164.00
			Total Charges Payable	164.00
AMOUNT PAYABLE BEFORE ADD: 7% GST	TAX			164.00
				11.48
AMOUNT PAYABLE AFTER T	AX			175.48
NET AMOUNT PAYABLE				175.48
GUO JIEXIN			Ì	175.48
PAYMENT				
GUO JIEXIN	14.05.2019	NETS	175.48	175.48
AMOUNT DUE FROM GUO JIEXIN				
SOO SIEXIIV				0.00
T: P S9024842A				
irst Consultation - without refer				
"You are served by CHONG W	VEI FANG ***		1	- 1



ORIGINAL	MEDICAL CERTIFICATE	OBS201914989
Name		NRIC No.
GUO JIEXIN		S9024842A
This is to certify that the above-named is unfit for duty for a per inclusive.	riod of days fro	14-May-2019 to 14-May-2019
Type of medical leave granted :		
Hospitalization Leave	Outpatient Sick Leave	
Admitted on	Maternity Leave,	Delivered on :
Discharged an	Sterillization Leave.	Operated on
This certificate is not valid for absence from cour	t attendance.	
Diagnosis	Surgical Ope	eration (if applicable)
Fit for light duty from N. A.	***	
Comments:	lo N.A.	
The above-named patient attended my clinic at No medical leave is necessary.	N.A. and left at	N.A.
Hospital	Date	Signature, Name (In BLOCK LETTERS) and Designation/MCR No.
KK Women's and Children's Hospital Pte. Ltd.	14-May-2019	UNARKAR AMI JAX, 61571D



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To: M/s ERGO INSURANCE PTE LTD

Date: 27/08/2019

#### THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	YP 9511C	(Insd Veh)	Your Ref. No. : YP9511C/SL/jc
venicle No.	SGQ 5255B	(TP Veh)	Our Ref. No. : CC4/EGI19008622/Akb3q2
Date of Accident	14/5/2019		

Liability		100%	
Final Repair Cost	: \$	6,206.00	
Loss of Use	: \$	640.00	8 days
Rental (If any)	: \$		days
Others:	: \$	7.45	
Medical Fee	: \$	175.48	
		7,028.93	
Final Settlement Sum	: \$	7,028.93	
Remarks	:		

Payment Instruction: Payee's Breakdown				
1)	NEW HOCK TECK MOTOR PTE.LTD.	: \$	7,028.93	
		: \$		

JOANNE LEE LKK Auto Consultants Pte Ltd



#### LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Inte	ernationale Des Experts En Aut	tomobile
ERGO INSURAN	NCE PTE	LTD	Ref : CC4/EGI190	008622/Akb3q2
5 TEMASEK BOI #04-05 SUNTEC SINGAPORE 03	TOWER		Date: 27-08-2019	
1.		Policy Particu	ulars :- THIRD PARTY CL	AIM
Insured Ve	eh.	YP 9511C	Veh. Inspected	SGQ 5255B
Policy No.	. 1	DMCG18004236	Coverage (\$)	0.00
Claim No.	63	YP9511C/SL/jc	Excess (\$)	0.00
Assign Fro	om .	JEANNIE	Assign Date	15/05/2019
2.		Vehicle	Particulars & Condition	
Make & Mo	odel l	HONDA CIVIC	c.c	1799
Engine No	). I	HIDDEN	Year of Reg.	2007
Chassis N	0.	JHMFD16307S202548	Colour	SILVER
Odometer		306723	Steering	IN ORDER
Brakes	1	N ORDER	Modification	SPORTS RIM
General	(	GOOD		
3.		Co	enditions of Tyres	
		Size	Make	Balance
R/H Front	.,	205/55 R16	BRIDGESTONE	6 mm
L/H Front		205/55 R16	BRIDGESTONE	6 mm
R/H Rear T	.,	205/55 R16	BRIDGESTONE	6 mm
L/H Rear T	yre 2	205/55 R16	BRIDGESTONE	6 mm
4.	105		ription of Damages	
THE VEHIC	LE SUST	AINED DAMAGES AT TH	E REAR PORTION.	
DAMAGES 8	SEE DET	AILS.		
5.		Ge	neral Information	
Accident D	4.00Mp	14/05/2019	Inspection Date	15/05/2019
Survey hel		NEW HOCK TECK MOTOR		
		I KAKI BUKIT AVENUE 6 # SINGAPORE 417883	#01-43 AUTOBAY @ KAKI B	UKIT
5a.			Remarks	
A)THE INSP B)IN ACCOR	PECTION	WAS CONDUCTED ON A	A"WITHOUT PREJUDICE" BA	ASIS. RISED REPAIRS
5b.			nate Days of Repair	THE RESTRICTION OF THE PARTY OF

7 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR:



#### LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

#### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGQ 5255B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			1.00
1	REAR BOOT LID	DISTORTED	621.40	621.40
2	REAR BOOT LID HINGE @\$48.00	BENT	96.00	96.00
1	REAR BOOT LID EMBLEM LOGO	NECESSARY	35.00	35.00
1	REAR BOOT LID CIVIC LOGO	NECESSARY	38.80	38.80
-1	REAR BOOT LID IVTEC LOGO	NECESSARY	36.10	36.10
2	REAR BOOT LID SIDE REFLECTOR @\$202.20	CRACKED	404.40	404.40
-1	REAR BOOT LID NUMBER PLATE	BENT	50.00	50.00
2	REAR BOOT LID NUMBER PLATE LAMP @\$83.10	NOT NECESSARY	166.20	
1	REAR BOOT LID LOCK CABLE	NOT NECESSARY	127.60	
-1	REAR BOOT LID INNER LOCK	DAMAGED	194.50	194.50
1	REAR BOOT LID INNER RUBBER	CUT	137.60	137.60
2	REAR TAIL LAMP @\$328.70	CUT	657.40	657.40
4	REAR TAIL LAMP CLIPS @\$6.50	NECESSARY	26.00	26.00
2	REAR TAIL LAMP PANEL	DENTED	158.30	158.30
4	REAR BUMPER	DEFORMED	645.30	645.30
10	REAR BUMPER CLIP @\$6.50	NECESSARY	65.00	30.00
2	REAR BUMPER SIDE RETAINER @\$33.10	NECESSARY	66.20	66.20
2	REAR BUMPER MUD SHIELD	NOT NECESSARY	65.10	3311.41.43
12	REAR BUMPER MUD SHIELD CLIP @\$6.50	NOT NECESSARY	78.00	
2	REAR BUMPER BRACKET	NOT NECESSARY	55.20	
1	REAR END PANEL	DENTED	318.30	318.30
1	REAR END PANEL TOP GARNISH	DEFORMED	161.20	161.20
2	REAR FENDER	TO REPAIR SEE LABOUR	980.50	
2	REAR FENDER INNER TRIM BOARD @\$232.80	CRUMPLED	465.60	465.60
16	REAR FENDER INNER TRIM BOARD CLIP @\$6.50	NECESSARY	104.00	60.00
2	REAR FENDER AIR-DUCT	NOT NECESSARY	38.00	
1	REAR SPARE TYRE PANEL	TO REPAIR SEE LABOUR	1,254.40	
1	REAR SPARE TYRE PANEL TOP COVER	DEFORMED	329.96	329.96
1	REAR SPARE TYRE PANEL & END PANEL SEALANT	NOT NECESSARY	450.00	

Report Ref No. CC4/EGI19008622/Akb3q2



#### LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
- 1	REAR EXHAUST	BENT	728.50	635.00
-1	REAR CENTER EXHAUST	TO REPAIR SEE LABOUR	637.50	
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	100.80	
	LESS 20% DISCOUNT		2.0	-1,033.41
			9,292.86	4,133.65
	SPECIAL NETT ITEMS			
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	350.00	200.00
2	REAR EXHAUST CHROME PIPE @\$186.00 (SN)	BENT	372.00	220.00
			722.00	420.00
	LABOUR			
	TO REMOVE & REFIT REAR CUSHION .		280.00	60.00
	TO REMOVE & REFIT REVERSE SENSOR .		100.00	50.00
	TO REMOVE & REFIT REAR EXHAUST .		280.00	80.00
	TO REMOVE & REFIT REAR WINDSCREEN.	NOT NECESSARY	120.00	-
	GUM.	NOT NECESSARY	50.00	
	TO REMOVE & REFIT PETROL TANK .	NOT NECESSARY	280.00	-
	TO CHECK WIRING.		100.00	30.00
	TUFF KOTE.		150.00	60.00
	TOWING FEE.	NOT NECESSARY	100.00	
	PANEL BEATING INCLUSIVE OF THE REPAIR OF REAR FENDER, REAR SPARE TYRE PANEL AND REAR CENTER EXHAUST.		1,600.00	1,200.00
	SPRAY PAINTING:		1,600.00	1,300.00
			4,660.00	2,780.00
	GRAND TOTAL		14,674.86	7,333.65

RECOMMENDED COST OF LUMP SUM REPAIRS	5,800.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CC4/EGI19008622/Akb3q2



ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part, Any third party acting or replying on this Report, in whole or in part, does so at his or her swn risk.