



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com

Website: www.nhtmotor.com

Tel: 6747 9241

Fax: 6741 7276

UEN: 201718370K

ERGO
UKK

ONG SOON BOON

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

16/05/2019

Nett: 5.4K

TP Ergo

Khanchua

JAMF0163075202548

Accident date: 14/05/2019

Estimated repair cost for vehicle no: SGQ5255B HONDA CIVIC 1.8 A '07

S/n	Qty	Items	U/price	Amount	
1	1	Rear Boot Lid Distorted		\$621.40	✓
2	2	Rear Boot Lid Hinge Bent	\$48.00	\$96.00	✓
3	1	Rear Boot Lid Emblem Logo		\$35.00	✓
4	1	Rear Boot Lid Civic Logo		\$38.80	✓
5	1	Rear Boot Lid Ivtec Logo		\$36.10	✓
6	2	Rear Boot Lid Side Reflector Cracked	\$202.20	\$404.40	✓
7	1	Rear Boot Lid Number Plate		\$50.00	✓
8	2	Rear Boot Lid Number Plate Lamp Not Nec	\$83.10	\$166.20	✗
9	1	Rear Boot Lid Lock Cable Not Nec		\$127.60	✗
10	1	Rear Boot Lid Inner Lock Dented		\$194.50	✓
11	1	Rear Boot Lid Inner Rubber		\$137.60	✓
12	2	Rear Tail Lamp	\$328.70	\$657.40	✓
13	4	Rear Tail Lamp Clips Nec	\$6.50	\$26.00	✓
14	2	Rear Tail Lamp Panel Dented		\$158.30	✓
15	1	Rear Bumper Deformed		\$645.30	✓
16	10	Rear Bumper Clip	\$6.50	\$65.00	30
17	2	Rear Bumper Side Retainer	\$33.10	\$66.20	✓
18	1	Rear Bumper Reverse Sensor (Special Nett) Damaged		\$350.00	200/SN
19	2	Rear Bumper Mud Shield		\$65.10	✗
20	12	Rear Bumper Mud Shield Clip	\$6.50	\$78.00	✗
21	2	Rear Bumper Bracket		\$55.20	✗
22	1	Rear End Panel Dented		\$318.30	✓
23	1	Rear End Panel Top Garnish Deformed		\$161.20	✓
24	2	Rear Fender Repair		\$980.50	✗
25	2	Rear Fender Inner Trim Board Crumpled	\$232.80	\$465.60	✓
26	16	Rear Fender Inner Trim Board Clip	\$6.50	\$104.00	60
27	2	Rear Fender Air-Duct Not Nec		\$38.00	✗
28	1	Rear Spare Tyre Panel Repair		\$1,254.40	✗

29	1	Rear Spare Tyre Panel Top Cover	Rehnd.	\$329.96	✓
30	1	Rear Spare Tyre Panel & End Panel Sealant	renew	\$450.00	X
31	1	Rear Exhaust	Best	\$728.50	655
32	2	Rear Exhaust Chrome Pipe	Best	\$186.00	\$372.00 224 (1.2)
33	1	Rear Center Exhaust	Rys	\$637.50	X
34	1	Rear Windscreen Moulding	renew	\$100.80	X

5167.06
4133.64

Subtotal :- \$10,014.86

Labour charges

To remove & refit rear cushion	\$280.00	60
To remove & refit reverse sensor	\$100.00	50
To remove & refit rear exhaust	\$280.00	80
To remove & refit rear windscreen	\$120.00	X
Gum	\$50.00	X
To remove & refit petrol tank	\$280.00	X
To check wiring	\$100.00	30
Tuff kote	\$150.00	60
Towing fee	\$100.00	X
Panel beating	\$1,600.00	1200
Spray painting	\$1,600.00	1300

2780

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Subtotal :- \$4,660.00

Total:- \$14,674.86

total. \$958.44.

4/5: 58K.

07 Days.

58K