

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ong Li Li

Date: 17 May 2019

Preliminary Advice

Vehicle No	: SFB6883Y	Accident Date	: 12/05/2019
Make	: MERCEDES-BENZ E200	Policy No.	: Z18VP05020130
Assignment Date	: 15/05/2019	Excess	: S\$0.00
Date of Inspection	: 16/05/2019	Est. Duration of Repair	: 5 days
Inspection At	: Falcon-Air Auto Services Pte Ltd (Sin Ming) 176 Sin Ming Drive #01-06, Sin Ming Autocare Singapore 575721		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,065.05
Revised Amount	:S\$	6,672.80
Check Items (Estimated)	:S\$	1,512.25
Total	:S\$	8,185.05
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	175,000.00
COE / PARF Rebate	:S\$	94,683.00
Salvage Value	:S\$	
Margin for Repair	:S\$	80,317.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :