

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5819L**AAD1905-105**

L/s \$2200/ 3071.

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration:

SHC 5819L

VF1ABL15AUC280917

RENAULT

LATITUDE

10.5.19

AIG

11/12/2014

	PART		LIST
1	BUMPER COVER FRT ✓	\$	1,259.42
1	BUMPER SPOILER FRT X	\$	181.75
1	BUMPER ABSORBER FRT X	\$	394.68
1	BUMPER RETAINER FRT RH X	\$	151.41
1	BUMPER SUPPORT FRT X	\$	123.88
1	BUMPER UNDERTRAY FRT X	\$	472.83
1	BUMPER GRILLE LOWER FRT X	\$	266.80
1	BUMPER FOG LAMP GRILLE RH X	\$	207.21
1	BUMPER BEAM FRT X	\$	914.08
1	HEADLAMP RH X	\$	1,184.43
1	HEADLAMP PANEL FRT RH X	\$	152.15
1	FENDER PANEL FRT RH ✓	\$	783.83
1	WHEELARCH FRT RH X	\$	278.84
1	FENDER BRACKET LOWER RH X	\$	15.79
1	FENDER INSULATOR RH X	\$	130.84
1	TOW COVER FRT X	\$	28.61
1	FRONT BRACE PANEL X	\$	177.22
1	RADIATOR GRILLE X	\$	1,707.78
1	RADIATOR GRILLE BADGE 'RENAULT' X	\$	225.36
1	RADIATOR GRILLE FRAME X	\$	1,353.75
1	FRAME FULL SUPPORT PANEL X	\$	615.90
1	FRAME FULL SUPPORT BRACKET X	\$	89.79
1	DOOR PANEL FRT RH X	\$	2,844.66
1	DOOR MIRROR ASSY RH X	\$	1,483.40
1	DOOR MIRROR GLASS RH X	\$	148.20
1	DOOR MIRROR BACK COVER RH X	\$	218.46
1	WIPER RESERVOIR MOTOR X	\$	270.06
1	WIPER RESERVOIR X	\$	348.25
1	WIPER RESERVOIR NECK X	\$	136.11
1	ROCKER PANEL INNER GARNISH RH X	\$	466.51

Trans-cab Auto Services Pte Ltd

AAD1905-105

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5819L

1	ROCKER PANEL INNER RH	X	\$	1,024.79
1	ROCKER PANEL CENTER RH	X	\$	990.25
1	ROCKER PANEL OUTER RH	X	\$	1,184.99
1	DOOR HARNESS WIRE RH	X	\$	2,670.00
			TOTAL \$	22,502.04
			10% \$	2,250.20
			\$	20,251.84

Special Nett

1	FRONT DOOR STICKER 'Trans-cab'	X	\$	80.00
1	FRONT DOOR STICKER 'Classic'	X	\$	80.00
1	BUMPER CLIP FRT		\$	66.00
1	BUMPER BRACKET CLIP FRT RH	X	\$	12.00
1	BUMPER SUPPORT CLIP FRT RH	X	\$	10.50
1	BUMPER GRILLE LOWER CLIP	X	\$	69.00
1SET	FRAME FULL SUPPORT PANEL CLIP	X	\$	70.00
2	FRAME FULL SUPPORT PANEL NUT	X	\$	20.00
2	FRAME FULL SUPPORT PANEL STUD	X	\$	30.00
1	WHEELARCH CLIP FRT RH	X	\$	30.50
1	FRONT RIGHT TYRE	X	\$	300.00
1	FRONT RIGHT TYRE RIM	X	\$	380.00
1SET	Front licence plate with holder	X	\$	80.00
1SET	RADIATOR GRILLE SCREW	X	\$	16.00
1SET	RADIATOR GRILLE FRAME CLIP	X	\$	52.00

TOTAL \$ 1,296.00**TOTAL PARTS \$ 21,547.84****LABOUR**

To transfer of front windscreen fittings and conduct water seepage test.

\$

~~170.00~~ X

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$

~~7,500.00~~
400

To rust-proofing of the affected areas.

\$

~~170.00~~
50

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5819L**AAD1905-105**

Putty and spray painting of the affected portion.	\$	7,500.00 ⁴⁰⁰
To transfer of front fender fittings, attachment and perform water seepage test.	\$	380.00 ⁵⁰
To check steering geometry and computer wheel alignment	\$	220.00 X
To transfer of tire, rim and on wheel balancing.	\$	170.00 X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	380.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00 X
To transfer of front door fittings, attachment and perform water seepage test.	\$	380.00 X
To Check Electrical Lighting Concerned.	\$	170.00 X
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	380.00 X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00 X
To apply paint protection system (PPS) maintain and enhancement	\$	380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00 X
To remove and refit air bag system and reset vehicle warning indicators.	\$	480.00 X
To check ABS brake efficiency, final checking and testing.	\$	380.00 X

Trans-cab Auto Services Pte Ltd

AAD1905-105

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5819L

To dismantle and refit aircon assy and attachment,
vacuum and charge-in-gas.

	\$	380.00	X
TOTAL	\$	20,180.00	

Over All Total	\$	41,727.84
-----------------------	----	------------------

LUMP SUM (REPAIR DAY)

25 DAYS

Kaluh / Clerk

M 14/5/19 1535 hrs

3 Days

96719399

L/S

Asst Repair photo

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: