



Cecilia Asher

Section A - Accident Details

Registration Number	SHC4313K
Case Reference Number	TAX/05/19/2051
Registration Date	6/12/2013
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	RAKESH DEV SINGH S/O SUKHDEV SINGH
Type of Accident	Side Swipe
Accident Date and Time	11/5/2019 10:35 PM
Accident Reported Date and Time	13/5/2019 8:56 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	11/5/2019 11:50 PM
Replacement Vehicle issued?	No
Job Card Number	24101471
Special Instruction to ARC, if any	TOWED \$40/ TP
Prepared Date and Time	13/5/2019 3:38 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



10/06/2019

L/S \$1900/- 4 days.

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$700.00
Total Spray Cost	\$1,872.00	\$950.00
Total Spare Part Cost	\$3,620.51	\$136.81
Total Other Cost	\$976.00	\$110.00
TOTAL COST	\$7,482.51	\$1,896.81
Lump Sum Total	\$7,500.00	\$1,900.00 (L/S)
Number of Repair Days	7.0	4.0
Prepared / Adjusted By	Tuck Foo Kok	Hwee Jie (LKK) / AIG
ARC / Surveyor Sign Off Date	14/05/2019 2:52 PM	14/05/2019 11:47 AM
Signature	<i>[Signature]</i>	<i>[Signature]</i>
Remarks	L/S REPAIR, PHOTO AFTER PAINT.	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68682623
Accident Reporting Number : 68682672

Data Generated : 10/08/2019

User ID : PohSuan

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1905-0448	Invoice Number	
Quotation Date	24.05.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	\$1,014.00	\$700.00
Total Labour	\$1,014.00	\$700.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$50.00
TO RESPRAY FRONT DOOR LH	\$378.00	\$200.00
TO RESRAY REAR DOOR LH	\$378.00	\$200.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$100.00
Total Spray Painting & Panel Beating	\$1,872.00	\$950.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$56.00	\$40.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$20.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$30.00
TO TRANSFER DOOR MECHANISM	\$240.00	\$0.00
TO REMOVE AND REFIT WIRE HARDESS	\$200.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$976.00	\$110.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119-47930	BUMPER FRT	1.00	\$482.00	100.00	\$0.00	Replace	Repair
		52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace
		52116-47040	BUMPER SUPPORT F/LH	0.00	\$76.40	0.00	\$0.00	Replace	Not Given
		52618-47050	BUMPER FRT ABSORBER LOWER	0.00	\$127.70	0.00	\$0.00	Replace	Not Given
		53802-47050	FENDER FRT/LH	1.00	\$723.40	100.00	\$0.00	Replace	Repair
		75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace
		53876-47030	FENDER LINER FRT/LH	0.00	\$171.70	0.00	\$0.00	Replace	Not Given
		53852-47020	FENDER LINER PAD, FR WHEEL. LH	0.00	\$49.30	0.00	\$0.00	Replace	Not Given

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662023
Accident Reporting Number : 68662672

Date Generated : 10/06/2019

User ID : PehSuan

6503707			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X
		42611-- 47140 (Frt)	WHEEL DISC. FRONT	1.00	\$1,484.20	100.00	\$0.00	Replace	Repair	R
		75852- 47900	MOULDING BODY, LH	1.00	\$673.60	100.00	\$0.00	Replace	Repair	R
		67002- 47070	DOOR FRT/LH	1.00	\$894.40	100.00	\$0.00	Replace	Repair	R
			STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace	R
		67004- 47080	DOOR RR/LH	1.00	\$954.50	100.00	\$0.00	Replace	Repair	R
			PIXEL STICKER	1.00	\$60.00	0.00	\$60.00	Replace	Replace	R
Total					\$5,937.45		\$171.01			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

171.01

- 20%

136.81

+ 700.00

+ 1060.00

1896.81

45 \$1900/-