

Jiale

ATTN: MOTOR CLAIMS DEPARTMENT  
 OWNER: YOW YUIT EE  
 TP INSURER: AIG Asia Pacific Insurance Pte Ltd  
 POLICY NO: 5099040986-01  
 REFERENCE: TP CLAIM  
 DOA: 10/05/2019

**REPAIR ESTIMATE**

Est. No. : E19050004  
 Date : 14/05/2019  
 Vehicle Num. : SJV817B  
 Make/Model : BMW,520I  
 Chassis/Eng# : WBAXG12050DX51811

No	Description	Qty	U/P	Amt
<b>Section: LIST ITEMS</b>				
1	Rear Bumper <i>Repld</i>	1.00	1,563.28	1,563.28 ✓
2	Rear End Panel <i>Neu</i>	1.00	817.30	817.30 ✗
3	Rear End Panel <i>Top Grmwsh. neu neu</i>	1.00	115.55	115.55 ✗
4	Rear Bumper Reinforcement <i>Set</i>	1.00	772.05	772.05 ✓
5	Rear Bumper Reinforcement Adaptor <i>amb neu</i>	1.00	50.65	50.65 ✗
6	Rear LH/RH Side Retainer <i>Neu</i>	2.00	137.75	275.50 ✓
7	Rear Reflector <i>Neu</i>	2.00	36.80	73.60 ✗
8	Bootlid <i>Neu</i>	1.00	1,642.45	1,642.45 ✗
9	Lower Guide <i>Repld</i>	1.00	60.45	60.45 ✓
10	Center Retainer <i>Repld</i>	1.00	65.55	65.55 ✓
11	Rear Bumper Clips <i>Neu</i>	10.00	5.00	50.00 <i>30</i>
12	Rear Reverse Sensor <i>and</i>	2.00	236.85	473.70 ✓
13	Reverse Sensor (Centre) <i>neu</i>	1.00	300.00	300.00 ✗

3235.53  
 3073.75

**Amt** S\$ 6,260.08  
**Discount (5.00%)** S\$ 313.00  
**Subtotal** S\$ 5,947.08

**Section: LABOUR**

14	To Remove and Replace Rear Bumper	1.00	120.00	120.00 ✓
15	To Remove and Replace Rear Bumper Reinforcement and Brackets	1.00	120.00	120.00 <i>80</i>
16	To Straighten Rear End Panel <i>neu</i>	1.00	200.00	200.00 ✗
17	To Transfer Bootlid Components <i>neu</i>	1.00	80.00	80.00 ✗
18	To Remove and Replace Bootlid <i>neu</i>	1.00	150.00	150.00 ✗
19	To Sand Down, Putty and Spraypaint Bootlid <i>neu</i>	1.00	300.00	300.00 ✗
20	To Sand Down, Putty and Spraypaint Rear Bumper <i>neu</i>	1.00	280.00	280.00 <i>250</i>

Continue on next page...

ATTN: MOTOR CLAIMS DEPARTMENT  
 OWNER: YOW YUIT EE  
 TP INSURER: AIG Asia Pacific Insurance Pte Ltd  
 POLICY NO: 5099040986-01  
 REFERENCE: TP CLAIM  
 DOA: 10/05/2019

**REPAIR ESTIMATE**

Est. No. : E19050004  
 Date : 14/05/2019  
 Vehicle Num. : SJV817B  
 Make/Model : BMW,520I  
 Chassis/Eng# : WBAXG12050DX51811

No	Description	Qty	U/P	Amt
21	To Sand Down, Putty and Spraypaint Rear End Panel	1.00	200.00	200.00
22	To Check Wiring	1.00	50.00	50.00
23	To Remove and Replace Reverse Sensor	1.00	50.00	50.00

550

Amt S\$ 1,550.00  
 Discount (0.00%) S\$ 0.00  
 Subtotal S\$ 1,550.00

*Adrian Limy Total: 3623.75*  
*2/5 15/05/19 4/5: 2.9K*  
*03 Days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:



*[Handwritten signature]*

Joo Hak Kee Auto Pte. Ltd.

LIST ITEMS Subtotal S\$ 5,947.08  
 LABOUR Subtotal S\$ 1,550.00  
 Total S\$ 7,497.08

