



松 利 摩 哆
SIONG LEE MOTOR

Company Reg. No.: 100838/00J

Sin Ming AutoCity
160 Sin Ming Drive #02-07 Singapore 575722
Tel: 6457 0410, 6453 1255 Fax: 6552 0692

We specialise in repairing all kinds of vehicles and pre-inspection servicing.
We also undertake accident insurance claims for our customers.

17 May 2019

ATTN: MOTOR CLAIM DEPARTMENT

ATTN: TAN BROS GAS SUPPLY
H/P: 9105 5622

Dear Sirs / Madam,

Accident Claim for Vehicle No.GZ 1311 L , Involving Vehicle No.SLH 8441 Z.
Accident on 09 MAY 2019, AT FARLEIGH ROAD (IN FRONT HOUSE NO.36)

With reference to the above vehicle. We hereby submit a list of parts required to be changed and append below the charges for changing and repairing ;

NO	PARTS REPLACEMENT	QTY	LIST PRICE
1	TAILGATE STOPPER PILLAR	1PC	\$ 145.23
2	TAILGATE STOPPER	1PC	\$ 130.50
3	TAILGATE SAFETY LOCK	1PC	\$ 220.45
4	REAR SIDE BOARD	1PC	\$ 1,600.00
	TOTAL LIST PRICE		\$ 2,096.18
	LESS 20%		\$ (419.24)
	TOTAL AMOUNT		\$ 1,676.94

	LABOUR :	
1	LABOUR TO SPRAY PAINT	\$ 400.00
2	LABOUR TO PANEL BEATING	\$ 380.00
3	LABOUR TO DISMANTLE AND REFIX SIDE BOARD WOOD.	\$ 200.00
	TOTAL LABOUR	\$ 980.00
	TOTAL AMOUNT	\$ 2,656.94

THANK YOU

FROM:
SIONG LEE MOTOR
Mr Tan Leng Huat

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanfikun 97495749 / 6741843
-wp
17/5/19 @ 11am
Resurvey after repair
tanfikun@lkkauto.com
02 days