

# BEST Solution Autocare Pte Ltd

53 Ubi Avenue 1, #03-01, Paya Ubi Industrial Park, Singapore 408934

Business Reg. No.: 201626438D

☎ 6744 0777

☎ 6744 2377

Steve (LKK)  
8322 8813

W/L 15/3/19, 12. Apr

4 days

L/S

Ry Al Sy

## Estimate Quotation

Quotation No	May 003/2019
Date	14/05/19
Vehicle No	SJS1126X
Make / Model	SUBARU IMPREZA

To: AXA Insurance Singapore Pte Ltd  
Address: 8 Shenton Way #27-01 AXA Tower Singapore 068811

Qty	DESCRIPTION	UNIT	Amount
	<b>Items</b>		
1 pc	front bumper / DD		
2 pcs	front bumper side retainer / DR		
1 pc	front bumper reinforcement X		
1 pc	front grille X		
1 pc	o/s head lamp / CUT ?		
1 pc	o/s head lamp lower bracket		
1 pc	o/s front fender / DD		
1 pc	o/s front fender inner shield / TN		
1 pc	o/s front bumper fog lamp garnish ?		
1 pc	o/s front bumper fog lamp ?		
1 pc	o/s front sport rim / CUT		
1 pc	o/s front shock absorber X		
1 pc	o/s front lower arm ?		
1 pc	o/s front knuckle arm ?		
1 pc	o/s front knuckle arm bearing ?		
1 set	front bumper clip / NEC		
1 set	front grille clip X		
1 pc	front support panel X		
1 pc	front bumper lower lip / DR		
	<b>Labour Charge</b>		
1	to dismantle damaged parts, panel beat, repair	\$	900.00
2	to putty and spray painting on affected area	\$	900.00
3	aircon	\$	80.00
4	anti rust	\$	150.00
5	undercarriage	\$	250.00
6	wheel alignment	\$	150.00
7	towing	\$	80.00
8	apply to unseal opc number plate/send car for seal inspection	\$	100.00
	<b>Subtotal:</b>	\$	2,610.00

450  
400  
600  
X  
30  
200  
60  
50  
80

### LKK Auto Consultants hence notify

#### the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

BEST SOLUTION AUTOCARE PTE LTD

Authorised Signature