



Cecilia
CARZ AUTO SERVICES PTE LTD

UEN/ GST 201409457D
 61 WOODLANDS IND PARK E9 (E9 PREMIUM) #04-04 Singapore 757047
 Email: alex@carzauto.com.sg Tel: 65 6493 1924 Fax: 65 6493 1928

Insurance Company: AXA INSURANCE SINGAPORE PTE LTD
 Address: 8 Shenton Way, #24-01 AXA Tower Singapore 068811
 Telephone: 6338 7288 Fax: 6880 4838 Email:

Make/ Model : NISSAN URVAN Date: 15/5/2019
 Chassis No : JN1MG4E2520781642 Vehicle No: GBB 2670 T
 Date/Time of Accident : 7/3/2019 17:20

Materials Cost/ Spare Parts Cost

TO BE COMPLETED BY SERVICE ADVISOR

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$	PARTS DISCOUNT	FINAL PRICE \$
1	FRONT BUMPER <i>DEF -</i>	1	\$ 588.20	10%	\$ 529.38
2	FRONT BUMPER SIDE RETAINER <i>nc</i>	2	\$ 259.00	10%	\$ 233.10
3	FRONT BUMPER FOG LAMP <i>CRA -</i>	2	\$ 690.00	10%	\$ 621.00
4	FRONT BUMPER FOG LAMP COVER LH <i>CRA -</i>	1	\$ 121.70	10%	\$ 109.53
5	FRONT BUMPER REINFORCEMENT <i>DD -</i>	1	\$ 236.90	10%	\$ 213.21
6	FRONT RADIATOR GRILLE <i>nx</i>	1	\$ 487.90	10%	\$ 439.11
7	FRONT RADIATOR GRILLE LOGO <i>nx</i>	1	\$ 85.90	10%	\$ 77.31
8	FRONT RADIATOR GRILLE BRACKET <i>nx</i>	1	\$ 68.80	10%	\$ 61.92
9	FRONT HEAD LAMP LH <i>CRA -</i>	1	\$ 552.30	10%	\$ 497.07
10	FRONT SIDE LAMP LH <i>CRA -</i>	1	\$ 215.80	10%	\$ 194.22
11	FRONT CORNER PANEL LH <i>DD -</i>	1	\$ 585.20	10%	\$ 526.68
12	FRONT PANEL <i>nx</i>	1	\$ 1,596.10	10%	\$ 1,436.49
13	FRONT WINDSCREEN GLASS MOULDING <i>nx</i>	1	\$ 140.40	10%	\$ 126.36

SPECIAL ITEMS	PARTS DESCRIPTION	QTY	PRICE \$	FINAL PRICE \$
1	FRONT BUMPER CLIP <i>nc</i>	10	\$ 40.00	\$ 30 40.00
2	FRONT NUMBER PLATE <i>nx</i>	1	\$ 50.00	\$ 50.00
3	FRONT RADIATOR GRILLE CLIP <i>nx</i>	8	\$ 32.00	\$ 32.00
4	FRONT WINDSCREEN GLASS SEALANT <i>nx</i>	1	\$ 50.00	\$ 50.00
Total Cost				\$ 5,237.38

Labour Works/ Panel Beating Related Works	
Job Scope	Quotation
TO RENEW DAMAGED PARTS, REPLACED AND REALIGNED HYDRAULIC, ALIGNED ALL PARTS	\$ 1,000.00 500
Spray Painting	
Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 800.00 300

Others Cost (Accident Repair Related Expenses)

Job Scope	Quotation	
TO REMOVE ANF REFIX FRONT WINDSCREEN	\$ 120.00	X
TO REMOVE/ REPLACE AIRCON CONDENSOR, VACUUM, TOP UP AIRCON GAS COMPUTERIZED	\$ 120.00	X
TO REMOVE/ REFIX DASHBOARD	\$ 350.00	X
TO REMOVE/ REFIX INTERIOR UPHOLSTERY	\$ 100.00	X
TO REMOVE/ REFIX WIRING CHECKS	\$ 60.00	30
Total Others Cost	\$ 750.00	
GRAND TOTAL		
	\$ 7,787.38	

CARZ AUTO SERVICES PTE LTD

Person Incharge: Ms Jeslyn Chua
 Job Title: Account Assistant
 Mobile: 65 8322 7418
 Email: jeslyn@carzauto.com.sg

Hwee Jie LKK

16/5/19

L/S 4 days

[Signature]

Total - \$3000/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: