

GREEN FOREST AUTOMOBILE PTE LTD

8 Kaki Bukit Avenue 4, #05-25 Premier @ Kaki Bukit Singapore 415875

GRACE AUTO LEASING
8 KAKI BUKIT AVENUE 4
05-25 PREMIER @ KAKI BIKIT
Singapore 415875

TPAxA.

Xiao Tong.

16th MAY 2019

Accident date: 14th MAY 2019

Estimated repair cost for vehicle no: SMK5980B TOYOTA WISH 2.0 '10

S/n	Qty	Items	U/price	Amount
1	1	Front bonnet <i>Detkd</i>		\$950.00 ✓
2	2	Front bonnet hinges <i>new</i>	\$131.75	\$263.50 +
3	1	Front bonnet inner sponge <i>3mm</i>		\$161.40 +
4	10	Front bonnet inner sponge clips	\$12.90	\$129.00 -
5	1	Front bonnet lock <i>new</i>		\$182.20 +
6	1	Front bonnet emble logo <i>ph</i>		\$61.00 ✓
7	1	Front bonnet inner rubber <i>new</i>		\$134.40 +
8	1	Front bonnet lock cable <i>3mm</i>		\$161.55 +
9	1	Front bonnet lock panel		\$182.20 +
10	1	front grill <i>could</i>		\$261.55 ✓
11	2	front grill nizzer <i>new</i>	\$18.50	\$37.00 +
12	4	front grill clips <i>new</i>	\$12.90	\$51.60 -20
13	2	Front horn <i>new</i>	\$161.10	\$322.20 +
14	2	Front head lamp <i>RH could</i>	\$781.20	\$1,562.40 781.20
15	1	Front support panel <i>Regis</i>		\$891.55 x
16	1	Front support panel top garnish <i>new</i>		\$261.55 +
17	8	Front support panel top garnish clips <i>new</i>	\$12.90	\$103.20 +
18	2	Front support panel side cover <i>RH Detkd</i>	\$161.10	\$322.20 -61.10
19	8	Front support panel side cover clips <i>new</i>	\$12.90	\$103.20 -10
20	1	Front bumper <i>Distorted</i>		\$681.20 ✓
21	2	Front Bumper Side Bracket <i>RH Detkd</i>	\$171.80	\$343.60 -68
22	8	Front bumper clips <i>new</i>	\$12.90	\$103.20 -30
23	1	Front bumper number plate <i>new</i>		\$50.00 x
24	2	Front Bumper Fog lamp <i>RH Missing</i>	\$287.75	\$575.50 -287.75
25	2	Front bumper fog lamp cover <i>RH Missing</i>	\$182.20	\$364.40 -182.20
26	1	Front bumper lower center cover <i>Detkd</i>		\$261.55 ✓

27	1	Front bumper lower garnish	torn		\$281.00	✓
28	1	Front bumper reinforcement	Bent		\$381.20	✓
29	1	Front bumper inner sponge	crushed		\$181.10	✓
30	10	front fender cowling clips	ru	\$12.90	\$129.00	30
31	1	front fender cowling	torn		\$182.40	✓
32	1	Front fender-RH	Distorted		\$561.50	✓
33	1	Front radiator	3 new		\$1,217.80	+
34	1	Front radiator fan motor assy	3 new		\$561.40	+
35	1	Front water tank	crushed		\$188.00	✓
36	1	Front air-con condenser	Not new		\$1,217.80	+
37	1	Front air-con condenser fan motor assy	Not new		\$561.40	+
38	1	front R/H shock absorber	Bent		\$387.40	✓
39	1	front R/H lower arm	Bent		\$365.10	✓
40	1	Front R/H knuckle arm	Not new		\$361.40	+
41	1	front R/H knuckle arm bearing	Done	\$182.50	\$182.50	✓
42	1	Rim-RH	Not new		\$400.00	+
43	1	Tyre-RH	Punctured		\$300.00	180/sv

649575

S.N: 180

Subtotal :-

\$15,980.15

4871.81

Labour charges

Remove & refix front radiator, air cond condenser, fan motor
& top up gas

~~\$300.00~~ 120

Remove & refix Front RH undercarriage

~~\$200.00~~ ✓

Tuff kote

~~\$120.00~~ 50

To Check Wiring System

~~\$60.00~~ 30

Towing charges

2260

~~\$100.00~~ 60

Panel beating

~~\$1,000.00~~ 900

Spray painting

~~\$1,000.00~~ 900

Subtotal :-

\$2,780.00

Total:-

\$18,760.15

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 7311.81

L/S: S-81C ✓

07 Days