

ASS. REC. BY:

REF: CS/MSG19008676/AGtd3/n2 Special Instruction:

Surveyor: Amberney ASSIGNMENT (Office)

From (Person): Ong Zi Hui of MSG Date/Time: 16/5/19 @ 9.08am

Estimated Cost: _____ Bill to: _____

OD WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKT 9217Y Insured: SJT 1910T

at Workshop m/s U2 spray Painting Tel: 92712214

of Blk 25 kaki Bukit Rd 4 #06-43 Synergy

Policy No: _____ Claim No: _____

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 19/05/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement: _____

Date/Time: 9.45am @ 16/5/19 Person Contacted: Chris Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SKT 9217Y - (03/MSG/6007625/Ag 3y 2) Est. Date: 23/04/2016
	SJT 1910T - X
16/5 @ 5:27pm	sent email pending estimate
	lump sum \$3900 (Red: -7985.40; 67%)

ASS. REC. BY:

REF:

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Pot:ty Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKT92174 Yr Regn: 2015 / June

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda 5 c.c. 1998

Colour: Grey A/C: Insured / Std / Nil / NA

Sp. Reading: 93131 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: Jm6chw1077F0121286

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

R/Bal. 06 mm

L/Bal. 06 mm

D.O.A. _____

Sun:ey held at u2 spray painting

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

19 ms16

RECEIVED 13 JUN 2019

MV: 651c

PV: 55.61c

Nett: 9.41c

75702

Date/Time, File Pass to?

1) 12/6 TYP1 st

3) _____

5) _____

Prel. Report: _____

Final Report: _____

Date/Time, File Return to?

2) _____

4) _____

6) _____

Part Prices Check:

IN

OUT

\$3900

Survey Fee:

Date:

Basic & Add.

S + RS \$

Photos

Others

TOTAL

200

11

211

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Thursday, 16 May 2019 5:28 PM
To: Admin-D (LKKAuto); 'Ong Zi Hui'; assignments
Cc: 'Crystal Lee'; SUR
Subject: RE: Survey Request - Manual Assigned

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SKT 9217Y on 15/05/2019
We are pending estimate from repairer.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 16 May 2019 9:43 AM
To: 'Ong Zi Hui' <zihui_ong@sg.msig-asia.com>; assignments <assignments@lkkauto.com>
Cc: 'Crystal Lee' <crystal_lee@sg.msig-asia.com>; SUR <sur@lkkauto.com>
Subject: RE: Survey Request - Manual Assigned

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ong Zi Hui [mailto:zihui_ong@sg.msig-asia.com]
Sent: Thursday, 16 May 2019 9:08 AM
To: admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Crystal Lee <crystal_lee@sg.msig-asia.com>
Subject: Survey Request - Manual Assigned

SKT9217Y & SJT1910T (MSIG) DOA 14.05.2019 (NR case)

Nivitha (LKK Auto)

From: Ong Zi Hui <zihui_ong@sg.msig-asia.com>
Sent: Thursday, 16 May 2019 9:08 AM
To: admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Crystal Lee
Subject: Survey Request - Manual Assigned
Attachments: 16052019090407-0001.pdf

SKT9217Y & SJT1910T (MSIG) DOA 14.05.2019 (NR case)

Manual Assigned

Dear LKK

Refer to the attachment, please survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment.

Thank you.

Ong Zi Hui
Admin Officer, Claims Services
D: +65 6643 1320 | F: +65 6225 7402 | zihui_ong@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Venessa Chan
Sent: Wednesday, 15 May, 2019 4:53 PM
To: chan pick yuen <chris_chanbebe@hotmail.com>
Cc: Nabilah Rasol <nabilah_rasol@sg.msig-asia.com>; Ong Zi Hui <zihui_ong@sg.msig-asia.com>; Crystal Lee <crystal_lee@sg.msig-asia.com>
Subject: SKT9217Y & SJT1910T (MSIG) DOA 14.05.2019 (NR case)

Dear Chris,

Thank you for your selection of LKK Auto Consultants.

We will proceed to appoint LKK Auto Consultants via Merimen at our end and update you upon confirmation.

Please do not contact them directly to prevent confusion.

Please be informed that our surveyor will also be conducting a post repair inspection within the stipulated timeline under the protocol

Thank you.

Have A Great Week Ahead!

Venessa Chan

Admin Officer, Claims Services (Motor)

Direct line +65 6594 2470 | Direct fax +65 6225 7402 | venessa_chan@sg.msig-asia.com



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: chan pick yuen [mailto:chris_chanbebe@hotmail.com]
Sent: Wednesday, 15 May, 2019 2:43 PM
To: Venessa Chan <venessa_chan@sg.msig-asia.com>
Subject: Re: SKT9217Y & SJT1910T (MSIG) DOA 14.05.2019 (NR case)

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear Venessa ,

LKK AUTO CONSULTANT PTE LTD .

Please let us have your surveyor reply soon . Thanks

Regards,
Chris Chan Pick Yuen

From: Venessa Chan <venessa_chan@sg.msig-asia.com>
Sent: Wednesday, May 15, 2019 2:17 PM
To: chan pick yuen
Cc: Nabilah Rasol
Subject: SKT9217Y & SJT1910T (MSIG) DOA 14.05.2019 (NR case)

Dear Chris,

We refer to your email on 15.05.19.

Please choose one surveyor from the list that you wish for us to appoint to conduct the pre-repair inspection:

- 1) LKK Auto Consultants Pte Ltd
- 2) Formteam Consultancy Pte Ltd
- 3) Automobile Inspection Services Pte Ltd
- 4) STA Inspection Pte Ltd
- 5) **MSIG In-House Surveyors (unable to survey today 15.05.19)**

To facilitate an expeditious claim settlement, we hope you are agreeable for the above surveyor to be the SJE (Single Joint Expert).

If not, you may wish to nominate any of the 10 surveyors listed below as the SJE, depending on their availability:

- 1 Calvin Ang
- 2 Kenneth Kong
- 3 Marcus Chua
- 4 Henry Ng
- 5 Lau Kwok Kwong
- 6 Frankie Pang
- 7 Ng You Han
- 8 Gary Soon
- 9 Chow Bo Xiong
- 10 Axel Lee

NB:
(a) *Fast-Lane Settlement is not applicable for cases that liability is in dispute*
(b) If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

We have created a dedicated motor survey mailbox for your motor survey request and pre-repair inspection. Please contact us (MSIG) by clicking this link: motorsurvey@sg.msig-asia.com

Thank you

Have A Great Week Ahead!

Venessa Chan

Admin Officer, Claims Services (Motor)

Direct line +65 6594 2470 | Direct fax +65 6225 7402 | venessa_chan@sg.msig-asia.com



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: chan pick yuen <chris_chanbebe@hotmail.com>

Sent: Wednesday, 15 May 2019 8:57 AM

To: Claims <claims@sg.msig-asia.com>

Subject: SKT9217Y & SJT1910T DOA 14.05.2019

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear Sir / Mdm ,

Enclosed is our client's GIA report .

Please let us have your 10 name list of surveyor to survey our client's car : SKT9217Y . Thanks

Regards,
Chris Chan Pick Yuen
U2 SPRAY PAINTING PTE LTD
HP: 92712214

Chris Chan

To: chan pick yuen <chris_chanbebe@hotmail.com>
From: Venessa Chan
Date: Wednesday, 15 May, 2019 6:45 PM
Subject: Re: SKT9217Y & SJT1910T (MSIG) DOA 14.05.2019 (NR case)

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear Venessa,

US SPRAY PAINTING PTE LTD
BLK 25 KAKI BUKIT ROAD 4
06-43 SYNERGY @ KB
SINGAPORE 417800

Regards,
Chris Chan Pick Yuen

From: Venessa Chan <venessa_chan@sg.msig-asia.com>
Sent: Wednesday, May 15, 2019 4:57 PM
To: chan pick yuen
Cc: Nabillah Rasol; Ong Zi Hui; Crystal Lee
Subject: RE: SKT9217Y & SJT1910T (MSIG) DOA 14.05.2019 (NR case)

Dear Chris,

Please assist to provide us your workshop details.

Thank you.

Have A Great Week Ahead!

Venessa Chan
Admin Officer, Claims Services (Motor)
Direct line +65 6594 2470 | Direct fax +65 6225 7402 | venessa_chan@sg.msig-asia.com




Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Venessa Chan
Sent: Wednesday, 15 May, 2019 4:53 PM
To: chan pick yuen <chris_chanbebe@hotmail.com>



FOR SALE BY OWNER

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#) | [Advertiser Login](#) | [Ways of Selling](#)

New 5 Years Coe Renewal Toyota Vios 1.5A

2.98% P.A \$0 Admin Fees @ GV
Finance 2 Years Warranty \$1500
Down Monthly From \$448
GV Credit Fin Ltd StarAd

HIN LUNG AUTO **30 years of car sale**

HoBee Group

One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars

Browse by Category Save Search Sort by Date Posted 20 results/page

6 vehicles | Search Advanced Search Search View All

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

Search Selection mazda 5 Any Any 2015 Any Any Any Available



Mazda 5 2.0A Sunroof \$63,800 \$10,070 /yr 30-Jan-2015 1,998 cc 88,000 km MPV Available

1 Owner, Well Taken Care By The Previous Owner. Loan Available With High Trade In. Price Negotiable. Call Now Or Visit Our Showroom Today!

Posted: 03-Apr-2019 Tags: 2015 Mazda 5, 2015 mazda 5, Mazda 5, mazda 5, Mazda, 5, Used Mazda



Mazda 5 2.0A Sunroof \$68,800 \$10,500 /yr 20-Apr-2015 1,998 cc 47,000 km MPV Available

1 Owner, Low Mileage Done Only 47,000Km, Full Serviced Histories With Agent, 100% Loan Available, Ex-Bankruptcy And Bad Credit Welcome, High Trade In.

Faster Auto Trading

Posted: 04-May-2019 Tags: 2015 Mazda 5, 2015 mazda 5, Mazda 5, mazda 5, Mazda, 5, Used Mazda



Mazda 5 2.0A Sunroof \$66,800 \$10,070 /yr 13-May-2015 1,998 cc 80,000 km MPV Available

Well Taken Care By The Previous Owner. High Loan And Trade In Available. Skyactive Engine Supreme Fuel Consumption For A Big MPV! Viewing By Appointment Only. Consignment Unit.

Posted: 01-Apr-2019 Tags: 2015 Mazda 5, 2015 mazda 5, Mazda 5, mazda 5, Mazda, 5, Used Mazda



Mazda 5 2.0A Sunroof \$66,800 \$9,970 /yr 17-Jun-2015 1,998 cc 85,000 km MPV Available

Attractive Depreciation Of Below 10k.! With Set Of Tyres Newly Replaced & Exterior New Coat Of Paint & Polished! Major Servicing Just Done At Mazda Service Centre! A Family Car With Generous & Flexibl...

Eurokars Pre Owned

Posted: 25-Apr-2019 Tags: 2015 Mazda 5, 2015 mazda 5, Mazda 5, mazda 5, Mazda, 5, Used Mazda

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle

STA **Buying a pre-owned car, but Unsure of its Condition?**
Get STA Car Evaluation



Mazda 5 2.0A Sunroof \$70,800 \$10,540 /yr 30-Jun-2015 1,998 cc 38,896 km MPV Available

A Family Car With Generous Cabin Space And Relatively Fuel Efficient Family Transportation! Financing Packages Available! Trade In Welcome! Buy With Confidence From Mazda/Eurokars Pre-Owned Centre! Hi...

Posted: 08-May-2019 Tags: 2015 Mazda 5, 2015 mazda 5, Mazda 5, mazda 5, Mazda, 5, Used Mazda



Mazda 5 2.0A Sunroof \$82,888 \$11,290 /yr 24-Nov-2015 1,998 cc 42,000 km MPV Available

1 Owner! AA Trust Certified Quality 1 Owner Vehicle! Extremely Well Maintained By 1 Owner Only! Extremely Low Mileage! Yet Another Popular MPV Stock By Demand In The Market! Flexible Bank/In-House Loa...

AA Trust Automotive

Posted: 01-May-2019 Tags: 2015 Mazda 5, 2015 mazda 5, Mazda 5, mazda 5, Mazda, 5, Used Mazda

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For all advertisements view Expired ads

SHORTLISTED HISTORY

PARF/COE Rebate Enquiry

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC
7570Z

Owner ID:

Vehicle Details

Vehicle No:

SKT9217Y

Vehicle to be Exported:

Yes

Intended Deregistration Date:

15 May 2019

Vehicle Make:

MAZDA

Vehicle Model:

MAZDA5 5-DOOR WAGON 2.0L 5P.6EAT SUNROOF

Primary Colour:

Grey

Secondary Colour:

Black

Manufacturing Year:

2015

Engine No.:

PE10213490

Chassis No.:

JM6CW1071F0121286

Maximum Power Output:

111.0 kW (148 bhp)

Open Market Value:

\$18,069.00

Original Registration Date:

25 Jun 2015

First Registration Date:

25 Jun 2015

Transfer Count:

0

Actual ARF Paid:

\$13,069.00

Intended PARF Rebate Details:

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

24 Jun 2025

PARF Rebate Amount:

\$9,801.00

Intended COE Rebate Details:

COE Expiry Date:

24 Jun 2025

COE Category:

B - Car above 1600cc or 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$75,000.00

COE Rebate Amount:

\$45,812.00

Total Rebate Amount:**\$55,613.00**

The information contained herein is correct as at 15 May 2019

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7570Z
Vehicle Details	
Vehicle No.:	SKT9217Y
Vehicle to be Exported:	Yes
Intended Deregistration Date:	16 May 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA5 5-DOOR WAGON 2.0L SP.6EAT SUNROOF
Primary Colour:	Grey
Secondary Colour:	Black
Manufacturing Year:	2015
Engine No.:	PE10213490
Chassis No.:	JM6CW1071F0121286
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$18,069.00
Original Registration Date:	25 Jun 2015
First Registration Date:	25 Jun 2015
Transfer Count:	0
Actual ARF Paid:	\$13,069.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Jun 2025
PARF Rebate Amount:	\$9,801.00
Intended COE Rebate Details	
COE Expiry Date:	24 Jun 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$75,000.00
COE Rebate Amount:	\$45,791.00
Total Rebate Amount:	\$55,592.00

The information contained herein is correct as at 16 May 2019

OK

U2 SPRAY PAINTING PTE LTD

Block 25 KAKI BUKIT ROAD 4 #06-43 SYNERG @KB (S)417800

Tel : (65) 65250431 HP: 92712214

Email : chris_chanbebe@hotmail.com

JMB6CW1071 F 0121286.

15th MAY 2019

MOHD JAILANI BIN MUSA
Bk 25 Kaki Bukit Rd 4
06-43 SYNERGY @KB
Singapore 417800

TPMS 16.
Denise

Accident date: 15th MAY 2019

Estimated repair cost for vehicle no: SKT9217Y MAZDA 5 2.0 '15

S/n	Qty	Items	U/price	Amount
				\$1,252.20 ✓
1	1	Rear Boot Lid <i>Dented</i>		\$35.00 ✓
2	1	Rear Boot Lid Mazda 5 logo		\$30.90 ✓
3	1	Rear Boot Lid mazda logo		\$58.50 ✓
4	1	Rear Boot Lid mazda emblem		\$125.20 ✓
5	1	Rear Boot Lid windscreen inner seal <i>new</i>	\$558.20	\$1,116.40 +
6	2	boot lid lamp <i>new</i>		\$155.20 +
7	1	Rear Boot Lid rubber <i>new</i>		\$257.90 ✓
8	1	Rear Boot Lid Inner Lock <i>Damaged.</i>	\$625.20	\$1,250.40 +
9	2	Rear tail lamp <i>new</i>		\$485.10 ✓
10	1	Rear end panel <i>Dented</i>		\$165.20 ✓
11	1	Rear End Panel Top Garnish <i>deformed.</i>		\$955.40 915.40 ✓
12	1	Rear Bumper <i>deformed.</i>		\$116.40 ✓
13	2	Rear Bumper Side Bracket <i>new</i>	\$58.20	\$90.80 +
14	2	Rear Bumper towing cover <i>new</i>	\$45.40	\$130.00 +
15	2	Rear Bumper side reflector <i>new</i>	\$65.00	\$110.40 +
16	2	Rear Bumper bracket <i>new</i>	\$55.20	\$72.40 +
17	4	Rear Bumper center clips - out <i>new</i>	\$18.10	\$62.40 +
18	4	Rear Bumper center clips - in <i>new</i>	\$15.60	\$62.40 +
19	1	Rear Bumper reverse sensor assy <i>Damaged</i>		\$350.00 200 (SN) ✓
20	1	Rear Bumper reinforcement <i>sent</i>		\$568.70 148 ✓
21	8	Rear bumper clips <i>new</i>	\$55.50	\$444.00 30 ✓
22	1	rear bumper lower cover <i>new</i>		\$388.50 +
23	1	Rear Exhaust <i>new</i>		\$1,562.20 +
24	1	raer exhaust chrome pipe <i>new</i>		\$112.20 +
Subtotal :-				\$9,495.40

3619.80 S.N. 200
2895.84

Labour charges

To Remove & refix rear cushion

~~\$120.00~~ 60

To Remove & refix rear exhaust

\$200.00 X

To Remove & refix rear windscreen

\$120.00 ✓

Gum

\$50.00 ✓

To Remove & refix reverse Sensor

~~\$120.00~~ 50

Tuff kote

~~\$120.00~~ 60

To Check Wiring System

\$60.00 30

Towing charges

\$0.00 X

Panel beating

~~\$800.00~~ 700

Spray painting

~~\$800.00~~ 700

1770

Subtotal :- \$2,390.00

Total:- \$11,885.40

total: 4865.84

H/S: 3.9k.

06 Days.

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19008670/AGTD3N2
Date: 17/06/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29091761
Claimant:	SKT9217Y	Insured Vehicle No :	SJT1910T
Vehicle No :		Nature of Claim:	TP
Date of Loss:	14/05/2019	Claim No:	593637

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKT9217Y	Engine No:	PE10213490
Make & Model:	MAZDA 5, 2.0 SP.6EAT SUNROOF (A)	Chassis No:	JM6CW1071F0121286
Reg. Date:	25/06/2015 (Man. Year: 2015)	Odometer:	93131 km
Colour:	Grey		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	9,545.40	3,145.84	6,399.56	67.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,340.00	1,720.00	620.00	26.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,885.40	4,865.84	7,019.56	59.06
Approved Total (Overridden) (S\$)		3,900.00		
Nett Amount (S\$)	11,885.40	3,900.00	7,985.40	67.19

INSPECTION

Date of Assignment: 17/05/2019
Date Inspected: 15/05/2019 Inspected At:

U2 Spray Painting Pte Ltd (HQ)
BLOCK 25 KAKI BUKIT ROAD 4 #06-
43 SYNERGY @ KB
Singapore 417800

Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source:	(Last Synchronised: 17 Jun 2019)
Parts:	N/A MAZDA 5 2.0 SP.6EAT SUNROOF (A) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKT9217Y)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Dented	1,252.20 F	*1,252.20 FL
2	1		*REAR BOOT LID MAZDA 5 LOGO	Necessary	35.00 F	*35.00 FL
3	1		*REAR BOOT LID MAZDA LOGO	Necessary	30.90 F	*30.90 FL
4	1		*REAR BOOT LID MAZDA EMBLEM	Necessary	58.50 F	*58.50 FL
5	1		*REAR BOOT LID WINDSCREEN INNER SEAL	Necessary	125.20 F	*125.20 FL
6	2		*BOOT LID LAMP	Not Necessary	1,116.40 F	*- FL
7	1		*REAR BOOT LID RUBBER	Not Necessary	155.20 F	*- FL
8	1		*REAR BOOT LID INNER LOCK	Damaged	257.90 F	*257.90 FL
9	2		*REAR TAIL LAMP	Not Necessary	1,250.40 F	*- FL
10	1		*REAR END PANEL	Dented	485.10 F	*485.10 FL
11	1		*REAR END PANEL TOP GARNISH	Deformed	165.20 F	*165.20 FL
12	1		*REAR BUMPER	Deformed	955.40 F	*915.40 FL
13	2		*REAR BUMPER SIDE BRACKET	Necessary	116.40 F	*116.40 FL
14	2		*REAR BUMPER TOWING COVER	Not Necessary	90.80 F	*- FL
15	2		*REAR BUMPER SIDE REFLECTOR	Not Necessary	130.00 F	*- FL
16	2		*REAR BUMPER BRACKET	Not Necessary	110.40 F	*- FL
17	4		*REAR BUMPER CENTER CLIPS-OUT	Not Necessary	72.40 F	*- FL
18	4		*REAR BUMPER CENTER CLIPS-IN	Not Necessary	62.40 F	*- FL
19	1		*REAR BUMPER REINFORCEMENT	Bent	568.70 F	*148.00 FL
20	8		*REAR BUMPER CLIPS	Necessary	44.00 F	*30.00 FL
21	1		*REAR BUMPER LOWER COVER	Not Necessary	388.50 F	*- FL
22	1		*REAR EXHAUST	Not Necessary	1,562.20 F	*- FL
23	1		*REAR EXHAUST CHROME PIPE	Not Necessary	112.20 F	*- FL
24	1		*REAR BUMPER REVERSE SENSOR ASSY	Damaged	350.00 FS	*200.00 FS
25	1		*GUM	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,545.40	3,869.80
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	723.96
Total Parts (\$\$)	9,545.40	3,145.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIX REAR CUSHION	New	120.00	60.00
2	TO REMOVE & REFIX REAR EXHAUST	New	200.00	0.00
3	TO REMOVE & REFIX REAR WINDSCREEN	New	120.00	120.00
4	TO REMOVE & REFIX REVERSE SENSOR	New	120.00	50.00
5	TUFF KOTE	New	120.00	60.00
6	TO CHECK WIRING SYSTEM	New	60.00	30.00
7	TOWING CHARGES (NPA)	New	0.00	0.00
8	PANEL BEATING	New	800.00	700.00
9	SPRAY PAINTING	New	800.00	700.00
Gross Labour Cost (\$\$)			2,340.00	1,720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >