


> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	731J
Vehicle Details	
Vehicle No.:	SLT1756Z
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Sep 2019
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 CVT
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	2ZR0A21370
Chassis No.:	JTDGG20W40J008042
Maximum Power Output:	105.0 kW (140 bhp)
Open Market Value:	\$19,955.00
Original Registration Date:	20 Oct 2017
First Registration Date:	20 Oct 2017
Transfer Count:	0
Actual ARF Paid:	\$19,955.00 8877
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Oct 2027
PARF Rebate Amount:	\$14,966.00
Intended COE Rebate Details	
COE Expiry Date:	19 Oct 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$48,109.00
COE Rebate Amount:	\$39,095.00
Total Rebate Amount:	\$54,061.00

The information contained herein is correct as at 03 Sep 2019

OK



FALCON-AIR

MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE SINGAPORE 068877

Attention : Motor Claim Department
Contact : 62222311 Fax No. : 62223547

FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

Estimate : ES707472

Date : 02/09/2019
Vehicle Num. : SLT 1756Z
Make/Model : TOYOTA WISH
Chassis/Eng# : JTDGG20W40J008042
Accident Date : 28/12/2019
Claim No. :
Reference : 3PTY
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	12 PC	LIST ITEMS :		
2.	1 PC	FRONT BUMPER CLIP	5.00 <i>net</i>	60.00
3.	1 pc	O/S FRONT BUMPER SIDE RETAINER	<i>SVC</i> 69.70	
		FRONT BUMPER	<i>cut/pe</i> 784.70	
				645.10
		List TotalS\$:		914.40
		25.00% Discount S\$:		228.60
				685.80
		LABOUR :		
		TO CHECK WIRING AND LIGHT SYSTEM	20	50.00
		TO REMOVE NECESSARY PARTS TO REPAIR INNER PANEL, REPLACE	250	300.00
		ACCIDENT DAMAGED PARTS	400	500.00
		TO PUTTY AND RESPRAY ACCIDENT DAMAGED AREAS		
		Labour Total S\$:		850.00

E. & O.E. Total S\$: 1,535.80

for FALCON AIR AUTO SERVICES PTE LTD

TAMPINES BRANCH

- Link Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg

P-705.10
252
528.82
1198.82

Not Allowed
Link
Take the Behrman
P/P * 1198.82
327.
2/9/19



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19008673/Uqd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 10-09-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 8660S	Veh. Inspected	SLT 1756Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19003180MFSH	Excess (\$)	0.00	
Assign From	HENRY KAO	Assign Date	15/05/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA WISH (A)	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDGG20W40J008042	Colour	WHITE	
Odometer	33263	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	GOODYEAR	6 mm	
L/H Front Tyre	195/65 R15	GOODYEAR	6 mm	
R/H Rear Tyre	195/65 R15	GOODYEAR	6 mm	
L/H Rear Tyre	195/65 R15	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/12/2018	Inspection Date	02/09/2019	
Survey held at	FALCON-AIR AUTO SERVICES PTE LTD BLK 9006 TAMPINES ST 93 #01-200 SINGAPORE 528840			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 1756Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
12	FRONT BUMPER CLIP @\$5.00	NECESSARY	60.00	60.00
1	O/S FRONT BUMPER SIDE RETAINER	SERVICEABLE	69.70	-
1	FRONT BUMPER	CUT / DEFORMED	784.70	645.10
	LESS 25% DISCOUNT		-228.60	-176.28
			685.80	528.82
LABOUR				
	TO CHECK WIRING AND LIGHT SYSTEM.		50.00	20.00
	TO REMOVE NECESSARY PARTS TO REPAIR INNER PANEL.REPLACE ACCIDENT DAMAGED PARTS.		300.00	250.00
	TO PUTTY AND RESPRAY ACCIDENT DAMAGED AREAS.		500.00	400.00
			850.00	670.00
GRAND TOTAL			1,535.80	1,198.82
RECOMMENDED COST OF REPAIRS				1,198.82

Report Ref No. CS/FCI19008673/Uqd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.