

ASS. REC. BY:

REF: CBS/SPF18022678/R1vd3-1 Special Instruction:

Surveyor: ASSIGNMENT (Office)

From (Person): Frankie They of SPF Date/Time: 14/05/2019

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EYA / INV / MV / CS

To Inspect Vehicle No: SLF 909E Insured: Ym 41708

at Workshop m/s: Miracle Works Tel:

of: 48 Toh Guan Rd East #04-126

Policy No: Claim No: AEMD/105/009/2018/172

Sum Insured: Excess:

Make of Veh: D.O.A. 14-12-2018

(Client's Record) 07-01-2019 @ after 12pm H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS Wp. 18/12/2018 2:40pm Person Contacted: Nicole Vehicle IN/OUT

Date/Time: 18/12/2018 2:40pm

Date/Time	Action/Instruction ( x ) Estimate
	SLF 909E - x
	Ym 41708 x
16/1/19	Submit LS \$ 1650, 3 days Upper range \$2K - \$3K 400 - 500

10/6/19 Submit \$ 475, (Red 8125, 9490), 2 days

*[Signature]*  
3/6/2019

Do Not Finalise

RECEIVED 10 JUN 2019



## Nivitha (LKK Auto)

---

**From:** Hafizul Farhan RAHMAT (SPF) <Hafizul\_Farhan\_RAHMAT@spf.gov.sg>  
**Sent:** Tuesday, 14 May 2019 3:19 PM  
**To:** Admin-D (LKKAuto); assignments  
**Cc:** Frankie THAY (SPF); Abdul Rahman MOHAMAD SALIM (SPF)  
**Subject:** Re-Survey for SLF909E (YM4710B)

Our ref: AEMD/105/009/2018/172

Hi,

Kindly conduct a re-survey for vehicle SLF909E, we are still unable to close the gap on the third-party claim amount of \$9,202.

Thank you.

*Best Regards,*

*Hafizul Farhan Bin Rahmat*

*AEMD / PLD*

*Singapore Police Force*

*DID: (65) 6478 4840 | FAX: (65) 6478 4850*



**WARNING:** "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	17/12/2018 13:15
Date Of Accident	14/12/2018 19:30
Exact Location Of Accident	BLK 921 OPEN SPACE CARPARK JURONG WEST ST 92
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLF909E
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TAN KIAN WAI
NRIC No	S8270704B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90618558
Alternative Phone No	OFFICE-90618558
<b>Vehicle Particulars</b>	
Manufacturer	MERCEDES-BENZ
Model	C250 CGI
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5105345145
Cover Note Number	
<b>Driver</b>	
Name of Driver	TAN KIAN WAI
NRIC No	S8270704B
Date Of Birth	20/05/1980
Occupation	OUTDOOR
Date Of Driving Pass	03/08/2007
Driving Experience	11 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90618558
Fax Number	
Contact Number	OFFICE-90618558
EMail Address	NOEMAIL

Address 192 WESTWOOD AVENUE #10-25 WESTWOOD RESIDENCES  
 Postcode 648151  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OWNER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident COLLIDED INTO PARKED VEHICLE  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident 2  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 0

**Details of Police Action**

Was the accident reported to the police? YES  
 If Yes Please state which Police Station  
 Police Station Name NANYANG N.P.C  
 Police Station Address ROAD: 2 JURONG WEST AVE 5 , POSTCODE: 649482 , COUNTRY: SINGAPORE  
 Police Station Contact TEL NO: 1800-7929999 - FAX NO:  
 Was notice of intended Prosecution given? NO  
 If Yes,against whom?

**Circumstances of Accident**

REFER POLICE REPORT (ATTENDED BY: JAMES NG)

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? YES  
 Remarks/ Reasons: CANNOT BE UPLOADED  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number YM4170B  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category COMMERCIAL VEHICLE  
 Name of Driver RIZAL  
 NRIC/Passport Number  
 Contact Number 90092864  
 Address  
 Postcode  
 Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

## AUTOMOBILE ASSESSMENT REPORT

TO: TAN KIAN WAI  
C/O: MIRACLE WORKZ PTE LTD  
48 TOH GUAN ROAD EAST,  
#04-126 ENTERPRISE HUB,  
SINGAPORE 608586

Our Reference: 119/MW009  
Date: 28-Jan-2019

**ASSESSMENT OF VEHICLE NO. SLF 909 E**  
**DATE OF LOSS: 14-Dec-2018**

We have carried out a physical assessment at **MIRACLE WORKZ PTE LTD**,  
48 Toh Guan Road East, #04-126 Enterprise Hub, Singapore 608586, according to your instruction  
on **07-Jan-2019** and are pleased to submit our report herewith.

### 1. VEHICLE PARTICULARS

Registration No.: SLF 909 E  
Make & Model: MERCEDES BENZ C250 AMG LINE (R18 LED)  
Year of Registration: 2015  
Engine Capacity: 1991  
Chassis No.: WDD2050452R058523  
Engine No.: 27492030342342  
Colour: WHITE  
Mileage (km): 29575

### 2. VEHICLE CONDITION

Body Paint: GOOD  
Steering: SERVICEABLE  
Foot Brake: SERVICEABLE  
Parking Brake: SERVICEABLE  
Modification: NIL


### 3. TYRE PARTICULARS & CONDITION

Front  
RH Make/Size/Thread: MICHELIN 225/40 R19 - 80%  
LH Make/Size/Thread: MICHELIN 225/40 R19 - 80%

Rear  
RH Make/Size/Thread: MICHELIN 225/40 R19 - 80%  
LH Make/Size/Thread: MICHELIN 225/40 R19 - 80%

#### 4. DESCRIPTION OF DAMAGE

At the time of the inspection, the vehicle sustained damages to the FRONT portion



#### 5. REMARKS

Market Value: Na  
Salvage Value: Na  
Repair Limit: Na

Estimated Amount: \$13,895.10  
Assessed Amount: \$11,205.60  
Lump Sum: **\$8,600.00**  
Estimated Repair Days: 7 days

Pursuant to your instruction, we have **NOT AUTHORISED** repair.  
The assessment was conducted on a "**Without Prejudice**" basis.  
If we are not notified of anything to the contrary within **14 days** from the date hereof, this report shall be treated as correct.

#### Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by Aeon Auto Consultants LLP for any reliance on this report by any third party.

**ASSESSMENT REPORT FOR VEHICLE NO. SLF 909 E**

**PARTS (LIST ITEMS)**

Qty	Description	Condition	Workshop's Estimate	Our Assessment
1	FRONT BONNET	Repair	1,850.00	X
1	FRONT BONNET 'LOGO' EMBLEM	Reuse	55.00	X
2	FRONT BONNET LOCK STRIKER L/R	Bent	60.00	X 60.00
2	FRONT BONNET MECHANISM LOCK L/R	Bent	390.00	X 390.00
2	FRONT BONNET RUBBER GUIDE STOPPER L/R	Bent	18.00	X 18.00
1	FRONT BONNET WEATHER STRIP	Cut	135.00	X 135.00
2	FRONT HEADLAMP L/R	Cracked	3,150.00	X 3,150.00
1	FRONT GRILLE	Cracked	768.00	X 768.00
1	FRONT GRILLE 'LOGO' EMBLEM	Cracked	123.00	X 123.00
1	FRONT GRILLE 'LOGO' EMBLEM BASE	Cracked	85.00	X 85.00
1	FRONT GRILLE CHROME GARNISH ASSY	Cracked	297.00	X 297.00
1	FRONT BUMPER	Reuse	1,420.00	X 1,420.00
1	FRONT BUMPER INNER FRAME	Bent	350.00	X 350.00
6	FRONT BUMPER PARKING SENSOR (ORIGINAL)	Faulty	1,650.00	X 1,650.00
6	FRONT BUMPER PARKING SENSOR HOLDER	Necessary	111.00	X 111.00
6	FRONT BUMPER PARKING SENSOR RUBBER SEAL	Necessary	33.00	X 33.00
1	FRONT BUMPER PARKING SENSOR WIRE HARNESS - SET	Repair	268.00	X
2	FRONT BUMPER FOGLAMP GARNISH L/R	Cracked	178.00	X 178.00
2	FRONT AIRBAG SENSOR	Reuse	382.00	X
1	FRONT BUMPER SPONGE	Cracked	295.00	X 295.00
1	FRONT BUMPER LOWER CENTER GRILLE	Cracked	65.00	X 65.00
1	FRONT BUMPER DIFFUSER CHROME MOULDING	Cracked	650.00	X 650.00
2	FRONT BUMPER SIDE BRACKET L/R	Bent	114.00	X 114.00
2	FRONT BUMPER SIDE RETAINER L/R	Bent	70.00	X 70.00
1	FRONT BUMPER TOW HOOK COVER	Necessary	72.00	X 72.00
			12,589.00	10,034.00
Less 10% discount			1,258.90	1,003.40
Parts Total:			11,330.10	9,030.60

0

**ASSESSMENT REPORT FOR VEHICLE NO. SLF 909 E**

**SPECIAL NETT ITEMS**

1	FRONT BUMPER NUMBER PLATE	Bent	25.00	25.00
1	FRONT BUMPER NUMBER PLATE HOLDER	Cracked	50.00	50.00
1	FRONT BUMPER CLIPS - SET	Necessary	50.00	50.00
Special Nett Total			<u>125.00</u>	<u>125.00</u>

**LABOUR**

S/N	Description	Workshop's Estimate	Our Assessment
1	To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.	140.00	120.00
2	To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,000.00	350.00
3	To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	400 1,200.00	250 1,000.00
4	To apply anti-rust chemical on repaired and replaced panel.	100.00	80.00
Labour Total :		<u>2,440.00</u>	<u>2,050.00</u>
<b>TOTAL (PARTS &amp; LABOUR) \$</b>		<u>13,895.10</u>	<u>11,205.60</u>

The workshop has agreed to undertake the repair on a Lump Sum basis.

The final adjusted Lump Sum contract amount is

**\$8,600.00**

**(SINGAPORE DOLLARS EIGHT THOUSAND SIX HUNDRED ONLY)**



Amas Ong  
 Automobile Assessor

75.00  
 400.00  
475.00

2 days

P/P



## MIRACLE WORKZ PTE LTD

CO REF 201119510W  
GST Registration No 201119510W  
NO 48 TOH GUAN ROAD EAST  
#04-126 ENTERPRISE HUB  
SINGAPORE 608586  
DIRECT LINE 96472568  
TEL 64683096  
FAX 65155434


Attn. SPF Accident Claims Section  
Automotive Engineering & Management Division  
Police Logistics Department  
1 Mount Pleasant Road  
Block 8 Old Police Academy  
Singapore 298333

Final Bill: MW-298-909  
Date: 25/01/2019  
Vehicle No: SLF909E  
Make & Model: Mercedes Benz C250  
Accident Date: 14/12/2018  
Third Party Vehicle: YM4710B

S/N	DESCRIPTION	AMOUNT
1	REPAIR COST (LUMPSUM)	\$8,600.00

**SUB TOTAL** \$8,600.00  
**7% GST TOTAL** \$602.00  
**GRAND TOTAL** \$9,202.00

Kindly make payment to : MIRACLE WORKZ PTE LTD

  
MIRACLE WORKZ PTE LTD



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION

Ref : CS3/SPF18022678/R1vd3s2-1

ACCIDENT CLAIM SECTION (SPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMYSINGAPORE 298333

Date : 18-06-2019



ATTN: HAFIZUL FARHAN

Code : SPF

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YM 4170B	Veh. Inspected	SLF 909E
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2018/172	Excess (\$)	0.00
Assign From	HAFIZUL FARHAN	Assign Date	14/05/2019

## 2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ C250 AMG	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WDD2050452R058523	Colour	WHITE
Odometer	29575	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/40ZR19	MICHELIN	6 mm
L/H Front Tyre	225/40ZR19	MICHELIN	6 mm
R/H Rear Tyre	225/40ZR19	MICHELIN	6 mm
L/H Rear Tyre	225/40ZR19	MICHELIN	6 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.
---

## 5. General Information

Accident Date	14/12/2018	Inspection Date	07/01/2019
Survey held at	MIRACLE WORKZ PTE LTD 48 TOH GUAN ROAD EAST #04-126 ENTERPRISE HUB SINGAPORE 608586		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>2 Working Days</b>
-------------------------------------	-----------------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 909E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT BONNET	NOT NECESSARY	1,850.00	-
1	FRONT BONNET 'LOGO' EMBLEM	NOT NECESSARY	55.00	-
2	FRONT BONNET LOCK STRIKER L/R	NOT NECESSARY	60.00	-
2	FRONT BONNET MECHANISM LOCK L/R	NOT NECESSARY	390.00	-
2	FRONT BONNET RUBBER GUIDE STOPPER L/R	NOT NECESSARY	18.00	-
1	FRONT BONNET WEATHER STRIP	NOT NECESSARY	135.00	-
2	FRONT HEADLAMP L/R	NOT NECESSARY	3,150.00	-
1	FRONT GRILLE	NOT NECESSARY	768.00	-
1	FRONT GRILLE 'LOGO' EMBLEM	NOT NECESSARY	123.00	-
1	FRONT GRILLE 'LOGO' EMBLEM BASE	NOT NECESSARY	85.00	-
1	FRONT GRILLE CHROME GARNISH ASSY	NOT NECESSARY	297.00	-
1	FRONT BUMPER	TO REPAIR SEE LABOUR	1,420.00	-
1	FRONT BUMPER INNER FRAME	NOT NECESSARY	350.00	-
6	FRONT BUMPER PARKING SENSOR (ORIGINAL)	NOT NECESSARY	1,650.00	-
6	FRONT BUMPER PARKING SENSOR HOLDER	NOT NECESSARY	111.00	-
6	FRONT BUMPER PARKING SENSOR RUBBER SEAL	NOT NECESSARY	33.00	-
1	SET FRONT BUMPER PARKING SENSOR WIRE HARNESS	NOT NECESSARY	268.00	-
2	FRONT BUMPER FOGLAMP GARNISH L/R	NOT NECESSARY	178.00	-
2	FRONT AIRBAG SENSOR	NOT NECESSARY	382.00	-
1	FRONT BUMPER SPONGE	NOT NECESSARY	295.00	-
1	FRONT BUMPER LOWER CENTER GRILLE	NOT NECESSARY	65.00	-
1	FRONT BUMPER DIFFUSER CHROME MOULDING	NOT NECESSARY	650.00	-
2	FRONT BUMPER SIDE BRACKET L/R	NOT NECESSARY	114.00	-
2	FRONT BUMPER SIDE RETAINER L/R	NOT NECESSARY	70.00	-
1	FRONT BUMPER TOW HOOK COVER	NOT NECESSARY	72.00	-
	LESS 10% DISCOUNT		-1,258.90	-
			11,330.10	-
<b>SPECIAL NETT ITEMS</b>				
1	FRONT BUMPER NUMBER PLATE (SN)	BENT	25.00	25.00
1	FRONT BUMPER NUMBER PLATE HOLDER (SN)	CRACKED	50.00	50.00
1	SET FRONT BUMPER CLIPS (SN)	NOT NECESSARY	50.00	-
			125.00	75.00

Report Ref No. CS3/SPF18022678/R1vd3s2-1



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND REWIRE FOR PARKING SENSOR.	NOT NECESSARY	140.00	-
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		1,000.00	150.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRONT BUMPER.		1,200.00	250.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLAED PANEL.	NOT NECESSARY	100.00	-
			2,440.00	400.00
	<b>GRAND TOTAL</b>		<b>13,895.10</b>	<b>475.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>475.00</b>

Report Ref No. CS3/SPF18022678/R1vd3s2-1

THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$3,000.00

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.