

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 3163H

DATE 16/5/2019 13:37

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper			\$ 553.00
	Rear Bumper Clip 10 pcs			\$ 22.00
	Rear Bumper Under Cover X			\$ 228.00
	SUB TOTAL			\$ 803.00
	LESS 20%			\$ 160.60
	DISCOUNTED TOTAL			\$ 642.40
	Labour Charge			
	Panel Beating			\$ 400.00 200
	Spray Painting Charge			\$ 300.00 200
	Wiring Charge			\$ 30.00 X
	Remove/Refix Reverse Sensor			\$ 80.00 70
	TOTAL LABOUR			\$ 810.00
	ESTIMATE TOTAL			\$ 1,452.40
<p>Katun'Uley</p> <p>1345 hrs. 16/5/19</p> <p>2 Days,</p> <p>4/5</p> <p>After Repair & Ltr</p> <div data-bbox="812 1407 1331 1848"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before repair commencing • To display damaged parts for survey • Parts prices are subject to market basis • Third party survey is on a 'no win, no fee' basis • No illegal modifications are allowed • Supplementary item(s) must be returned and is subject to final approval from insurance company <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p> </div>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				